

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8152S

DATE 4/6/2018 11:25

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Door (RH) <i>X Rep</i>			\$ 1,351.10	
	Front Door (RH) <i>—</i>			\$ 1,403.05	
	Rocker Panel Outer Garnish (RH) <i>X Rep</i>			\$ 483.60	
	Rear Wheel Hub-Cap (RH) <i>—</i>			\$ 150.70	
	<i>Rev Bumper X Repair</i>				
	<i>Rev RH Fender X Repair</i>				
	SUB TOTAL			\$ 3,388.45	
	LESS 20%			\$ 677.69	
	DISCOUNTED TOTAL			\$ 2,710.76	
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>—</i>			\$ 80.00	Nett
	Front Door Coloured Comfort Logo (RH) <i>—</i>			\$ 75.00	Nett
				\$ 205.00	
	Labour Charge				
	Panel Beating-Repair Rear Fender			\$ 560.00 <i>400</i>	
	Spray Painting Charge-Door x2, Fender/Bumper			\$ 1,250.00 <i>1000</i>	
	Wiring Charge			\$ 50.00 <i>X</i>	
	Tuff Kote			\$ 50.00 <i>20</i>	
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X</i>	
	Transfer of Door		\$ 120.00	\$ 240.00 <i>50</i>	
	Rear Wheel Alignment			\$ 120.00 <i>X</i>	
				\$ 2,390.00	
				\$ 5,305.76	

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL LABOUR

ESTIMATE TOTAL

Kahm 11/11/14

4/6/18 1200h

3 Days

PIP Before Part pth