

ESTIMATE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

JM6BN4A8J0208415

TPEQ
Vic

Estimate Ref : 20332

Date : 04.06.2018

Vehicle Num : SLX 9203D

Make/Model : MAZDA 3

Chassis/Eng# :

Accident Date : 03.06.2018

Claim No : 0618-20332

Reference :

Policy No :

Particular	Amount S\$
List item	Unit price
1 Pc Head Lamp <i>at</i>	RH \$ 3,598.00 ✓
1 Pc Front Fender <i>Dishbed</i>	RH \$ 333.00 ✓
1 Pc Front Bumper Side Retainer <i>in</i>	RH 5349.70 \$ 18.70 ✓
1 Pc Front Fender Inner Shield <i>Rehd</i>	RH \$ 129.00 ✓
1 Pc Front Bumper <i>Rehd</i>	4279.76 \$ 1,031.00 ✓
1 Pc Wiper Washer Tank <i>Rehd</i>	\$ 240.00 ✓
1 Pc Front Bonnet <i>Repair</i>	\$ 1,067.00 x
Parts less 20%	\$ -1,283.34

Nett item	
1 Set Front Bumper Clips <i>Ne</i>	\$ 50.00 30
1 Set Front Bumper Top Cover Rivet Clips <i>new</i>	\$ 80.00 +
1 Set Front Fender Inner Shield Clip <i>new</i>	\$ 50.00 30

Labour Charge	
To Checking Wiring	1230 \$ 80.00 30
Check Wheel Alignment	\$ 80.00 +
Labour For Knock Dents and Renew Parts	\$ 850.00 700
Respray Painting	\$ 1,200.00 600
Point Protection	
• To display damaged parts during resurvey	
• Parts price is subject to confirmation	
• Third party survey is on a "Without Prejudice" basis	
• No illegal modification(s) is allowed	
• Supplementary item(s) must be resurveyed and	
is subject to final approval from Insurance Company	
Acknowledged by Repairer	
Signature:	
Date:	

Adrian Lim
H/S 04/06/18
OA Pays

total: 5569.76
L/S: H-HIC

\$ 7,523.36