

15/07/18

INS. CASE OWNER:

SUTON

CC 4/EQ1801 0157

LEK:

IDAC:

Surveyor:

Fenneth

DOI:

ASSIGNMENT

5/6/18

Date / Time:

5/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GAE 473AB

Name of Insured:

A-SQUARED EXPRESS

Insured Tel No.:

HP:

Excess Sec II :\$:

D.O.A.:

4/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

AW NIKH LAI ANDREW (HUNTER)

Driver Tel No.:

(V/L: YES / NO)

OL GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

by 31432

INSRS:
WSP:
Tel:
Liability:
RMKS:

LT

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

8/6/18
vicGAE 473AB - X
RECEIVED 23 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

18/07/18 - vic

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):
After call ltr to OI:
Authorisation To Act:
Release Voucher: 15 EV
Final Repair Bill:
Car Rental Invoice:
Towing Invoice:
LTA / GIA:
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD:
Payment Breakdown Form:
Post-Repair Photos:
Others:18/07/18 @
8:07PMspoke to OI. He confirmed
accident details & rate - evoked
tr. informed TP claim, agreed to
 settle & await NOD books. send
letter & bill to OI.
- PINKISHO.
- TP LOD IN BY BILL20/08/18
21/08/18send 1st offer to TP.
TP accepted offer. NO EV required.
all books in order.
to close.

PRELIMINARY ADVICE

Date/Time: 08/06/18

Sent By: b3

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

LIS

\$5 2,500.00

(5 days)

Reduction: 76 %

Email

Call

FINAL SET. LEMT

Date/Time:

Confirm with:

Final Liability:

100

(Agreed / Assessed)

BOLA S/N No.:

27

Repair Cost:

C01650

\$5 2,675.00

Loss of Rental (LOR):

\$5 700.00

(7 days)

X \$100.00

Loss of Use (LOU):

\$5 -

(5 x days)

Loss of Income (LOI):

\$5 -

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$5 7.45

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/Independent)

Legal Cost

\$5 -

Total:

\$5 3,302.45

Global Sum \$5:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

\$5

3,302.45

Name 1:

CT AUTO PTE LTD

Payee 2: (Strike if N.A.)

\$5 -

Name 2:

-

Payee 3: (Strike if N.A.)

\$5 -

Name 3:

-

Email

Call

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

C01650
5/9/18

REF: EOL

ASSIGNMENT

From: Date 05062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. GY 3143L

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 820k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: 3/26

Vehicle: IN / OUT

Person Contacted:

Date / Time Action / Instruction

6/6 PM parts to Coroner

Up to 2,500.00
(Gross of 7,900.20 / 76%.)

WV: \$20,000.00 (Gross)
VTR: \$9,470.00 (Gross)
Nett: \$10,530.00 (Gross)

Date/Time: File Pass to?

☐

Preli. Report

II

☐

Final Report

Date/Time: File Return to?

II

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Insp. (\$)☐ Workshop (\$)

Survey Fee:

Transportation

1. S + R = 31

2. Phone

3. Other

4. Total

TOTAL

Report Format :

Lump Sum / I.B.T. (\$)

Veh No. GY 3143L Vr Regn 03 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Mit L300

CC

2477

Colour

L. Blue

A/C

Insured / Std / NI / NA

Sp Reading

072960

T/Radio

Insured / Std / NI / NA

Eng/No:

C/No:

JMAJNP15VSA 000508

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185 R14 XR

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Journey

Front

Rear

R/Bal.

6 mm

R/Bal.

4 mm

L/Bal.

6 mm

L/Bal.

4 mm

D.O.A.

4 / 6 / 18

D.O.I.

5 / 6 / 18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQ118010157/Khb3

Date: 06.06.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GY3143L


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.06.2018 at the premises of M/s CT Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	10,406.28
Revised Estimate Amount	: S\$	3,624.75
"Check" Items Amount	: S\$	1,160.18
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Kh

CT AUTO PTE LTD

160 Sin Ming Drive, #02-14, Sin Ming AutoCity, Singapore 575722

Tel: 62666727 Fax: 62666358 Email: admin@ctauto.com.sg

Business Registration No. 201420132H

GST Registration No. 201420132H

ESTIMATE

Date: 5/6/2018

DOA: 4/6/2018

Vehicle No: GY3143L

Make & Model: Mitsubishi L300

S/N Qty Item Description Parts Price Surveyor

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Tailgate	\$ 1,280.30	✓
2	1	Tailgate outer moulding	\$ 118.30	✓
3	2	Tailgate outer moulding no. plate lamp	\$ 57.80	X
4	1	Tailgate "MITSUBISHI" Sticker	\$ 152.10	✓
5	1	Tailgate inner lock	\$ 179.80	✓
6	1	Tailgate lock stricker	\$ 26.80	X
7	1	Tailgate lock key cylinder	\$ 84.60	✓
8	1	Tailgate weatherstrip	\$ 149.80	5065m
9	1	Tailgate windscreen Moulding	\$ 109.20	5065m
10	1	Tailgate trimboard	\$ 72.80	X
11	1	Tailgate inner handle	\$ 34.30	X
12	2	Tailgate hydraulic damper	\$ 321.00	X
13	2	Taillamp	\$ 381.00	X
14	2	Taillamp base panel	\$ 498.70	X
15	2	Taillamp base panel inner cover	\$ 169.10	X
16	1	Rear center bumper	\$ 269.10	✓
17	2	Rear centre bumper reflector	\$ 278.20	X
18	2	Rear centre bumper reflector bracket	\$ 60.00	✓
19	2	Rear side bumper	\$ 205.50	✓
20	2	Rear side bumper reflector	\$ 92.10	X
21	2	Rear bumper bracket	\$ 91.00	X
22	1	Spare tyre bracket	\$ 173.40	✓
23	1	Spare tyre bracket fastener	\$ 49.30	X
24	1	Rear floor panel	\$ 2,321.90	X
25	1	Rear floor panel insulator	\$ 374.50	X
26	1	Rear end panel	\$ 317.80	✓
27	1	Rear end panel top garnish	\$ 233.30	X
Less 10%			\$ 8,101.70	
			\$ 2,025.43	
			\$ 6,076.28	

Special Nett Items

1	1	Sundries	\$ 50.00	X
2	1	Tailgate sticker "70km/h "	\$ 80.00	155m
	1	Tailgate sticker "6 pax "	\$ 80.00	155m
3	1	Tailgate windscreen sealant	\$ 120.00	X
4	1set	Tailgate trimboard clip	\$ 50.00	X
5	2	Tailgate outer moulding Reflector	\$ 60.00	X
6	2set	Rear bumper clip	\$ 50.00	X
7	1	Rear floor wooden plank	\$ 300.00	X
8	1	Rear number plate	\$ 50.00	201m
			\$ 840.00	

Total parts

\$ 6,916.28

S/N Labour Description

Labour for panel beating, cut, weld, straighten rear fenders and
1 replace rear damaged parts.

Amount

Amount

\$ 1,600.00

6000

2	To putty and spray painting rear portion.	\$	1,000.00	4000
3	To check rear lighting and wiring.	\$	50.00	151
4	To remove and install rear tail gate lock mechanism.	\$	120.00	601
	To remove and install rear inner garnish and trim to facilitate the			
5	repair.	\$	250.00	601
6	To apply anti rust proofing to rear affected area.	\$	200.00	601
7	To remove and install rear windscreen.	\$	150.00	601
	To remove & refit tail gate component to replace tail gate, check & re-			
8	adjust the close gap and alignment and water seepage	\$	120.00	X
	Total labour :	\$	3,490.00	
	Total parts :	\$	6,916.28	
	Total labour :	\$	3,490.00	
	Total repair cost : (Before GST)	\$	10,406.28	

LKX Auto Consultants hence notify
 the Reparer of the following:
 • To survey before/after spray painting
 • To display damaged part(s) during survey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No major modification(s) is allowed
 • Supplementary part(s) must be insured and
 is subject to prior approval from Insurance Company
 Acknowledged by Reparer
 Signature:
 Date:

CT AUTO PTE LTD

160 Sin Ming Drive, #02-14, Sin Ming AutoCity, Singapore 575722
Tel: 62666727 Fax: 62666358 Email: admin@ctauto.com.sg
Business Registration No. 201420132H
GST Registration No. 201420132H

ESTIMATE

Date: 5/6/2018

DOA: 4/6/2018

Vehicle No: GY3143L

Make & Model: Mitsubishi L300

S/N	Qty	Item Description	Parts Price	Surveyor
Nett Items				
1	1	Tailgate	\$ 1,280.30	✓
2	1	Tailgate outer moulding	\$ 118.30	✓
3	2	Tailgate outer moulding no. plate lamp	\$ 57.80	X
4	1	Tailgate "MITSUBISHI" Sticker	\$ 152.10	✓
5	1	Tailgate inner lock	\$ 179.80	✓
6	1	Tailgate lock stricker	\$ 26.80	X
7	1	Tailgate lock key cylinder	\$ 84.60	X
8	1	Tailgate weatherstrip	\$ 149.80	?
9	1	Tailgate windscreen Moulding	\$ 109.20	5011nt4.6
10	1	Tailgate trimboard	\$ 72.80	X
11	1	Tailgate inner handle	\$ 34.30	?
12	2	Tailgate hydraulic damper	\$ 321.00	X
13	2	Taillamp	\$ 381.00	X
14	2	Taillamp base panel	\$ 498.70	X
15	2	Taillamp base panel inner cover	\$ 169.10	?
16	1	Rear center bumper	\$ 269.10	✓
17	2	Rear centre bumper reflector	\$ 278.20	X
18	2	Rear centre bumper reflector bracket	\$ 60.00	X
19	2	Rear side bumper	\$ 205.50	✓
20	2	Rear side bumper reflector	\$ 92.10	X
21	2	Rear bumper bracket	\$ 91.00	?
22	1	Spare tyre bracket	\$ 173.40	?
23	1	Spare tyre bracket fastener	\$ 49.30	?
24	1	Rear floor panel	\$ 2,321.90	X
25	1	Rear floor panel insulator	\$ 374.50	X
26	1	Rear end panel	\$ 317.80	✓
27	1	Rear end panel top garnish	\$ 233.30	?
			\$ 8,101.70	
Less 10%			\$ 2,025.43	
			\$ 6,076.28	
Special Nett Items				
1	1	Sundries	\$ 50.00	?
2	1	Tailgate sticker "70km/h "	\$ 80.00	151m
	1	Tailgate sticker "6 pax "	\$ 80.00	151m
3	1	Tailgate windscreen sealant	\$ 120.00	X
4	1set	Tailgate trimboard clip	\$ 50.00	X
5	2	Tailgate outer moulding Reflector	\$ 60.00	X
6	2set	Rear bumper clip	\$ 50.00	X
7	1	Rear floor wooden plank	\$ 300.00	?
8	1	Rear number plate	\$ 50.00	205m
			\$ 840.00	
Total parts			\$ 6,916.28	
S/N	Labour Description		Amount	Amount
1	Labour for panel beating, cut, weld, straighten rear fenders and replace rear damaged parts.		\$ 1,600.00	6000

2	To putty and spray painting rear portion.	\$ 1,000.00	4000
3	To check rear lighting and wiring.	\$ 50.00	150
4	To remove and install rear tail gate lock mechanism.	\$ 120.00	600
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 250.00	600
6	To apply anti rust proofing to rear affected area.	\$ 200.00	600
7	To remove and install rear windscreen.	\$ 150.00	600
8	To remove & refit tail gate component to replace tail gate, check & re-adjust the close gap and alignment and water seepage	\$ 120.00	X
	Total labour :	\$ 3,490.00	
	Total parts :	\$ 6,916.28	
	Total labour :	\$ 3,490.00	
	Total repair cost : (Before GST)	\$ 10,406.28	

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature: _____

Date: _____

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	1937W

Vehicle Details

Vehicle No.:	GY3143L
Vehicle to be Exported:	No
Intended De-registration Date:	06 Jun 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	L300 HR M
Primary Colour:	Blue
Manufacturing Year:	2004
Engine No.:	4D56KX4671
Chassis No.:	JMAJNP15V5A000508
Maximum Power Output:	-
Open Market Value:	\$14,085.00
Original Registration Date:	02 Mar 2005
First Registration Date:	02 Mar 2005
Transfer Count:	2
Actual ARF Paid:	\$705.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	01 Mar 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$27,286.00
COE Rebate Amount:	\$9,470.00
Total Rebate Amount:	\$9,470.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 06 Jun 2018

OK

Vic (LKKAUTO)

From: Emellene Teng <admin@ctauto.com.sg>
Sent: Tuesday, 21 August, 2018 9:45 AM
To: Vic (LKKAUTO)
Cc: Admin A; Shawn Chen; Cady Lee
Subject: Letter of Authorisation & Invoice: DM18HO01420/JW: Accident Involving GY3143L & GBE4739B on 4/6/2018 - Letter of Demand
Attachments: image004.jpg; image005.png; image006.png; image007.png; GY3143L - LOA & Invoice.pdf

Dear Vic,

We accept the offer for **property damage only**.

Please find attached the duly signed letter of authorisation & invoice for your necessary action. The originals will be mailed to you.

Thank you for settling the claim swiftly & amicably. We look forward to the payment.

Best Regards,
Emellene Teng
CT Auto PTE LTD
Office: 6266-6727 Fax: 6266-6358

Please like our Facebook page at: <https://www.facebook.com/leongautogroup>

On Mon, Aug 20, 2018 at 4:26 PM, Vic (LKKAUTO) <vicalpeh@lkkauto.com> wrote:

Without Prejudice

Dear Emellene,

We refer further to the below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we offer settlement as below:

Cost of Repair (w/gst)	\$ 2,675.00
Loss of Rental (\$100 x 7 days)	\$ 700.00
LTA Search Fee	\$ 7.45
TOTAL	\$ 3,382.45

For your acceptance please. Kindly note that no DV no required.

The above amount is to be made payable to **CT AUTO PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Shu Pei (LKKAuto)

Sent: Friday, 3 August, 2018 4:10 PM

To: Janet Tan

Catherine Chong (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Tuesday, 5 June, 2018 9:22 AM
To: 'assignments'
Cc: Admin A; Francis Ng
Subject: FW: Request for Pre-Repair Inspection – GY3143L; GBE4739B; Accident on 04-06-2018

Dear all,

Please arrange to attend to the PRS as SJE.

Our insured driver has yet to report. We shall follow up on non reporting.

Aside to Francis, for your necessary followup.

Thank you.

Regards,


Janet Tan
Senior Executive | Claims

05062018 @ 1028am
Emellene veh in
Kenneth.



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shawn Chen [mailto:ctops@ctauto.com.sg]
Sent: Monday, June 4, 2018 6:26 PM
To: Francis Ng <francis.ng@eqinsurance.com.sg>
Cc: Emellene Teng <admin@ctauto.com.sg>; Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: Re: Request for Pre-Repair Inspection – GY3143L; GBE4739B; Accident on 04-06-2018

Dear Mr Ng,

Please help to arrange LKK to survey this vehicle.

Best Regards,
CT Auto Pte Ltd
Shawn Chen
Office : 62666727 Fax : 6266-6358

Please like our Facebook page at: <https://www.facebook.com/leongautogroup>

On Mon, Jun 4, 2018 at 5:31 PM, Francis Ng <francis.ng@eqinsurance.com.sg> wrote:

To: CT Auto PTE LTD

Dear Emellene,

Without Prejudice

We refer to your email below.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors.

If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us.

Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd	4) Priority Services Tel: 62934822

<p>Tel: 6281 6690 / 62832866</p> <p>Fax: 6281 8748</p> <p>Contact Person: Amy/ Grace</p>	<p>Fax: 62963283</p> <p>Contact Person: Hui Lian</p>
<p>5) RT Appraisal Pte Ltd</p> <p>Tel: 67486076</p> <p>Fax: 67480361</p> <p>Contact Person: Ricky Teng</p>	<p>6) LKK Auto Consultants Pte Ltd</p> <p>Tel: 6256-3561</p> <p>Fax: 6741-4108</p>
<p>7) Kelvin Automotive Appraising Services</p> <p>Tel: 81825263</p> <p>Fax: 67461148</p> <p>Contact Person: Kelvin</p>	<p>8) Automotive Appraiser & Surveying Services</p> <p>Tel: 96623655</p> <p>Fax: 67655662</p> <p>Contact Person: Mr Chee</p>
<p>9) JP Knights Pte Ltd</p> <p>Tel: 63450068</p> <p>Fax: 63445328</p> <p>Contact Person: Edna Lee</p>	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,
Francis Ng
 Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify

From: Janet Tan

Sent: Monday, June 4, 2018 5:18 PM

To: Francis Ng <francis.ng@eqinsurance.com.sg>

Cc: Shawn Chen <CTOps@ctauto.com.sg>; Emellene Teng <admin@ctauto.com.sg>

Subject: RE: Request for Pre-Repair Inspection – GY3143L; GBE4739B

Francis

For your necessary action.

Thank you.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify

From: Emellene Teng [mailto:admin@ctauto.com.sg]
Sent: Monday, June 4, 2018 5:18 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Shawn Chen <CTOps@ctauto.com.sg>
Subject: Request for Pre-Repair Inspection – GY3143L

Our Ref: GY3143L

To: The owner and/or driver of GBE4739B 3rd party
c/o EQ Insurance

cc: EQ Insurance

Dear Sir/Madam,

Accident Involving GY3143L & GBE4739B on 4/6/2018 along North Buona Vista Road towards South Buona Vista Road before AYE

With reference to the above, we hereby give EQ Insurance 2 days' notice to conduct a pre-repair inspection of vehicle GY3143L at our premise.

Please arrange your surveyor to inspect the vehicle at:

160 Sin Ming Drive, #02-13 Sin Ming AutoCity

Singapore 575722

Mobile No.: 9737 0733

If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle with further reference to you.

Please advise on liability for this case & let us have a list of surveyors to choose from.

Best Regards,

Emellene Teng

CT Auto PTE LTD

Office: 6266-6727 Fax: 6266-6358

Please like our Facebook page at: <https://www.facebook.com/leongautogroup>

Total Control Panel

[Login](#)

To: janet.tan@eqinsurance.com.sg

[Remove](#) this sender from my allow list

From: admin@ctaauto.com.sg

You received this message because the sender is on your allow list.

Shu Pei (LKKAuto)

From: Francis Ng <francis.ng@eqinsurance.com.sg>
Sent: Thursday, 7 June 2018 12:15 PM
To: Shu Pei (LKKAuto)
Cc: Admin A; Vic (LKKAuto)
Subject: RE: Request for Pre-Repair Inspection – GY3143L; GBE4739B; Accident on 04-06-2018 ***LKK REF:CC4/EQI18010157/Khb3
Attachments: GBE4739B 04.06.2018.PDF



Dear Shu Pei,

Our insured's report is attached.

Regards,
Francis Ng
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, June 6, 2018 5:25 PM
To: Francis Ng <francis.ng@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>
Subject: RE: Request for Pre-Repair Inspection – GY3143L; GBE4739B; Accident on 04-06-2018 ***LKK REF:CC4/EQI18010157/Khb3

WITHOUT PREJUDICE

Dear Francis,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle GY 3143L at M/s CT Auto Pte Ltd.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair

- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 5 June 2018 10:28 AM

To: 'Janet Tan' <janet.tan@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; 'Francis Ng' <francis.ng@eqinsurance.com.sg>

Subject: RE: Request for Pre-Repair Inspection – GY3143L; GBE4739B; Accident on 04-06-2018

Dear Janet,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [<mailto:janet.tan@eqinsurance.com.sg>]

Sent: Tuesday, 5 June, 2018 9:22 AM

To: 'assignments' <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Francis Ng <francis.ng@eqinsurance.com.sg>

Subject: FW: Request for Pre-Repair Inspection – GY3143L; GBE4739B; Accident on 04-06-2018

Dear all,

Please arrange to attend to the PRS as SJE.

Our insured driver has yet to report. We shall follow up on non reporting.

Aside to Francis, for your necessary followup.

Thank you.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shawn Chen [<mailto:ctops@ctauto.com.sg>]

Sent: Monday, June 4, 2018 6:26 PM

To: Francis Ng <francis.ng@eqinsurance.com.sg>

Cc: Emellene Teng <admin@ctauto.com.sg>; Janet Tan <janet.tan@eqinsurance.com.sg>

Subject: Re: Request for Pre-Repair Inspection – GY3143L; GBE4739B; Accident on 04-06-2018

Dear Mr Ng,

Please help to arrange LKK to survey this vehicle.

Best Regards,
CT Auto Pte Ltd

Shawn Chen

Office : 62666727 Fax : 6266-6358

Please like our Facebook page at: <https://www.facebook.com/leongautogroup>

On Mon, Jun 4, 2018 at 5:31 PM, Francis Ng <francis.ng@eqinsurance.com.sg> wrote:

To: CT Auto PTE LTD

Dear Emellene,

Without Prejudice

We refer to your email below.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within **2 working days** if you agree or have any objections to the appointment of any of the motor surveyors.

If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us.

Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Hui Lian
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Ricky Teng	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108

7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,
Francis Ng
Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Janet Tan
Sent: Monday, June 4, 2018 5:18 PM
To: Francis Ng <francis.ng@eqinsurance.com.sg>
Cc: Shawn Chen <CTOps@ctauto.com.sg>; Emellene Teng <admin@ctauto.com.sg>
Subject: RE: Request for Pre-Repair Inspection – GY3143L; GBE4739B

Francis

For your necessary action.

Thank you.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Emellene Teng [<mailto:admin@ctauto.com.sg>]
Sent: Monday, June 4, 2018 5:18 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Shawn Chen <CTOps@ctauto.com.sg>
Subject: Request for Pre-Repair Inspection – GY3143L

Our Ref: GY3143L

To: The owner and/or driver of GBE4739B 3rd party
c/o EQ Insurance

cc: EQ Insurance

Dear Sir/Madam,

Accident Involving GY3143L & GBE4739B on 4/6/2018 along North Buona Vista Road towards South Buona Vista Road before AYE

With reference to the above, we hereby give EQ Insurance 2 days' notice to conduct a pre-repair inspection of vehicle GY3143L at our premise.

Please arrange your surveyor to inspect the vehicle at:

160 Sin Ming Drive, #02-13 Sin Ming AutoCity

Singapore 575722

Mobile No.: 9737 0733

If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle with further reference to you.

Please advise on liability for this case & let us have a list of surveyors to choose from.

Best Regards,

Emellene Teng

CT Auto PTE LTD

Office: 6266-6727 Fax: 6266-6358

Please like our Facebook page at: <https://www.facebook.com/leongautogroup>

Total Control Panel

[Login](#)

To: janel.tan@eqinsurance.com.sg

[Remove](#) this sender from my allow list

From: admin@ctauto.com.sg

You received this message because the sender is on your allow list.

REPUBLIC OF SINGAPORE DRIVING LICENCE

S2570014G

CHEONG PENG CHENG

Valid From: 05 Dec 1989
Valid Until: 20 Dec 2018

0026403437

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S2570014G

CHEONG PENG CHENG

Race: CHINESE
Date of birth: 05-12-1959
Country/Place of birth: CHINA

52570014G

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	Effective Date
Class 2B	Motorcycles <= 200 cc	10 Jan 1995
Class 3	Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of drivers and other motor vehicles with unladen weight <= 2500kg	20 Aug 1994

Licence No: S2570014G

WP 421A

S2570014G

S2570014G

Date of issue: 13-12-2018

Address:
APT BLK 553 WOODLANDS DRIVE 4H
#11-18
SINGAPORE 730553



redefining / Insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

DATE
 02/03/2018

POLICY NUMBER
 CV2/GA327833

Certificate of Insurance

Commercial Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Commercial Vehicles (Third-Party Risks and Compensation) Rules, 1987 (Malaysia) / Commercial Vehicles (Third-Party Risks and Compensation) Rules, 1987 (Malaysia) / Commercial Vehicles (Third-Party Risks and Compensation) Rules, 1987 (Malaysia)

Policy details

Policyholder name	HARA HONG KONG TIM SUM PTE LTD	Certificate number	GA327833 / 1
Cover	Third Party Only	NCD	20%
Engine number	4D56HX4671	Chassis number	JMAJNP15V5A000508
Vehicle Registration number	GY3143L		
Period of Insurance	from 25/03/2018 to 24/03/2019 (both dates inclusive)		
Sum Insured	Nil		
Finance Loan Company	Nil		

EXCLUSIVE AUTHORIZED WORKSHOP
CHENG AUTO
 15 EDON LEE STREET
 #01-58/59, PIONEER POINT
 SINGAPORE 627607 (REPORTING CENTRE)
 24 Hours Towing: 8666 7775

Persons or classes of persons entitled to drive

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

- (a) Use in connection with the Policyholder's business.
- (b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
- (c) Use for social, domestic and pleasure purposes.

The Policy does not cover:

- (a) Use for the hire or reward or for racing, pace-making, reliability trial or speed testing.
- (b) Use whilst drawing a trailer except the towing of anyone disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Commercial Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Excess

An additional excess is applicable as follows:

Additional All Claims excess of \$2,000.00 is applicable for any named/unnamed drivers who:

- a) is 18 years old to 21 years old and/or
- b) is 71 years old and above and/or
- c) with driving experience of less than 1 year on the relevant classes of driving license

Additional Clause & endorsements to your policy

Nil

CT AUTO PTE LTD

160 Sin Ming Drive

#02-14 Sin Ming AutoCity

Singapore 575722

62666727

Sales@ctauto.com.sg

GST Registration No. : 201420132H

Company Registration No.

201420132H

ESTIMATE**ADDRESS**

GY3143L

EQ Insurance Company

LTD

22 Gemmill Lane

Singapore 069257

**PROFORMA
INVOICE****ESTIMATE NO. E643****DATE 03/08/2018****VEHICLE NO.**

GY3143L

TYPE

Mitsubishi L300

DOA/DOR DATE

04/06/2018

ACTIVITY

Cost of Repairs (as finalised with surveyor)

AMOUNT

2,500.00

GY3143L & GBE4739B DOA 04/06/2018

SUBTOTAL

2,500.00

GST TOTAL

175.00

TOTAL**S\$2,675.00****GST SUMMARY****RATE**

GST @ 7%

GST

175.00

NET

2,500.00

Accepted By

Accepted Date

Errors and omissions excepted (E&OE)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 05/09/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBE 4739B (Insd Veh)	Your Ref. No. : DM18HO01420/JW
	GY 3143L (TP Veh)	Our Ref. No. : CC4/EQI18010157/Khb3q2
Date of Accident	4/6/2018	

Liability	100%	
Final Repair Cost	: \$ 2,675.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 700.00	7 days
Others:	: \$ 7.45	
	: \$	
	3,382.45	
Final Settlement Sum	: \$ 3,382.45	
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	CT AUTO PTE LTD	: \$ 3,382.45
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

CT AUTO PTE LTD

160 Sin Ming Drive #02-14 Sin Ming AutoCity Singapore 575722
Tel: 6266 6727 Fax: 6266 6358 Email: admin@ctauto.com.sg
Business Registration No. 201420132H
GST Registration No. 201420132H

Our Ref: GY3143L
Your Ref: GBE4739B

3 August, 2018

EQ Insurance Company Ltd
5 Maxwell Road
#17-00, Tower Block, MND Complex
Singapore 069110

Attention: Motor Claims Department

Dear Sir/Madam,

ACCIDENT INVOLVING GY3143L & GBE4739B ON 4/6/2018

We are writing on behalf of Hara Hong Kong Tim Sum PTE LTD; the registered owner of Vehicle No. GY3143L involved in the above accident.

We are instructed that the above accident was caused solely and completely by the negligence of your insured's vehicle no. GBE4739B. As a result of which, our client had suffered loss and expenses.

We are instructed by our client to claim for:

- Cost of Repair	\$ 2,675.00	(as finalised with surveyor + GST)
- Loss of Rental (7 days x \$120/day)	\$ 840.00	
- LTA Search Fees	\$ 7.45	
Total	<u>\$ 3,522.45</u>	

We enclosed herewith the following documents for your consideration.

- | | |
|--------------------------------------|--|
| - Invoice | - GIA Report |
| - Vehicle Rental Agreement & Invoice | - Owner/Driver Identity Card/Driving License |
| - LTA Search Fee | - Certificate of Insurance |

Please acknowledge receipt of the above documents and we look forward to your favourable response.

Yours faithfully,
CT AUTO PTE LTD



Enc



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/EQ118010157/Khb3

18 JULY 2018

M/s A. SQUARED EXPRESS
BLOCK 30 BALAM ROAD
#03-40
SINGAPORE 370030
ATTN: THE MANAGEMENT

By Post and By Email

Dear Sir/Madam,

ACCIDENT INVOLVING GBE 4739B AND GY 3143L ON 04/06/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


Vic Alpeh Sanghilan
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c: *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)
Andrew_aw1723@yahoo.com
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Wednesday, 18 July, 2018 5:14 PM
To: Andrew_aw1723@yahoo.com
Cc: Admin A; Vic (LKKAUTO)
Subject: Your Ref: GBE 4739B_ACCIDENT INVOLVING GBE 4739B AND GY 3143L ON 04/06/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/EQI18010157/Khb3

18 JULY 2018

M/s A. SQUARED EXPRESS
BLOCK 30 BALAM ROAD
#03-40
SINGAPORE 370030
ATTN: THE MANAGEMENT

By Post and By Email

Dear Sir/Madam,

ACCIDENT INVOLVING GBE 4739B AND GY 3143L ON 04/06/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

TO :

Dear Sirs,

CLAIMANT :

ACCIDENT INVOLVING G43143L AND G15E4739B
ON 4/6/18 AT North Buona Vista towards South Buona Vista Road

I/We, Hara Hong Kong Tim Sum Pte Ltd, am/are the
registered owner of Vehicle No. G43143L.

Please note that I have assigned all compensation monies due to me/us in the above said
accident to M/S **CT AUTO PTE LTD**.

I/We, hereby authorize you to release all compensation monies pertaining to the above said
accident to M/S **CT AUTO PTE LTD**, and forward your settlement cheque to M/S **CT AUTO
PTE LTD** whom I/we had authorized to collect the said compensation monies.

Thank you.



Signature of Claimant

(Company Stamp, if applicable)

Name :

NRIC No :

Date:

CT AUTO PTE LTD

160 Sin Ming Drive
#02-14 Sin Ming AutoCity
Singapore 575722
62666727
Sales@ctauto.com.sg
GST Registration No. : 201420132H
Company Registration No.
201420132H

Tax Invoice

INVOICE TO

GY3143L
EQ Insurance Company
LTD
22 Gemmill Lane
Singapore 069257

INVOICE NO. 2018/1023**DATE** 20/08/2018**DUE DATE** 20/08/2018**TERMS** Due on receipt**VEHICLE NO.**

GY3143L

TYPE

Mitsubishi L300

DOA/DOR DATE

04/06/2018

ACTIVITY

Cost of Repairs (as finalised with surveyor)

AMOUNT

2,500.00

GY3143L & GBE4739B DOA 04/06/2018

SUBTOTAL

2,500.00

GST TOTAL

175.00

TOTAL

2,675.00

BALANCE DUE**S\$2,675.00****GST SUMMARY**

RATE
GST @ 7%

GST
175.00

NET
2,500.00



Errors and omissions excepted (E&OE)

Leong Auto Rental LLP
160 Sin Ming Drive
#02-13
Sin Ming AutoCity
Singapore 575722
82923333
leong@leongauto.com.sg
Company Registration No. T16LL0615D

INVOICE

INVOICE TO

Cheong Peng Cheng
Blk 553 Woodlands Drive 44
#11-18
Singapore 730553

INVOICE NO. 2018/111

DATE 11/06/2018

DUE DATE 11/06/2018

TERMS Due on receipt

VRA NO.
L0273

YOUR REF.
GY3143L

ACTIVITY

GW6123K

Vehicle Rental from 04/06/2018 1640 Hrs to 11/06/2018 1000 Hrs, 7 @ S\$120.00

AMOUNT

840.00

GW6123K/GY3143L

BALANCE DUE

S\$840.00



LEONG AUTO RENTAL LLP

160 Sin Ming Drive, #02-13 Sin Ming AutoCity, Singapore 575722

Tel: 64563008 Email: Leong@leongauto.com.sg

UEN Registration No. T16LL0615D

Operations Team

Mobile: 82923333







Mobile: 93533333

G43143L

CT

VEHICLE RENTAL AGREEMENT

No. L 0273

HIRER'S PARTICULAR Name : (as in I/C) <u>CHEONG PENG CHENG</u> NRIC / PASSPORT No : <u>S257014 G</u> Address (Res) : _____ Name & Address of Employer : _____ Occupation : _____ Driving Exp : _____ D/L No : _____ D/L Type : Local/International Pass Date : _____ Date of Birth : _____ Tel : (O) _____ (R) _____ HP/PG : _____		Veh No : <u>G43143L</u> Replace Veh No : _____ Mileage Out : _____ Mileage In : _____ Make & Model : <u>Toyota</u> Make & Model : _____ Auto / Manual : <u>Life</u> Auto / Manual : _____ OUT Date : <u>4/6/13</u> OUT Date : _____ OUT Time : <u>10:40hrs</u> OUT Time : _____	
ADDITIONAL DRIVER'S PARTICULARS Name : (as in I/C) _____ NRIC / PASSPORT No : _____ D/L No : _____ D/L Type : Local/International Address (Res) : _____ Tel/Hp : _____		RENTAL CHARGES Daily : <u>7</u> @ \$ <u>120</u> Weekly : @ \$ _____ Monthly : @ \$ _____ Hours : @ \$ _____ Others : @ \$ _____ GDW : @ \$ _____ PAI : @ \$ _____ Delivery Service : _____	
(A) - ACCIDENTS (D) - DENTS (S) - SCRATCHES <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  FRONT </div> <div style="text-align: center;">  LEFT </div> <div style="text-align: center;">  TOP </div> <div style="text-align: center;">  RIGHT </div> <div style="text-align: center;">  REAR </div> </div>		SUB-TOTAL \$ <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  OUT </div> <div style="text-align: center;">  IN </div> </div>	
ACCESSORIES CHECK <input type="checkbox"/> Ashtray <input type="checkbox"/> Cig Lighter <input type="checkbox"/> W <input type="checkbox"/> STD Tools <input type="checkbox"/> Jack <input type="checkbox"/> S / Tyre <input type="checkbox"/> Radio / Cass <input type="checkbox"/> CD/Cartridges <input type="checkbox"/> Hub Caps <input type="checkbox"/> S / P/M		ESTIMATED TOTAL RENTAL \$ Sales Person Code : _____ Non Waiver Excess : \$ <u>3500</u> Hirer's Signature : _____ Addition Driver's Signature : _____	

I/We agreed to the terms and conditions above, overleaf and that all information given are true & correct in all respect. My/Our driving licence(s) is/are current and not disqualified from driving. You may charge all amount due on the rental to my/our credit card.

* IMPORTANT

- ONLY PERSONS ABOVE 25 YEARS OF AGE WITH MORE THAN 3 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY LEONG AUTO RENTAL LLP
- IN THE EVENT OF AN ACCIDENT, THE HIRER OR AUTHORIZED DRIVER :
 - shall report all accidents involving the said vehicle to the Owner immediately
 - shall take immediate steps to complete and sign Form MAH 1 (Motor Accident Report Form) and file all other acts required in compliance with the "NON-INJURY MOTOR ACCIDENT REPORT SCHEME" (this form will be made available when the accident is report to the Owner)
 - shall report to the police within 24 hours from the occurrence, the following types of accidents :
 - injury case
 - non-injury case involving a Government vehicle, or damage to Government property
 - non-injury case involving a foreign vehicle to obtain their motor insurance policy. Passport No./Name of the driver, Vehicle number, Log card and Vehicle registration information
 - non-injury case involving a pedestrian or cyclist

RETURN OF VEHICLE: THE HIRER/DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER/DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO LEONG AUTO RENTAL LLP AND THE DATE SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER

DATE IN	TIME IN	MILEAGE	CHECKED BY	SIGNATURE OF HIRER/DRIVER
<u>11/6/13</u>	<u>10:40</u>			

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No.: M4-0006529-2

643143L

Print Date/Time: 04 Jun 2018 / 17:10:44

Receipt Date/Time: 04 Jun 2018 / 17:10:44

Tax Invoice/Receipt

Receipt No.: ITNET-00000-180604-002063

Previous Receipt No.:

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - GBE4739B

As at 04 Jun 2018/14:30:00

Insurance Co: EQ INSURANCE COMPANY LTD

1	Insurance Enquiry - GBE4739B Enquiry Fee 20180604170958995180	7.00	0.49	7.49
---	---	------	------	------

Sub-Total	7.00	0.49	7.49
-----------	------	------	------

Total Before Rounding	7.00	0.49	7.49
-----------------------	------	------	------

Rounding Difference			0.04
---------------------	--	--	------

Total Amount Payable			7.45
----------------------	--	--	------

Paid By

20180604171014652	Direct Debit: eNETS Debit (Internet Banking)	7.45
-------------------	---	------

Total	7.45
-------	------

Cash Change	0.00
-------------	------

Tendered Amount	7.45
-----------------	------

Excess Refundable Amount	0.00
--------------------------	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQI18010157/Khb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 05-09-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 4739B	Veh. Inspected	GY 3143L	
Policy No.	DMCPHQ17-006873	Coverage (\$)	0.00	
Claim No.	DM18HO01420/JW	Excess (\$)	0.00	
Assign From	JUSTIN	Assign Date	05/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI L300 (M)	c.c	2477	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	JMAJNP15V5A000508	Colour	LIGHT BLUE	
Odometer	672960	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14 X8	JOURNEY	6 mm	
L/H Front Tyre	185 R14 X8	JOURNEY	6 mm	
R/H Rear Tyre	185 R14 X8	JOURNEY	4 mm	
L/H Rear Tyre	185 R14 X8	JOURNEY	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/06/2018	Inspection Date	05/06/2018	
Survey held at	CT AUTO PTE LTD 160 SIN MING DRIVE #02-14 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GY 3143L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (N)	BENT	1,280.30	952.00
1	TAILGATE OUTER MOULDING (N)	CRACKED	118.30	118.30
2	TAILGATE OUTER MOULDING NO.PLATE LAMP (N)	SERVICEABLE	57.80	-
1	TAILGATE 'MITSUBUSHI' STICKER (N)	NECESSARY	152.10	152.10
1	TAILGATE INNER LOCK (N)	JAMMED	179.80	105.00
1	TAILGATE LOCK STRICKER (N)	TO REPAIR SEE LABOUR	26.80	-
1	TAILGATE LOCK KEY CYLINDER (N)	SERVICEABLE	84.60	-
1	TAILGATE TRIMBOARD (N)	SERVICEABLE	72.80	-
1	TAILGATE INNER HANDLE (N)	SERVICEABLE	34.30	-
2	TAILGATE HYDRAULIC DAMPER (N)	SERVICEABLE	321.00	-
2	TAILLAMP (N)	SERVICEABLE	381.00	-
2	TAILLAMP BASE PANEL (N)	TO REPAIR SEE LABOUR	498.70	-
2	TAILLAMP BASE PANEL INNER COVER (N)	TO REPAIR SEE LABOUR	169.10	-
1	REAR CENTER BUMPER (N)	BENT	269.10	269.10
2	REAR CENTRE BUMPER REFLECTOR (N)	NO SUCH PARTS	278.20	-
2	REAR CENTRE BUMPER REFLECTOR BRACKET (N)	NO SUCH PARTS	60.00	-
2	REAR SIDE BUMPER (N)	O/S CRACKED / N/S BUCKLED	205.50	205.50
2	REAR SIDE BUMPER REFLECTOR (N)	NO SUCH PARTS	92.10	-
2	REAR BUMPER BRACKET (N)	TO REPAIR SEE LABOUR	91.00	-
1	SPARE TYRE BRACKET (N)	BENT	173.40	173.40
1	SPARE TYRE BRACKET FASTENER (N)	SERVICEABLE	49.30	-
1	REAR FLOOR PANEL (N)	TO REPAIR SEE LABOUR	2,321.90	-
1	REAR FLOOR PANEL INSULATOR (N)	SERVICEABLE	374.50	-
1	REAR END PANEL (N)	BENT	317.80	317.80
1	REAR END PANEL TOP GARNISH (N)	SERVICEABLE	233.30	-
	LESS 10% DISCOUNT		-784.27	-229.32
			7,058.43	2,063.88

Report Ref No. CC4/EQI18010157/Khb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE WEATHERSTRIP (SN) (50%)	CUT	149.80	74.90
1	TAILGATE WINDSCREEN MOULDING (SN) (50%)	NECESSARY	109.20	54.60
	LESS 10% DISCOUNT		-25.90	-
			233.10	129.50
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	TAILGATE STICKER '70KM/H' (SN)	NECESSARY	80.00	15.00
1	TAILGATE STICKER '6 PAX' (SN)	NECESSARY	80.00	15.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NOT NECESSARY	120.00	-
1	SET TAILGATE TRIMBOARD CLIP (SN)	NOT NECESSARY	50.00	-
2	TAILGATE OUTER MOULDING REFLECTOR (SN)	NO SUCH PARTS	60.00	-
2	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	50.00	-
1	REAR FLOOR WOODEN PLANK (SN)	SERVICEABLE	300.00	-
1	REAR NUMBER PLATE (SN)	DENTED	50.00	20.00
			840.00	50.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN REAR FENDERS AND REPLACE REAR DAMAGED PARTS .INCLUSIVE OF THE REPAIR OF TAILGATE LOCK STRICKER ,TAILLAMP BASE PANEL ,TAILLAMP BASE PANEL INNER COVER,REAR BUMPER BRACKET AND REAR FLOOR PANEL .		1,600.00	600.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION .		1,000.00	400.00
	TO CHECK REAR LIGHTING AND WIRING .		50.00	15.00
	TO REMOVE AND INSTALL REAR TAIL GATE LOCK MECHANISM .}		120.00	60.00
	TO REMOVE & REFIT TAIL GATE COMPONENT TO REPLACE TAIL GATE ,CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.}		120.00	-
	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		250.00	60.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		200.00	60.00

Report Ref No. CC4/EQI18010157/Khb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL REAR WINDSCREEN.		150.00	60.00
			3,490.00	1,255.00
	GRAND TOTAL		11,621.53	3,498.38
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CC4/EQI18010157/Khb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.