

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

Tanjin 97495749  
-wp  
4/6/18 @ 1540  
resurvey before paint  
sun @ 11am to 12pm  
6 days

30-May-18

## ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1404 X

1 pc	Front bumper	\$	811.11	der
1 pc	Front bumper emblem	\$	27.80	?
1 pc	Front n/s side bracket @ \$32.51	\$	32.51	ner
1 pc	Front n/s fender	\$	514.02	bl
1 pc	Front n/s fender inner shield	\$	176.72	x
1 pc	Front n/s fender signal lamp @ \$32.10	\$	32.10	cut
1 pc	Front n/s rim	\$	246.00	at
1 pc	Front n/s door @ \$1723.60	\$	1,723.60	bb
2 pcs	Front n/s hinges @ \$36.10	\$	72.20	RY
1 pc	Rear n/s door	\$	2,017.48	RY
2 pcs	Rear n/s hinges @ \$39.00	\$	78.00	RY
1 pc	Rear n/s rim	\$	246.00	RY
		\$	5,977.54	
		\$	1,195.51	
		\$	4,782.03	
		\$	48.00	ner
1 pc	Front bumper clips	\$	30.00	ner
1 pc	Front n/s fender sticker	\$	28.00	ner
1 pc	Front n/s fender inner shield clips	\$	100.00	ner
1 set	n/s door sticker	\$	60.00	ner
1 pc	Rear n/s fender sticker	\$	50.00	30
Sundry		\$	50.00	✓
Towing Fee		\$	300.00	60
To dismantle / refit inner components of the front n/s and rear n/s door into new shell door		\$	80.00	✓
To check wheel alignment		\$	120.00	60
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	850.00	700
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s fender, etc.		\$	1,000.00	800
To putty and spray painting on front bumper, front n/s fender, front n/s door, rear n/s door, rear n/s fender		\$	120.00	60
To apply rustproofing on the repaired and replaced panels.		\$	7,618.03	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Less 20%
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.