

AxH

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

02/06/2018

Owner: FAVORIDE PTE LTD

*Not Autharw
6/1/2018 @ 7
Purning After Pains
8 days*

ESTIMATE TO REPAIR TOYOTA ALITS -SJJ8477J

1pc	front RH fender	R	\$	281.45	X
1pc	front RH door	R	\$	972.45	—
1pc	front RH door protector	R	\$	121.35	—
1pc	front RH door protector chrome	R	\$	121.10	—
1pc	front RH door frame sticker	R	\$	83.10	—
1pc	front RH door handle	R	\$	258.55	—
1pc	front RH door glass moulding	R	\$	191.85	X ?
1pc	front RH door glass motor		\$	281.85	?
1pc	front RH door glass motor gear		\$	181.50	?
1pc	front RH door inner lock	R	\$	281.55	X
1pc	front RH door inner rubber		\$	181.50	?
1pc	rear RH door	R	\$	981.50	—
1pc	rear RH door protector	R	\$	121.38	—
1pc	rear RH door protector chrome	R	\$	141.45	—
1pc	rear RH door frame sticker	R	\$	121.15	—
1pc	rear RH fender	R	\$	972.45	X
1pc	rear bumper	R	\$	371.25	X
1pc	rear bumper side retainer	R	\$	43.50	X
1pc	rear bumper RH side garnish	R	\$	43.10	X

less 25%

remove & refix rear windscreen glass

sealant

tuffkote

wiring

spray painting

labour charges

Total

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 5,752.03

\$ 1,438.00

\$ 4,314.03

\$ 120.00 X

\$ 80.00 X

\$ 120.00 601

\$ 150.00 201

\$ 1,400.00 10001

\$ 1,000.00 6001

\$ 7,184.03

