

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5673P**AAD1806-006***Not Authored
11 May 2018*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5673P

VF1ABL15AUC279760

RENAULT

LATITUDE

1.6.2018

AXA**PART****LIST**

1	FENDER PANEL FRT LH	\$	<i>B</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>Dir</i> 278.84 ✓
1	FENDER BRACKET LOWER LH	\$	<i>Sn</i> 15.79 X
1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84 X
1	DOOR PANEL FRT LH	\$	<i>B</i> 2,844.66 ✓
1	DOOR HINGE UPPER LH L70Y	\$	<i>R</i> 261.28 X
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55 X
1	DOOR CHECK FRT LH	\$	<i>Sn</i> 194.77
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69
1	DOOR LOCK FRT LH	\$	<i>R</i> 908.75
1	DOOR CATCH FRT LH	\$	<i>Sn</i> 131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>Sn</i> 477.76
1	DOOR HANDLE COVER FRT LH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR FRT LH	\$	<i>R</i> 505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Sn</i> 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sn</i> 120.97
1	DOOR PANEL REAR LH L70Y	\$	<i>R</i> 2,844.66
1	DOOR MIRROR ASSY LH	\$	<i>CR</i> 1,483.40 ✓
1	ROCKER PANEL INNER GARNISH LH	\$	<i>Sn</i> 466.51 X
1	ROCKER PANEL INNER LH	\$	<i>R</i> 1,024.79 X
1	ROCKER PANEL CENTER LH	\$	<i>R</i> 990.25 X
1	DOOR HARNESS WIRE	\$	<i>Sn</i> 2,670.00 X

\$ 17,400.0510% **\$ 1,740.00****\$ 15,660.04**

Trans-cab Auto Services Pte Ltd**AAD1806-006**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5673P**Specical Nett**

1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00 X
1	BUMPER BRACKET CLIP FRT LH	\$	<i>nn</i> 12.00 X
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>nn</i> 10.50 X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00 X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>nn</i> 70.00 X
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>nn</i> 20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>nn</i> 30.00 X
1SET	WHEELARCH CLIP FRT LH	\$	<i>nn</i> 30.50 ✓
1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>nn</i> 80.00 <i>6000</i>
1	FRONT DOOR STICKER 'Chassis'	\$	<i>nn</i> 50.00 <i>1500</i>
1	REAR DOOR STICKER '6555 3333'	\$	<i>nn</i> 80.00 X
1	FRONT LEFT TYRE RIM	\$	<i>nn</i> 380.00 X

TOTAL	\$	898.00
--------------	-----------	---------------

TOTAL PARTS	\$	16,558.04
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 <i>6000</i>
Putty and spray painting of the affected portion.	\$	4,000.00 <i>6600</i>
To rust-proofing of the affected areas.	\$	170.00 <i>600</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>600</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>600</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>

Trans-cab Auto Services Pte Ltd**AAD1806-006**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5673P

To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>un</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	⚡ 380.00 X
To replace, refix and top up coolant for radiator	\$	⚡ 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	⚡ 170.00 X

TOTAL	\$	10,710.00
--------------	-----------	------------------

Over All Total	\$	27,268.04
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~15 DAYS~~*4 days*

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--