

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

5-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6287 P

1 pc	Boot lid <i>X repair</i>	\$	1,119.00
1 pc	Boot lid lock <i>X</i>	\$	99.00
1 pc	Bootlid striker <i>X</i>	\$	21.00
1 pc	Bootlid emblem <i>/</i>	\$	27.00
1 pc	Bootlid CRDi <i>/</i>	\$	29.00
1 pc	Bootlid rubber weatherstrip <i>X</i>	\$	96.00
1 pc	Bootlid lower garnish <i>X repair</i>	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 <i>X</i>	\$	132.00
2 pcs	n/s & o/s tail lamp @ \$421.00 <i>X</i>	\$	842.00
1 pc	End panel <i>X repair</i>	\$	250.00
1 pc	End panel garnish <i>?</i>	\$	74.00
1 pc	Spare tyre clamp <i>X</i>	\$	6.00
1 pc	Rear bumper <i>/</i>	\$	696.00
1 pc	Rear bumper lower cover <i>/</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>/</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>?</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>/</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>?</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>?</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>?</i>	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>X</i>	\$	92.00
		\$	4,938.00
		Less 10%	\$ 569.80
		\$	4,368.20

S/NETT

1 set	Rear bumper clips <i>/</i>	\$	48.00
1 set	End panel inner garnish clips <i>X</i>	\$	30.00
1 set	Bootlid lower garnish clips <i>X</i>	\$	60.00
1 set	Bootlid stickers <i>/</i>	\$	100.00
1 set	Reverse sensor <i>/</i>	\$	280.00
1 pc	Rear bumper top protector <i>/</i>	\$	80.00
			<i>200</i>
			<i>50</i>

5-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6287 P

Sundry	\$ 50.00 20
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$ 1,200.00 400
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel	\$ 800.00 720
To apply rustproofing on the repaired and replaced panels.	\$ 150.00 X
	\$ 7,466.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahin call
M 5/6/18 1535 hrs.
3 days
4s
After Repair to

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts at time of resurvey
- Parts prices are on "market" basis
- Third party labour is on "no prejudice" basis
- No illegal trade in parts to be allowed
- Supplemental work to be surveyed and is subject to liability from Insurance Company

Acknowledged by Repairer

Signature:

Date: