

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF155K
 Ref. No : TAX/06/18/2005
 Reg. Date : 28/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : LAU WEI SUN LAWRENCE
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 01/06/2018 04:30:00 PM
 Accident Reported Date / Time : 02/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096405
 Special Instruction to ARC, if any :
 SHB7935B (TRANSCAB) - AXA
 Prepared Date : 02/06/2018 11:13:14 AM



Satya Sai

5/6/2018

sebastianyeang@lkkauto.com

- Part by Part repair
- Question mark item photo
- Photo before paint

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303575335

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,859.00	0.00
Total Spray Painting Charges :	2,412.00	0.00
Total Material Charges :	14,736.01	14,736.01
Other Charges :	1,040.00	0.00
TOTAL :	20,047.01	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	11.00	<i>0.00 5 days</i>
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	04/06/2018 11:03:25 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/06/2018 11:03:25 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 600
TO REPAIR FRONT PORTION	845.00	0.00 400
Total Labour	1,859.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 ?
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 ?
TO RESPRAY REAR PANEL	180.00	0.00 ?
TO RESPRAY TAIL GATE	378.00	0.00 x
TO RESPRAY TAILGATE OUTSIDE GARNISH	378.00	0.00 x
TO RESPRAY REAR SPOILER	180.00	0.00 x
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 ?
Total Spray Painting & Panel Beating	2,412.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 100
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 x
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 x
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 60
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 x
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 x
Total Other Costs	1,040.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY ✓DT	1	423.90	25.00	317.92	Replace	Replace	No
5202347030			REAR BUMPER REINFORCEMENT ?	1	318.80	25.00	239.10	Replace	Replace	No
5245347010			GUARD, RR BUMPER, LOWER ?	1	558.30	25.00	418.72	Replace	Replace	No
5216947020			COVER, GUARD RR BUMPER LOWER ✓DT	1	14.80	25.00	11.10	Replace	Replace	No
5257647040			RETAINER, RR BUMPER, LH ?	1	111.50	25.00	83.62	Replace	Replace	No
5257547040			RETAINER, RR BUMPER, RH ?	1	112.70	25.00	84.52	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH , 1 ?	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH , 2 ?	2	3.80	25.00	5.70	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH , 3 ?	2	3.80	25.00	5.70	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH ?	2	11.00	25.00	16.50	Replace	Replace	No
5256647900			FILLER, RR BUMPER , LH ?	1	119.90	25.00	89.92	Replace	Replace	No
5256547900			FILLER, RR BUMPER , RH ?	1	119.90	25.00	89.92	Replace	Replace	No
			SENSOR REVERSE ✓SE	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER ✓NEC	2	60.00	0.00	120.00	Replace	Replace	No
5259247040			SEAL, RR BUMPER , LH X	1	85.20	25.00	63.90	Replace	Replace	No
5259147050			SEAL, RR BUMPER , RH X	1	85.20	25.00	63.90	Replace	Replace	No
5839947030			COVER, REAR FLOOR UNDER , LH X	1	234.30	25.00	175.72	Replace	Replace	No
7697147010C0			COVER, REAR UNDER , CENTER ?	1	106.90	25.00	80.17	Replace	Replace	No
5839847050			COVER, REAR FLOOR UNDER , RH X	1	169.50	25.00	127.12	Replace	Replace	No
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK ?	1	629.80	25.00	472.35	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX X	1	37.00	0.00	37.00	Replace	Replace	No
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR X	1	929.60	25.00	697.20	Replace	Replace	No
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY X	1	891.20	25.00	668.40	Replace	Replace	No
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE X	2	27.90	25.00	41.85	Replace	Replace	No
7557547051			TAIL GATE MOULDING LOWER GLASS , BACK DOOR X	1	19.70	25.00	14.77	Replace	Replace	No
7544147030			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR X	1	52.30	25.00	39.22	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR X	1	52.30	25.00	39.22	Replace	Replace	No
7540348010			EMBLEM SUB-ASSY REAR X	1	46.30	25.00	34.72	Replace	Replace	No
	COMMON		SMRT LOGO X	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 65558888 X	1	21.60	0.00	21.60	Replace	Replace	No
6788147050			TAIL GATE WEATHERSTRIP, BACK DOOR X	1	360.70	25.00	270.52	Replace	Replace	No
6471847080C0			END PANEL, COVER, DECK TRIM SERVICE HOLE X	1	47.00	25.00	35.25	Replace	Replace	No
6471647130C0			END PANEL, COVER, DECK TRIM, REAR X	1	122.80	25.00	92.10	Replace	Replace	No
7608547916			SPOILER SUB-ASSY, REAR X	1	1,322.10	25.00	991.57	Replace	Replace	No
8156147151			LENS & BODY, REAR COMBINATION LAMP, LH ?	1	438.10	10.00	394.29	Replace	Replace	No
			NUMBER PLATE X BR	1	35.00	0.00	35.00	Replace	Replace	No
			NUMBER PLATE FRAME X	1	25.00	0.00	25.00	Replace	Replace	No
5211947962			COVER, FR BUMPER ✓ CUT	1	495.50	25.00	371.62	Replace	Replace	No
5212847906			COVER, FR BUMPER LH X	1	28.10	25.00	21.07	Replace	Replace	No
5212747907			COVER, FR BUMPER RH ✓ BR	1	28.10	25.00	21.07	Replace	Replace	No
5311247240			GRILLE, RADIATOR X BR	1	165.00	25.00	123.75	Replace	Replace	No
5310147080			GRILLE SUB-ASSY ✓ CR	1	335.60	25.00	251.70	Replace	Replace	No
5211447190			BRACKET, FR BUMPER ?	1	99.80	25.00	74.85	Replace	Replace	No
			NUMBER PLATE ✓ BR	1	35.00	0.00	35.00	Replace	Replace	No
			NUMBER PLATE FRAME ✓ BR	1	25.00	0.00	25.00	Replace	Replace	No
7531047030			EMBLEM ASSY FRONT ✓ CUT	1	87.10	25.00	65.32	Replace	Replace	No
5211647050			SUPPORT, FR BUMPER LH ?	1	82.30	25.00	61.72	Replace	Replace	No
5211547050			SUPPORT, FR BUMPER RH ?	1	76.90	25.00	57.67	Replace	Replace	No
5202147110			REINFORCEMENT FRONT UPPER ?	1	691.10	25.00	518.32	Replace	Replace	No
5261147140			ABSORBER, FR BUMPER ?	1	70.30	25.00	52.72	Replace	Replace	No
5210347010			EXTENSION SUB-ASSY, LH ?	1	116.30	25.00	87.22	Replace	Replace	No
5210247020			EXTENSION SUB-ASSY, RH ?	1	116.30	25.00	87.22	Replace	Replace	No
5213247010			REINFORCEMENT FRONT LOWER ?	1	238.50	25.00	178.87	Replace	Replace	No
5261847030			ABSORBER, FR BUMPER LOWER ?	1	117.00	25.00	87.75	Replace	Replace	No
5320547930			SUPPORT S/A UPPER ?	1	364.90	25.00	273.67	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
8118547691			UNIT, HEADLAMP , LH ?	1	2,558.90	10.00	2,303.01	Replace	Replace	No
8114547691			UNIT, HEADLAMP , RH ?	1	2,558.90	10.00	2,303.01	Replace	Replace	No
8122047020			LAMP ASSY, FOG, LH ?	1	910.20	10.00	819.18	Replace	Replace	No
8121047020			LAMP ASSY, FOG, RH ?	1	910.20	10.00	819.18	Replace	Replace	No
TOTAL MATERIALS							14,736.15	14,736.01		
TOTAL MATERIALS(Discounted)							14,736.01	14,736.01		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									