



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TPVehicle No. : SCY9003RMake & Model : TOYOTA CAMRY 2.0 AUTOYear of Manufacture : 2008Chassis No. : MR053BK4107036386Ins Company : AIG VS FWDEngine No. : 1AZE118185Excess : -Policy No. : -Date of Accident : 5/28/2018Time of Accident : 13:15

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimates**Case Owner : ROHANI

Signature : \_\_\_\_\_

Contact No

63837466 – Patrick  
[patricktia@sparkcarcare.com](mailto:patricktia@sparkcarcare.com)**Parts (a) Cost / List Price Items** \$827.40Plus/Less 25% \$206.85Total of Cost / List \$620.55(b) Nett Price Items \$-

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$-63837890 – Eric  
[ericppg@sparkcarcare.com](mailto:ericppg@sparkcarcare.com)

63838115 – WILLIAM

63837362 – EZEL

63837656 - Ngo  
[ngotw@cdge.com.sg](mailto:ngotw@cdge.com.sg)

63837730 – Brenda Ng

**Total Parts Cost (Appendix A)** \$620.55**Labour (Appendix B)** \$1,020.00**Total Repair Cost** \$1,640.55*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax:62815767

## Spare Parts

Vehicle No	: <u>SCY9003R</u>	Case Owner	: <u>ROHANI</u>
Make & Model	: <u>TOYOTA CAMRY 2.0 AUTO</u>	Year Manufacture	: <u>2008</u>
Chassis No	: <u>MR053BK4107036386</u>	Engine No	: <u>1AZE118185</u>
Sales Order	: _____	Supplier	: _____
Order By	: _____	Type of Claim	: <u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	FRONT BUMPER	1		\$487.10		
2	FRT BUMPER SIDE RETAINER RH	1		\$75.10		
3	FRT BUMPER SIDE RETAINER LH	1		\$75.10		
4	FRT BUMPER CLIP	8		\$45.68		
5	FRONT BUMPER CHROME MOULDING LH	1		\$72.21		
6	FRONT BUMPER CHROME MOULDING RH	1		\$72.21		
7	0	0				
8	0	0				
9	0	0				
10	0	0				
11	0	0				
12	0	0				
13	0	0				
14	0	0				
15	0	0				
16	0	0				
17	0	0				
18	0	0				
19	0	0				
20	0	0				
21	0	0				
22	0	0				
23	0	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29		0				
30		0				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

## : 2008

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*