

67472942

GBF1764S

TP Chin.

Nissan Navarra.

Vic.

MINTCB4D23Z0000086.

Front Number Plate	$\left. \begin{array}{l} \text{HP} \\ \text{over} \end{array} \right\}$	30 (SN) X
Front Number Plate Garnish		77.30 X
Front Bumper	Delivered	473 ✓
		30 ✓
Front Bumper Clips.	m	
Front Bumper Side Holder x 02	m	$26.3 \times 2 = 52.60$ ✓
Front Bumper Fog Lamp x 02	$\left. \begin{array}{l} \text{HP} \\ \text{m} \end{array} \right\}$	$321.6 \times 2 = 643.20$ X
Front Bumper Fog Lamp Cover x 02	$\left. \begin{array}{l} \text{HP} \\ \text{m} \end{array} \right\}$	$108.6 \times 2 = 217.20$ X
Front Bumper Bracket x 03	Best	$35 \times 3 = 105$ ✓
Front Bumper Reinforcement	X	
Front Grille	c/w Chrome Moulding	576.80 ✓
Front Grille Chrome Moulding		
Front Grille Logo.	m	118.10. ✓
Front Support Panel	Delivered	1193.40. ✓
Front Support Panel Top Cover		
Front Support Panel Top Cover Clips		
Headlamp x 02	could	$494.6 \times 2 = 989.20$ ✓
Headlamp Bonnet	Disbld	731.50 ✓
Bonnet Lock	Damaged	105.80. ✓

GBF1764S.

Bonnet Weatherstripe

cut

31.60 ✓

Bonnet Hinge x 02

not
new

$32.6 \times 2 = 65.20 \cdot X$

Bonnet Insulator

2 x 10m

104.70 · X

Bonnet Insulator Clips.

30 · X

RH Buckled $548.2 \times 2 = 1096.40$ ✓
548.20

Front Fender x 02

Front Brace Panel.

Bent

48.20 ✓

Power Steering Cooler Pipe.

Bent

291.50 ✓

Air Con Condenser

Bent

760.60 ✓

~~Off~~ Air Con Condenser Side Garnish x 02

tom

$41 \times 2 = 82$ ✓

Oil Cooler

Bent

624 (SN) ✓

Radiator

Bent

712.40 ✓

Radiator Fan Cowling

crushed

130.70 ✓

Radiator Fan Blade

Not new

150.70 · X

Radiator Top Panel.

Buckled

345.40. ✓

Nett. 7326

S.N: 624

Len 10%: 659340

GBF1764S.

Panel Beating -
Spray Painting.

Wiring.
To undersend

To remove condenser &
radiator and to re-gas.

~~1400.~~ 1000

~~1400~~ 1000

~~50~~ 30

2000
2180.

~~150.X~~ 30.

~~180.~~ 120.

total 9397.40.

L/S: 7.5K

07 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: