

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2783A

DATE 4/6/2018 11:21

MAKE :

MODEL : MERCEDES

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt <i>X repair</i>			\$ 1,890.50
	Bumper Bracket, Frt/RH <i>X</i>			\$ 95.00
	Bumper Absorber, Frt/RH <i>X</i>			\$ 207.00
	<i>RH Front Door X repair</i>			
	<i>RH Front Door Hand Skin repair</i>			
	SUB TOTAL			\$ 2,192.50
	LESS 20%			\$ 438.50
	DISCOUNTED TOTAL			\$ 1,754.00
	<i>RH Rear Door X repair</i>			
	<i>RH Rear fender X repair</i>			
	<i>Rear Bumper X repair</i>			
	<i>Rear RH Door skin</i>			
	<i>\$60</i>			
	Labour Charge			
	Panel Beating			\$ 500.00
	Spray Painting Charge-Fender/Bumper			\$ 500.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 1,050.00
	ESTIMATE TOTAL			\$ 2,804.00

Kahill (K)

4/6/18 1156h

2 Reps

4/5

After Repair pld

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: