

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

*W/Kawin* *L/Sam*  
*Lice* *AIG*

VEHICLE NO : SHB 4267R  
 MAKE :  
 MODEL : HYUNDAI i40

DATE 2/6/2018 10:28

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Licence Lamp Cover ✓			\$ 100.00
	Rear Bumper <i>x Agri</i>			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00
	Rear Bumper Clips 10 pcs <i>x</i>			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover <i>x</i>			\$ 225.00
	<b>SUB TOTAL</b>			<b>\$ 1,958.35</b>
	<b>LESS 20%</b>			<b>\$ (391.67)</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,566.68</b>
	Rear No.Plade ✓			\$ 25.00
	Rear Bumper Reverse Sensor <i>x</i>			\$ 135.70
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
				<b>\$ 360.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>350.00</del> <sup>100</sup>
	Spray Painting Charge			\$ <del>250.00</del> <sup>200</sup>
	Wiring Charge			\$ <del>30.00</del> <i>x</i>
	Remove/Refix Reverse Sensor			\$ <del>120.00</del> <i>x</i>
	<b>TOTAL LABOUR</b>			<b>\$ 750.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,677.38</b>

Nett  
 Nett  
 Nett

*Kalinellly*  
*4/6/18 1050h*  
*2 Rps*  
*4/5*  
*After Repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: