

VIN'S MOTOR PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref : TP/062018/3594

Accident date: 2/6/2018

Your Ref : SLV515Z

Tax Invoice :

Date : 4/6/2018

MOTOR CLAIM DEPARTMENT
AXA INSURANCE (S) PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Not Authorized
1.B.1
Resony B4 pain
10 days

ESTIMATE COST OF REPAIRS TO HONDA SHUTTLE SLV2518C

1	pc	Rear windscreen moulding	<i>Ne</i>	\$	120.10	✓
1	pc	Rear boot cover	<i>B</i>	\$	1,193.00	✓
2	pcs	Rear boot cover hinge @ \$40.80/pc	<i>R</i>	\$	81.60	X
2	pcs	Rear boot cover shocker bracket @ \$165/pc	<i>R</i>	\$	330.00	X
1	pc	Rear boot cover lock	<i>\$R</i>	\$	157.10	✓
1	pc	Rear boot cover lock motor	<i>\$</i>	\$	490.00	✓
2	pcs	Rear boot cover reflector @ \$395/pc	<i>\$</i>	\$	790.00	✓
2	pcs	Rear boot cover number plate lamp @ \$38.50/pc	<i>\$R</i>	\$	77.00	X
1	pc	Rear boot cover moulding	<i>\$</i>	\$	383.40	✓
1	pc	Rear boot cover "Shuttle" name plate	<i>Ne</i>	\$	55.00	✓
1	pc	Rear boot cover emblem	<i>Ne</i>	\$	38.00	✓
1	pc	Rear boot cover inner trim	<i>\$</i>	\$	320.90	✓
1	pc	Rear boot cover rubber	<i>Dis</i>	\$	168.50	✓
1	pc	Rear lamp @ \$520.60/pc	<i>clsum</i>	\$	1,041.20	✓
1	pc	Rear end panel	<i>B</i>	\$	560.80	✓
1	pc	Rear end panel inner trim	<i>B</i>	\$	251.40	✓
1	pc	Rear tool box	<i>Ne</i>	\$	587.30	✓
1	pc	Rear spare tyre panel <i>P.</i>	<i>B/B</i>	\$	1,980.00	✓
1	pc	Rear spare tyre panel top cover	<i>\$</i>	\$	585.50	✓
1	pc	Rear bumper	<i>B</i>	\$	1,150.60	✓
1	pc	Rear bumper sponge	<i>NSP</i>	\$	170.60	X
2	pcs	Rear bumper side retainer @ \$26.50/pc	<i>Sm</i>	\$	53.00	X
2	pcs	Rear bumper reflector @ \$45.20/pc	<i>MS?</i> <i>clsum</i>	\$	90.40	
2	pcs	Rear fender inner trim @ \$489.60/pc	<i>MS?</i> <i>clsum</i>	\$	979.20	✓
1	pc	Rear exhaust silence	<i>\$R</i>	\$	745.70	X
					\$	12,400.30
Less: 20%					\$	(2,480.06)
					\$	9,920.24

VIN'S MOTOR PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref : TP/062018/3594

Page 2

Balance b/d

\$ 9,920.24

1 pc Rear windscreen gum

Me \$ 60.00 N

1 set Rear bumper sensor

Ref \$ 280.00 N

To remove and refix rear glass

\$ 150.00 120h

To repair rear damage

\$ 1,400.00 120ch

To spray painting

\$ 1,200.00 1000h

\$ 13,010.24

VIN'S MOTOR PTE LTD

**LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: