

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/06-1015	Quotation Date : 02/06/2018	Terms : 30 DAYS
Vehicle No : SLS4089B	Chassis No : JM6BN22A8H0158935	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: ,INSURED'S VEH NO: ,DATE OF ACCIDENT: 01.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR FENDER LH	1	1,175.0000	but 1,175.00
2	REAR FENDER INNER LINER	1	146.0000	de 146.00
3	REAR FENDER INNER LINER CLIPS	6	5.0000	we 30.00
4	REAR FENDER AIR VENT	1	72.0000	de 72.00
5	REAR FENDER INNER TRIM	1	236.0000	x 236.00
6	REAR FENDER INNER TRIM CLIPS	6	5.0000	x 30.00
7	REAR FENDER LOWER PANEL	1	155.8000	be 155.80
8	REAR LAMP LH	1	509.0000	cr 509.00
9	REAR LAMP PANEL	1	378.0000	Ry 378.00
10	REAR BUMPER SIDE RETAINER LH - de, RH - x	2	37.0000	we 74.00
11	REAR BUMPER CLIPS	2	5.0000	de 10.00
12	REAR BUMPER REFLECTOR LH - mis, RH - x	2	57.0000	114.00
13	REAR BUMPER SIDE HOLDER LH - we, RH - x	2	46.0000	92.00
14	REAR BUMPER SIDE HOLDER RIVETS	4	5.0000	we 20.00
15	REAR BUMPER REINFORCEMENT	1	538.0000	Ry 538.00
16	REAR BUMPER TOW COVER	1	17.0000	mis 17.00
17	REAR BUMPER	1	1,075.0000	de 1,075.00
18	REAR END PANEL	1	506.0000	be 506.00
19	BOOTLID	1	958.0000	Ry 958.00
20	BOOTLID REFLECTOR	1	265.0000	? 265.00
21	BOOTLID CENTRE EMBLEM BADGE	1	75.0000	we 75.00
22	BOOTLID SKYACTIV BADGE	1	64.0000	we 64.00
23	BOOTLID MAZDA 3 BADGE	1	54.0000	we 54.00

C/F 0.00

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/06-1015	Quotation Date : 02/06/2018	Terms : 30 DAYS
Vehicle No : SLS4089B	Chassis No : JM6BN22A8H0158935	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: ,INSURED'S VEH NO: ,DATE OF ACCIDENT: 01.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	BOOTLID WEATHERSTRIP	1	130.0000	X 130.00
25	LESS 20% ON ITEM 1 - 24	1	-1,344.7600	-1,344.76
26	REAR BUMPER PARKING SENSOR	1	450.0000	X 450.00
27	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	30 60.00
28	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	180.0000	120 180.00
29	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	30 120.00
30	TO RUST-PROOFING OF THE AFFECTED PORTION	1	180.0000	40 180.00
31	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,500.0000	1000 1,500.00
32	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,400.0000	900 1,400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Tan Lim 97415749
 WP
 4/6/18 @ 1230
 7 days.
 Resurvey after repair.
 Lump sum.
 Sum @ lkk auto.com.

Sub Total	9,269.04
GST(7.00%)	648.83
Total (SGD)	9,917.87