

Trans-cab Auto Services Pte Ltd

AAD1805-276

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z*Not Authorized*
Presumy B4 painting

Vehicle No.:

SHD 957Z

Chassis No.:

VF1ABL15AUC283400

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

30.5.2018

Third Party Insurer :

AIG**PART****LIST**

1	1	BUMPER COVER FRT	\$	Bu	1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	Sn	181.75	X
3	1	BUMPER ABSORBER FRT	\$	Sn	394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	Sn	151.41	}
5	1	BUMPER SUPPORT FRT	\$	Sn	123.88	
6	1	BUMPER RETAINER FRT RH	\$	Sn	150.77	
7	1	BUMPER SUPPORT FRT	\$	Sn	123.88	
8	1	BUMPER UNDERTRAY FRT	\$	Sn	472.83	
9	1	BUMPER GRILLE LOWER FRT	\$	Sn	266.80	
10	1	BUMPER FOG LAMP GRILLE LH	\$	Sn	207.21	
11	1	BUMPER FOG LAMP GRILLE RH	\$	Sn	207.21	
12	1	BUMPER BEAM FRT	\$	R	914.08	
13	1	TOW COVER FRT	\$	Sn	28.61	
14	1	RADIATOR GRILLE	\$	Sn	1,707.78	} X
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	Sn	225.36	
16	1	RADIATOR GRILLE FRAME	\$	Sn	1,353.75	
17	1	FRAME FULL SUPPORT PANEL	\$	Sn	615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	R	89.79	
19	1	FRONT BRACE PANEL	\$	R	177.22	
20	1	HORN	\$	Sn	314.17	
21	1	HORN BRACKET	\$	R	40.45	
22	1	HEADLAMP LH	\$	Sn	1,184.43	
23	1	HEADLAMP RH	\$	Sn	1,184.43	
24	1	HEADLAMP PANEL FRT LH	\$	R	152.15	
25	1	HEADLAMP PANEL FRT RH	\$	R	152.15	
26	1	BONNET	\$	R	1,941.63	
27	1	BONNET INSULATOR	\$	Sn	405.73	
28	1	BONNET STRUT LH	\$	Sn	88.61	

Trans-cab Auto Services Pte Ltd**AAD1805-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z

29	1	BONNET STRUT RH	\$	S ₂	88.61	}	X
30	1	BONNET HINGE LH	\$	R	348.31		
31	1	BONNET HINGE RH	\$	R	348.31		
32	1	BONNET LOCK	\$	R	305.48		
33	1	BONNET CABLE	\$	S ₂	119.19		
34	1	BONNET CABLE COVER	\$	S ₂	161.03		
35	1	BONNET SEAL OUTER	\$	S ₂	92.36	}	
36	1	BONNET SEAL INNER	\$	S ₂	157.28		
37	1	FENDER PANEL FRT LH	\$	B ₂	783.83	}	—
38	1	WHEELARCH FRT LH	\$	S ₂	278.84		
39	1	FENDER BRACKET LOWER LH	\$	S ₂	15.79	}	X
40	1	FENDER INSULATOR LH	\$	S ₂	130.84		
41	1	FENDER INSULATOR RH	\$	S ₂	130.84		
42	1	WIPER RESERVOIR	\$	S ₂	348.25		
43	1	WIPER RESERVOIR NECK	\$	S ₂	136.11		
44	1	WIPER RESERVOIR MOTOR	\$	S ₂	270.06		
45	1	AIR CLEANER LOWER	\$	S ₂	271.26		
46	1	AIR CLEANER HOSE	\$	S ₂	76.14		
47	1	BASE BATTERY TRAY	\$	S ₂	363.40		
48	1	AIR CLEANER BOX	\$	S ₂	464.20		
49	1	TURBO DUCT	\$	S ₂	1,027.80		
50	1	A/C HEATER VALVE	\$	S ₂	484.50		
51	1	SUBFRAME OUTER FRT	\$	S ₂	2,652.45		
52	1	SUBFRAME BRACKET OUTER LH	\$	S ₂	92.36		
53	1	ENGINE UNDERTRAY	\$	S ₂	564.98		
54	1	A/C CONDENSER	\$	S ₂	2,020.37		
55	1	A/C CONDENSER GARNISH LH UPPER	\$	S ₂	39.67		
56	1	A/C CONDENSER GARNISH RH UPPER	\$	S ₂	39.67		
57	1	A/C CONDENSER GARNISH LH	\$	S ₂	58.81		
58	1	A/C CONDENSER GARNISH RH	\$	S ₂	59.60		
59	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	S ₂	208.39		
60	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	S ₂	658.72		
61	1	A/C PIPE COMPRESSOR	\$	S ₂	334.29		
62	1	A/C PIPE	\$	S ₂	658.72		
63	1	A/C COMRPRESSOR	\$	S ₂	2,684.61		
77	1	AIR COOLER	\$	S ₂	792.60		
78	1	AIR INTERCOOLER HOSE (LONG)	\$	S ₂	1,014.13		
79	1	AIR INTERCOOLER HOSE (Short)	\$	S ₂	375.14		

Trans-cab Auto Services Pte Ltd**AAD1805-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z

80	1	TRANSMISSION COOLER	\$	Sn 1,219.30	}
81	1	TRANSMISSION COOLER PAD	\$	Sn 17.96	
82	1	RADIATOR	\$	Sn 1,202.20	
83	2	RADIATOR STUD UPPER	\$	Sn 14.41	
84	2	RADIATOR BUSH UPPER	\$	Sn 50.12	
85	2	RADIATOR MTG LOWER	\$	Sn 55.85	
86	1	RADIATOR FAN COWLING	\$	Sn 820.54	
87	1	RADIATOR FAN MOTOR LH	\$	Sn 967.36	
88	1	RADIATOR FAN MOTOR RH	\$	Sn 1,479.46	
89	1	RADIATOR TANK	\$	Sn 324.62	
90	1	RADIATOR HOSE UPPER	\$	Sn 240.56	
91	1	RADIATOR HOSE LOWER	\$	Sn 491.18	
92	1	RADIATOR TANK HOSE	\$	Sn 61.18	
93	1	AUTO COMPUTER	\$	Sn 5,032.17	
94	1	INJECTION COMPUTER	\$	Sn 4,706.30	
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	Sn 5,154.52	}
96	1	STEERING PUMP ELECTRIC L70Y	\$	Sn 2,306.90	
97	1	STEERING PINION RACK L70Y	\$	Sn 4,413.11	
98	1	SUBFRAME OUTER FRT L70Y	\$	Sn 2,652.45	
99	1	SUBFRAME INNER FRT L70Y	\$	Sn 2,284.80	
100	1	LOWER ARM LH L70Y	\$	Sn 685.76	
101	1	KUNCKLE ARM LH L70Y	\$	Sn 846.98	
102	1	ABSORBER FRT LH L70Y	\$	Sn 360.54	

TOTAL	\$	68,161.28
10%	\$	6,816.13
	\$	61,345.15

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	Sn 52.00	X
2	1SET	BUMPER CLIP FRT	\$	Sn 66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	Sn 12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	Sn 10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	Sn 12.00	X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	Sn 10.50	X
7	1	TOW COVER FRT	\$	Sn 14.50	X

Trans-cab Auto Services Pte Ltd

AAD1805-276

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z

8	1SET	RADAIOR GRILLE SCREW	\$	nn	16.00	}	X
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00		
21	1	Windscreen moulding	\$	nn	100.00		
22	1SET	Front licence plate with holder	\$	nn	80.00	}	X
23	1	Front left tyre rim	\$	nn	380.00		
24	2	Front left tyre	\$	nn	300.00		

TOTAL	\$	1,242.50
TOTAL PARTS	\$	62,587.65

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 5,400.00 400/

Towing Fees.

\$ nn 120.00 X

To apply paint protection system (PPS) maintain
and enhancement

\$ nn 380.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 440/

To rust-proofing of the affected areas.

\$ 170.00 30/

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To check steering geometry and computer wheel
alignment

\$ nn 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

To Check Electrical Lighting Concerned.

\$ nn 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1805-276

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	↪ 380.00	X
To lift-up engine with gear box and refit.	\$	↪ 440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	↪ 440.00	X
To remove and refit air bag system and reset.	\$	↪ 480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	↪ 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	↪ 380.00	X
To replace, refix and top up coolant for radiator	\$	↪ 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	↪ 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	↪ 170.00	X

TOTAL \$ **16,400.00****Over All Total** \$ **78,987.65****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to repair order
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Days (PART-BY-PART)~~20~~ DAYS

2 days