

22/03/2002

ASS. REC. BY:

REF: CS/MS(18010184/TTHbez

Special Instruction:

SUNVNOY

Mentmen

Paulden

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

mslh

Date/Time:

04062018 4:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCV 7000C

Insured:

SLA 8537T

at Workshop m/s

Munich Automobiles

Tel:

of

30 Teban Crescent

Policy No:

289202480MY

Garden

Claim No:

559319

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20052018

CA / REV / REP. / REV 24 HRS

'DS'

11.062018 @ 12pm

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Wilber

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SCV 7000C - CS/CA715005194 / Mivdi

DA: 220315

SLA 8537T - NA / MS(18009145 / K4

DA: 200518

22/6

Submit preli advise

Final Figure @ \$5025.51 (Red: 2625 : 34%)

REF: MSLG

ASSIGNMENT

From: Date: 11/6/18

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MVTo inspect Vehicle No: SCV 7000C
at Workshop m/s: Munich Automobik
of: 30 feban Garden Crescent

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

12pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'ds'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SCV 7000C Yr Regn: 2013 March

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: BMW M5 c.c. 4395

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 41065 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 26 JUN 2018

Date/Time: File Pass to?

☐

Preli. Report

1) 26/6 Typist

☒

Final Report

Date/Time: File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS ☐ SI☐ Photos☐ Others☐

TOTAL

Report Format: TP

Lump Sum / (B): (\$ 5025.51)

150
10
160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2018		04 Jun 2018 16:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured:	ARUN TEJ PAL, ID: S7062532F																							
Main Claimant:	LEONG KUM CHOY, ID: S6828957B																							
Vehicle Reg. No.:	SCV7000C	Date of Loss:	20/05/2018 00:00 - :59 [62 Months and 5 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / 559319	Policy/Cover Note No.:	28920248QMY Coverage: 18/03/2018 - 17/03/2019																					
Vehicle Reg. No. (Insured):	SLA8537T	Policy No. (Claimant):																						
		Excess:																						
Repairer:	Munich Automobiles Pte Ltd (HQ) 30 Teban Gardens Crescent, 608927 West Coast - Tel: 6566-7666																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/06/2018]																							
Adj Asg. Remarks:	on WP. Please contact us ASAP if you cannot attend this assignment. Liability is down.																							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail																								
There are no mail for this case.																								
ALL ASSOCIATED TASKS																								
<div style="display: flex; justify-content: space-between;"> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Rasul

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 22 Jun 2018

Preliminary Advice

Insured Vehicle No	: SLA8537T	Accident Date	: 20/05/2018
TP Vehicle No	: SCV7000C	Assignment Date	: 04/06/2018
Make	: BMW M5	Est. Duration of Repair	: 3.00
Date of Inspection	: 11/06/2018		
Inspection At	: MUNICH AUTOMOBILES PTE LTD (HQ) 30 TEBAN GARDENS CRESCENT SINGAPORE 608927		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S	7,584.48
Revised Amount	:S\$	4,959.48
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,959.48

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 26 June 2018 9:59 AM
To: Wilber Kuang; Taufikh (LKKAuto)
Cc: Admin-D (LKKAuto)
Subject: RE: SCV7000C Third Party Claim- Finalise

Dear Wilber,

Confirm final figure at 5025.51, 3days

Please submit all documents to MSIG

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wilber Kuang [mailto:wilber.kuang@munichauto.com.sg]
Sent: Tuesday, 26 June 2018 9:47 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: FW: SCV7000C Third Party Claim- Finalise

Hi Taufikh

Please assist to finalize this case ASAP.

Thanks,

Munich Automobiles Pte Ltd

Wilber Kuang

Customer Service Advisor

30 Teban Gardens Crescent

Singapore 608927

Main: +65 6566 7666

Fax: +65 6565 9220

Website: www.munichauto.com.sg



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2018 17:48
Date Of Accident	20/05/2018 19:15
Exact Location Of Accident	BEDOK MALL MSCP LEVEL 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCV7000C
Insured/Policyholder	
Name Of Registered Owner	LEONG KUM CHOY
NRIC No	S6828957B
Email Address	GORDON@GPLAN.COM.SG
Mobile Phone No	(LOCAL) +65-90221311
Alternative Phone No	OTHERS-90221311

Vehicle Particulars

Manufacturer	BMW
Model	M5 D/AB SR ABS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01012872
Cover Note Number	N.A

Driver

Name of Driver	LEONG KUM CHOY
NRIC No	S6828957B
Date Of Birth	04/08/1968
Occupation	INDOOR
Date Of Driving Pass	25/10/1988
Driving Experience	29 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90221311
Fax Number	
Contact Number	OTHERS-90221311
Email Address	GORDON@GPLAN.COM.SG

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER


Ammar Hamizan Bin Khairudin

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **M0006**

Invoice Name & Address:

MSIG Insurance Singapore Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807
Attn: Motor Claim Dept
068807

Customer Name & Address:

Mr Leong Kum Choy
137 Bedok North Ave 3
#11-170

460137

Email: -

Inv. Printed By: WIL Service Advisor:

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 55369	0	0	BK	11/06/2018	10:34	1
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SCV7000C	DX96069	FV92 F10	M5	15/03/2013	0	
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
1	5199000	Remove damaged body parts and repalce effected body parts		288.00	12.50		0.00	3,600.00
2	9999000	Painting front bumper trim		72.00	12.50		0.00	900.00
3	6199000	Vehicle diagnosis - carrying out the ABL and delete fault code		50.00	12.50		0.00	625.00
4	6199000	Check and secure wiring electrical system		50.00	12.50		0.00	625.00
5	SUN	Sundry items		200.00	1.00		0.00	200.00
6		Primed frt.bumper		1.00	1,660.80 EACH		5.00	1,577.76
7		A010676B Set of moun		1.00	33.85 EACH		5.00	32.16
8		Bracket		1.00	14.20 EACH		5.00	13.49
9		Bracket		1.00	11.65 EACH		5.00	11.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

V	Rate	Service/Goods	GST

Tanpin 97495749
u/p
u/p
Resurvey before paint

Acknowledged by Repairer
Customer's Signature _____ Authorized Signature _____

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No: _____

N.B. Goods sold are not returnable.

3 days
SURE 11/11/18
M

Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **M0006**

Invoice Name & Address:

MSIG Insurance Singapore Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807
Attn: Motor Claim Dept
068807

Customer Name & Address:

Mr Leong Kum Choy
137 Bedok North Ave 3
#11-170

460137

Email: -

Inv. Printed By: WIL Service Advisor: Wilber Kuang

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 55369	25058	0	BK	13/06/2018	18:19	1
Reg No.	Chassis No.	Model		Reg Date	Date In	Mileage
SCV7000C	DX96069	FV92 F10	M5	15/03/2013	11/06/2018	41065
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
1	5199000	Remove damaged body parts and repalce effected body parts		96.00	12.50		0.00	1,200.00
2	9999000	Painting front bumper trim		72.00	12.50		0.00	900.00
3	6199000	Vehicle diagnosis - carrying out the ABL and delete fault code		50.00	12.50		0.00	625.00
4	6199000	Check and secure wiring electrical system		40.00	12.50		0.00	500.00
5	SUN	Sundry items		100.00	1.00		0.00	100.00
6		Primed frt.bumper tr		1.00	1,660.80 EACH		5.00	1,577.76
7		Set of mount		1.00	33.85 EACH		5.00	32.16
8		Bracket		1.00	14.20 EACH		5.00	13.49
9		Bracket		1.00	11.65 EACH		5.00	11.07

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **M0006**

Invoice Name & Address:

MSIG Insurance Singapore Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807
Attn: Motor Claim Dept
068807

Customer Name & Address:

Mr Leong Kum Choy
137 Bedok North Ave 3
#11-170

460137

Email: -

Inv. Printed By: WIL Service Advisor: Wilber Kuang

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 55369	25058	0	BK	13/06/2018	18:19	2
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SCV7000C	DX96069	FV92 F10	M5	15/03/2013	11/06/2018	41065
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
Menu Subtotal:								4,959.48
10		Plaque		1.00	69.50 EACH	5.00		66.03
Menu Subtotal:								66.03

Parts	1,700.51	V	Rate	Service/Goods	GST	Net	5,025.51
Surcharge	0.00	S	7.00	5025.51	351.79	G.S.T.	351.79
Labour	3,325.00					Total	5,377.30
Sublet	0.00					Deposit	0.00
Menus	0.00					Owing	5,377.30

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 May 2018		04 Jun 2018 16:40 Edit Adj Rpt	S\$5,025.51 Edit Estimates	S\$5,025.51 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ARUN TEJ PAL , ID: S7062532F									
Main Claimant: LEONG KUM CHOY , ID: S6828957B									
Vehicle Reg. No.: SCV7000C		Date of Loss: 20/05/2018 00:00 - :59 [62 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 559319		Policy/Cover Note No.: 28920248QMY Coverage: 18/03/2018 - 17/03/2019							
Vehicle Reg. No. (Insured): SLA8537T		Policy No. (Claimant):							
		Excess:							
Repairer: Munich Automobiles Pte Ltd (HQ) 30 Teban Gardens Crescent, 608927 West Coast - Tel: 6566-7666									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 04/07/2018]									
Adj Asg. Remarks: on WP. Please contact us ASAP if you cannot attend this assignment. Liability is down.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SCV7000C (559319)**
[SLA8537T]
TP
LEONG KUM CHOY
May 20 2018 12:00AM
[ARUN TEJ PAL]
Munich Automobiles Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	28/05/18 11:48	Video - Accident by TP		Load MP4	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/06/18 15:07	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/06/18 10:00	General View		Load JPG	
2	26/06/18 10:00	General View		Load JPG	
3	26/06/18 10:00	General View		Load JPG	
4	26/06/18 10:00	General View		Load JPG	
5	26/06/18 10:00	General View		Load JPG	
6	26/06/18 10:00	General View		Load JPG	
7	26/06/18 10:00	General View		Load JPG	
8	26/06/18 10:00	General View		Load JPG	
9	26/06/18 10:00	General View		Load JPG	
10	26/06/18 10:00	General View		Load JPG	
11	26/06/18 10:00	General View		Load JPG	
12	26/06/18 10:00	General View		Load JPG	
13	26/06/18 10:00	General View		Load JPG	
14	26/06/18 10:00	Reinspection Photo		Load JPG	
15	26/06/18 10:00	Reinspection Photo		Load JPG	
16	26/06/18 10:00	Reinspection Photo		Load JPG	
17	26/06/18 10:00	Reinspection Photo		Load JPG	

Documentation

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/05/18 15:02	Email frm TP - PRI		Load PDF	
2	24/05/18 15:03	Estimate		Load PDF	
3	24/05/18 15:03	SCV7000C GIA Rpt		Load PDF	
4	04/06/18 16:57	email LKK to check on consistency as OI send us scene photos of TP vehicle which seems minor		Load PDF	

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	04/06/18 16:39	Email - Outsouce LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010184/T1TBE2

Date: 28/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28920248QMY

Claimant Vehicle No : SCV7000C

Insured Vehicle No : SLA8537T

Date of Loss: 20/05/2018

Nature of Claim: TP

Claim No: 559319

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCV7000C

Make & Model: BMW M5, 4.4 (A)

Engine No: 22790346S63B44B

Reg. Date: 15/03/2013 (Man. Year: 2012)

Chassis No: WBSFV92040DX96069

Colour: Black

Odometer: 41065 km

Engine Capacity: 4395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35 R20

Rear Tyre Size: 265/35 R20

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,700.51	1,700.51	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	3,325.00	2,625.00	44.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,650.51	5,025.51	2,625.00	34.31
+ GST 7.00/7.00% (S\$)	535.54	351.79	183.75	34.31
Nett Amount (S\$)	8,186.05	5,377.30	2,808.75	34.31

INSPECTION

Date of Assignment: 04/06/2018

Date Inspected: 11/06/2018 Inspected At:

Munich Automobiles Pte Ltd (HQ)

30 Teban Gardens Crescent

Singapore 608927

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jun 2018)

Parts: M1-COUPE BMW M5 4.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCV7000C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PRIMED FRT BUMPER	Deformed	1,577.76 FS	*1,577.76 FS
2	1		*A010676B SET OF MOUN	Necessary	32.16 FS	*32.16 FS
3	1		*BRACKET	Necessary	13.49 FS	*13.49 FS
4	1		*BRACKET	Necessary	11.07 FS	*11.07 FS
5	1		*PLAQUE	Necessary	66.03 FS	*66.03 FS
Total Parts (S\$)					1,700.51	1,700.51

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE DAMAGED BODY PARTS AND REPLACE EFFECTED BODY PARTS	New	3,600.00	1,200.00
2	PAINTING FRONT BUMPER TRIM	New	900.00	900.00
3	VEHICLE DIAGNOSIS-CARRYING OUT THE ABL AND DELETE FAULT CODE	New	625.00	625.00
4	CHECK AND SECURE WIRING ELECTRICAL SYSTEM	New	625.00	500.00
5	SUNDRY ITEMS	New	200.00	100.00
Gross Labour Cost (S\$)			5,950.00	3,325.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >