

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: **AXA INSURANCE SINGAPORE PTE LTD**
8 SHENTON WAY #27-10
Singapore 068811

Date : 01.06.2018

Motor Claim Dept

Vehicle number : **GBB 8386 A**
Make/Model : **VOLKSWAGEN CADDY 2.0**
Date of accident : **01.06.2018**
Claim Type : **TP Claim**

Accident involving GBB 8386 A & GBE 8518 X along PIE on 01.06.2018.

Re: Estimate

1.	1 pc	Rear door LH ✓OT		\$	1,850.00
2.	1 pc	Rear door RH R		\$	1,850.00
3.	1 pc	Rear number plate & casing x	s/nett	\$	55.00
4.	1 pc	Rear emblem 'caddy' ✓NEC		\$	120.00
5.	1 pc	Rear lamp LH ?		\$	300.00
6.	1 pc	Rear bumper ✓CUT		\$	650.00
7.	1 pc	Reverse sensor ✓DMG		\$	220.00
8.	1 pc	70 km/h sticker ✓NEC		\$	5.00
				\$	5,050.00

To towing services				\$	80.00 50
To wiring services				\$	100.00 40
To remove & refix door glass to assist of repair				\$	150.00 100
To supply sealants				\$	50.00 30
To Replace & Repair Labour Charge				\$	800.00 600
To Putty & Spray Painting				\$	700.00 600

Total				\$	6,930.00

Yours Faithfully,

Total

\$ 6,930.00 3 days

李光華摩嘜燒焊
LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

- Part by Part repair
- Question mark
item photo
- photo before
paint

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: