

22/03/2002

ASS. REC. BY:

REF:

CS/SPF18010186/Rimber

Special Instruction:

Surveyor: RGSW

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 05062018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 6257 Z Insured: QX 212C

at Workshop m/s Vermogen Tel: 6358 3031

of 6 Bendi Sector

Policy No: Claim No: AEMP/105/009/2018/072

Sum Insured: Excess:

Make of Veh: D.O.A. 02062018  
(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time: 05062018 923am Person Contacted: Pila Vehicle: IN/OUT


Date/Time	Action/Instruction (✓) Estimate
	SLD 6257 Z - X
	QX 212C - X
	Submit LIs \$4400.00 @ 5 days
	Red: \$7389.36, 62%.

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLO 62572  
 at Workshop m/s VERMOLAN  
 of \_\_\_\_\_  
 Insured: SPF / mp  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLO 62572 Yr Regn: 2016 / Jun  
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Honda Vezel 1.5x c.c. 1896  
 Colour: WHITE A/C: Insured / Std / NI / NA  
 Sp.Reading: 143534 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: RU1115242  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 215/60R16  
 R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or ROADSTONE

Front		Rear
R/Bal. <u>S</u> mm		R/Bal. <u>S</u> mm
L/Bal. <u>S</u> mm		L/Bal. <u>S</u> mm
D.O.A. <u>02/06/18</u>		D.O.I. <u>05/06/18</u>

Survey held at VERMOLAN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 03 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : SPF-1P

Lump Sum / L.B.I. (\$ 4400)

280

280



# SINGAPORE POLICE FORCE

SPF Accidents Claims Section  
Automotive Engg & Mgmt Div  
Police Logistics Department  
No. 1 Mount Pleasant Road  
Block 8 Old Police Academy  
#02-12 Singapore 298333

Your Ref : SLD6257Z

Our Ref : AEMD/105/009/2018/072

Date : 5 June 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd  
Paya Ubi Industrial Park  
51 Ubi Avenue 1 #01/02-25  
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

## RTA ON 2 JUNE 2018 INVOLVING GOVT VEHICLE QX212C AND OTHER VEHICLE SLD6257Z

We refer to the above matter.

- 2 Please assist to arrange for a PRI of Vehicle no. **SLD6257Z** at **M/s Vermogen Ace Pte Ltd** of **1 Bukit Batok Crescent #05-23 Wcega Plaza**, Singapore **658064**.
- 3 For appointment kindly contact **Edmond Lim** at Tel: **63583031**.
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

05062018 @ 9:30am  
Pila veh in

Yours faithfully,

Abdul Rahman  
Accident Claims Officer  
for Assistant Director

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/06/2018 15:35
Date Of Accident	02/06/2018 11:10
Exact Location Of Accident	ENG NEO AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD6257Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995064
Cover Note Number	

### Driver

Name of Driver	CHUA THIAM HOCK (CAI TIAN FA)
NRIC No	S8205543F
Date Of Birth	02/02/1982
Occupation	OUTDOOR
Date Of Driving Pass	30/06/2010
Driving Experience	7 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	6 BENOI SECTOR
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO FOLLOWING ATTACHED, THANK YOU.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX212C
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*ck*




Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

Eng Neo Avenue

## SKETCH PLAN



A-SLD6257Z  
B-QX212C

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Eng Neo Avenue, I was going to turn right, my vehicle was stationary, suddenly I felt a impact at the rear left portion of my vehicle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:




Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*CK*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:









# SLD6257Z

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)  
6 Benoi Sector, Singapore (629904)  
Tel : 6358 3031 | Fax No : 6694 4929

## ACCIDENT REPAIR ESTIMATE

TP INSURER : SPF  
OWN INSURER : AIG  
CLAIM TYPE : TP  
Date of Accident : 2/6/2018

Vehicle Reg. No. : SLD6257Z  
Vehicle Reg. Date: 23-Jun-2016  
Make / Model : VEZEL 1.5X CVT  
Engine No. : L15B4035248  
Chassis No. : RU11115242

## COST OF CLAIMS

Parts Cost / List Items : \$ 10,349.20  
Plus/Less 20% \$ 2,069.84  
Total Cost / List : \$ 8,279.36  
Special Nett Items : \$ 300.00  
Total Parts Amount : \$ 8,579.36  
Total Labour Amount : \$ 3,210.00  
Gross Total : \$ 11,789.36  
GST % : 7% \$ 825.26  
Nett Amount : \$ 12,614.62

## Surveyor Name and Company :

RASUL CLKK  
Date of survey : 05/06/18  
Part by Part / Lump Sum 5 days  
Resurvey Before Paint / After Paint  
Authorize/Not Authorize/Without Prejudice  
Email : rsul@ikkawto.com  
Fax No : \_\_\_\_\_  
HP No : 90010068

This claim is handled by : MINOKO

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD6257Z**  
 Vehicle Reg. Date: **23/6/2016**  
 Make / Model : **VEZEL 1.5X CVT**  
 Engine No. : **L15B4035248**  
 Chassis No. : **RU11115242**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear fender LH	X SUC	\$ 950.00		
2	1	Rear fender arch garnish LH	neu /	\$ 165.00		
3	1set	Rear fender arch garnish clips	neu /	\$ 40.00		
4	1	Rear fender inner water shield LH	X M	\$ 160.00		
5	1set	Rear fender inner water shield clips	X neu	\$ 40.00		
6	1	Tailgate	BA -	\$ 1,860.00		
7	1	Tailgate outer garnish	X M	\$ 285.00		
8	1set	Tailgate outer garnish clips	X neu	\$ 40.00		
9	1	Tailgate logo	neu X M	\$ 52.00		
10	1	Tailgate emblem "VEZEL"	neu /	\$ 56.20		
11	2	Tailgate lamp LH/RH	X 7	\$ 980.00		
12	2set	Tailgate lamp clips	X 7	\$ 50.00		
13	1	Tailgate outer handle switch	X X SUC	\$ 180.00		
14	2	Tailgate damper LH/RH	X 7	\$ 424.00		
15	1	Tailgate wiper motor	X 7	\$ 250.00		
16	1	Tailgate wiper blade	X	\$ 75.00		
17	1	Tailgate buzzer	X ? cut	\$ 150.00		
18	1	Tailgate inner handle	X 7	\$ 74.00		
19	1	Tailgate inner lock	X	\$ 245.00		
20	1	Tailgate lock sensor	X SUC	\$ 220.00		
21	1	Tailgate striker	X	\$ 32.00		
22	1	Tailgate trimboard	X (CR)	\$ 295.00		
23	1set	Tailgate trimboard clips	neu /	\$ 45.00		
24	1	Tailgate weatherstrip	neu /	\$ 145.00		
25	1	Tailgate windscreen moulding	neu /	\$ 164.00		
26	1	Tail lamp LH	CR /	\$ 489.00		
27	1set	Tail lamp clips	neu /	\$ 36.00		
28	1	Rear bumper	DE /	\$ 950.00		
29	1set	Rear bumper clips	neu /	\$ 50.00		
30	1	Rear bumper retainer LH	X 7 X SUC	\$ 72.00		
31	1	Rear bumper bracket LH	X SUC ? B	\$ 116.00		
32	1	Rear bumper reflector LH	X cut	\$ 167.00		
33	1	Rear bumper cover LH	DE /	\$ 210.00		
34	1set	Rear bumper cover clips	neu /	\$ 50.00		
35	1	Rear bumper cover retainer LH	X SUC	\$ 42.00		
36	1	Rear end panel outer	Repair	\$ 585.00		
37	1	Rear end panel inner	X "	\$ 396.00		
38	1	Rear end panel top garnish	X DE	\$ 184.00		
39	1set	Rear end panel top garnish clips	neu /	\$ 25.00		
40	1	Reverse sensor	neu /		\$ 300.00	200

**6 Benoi Sector, Singapore (629904)**  
**Tel : 6358 3031 | Fax No : 6694 4929**

Vehicle Reg. No. :	<b>SLD6257Z</b>
Vehicle Reg. Date:	23/6/2016
Make / Model :	VEZEL 1.5X CVT
Engine No. :	L15B4035248
Chassis No. :	RU11115242

### Estimates on Labour

[illegible]

**Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)**

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

**FINALIZATION FORM**

ATTN TO: RASUL  
Surveyor Name and Company

Date of Accident : **2/6/2018**

BILL TO: SPF  
TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM: TP

**SLD6257Z**

Make / Model : VEZEL 1.5X CVT

**COST OF CLAIMS**

Parts Cost / List : \$ 5,081.20

Supp. Parts : \$ -

Special Nett : \$ 200.00

Total Parts : \$ 4,264.96

Total Labour : \$ 1,330.00

TOTAL REPAIR COST : \$ 5,594.96

Total Parts Cost/List :	\$	5,081.20
Plus / Less : 20%	\$	1,016.24
Total :	\$	4,064.96

Lump Sum Discount : 20%	\$	1,118.99
Lump Sum Amount:	\$	4,475.97

Final Lump Sum Amount : \$ 4,500.00

Submitted by / Date : MINOKO

No. of Repair Days: 5

Confirmed by / Date : \_\_\_\_\_

**Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)**

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD6257Z**

Vehicle Reg. Date: **23/6/2016**

Make / Model : **VEZEL 1.5X CVT**

Engine No. : **L15B4035248**

Chassis No. : **RU11115242**

PAGE 1

**Estimates on Parts**

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear fender LH		\$ 950.00		
2	1	Rear fender arch garnish LH		\$ 165.00		\$ 165.00 ✓
3	1set	Rear fender arch garnish clips		\$ 40.00		\$ 40.00 ✓
4	1	Rear fender inner water shield LH		\$ 160.00		
5	1set	Rear fender inner water shield clips		\$ 40.00		
6	1	Tailgate		\$ 1,860.00		\$ 1,860.00 ✓
7	1	Tailgate outer garnish		\$ 285.00		
8	1set	Tailgate outer garnish clips		\$ 40.00		
9	1	Tailgate logo		\$ 52.00		
10	1	Tailgate emblem "VEZEL"		\$ 56.20		\$ 56.20 ✓
11	2	Tailgate lamp LH/RH		\$ 980.00		
12	2set	Tailgate lamp clips		\$ 50.00		
13	1	Tailgate outer handle switch		\$ 180.00		
14	2	Tailgate damper LH/RH		\$ 424.00		
15	1	Tailgate wiper motor		\$ 250.00		
16	1	Tailgate wiper blade		\$ 75.00		
17	1	Tailgate buzzer		\$ 150.00		\$ 150.00 ✓
18	1	Tailgate inner handle		\$ 74.00		
19	1	Tailgate inner lock		\$ 245.00		
20	1	Tailgate lock sensor		\$ 220.00		
21	1	Tailgate striker		\$ 32.00		
22	1	Tailgate trimboard		\$ 295.00		\$ 295.00 ✓
23	1set	Tailgate trimboard clips		\$ 45.00		\$ 45.00 ✓
24	1	Tailgate weatherstrip		\$ 145.00		\$ 145.00 ✓
25	1	Tailgate windscreen moulding		\$ 164.00		\$ 164.00 ✓
26	1	Tail lamp LH		\$ 489.00		\$ 489.00 ✓
27	1set	Tail lamp clips		\$ 36.00		\$ 36.00 ✓
28	1	Rear bumper		\$ 950.00		\$ 950.00 ✓
29	1set	Rear bumper clips		\$ 50.00		\$ 50.00 ✓
30	1	Rear bumper retainer LH		\$ 72.00		
31	1	Rear bumper bracket LH		\$ 116.00		
32	1	Rear bumper reflector LH		\$ 167.00		\$ 167.00 ✓
33	1	Rear bumper cover LH		\$ 210.00		\$ 210.00 ✓
34	1set	Rear bumper cover clips		\$ 50.00		\$ 50.00 ✓
35	1	Rear bumper cover retainer LH		\$ 42.00		
36	1	Rear end panel outer		\$ 585.00		
37	1	Rear end panel inner		\$ 396.00		
38	1	Rear end panel top garnish		\$ 184.00		\$ 184.00 ✓
39	1set	Rear end panel top garnish clips		\$ 25.00		\$ 25.00 ✓
40	1	Reverse sensor			\$ 200.00	

**6 Benoi Sector, Singapore (629904)**  
**Tel : 6358 3031 | Fax No : 6694 4929**

PAGE 1

[illegible]




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS/SPF18010186/R1rbe2	
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333			Date : 06-09-2018 	
ATTN : ABDUL RAHMAN			Code : SPF	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	QX 212C	Veh. Inspected	SLD 6257Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	AEMD/105/009/2018/072	Excess (\$)	0.00
	Assign From	ABDUL RAHMAN	Assign Date	05/06/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA VEZEL 1.5X	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	RU11115242	Colour	WHITE
	Odometer	143534	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	ROADSTONE	5 mm
	L/H Front Tyre	215/60 R16	ROADSTONE	5 mm
	R/H Rear Tyre	215/60 R16	ROADSTONE	5 mm
	L/H Rear Tyre	215/60 R16	ROADSTONE	5 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
	Accident Date	02/06/2018	Inspection Date	05/06/2018
	Survey held at	6 BENOI SECTOR		
	Repairer	VERMOGEN ACE PTE LTD		
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 6257Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR FENDER LH	SERVICEABLE	950.00	-
1	REAR FENDER ARCH GARNISH LH	NECESSARY	165.00	165.00
1	SET REAR FENDER ARCH GARNISH CLIPS	NECESSARY	40.00	40.00
1	REAR FENDER INNER WATER SHIELD LH	NOT NECESSARY	160.00	-
1	SET REAR FENDER INNER WATER SHIELD CLIPS	NOT NECESSARY	40.00	-
1	TAILGATE	BENT	1,860.00	1,860.00
1	TAILGATE OUTER GARNISH	NOT NECESSARY	285.00	-
1	SET TAILGATE OUTER GARNISH CLIPS	NOT NECESSARY	40.00	-
1	TAILGATE LOGO	NOT NECESSARY	52.00	-
1	TAILGATE EMBLEM "VEZEL"	NECESSARY	56.20	56.20
2	TAILGATE LAMP LH / RH	SERVICEABLE	980.00	-
2	SET TAILGATE LAMP CLIPS	SERVICEABLE	50.00	-
1	TAILGATE OUTER HANDLE SWITCH	SERVICEABLE	180.00	-
2	TAILGATE DAMPER LH / RH	SERVICEABLE	424.00	-
1	TAILGATE WIPER MOTOR	SERVICEABLE	250.00	-
1	TAILGATE WIPER BLADE	SERVICEABLE	75.00	-
1	TAILGATE BUZZER	CUT	150.00	150.00
1	TAILGATE INNER HANDLE	SERVICEABLE	74.00	-
1	TAILGATE INNER LOCK	SERVICEABLE	245.00	-
1	TAILGATE LOCK SENSOR	SERVICEABLE	220.00	-
1	TAILGATE STRIKER	SERVICEABLE	32.00	-
1	TAILGATE TRIMBOARD	CRACKED	295.00	295.00
1	SET TAILGATE TRIMBOARD CLIPS	NECESSARY	45.00	45.00
1	TAILGATE WEATHERSTRIP	NECESSARY	145.00	145.00
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	164.00	164.00
1	TAIL LAMP LH	CRACKED	489.00	489.00
1	SET TAIL LAMP CLIPS	NECESSARY	36.00	36.00
1	REAR BUMPER	DEFORMED	950.00	950.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER RETAINER LH	SERVICEABLE	72.00	-
1	REAR BUMPER BRACKET LH	SERVICEABLE	116.00	-
1	REAR BUMPER REFLECTOR LH	CUT	167.00	167.00
1	REAR BUMPER COVER LH	DEFORMED	210.00	210.00
1	SET REAR BUMPER COVER CLIPS	NECESSARY	50.00	50.00

Report Ref No. CS/SPF18010186/R1rbe2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER COVER RETAINER LH	SERVICEABLE	42.00	-
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	585.00	-
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	396.00	-
1	REAR END PANEL TOP GARNISH	DEFORMED	184.00	184.00
1	SET REAR END PANEL TOP GARNISH CLIPS	NECESSARY	25.00	25.00
	LESS 20% DISCOUNT		-2,069.84	-1,016.24
			8,279.36	4,064.96
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REVERSE SENSOR (SN)	NOT WORKING	300.00	200.00
			300.00	200.00
	<b><u>LABOUR</u></b>			
	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF REAR END PANEL OUTER AND REAR END PANEL INNER.		1,200.00	600.00
	TO PUTTY, RESPRAY PAINTING AND POLISH ACCIDENT AREA.		1,400.00	500.00
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.		120.00	30.00
	TO RUST PROOF AFFECTED AREAS.		120.00	60.00
	TO REMOVE AND REFIT INTERIOR TRIMS, SEATS, UPHOLSTERY TO FACILITATE REPAIR.		250.00	80.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	60.00
			3,210.00	1,330.00
	<b>GRAND TOTAL</b>		<b>11,789.36</b>	<b>5,594.96</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,400.00</b>

Report Ref No. CS/SPF18010186/R1rbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.