

ASS. REC. BY:

REF:

CS/FCL18010193/Usbnz

Special Instruction:

Summary:

Marius

ASSIGNMENT (Office)

From (Person):

CWS

Sithara

of

FCL

Date/Time:

08062018 1025am

Estimated Cost:

Bill to:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XE 6759

Insured:

SHA 8772C

at Workshop m/s

Tan Lim Motor.

Tel:

6858 5151

of

51 Dafu Lane 10

Policy No:

Claim No:

D18004376 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31052018

CA / REV / REP. / REV 24 HRS

'Wp'

20-062018 @ after 9.30am

H.O.D. Endorsement:

Date/Time:

08062018 10.34am

Person Contacted:

William

Vehicle IN / OUT

Date/Time

Action/Instruction (☒) Estimate

XE 6759 - X

SHA 8772C - CS/FCL16005157/Tlgobz

DUA: 17032016

21.06/18 @ 15:42 p.m. revised PA to Sithara via email.

REF: FCI

ASSIGNMENT

From:

Date:

20/06/18

Veh No.

XE6755

Yr Regn:

615

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

Tanker

To Inspect Vehicle No:

XE6755

Make:

MAN TGM

C.C.

6871

at Workshop n/s

Tan Lim Motor

Colour:

Blue

A/C: Insured / Std / NI / NA

of

51 Defu Lane 10

Sp Reading

132102

T/Radio: Insured / Std / NI / NA

Insured

Eng/No:

Policy No.

C/No:

VMAN0822861307773

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

after 9.30 am

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: ☒ Nil S/Rim / STD A/Rim or

Tyre Size:

F:

295/R22.5

R:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

☒ SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

7

Rear

7/7

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

2

days

Res:

Yes or No

D.O.A.

31/5/18

D.O.I.

20/6/18

Lum Sum:

1.31

%

3 Val:

Yes or No

Survey held at

CA / REV / REP. / 24 HRS

1 up

Des. of Damages - Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

20/7/18 continue final by 2200 with willian.

(\$1,610 Red - 42%)

RECEIVED 23 JUL 2018

Date/Time: File Pass to?

23/07/18

☐

Preli. Report

1)

Typist

☒

Final Report

Date/Time: File Return to?

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation

1.5 + 0.5 = 2.0

1.000

1.000

TOTAL

130

50

50

31

261

Report Format :

Lump Sum / I.B.I: (\$ 2,200.00 p/p)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004376MFSH

Date: 21 June 2018

Our Ref: CS/FCI18010193/Usb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. XE 675S .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/06/2018 at the premises of M/s Tan Lim Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,810.00</u> .
Revised Estimate Amount	: S\$ <u>2,200.00</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 2 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	01-06-2018	Our Ref No. D18004376MFSH
Accident Date	31-05-2018	Claim Type. Third Party
Insured Vehicle	SHA8772C	Third Party Vehicle. XE675S
Survey Location	51 DEFU LANE 10	
Contact Person.	LAM WEI SHONG WILLIAM	
Contact No.	68585151/0	Fax No. 68580877
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

05062018 @ 10:24am
 William veh not in

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN LIM MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 21 June 2018 3:42 PM
To: SITHARA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'SUR'; 'Catherine Chong (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18004376MFSH/1
Attachments: XE 675S - Preli Advise.pdf

Dear Sithara,

Enclosed preliminary revised for XE 675S.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 5 June 2018 10:25 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004376MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 5 June, 2018 9:29 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004376MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	0346W

Vehicle Details

Vehicle No.:	XE675S
Vehicle to be Exported:	No
Intended De-registration Date:	31 May 2018
Vehicle Make:	MAN
Vehicle Model:	TGM 18.290 4X2 BB
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	22836665873668
Chassis No.:	WMAN08ZZ8EY307773
Maximum Power Output:	-
Open Market Value:	\$101,626.00
Original Registration Date:	03 Jun 2015
First Registration Date:	03 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$5,082.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	02 Jun 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$52,001.00
COE Rebate Amount:	\$36,429.00
Total Rebate Amount:	\$36,429.00

The information contained herein is correct as at 31 May 2018

OK



陳林學峰私人有限公司
TAN LIM MOTOR PTE LTD

MS FCIL Insured's Veh No : SHA8772C

Date of Accident : 31 May 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs AJ Jetting Pte Ltd

Date : 31 May 2018

Estimate To Repair XE675S - MAN TGM 18.290 4X2 BB

Chassis No : WMAN08ZZ8EY307773

LKK - Marcus
20/06/18 @ 1530h

S/No	Quantity	Description	Amount
SPECIAL NETT ITEMS			
01	1 pc	rear bumper under-run with stay <i>self/tnl</i>	\$ 1,500.00
02	1 pc	rear bumper under-run reflective marker <i>tnl</i>	\$ 150.00
03	1 pc	rear licence plate <i>self</i>	\$ 50.00
04	1 pc	rear licence plate bracket <i>R</i>	\$ 250.00
05	1 pc	rear licence plate lamp <i>17</i>	\$ 80.00
06	1 pc	left rear lamp <i>tnl</i>	\$ 350.00
07	1 pc	left rear lamp panel <i>R</i>	\$ 450.00
08	1 pc	left rear lamp panel 60 KM/H sticker <i>tnl</i>	\$ 20.00
			\$ 2,850.00
LABOUR & MISC. CHARGES			
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 450.00
02		Putty and spray painting of the affected portion.	\$ 450.00
03		To check electrical lighting concerned.	\$ 60.00
			\$ 960.00
Total			\$ 3,810.00

1200
100
20
X
X
X
10
T60
300
200
20

not Admit
LKK

take photo After repair

20/6/18

2h.

p/p @ 2200

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010193/Usbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8772C	Veh. Inspected	XE 675S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004376MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	05/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAN TGM	c.c	6871	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WMAN08ZZ8EY307773	Colour	BLUE	
Odometer	132102	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	7 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	7 mm	
R/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	7/7 mm	
L/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/05/2018	Inspection Date	20/06/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 675S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER UNDER-RUN WITH STAY (SN)	TWISTED / BENT	1,500.00	1,200.00
1	REAR BUMPER UNDER-RUN REFLECTIVE MARKER (SN)	NECESSARY	150.00	100.00
1	REAR LICENCE PLATE (SN)	BENT	50.00	20.00
1	REAR LICENCE PLATE BRACKET (SN)	TO REPAIR SEE LABOUR	250.00	-
1	REAR LICENCE PLATE LAMP (SN)	NOT NECESSARY	80.00	-
1	LEFT REAR LAMP (SN)	CRACKED	350.00	350.00
1	LEFT REAR LAMP PANEL (SN)	TO REPAIR SEE LABOUR	450.00	-
1	LEFT REAR LAMP PANEL 60KM/H STICKER (SN)	NECESSARY	20.00	10.00
			2,850.00	1,680.00
LABOUR				
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR LICENCE PLATE BRACKET AND LEFT REAR LAMP PANEL.		450.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		450.00	200.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
			960.00	520.00
GRAND TOTAL			3,810.00	2,200.00
RECOMMENDED COST OF REPAIRS				2,200.00

Report Ref No. CS/FCI18010193/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.