

ASS. REC. BY:

REF:

CS/EG18010194/Avbn2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGL

Date/Time:

05062018 1005am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 1699J

Insured:

SGF 2872Y

at Workshop m/s

Modern Automotive

Tel:

8121 3226

of

Blk 3033A Ubi Rd 1 #D1-61

Policy No:

Claim No:

SGF 2872Y / SL/pi

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04062018

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

05062018 10.20am

Person Contacted:

Mei

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJS 1699J - NA / INC 13010124 / h4
	SGF 2872Y - X
6/6/18	Informed Pei Li pending workshop est by email
21/6/18	Adrian confirmed LS \$8000 (Rev 10,479.68, 56%)
21/6/18	Email preli revised to Pei Li

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJS1699J Yr Regn: 2008 July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I30 HB c.c. 1591

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 20036 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHDCSIDR9U185480

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 05/06/18

Survey held at Modern

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Ego

MV: 17K

PV: 9K

Nett: 8K

RECEIVED 21 JUN 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 21/6 - typist

Report Format: TP

Lump Sum / L.B.I: (\$) 8000/f

Days Of Repair: 14

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

☐ : S + RS: ☐ SI

☐ : Photos

☐ : Others

TOTAL

350



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SGF2872Y/SL/pl

Our ref: CS/EGII8010194/Avb

Date : 21/6/2018

The Motor Claims Department
M/s: ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SJS 1699J


We thank you for your instruction on 5/6/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 5/6/2018 at the premises of M/s MODERN AUTOMOTIVE PTE LTD

Workshop Estimate Amount	: S\$18,479.68
Revised Estimate Amount	: S\$8,800.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 21 June 2018 11:12 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: SGF2872Y / TP : SJS1699J/LKK / DOA : 04.06.2018
Attachments: SJS 1699J PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SJS 1699J
Date of survey: 5/6/2018
Number of days :14 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 6 June 2018 10:57 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SGF2872Y / TP : SJS1699J/LKK / DOA : 04.06.2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SJS 1699J on 5/6/18 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 5 June 2018 10:46 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SGF2872Y / TP : SJS1699J/LKK / DOA : 04.06.2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]

Sent: Tuesday, 5 June, 2018 10:05 AM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Cc: ASSIGNMENTS@LKKAUTO.COM; SUR (sur@lkkauto.com) <sur@lkkauto.com>

Subject: OI : SGF2872Y / TP : SJS1699J/LKK / DOA : 04.06.2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **MODERN AUTOMOTIVE PTE LTD**.

ADDRESS : BLOCK 3023A UBI ROAD 1
#01-61
SINGAPORE 408717

PERSON TO CONTACT : MEI @ 6744 4422 / 8121 3226

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and Third Parties' SAS (note: reports not to be released to any Third Party). No estimate was provided.

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li

Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

DID: 65 6829 9194

Fax: 65 6829 9247

Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most
affordable prices available in the market.

ERGO
TravelProtect
your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Plc. Ltd.

 **BUY NOW**

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 6 June 2018 10:57 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: SGF2872Y / TP : SJS1699J/LKK / DOA : 04.06.2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SJS 1699J on 5/6/18 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 5 June 2018 10:46 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SGF2872Y / TP : SJS1699J/LKK / DOA : 04.06.2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 5 June, 2018 10:05 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: ASSIGNMENTS@LKKAUTO.COM; SUR (sur@lkkauto.com) <sur@lkkauto.com>
Subject: OI : SGF2872Y / TP : SJS1699J/LKK / DOA : 04.06.2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **MODERN AUTOMOTIVE PTE LTD**,

ADDRESS : BLOCK 3023A UBI ROAD 1
#01-61
SINGAPORE 408717

PERSON TO CONTACT : MEI @ 6744 4422 / 8121 3226

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and Third Parties' SAS (note: reports not to be released to any Third Party). No estimate was provided.

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most affordable prices available in the market.

ERGO
TravelProtect
your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Pte. Ltd.

 **BUY NOW**

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 5 June, 2018 10:05 AM
To: 'admin-d@lkkauto.com'
Cc: ASSIGNMENTS@LKKAUTO.COM; SUR (sur@lkkauto.com)
Subject: OI : SGF2872Y / TP : SJS1699J/LKK / DOA : 04.06.2018
Attachments: OI - SGF2872Y - SAS.pdf; SJS1699J - SAS.pdf; 1ST VEH SLJ3981D - SAS.pdf; SJS1699J - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **MODERN AUTOMOTIVE PTE LTD,**

ADDRESS : BLOCK 3023A UBI ROAD 1
#01-61
SINGAPORE 408717

Action

PERSON TO CONTACT : MEI @ 6744 4422 / 8121 3226

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and Third Parties' SAS (note: reports not to be released to any Third Party). No estimate was provided.

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most
affordable prices available in the market.

ERGO
TravelProtect

Your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Plc, UK.



ERGO

Date: 05.06.2018
Our Reference: SGF 2872Y/SL/pl
Your Reference: SJS 1699J

Sent via Fax

or

Email

meeihuey@modernaautomotive.com.sg

To: MODERN AUTOMOTIVE PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SJS 1699J
Insured's Vehicle: SGF 2872Y
Date Of Accident: 04.06.2018

We acknowledge receipt of your request for PRS on: 04.06.2018


In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☐ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☒ Our Insured's driver has not reported the accident to us todate.
- ☒ Others: **We are therefore not in a position to discuss on liability at this juncture.**

OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6074I
Vehicle Details	
Vehicle No.:	SJS1699J
Vehicle to be Exported:	Yes
Intended De-registration Date:	05 Jun 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	I30 (FD) 1.6 DOHC AUTO
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	G4FC9U667112
Chassis No.:	KMHDC51DR9U185480
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$13,615.00
Original Registration Date:	31 Jul 2009
First Registration Date:	31 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$13,615.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2019
PARF Rebate Amount:	\$7,488.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,291.00
COE Rebate Amount:	\$1,759.00
Total Rebate Amount:	\$9,247.00

The information contained herein is correct as at 05 Jun 2018

OK

MYCARFORUM
THE OFFICIAL FORUM OF SGCARMART.COM

ASK • DISCUSS
LEARN • SHARE

- Liverpool 2017/18: YNWA with Klopp
- New immigrant skills in NZ
- 2018 FIFA World Cup

[SEARCH](#)
[Price Range](#) [Depreciation](#) [2009](#) [Vehicle Type](#)
[Search](#)
[View All](#)
[Advanced Search](#)

Used Car Comparison

--- Comparing 3 Vehicles ---

Hyundai i30 1.6A

Hyundai i30 Wagon 1.6A Sunroof

Hyundai i30 1.6A Sunroof



Clear All

[Add all to Shortlist](#)

[Add to Shortlist](#)

[Add to Shortlist](#)

[Add to Shortlist](#)

[Back to search result](#)

CAR DETAILS

Price	\$13,800	\$16,666	\$19,900	-
Instalment	\$990	\$862	\$854	-
Registration Date	14-Apr-2009	14-Aug-2009	16-Nov-2009	-
Manufactured	2008	2009	2009	-
Mileage	103,940 km	146,307 km	130,760 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,591 cc	1,591 cc	1,591 cc	-
Road Tax	\$738 /yr	\$738 /yr	\$738 /yr	-
Power	89.7 kW (120 bhp)	89.7 kW (120 bhp)	89.7 kW (120 bhp)	-
Curb Weight	1,314 kg	1,360 kg	1,314 kg	-
Features	1.6L DOHC Engine, Auto Transmission, SRS Airbags, ABS, EBD, Fog Lamps, Knockdown Rear Seats.	Original Condition.	Fuel Efficient 1.6L 16 Valves DOHC Engine Producing 120Bhp, Smooth CVT Auto Transmission, ABS, Multi Steering Controls, Dual Airbags.	-
Accessories	Sports Rims, Pioneer Car Stereo System, Solar Film, Electrical Retractable Side Mirrors.	Factory Fitted Interior.	Leather Seats, Sports Rims, Multi Function Steering Wheel, Factory Fitted Audio Systems, Rear Knockdown Seat, Retractable Side Mirror.	-
Description	Low Mileage, Average Clocked At 11500Km Yearly Only! Extended Warranty Avail! Professional Evaluation Services Provided! Well Taken Care Stylish Hatch In Tip Top Condition, See It For Yourself To Believe! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Drop By Our AC Showroom To Appreciate It In Pristine Condition Today!	(100% Quality Buy!) Shop With Peace Of Mind From CaseTrust Accredited Company. Purchase And Enjoy 180 Days Engine And Gearbox Protection Shield With 24/7 Roadside Assistance And Replacement Vehicle Coverage Worth \$688! STA/VICOM/AA/IDAC Evaluation Friendly. (Viewing Available Daily By Appointment.)	All Our Quality Pre Owned Cars Are Selling At The Most Reasonable Price And With A Peace Of Mind! STA/VICOM Evaluate Are Welcome. Easy Approval Down Payment \$3900, Our Flexible Bank And In House Financing Loan Up To \$16000, Low Usage! Accident Free, Pristine And Immaculate Condition! View To Appreciate! Test Drive Today.	-
COE	\$7,090	\$13,658	\$18,899	-
OMV	\$12,100	\$14,576	\$13,350	-
ARF	\$12,100	\$14,576	\$13,350	-
Depreciation	\$9,070 /yr	\$7,890 /yr	\$9,140 /yr	-
No. of Owners	4	2	2	-
Type of Vehicle	Hatchback	Stationwagon	Hatchback	-
Category	PARF Car	PARF Car, Premium Ad Car	PARF Car	-
Availability	Available	Available	Available	-

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Ergo Insurance Pte Ltd
 5 Temasek Boulevard
 #04-01 Suntec Tower Five
 Singapore 038985
 Tel : 6829 - 9170
 Fax : 6829 - 9247

Quotation
 DATE : 05.06.2018
 VEH NO : SJS1699J
 MODEL : Hyundai i30
 D O A : 04.06.2018
 YR REF : SGF2872Y

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJS1699J (Hyundai i30)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS - FRONT PORTION		
1	Front Bumper <i>Distorted</i>	1	451.80 ✓
2	Front Bumper Clips <i>m</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - LH & RH <i>m</i>	2	66.00 ✓
4	Front Bumper Lower Grille <i>dist</i>	1	247.00 ✓
5	Front Bumper Reinforcement <i>dist</i>	1	253.00 ✓
6	Front Grille <i>crushed</i>	1	220.40 ✓
7	Front Grille Chrome Moulding <i>crushed</i>	1	120.80 ✓
8	Front Grille Emblem <i>m</i>	1	45.10 ✓
9	Headlamp - LH & RH <i>crushed</i>	2	1,153.80 ✓
10	Bonnet <i>Distorted</i>	1	1,184.00 ✓
11	Bonnet Lock <i>Distorted</i>	1	96.00 ✓
12	Bonnet Insulator <i>crumpled</i>	1	182.00 ✓
13	Bonnet Insulator Clips <i>m</i>	1 set	30.00 ✓
14	Front Support Panel <i>Distorted</i>	1	855.60 ✓
15	Front Support Panel Top Cover <i>Deformed</i>	1	127.10 ✓
16	Front Support Panel Top Cover Clips <i>over</i>	1 set	25.00 ✓
17	Air Con Condenser <i>Bent</i>	1	906.80 ✓
18	Air Con Discharge Pipe <i>not m</i>	1	226.30 +
19	Air Con Suction Pipe <i>not m</i>	1	214.90 +
20	Radiator <i>Bent</i>	1	689.00 ✓
21	Radiator Fan Assy <i>crushed</i>	1	684.00 ✓
22	Radiator Top Hose <i>torn</i>	1	52.00 ✓
23	Engine Top Cover <i>crushed</i>	1	195.40 ✓
24	Front Fender - LH & RH <i>RH Buckled</i>	2	980.20 - 490.10

\$ 9,046.20
 (1,809.24)
 \$ 7,236.96

Less 20%

120049
 960392

RE : ESTIMATE FOR ACCIDENT REPAIR SJS1699J (Hyundai i30)

LIST ITEMS - REAR PORTION

1	Rear Number Plate Lamp - LH & RH	2	124.20	62.10
2	Rear Bumper	1	447.00	✓
3	Rear Bumper Clips	1 set	30.00	✓
4	Rear Bumper Side Holder - LH & RH	2	76.00	✓
5	Rear Bumper Sponge	1	179.30	✓
6	Rear Bumper Tow Cover	1	15.20	✓
7	Rear Bumper Reinforcement	1	271.40	✓
8	Rear Bumper Reinforcement Bracket	5	90.00	✓
9	Rear End Panel	1	364.70	✓
10	Rear End Panel Top Garnish	1	96.20	✓
11	Tailamp - LH & RH	2	895.80	✓
12	Tailgate	1	1,152.00	✓
13	Tailgate Lock	1	166.80	✓
14	Tailgate Weatherstripe	1	124.80	✓
15	Tailgate Glass Moulding	1	122.40	✓
16	Hyundai Wording	1	38.90	✓
17	i30 Wording	1	39.40	✓
18	S Wording	1	30.40	✓
19	Spare Tyre Panel	1	776.20	X
20	Spare Tyre Panel Top Cover	1	251.20	✓
21	Spare Tyre Lock Screw	1	46.60	X
22	Rear Exhaust Pipe	1	712.00	X
23	Rear Exhaust Mounting	1	27.90	X

\$ 6,078.40
 (1,215.68)
 \$ 4,862.72

Less 20%

S/NETT ITEMS

1	Front Number Plate	30.00	✓
2	Front Number Plate Holder	30.00	✓
3	Rear Number Plate	30.00	✓
4	Rear Number Plate Holder	30.00	✓
5	Reverse Sensor	280.00	200
6	Rear End Panel Sealant	60.00	✓
7	Tailgate Glass Sealant	60.00	✓

\$ 520.00

Total Parts

\$ 12,619.68

LABOUR CHARGE

1	To knocking & pull out front & rear portion & renew above parts	\$ 2,500.00	1800
2	To putty & spray up paint works	\$ 2,200.00	1500

RE: ESTIMATE FOR ACCIDENT REPAIR SJS1699J (Hyundai i30)

3	To check wiring	\$	100.00 60
4	To underseal	\$	150.00 80
5	To remove reverse sensor	\$	100.00 50
6	To remove upholstery	\$	150.00 80
7	To transfer tailgate fittings	\$	150.00 80
8	To remove tailgate glass	\$	180.00 120
9	To remove exhaust pipe	\$	150.00 X
10	To remove condenser, radiator & to re-gas	\$	180.00 120
Total Labour		\$	5,860.00
Grand Total		\$	18,479.68

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total 17496.80
w/s 8K (Nett Value)
14 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18010194/Avbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 25-06-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGF 2872Y	Veh. Inspected	SJS 1699J
Policy No.		Coverage (\$)	0.00
Claim No.	SGF2872Y/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	05/06/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I30 HB	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KMHDC51DR9U185480	Colour	WHITE
Odometer	200036	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	FALKEN	6 mm
L/H Front Tyre	185/65 R15	FALKEN	6 mm
R/H Rear Tyre	185/65 R15	FALKEN	6 mm
L/H Rear Tyre	185/65 R15	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/06/2018	Inspection Date	05/06/2018
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 1699J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DISTORTED	451.80	451.80
1	SET FRONT BUMPER CLIPS	NECESSARY	30.00	30.00
2	FRONT BUMPER SIDE HOLDER-LH & RH	NECESSARY	66.00	66.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	247.00	247.00
1	FRONT BUMPER REINFORCEMENT	BENT	253.00	253.00
1	FRONT GRILLE	CRACKED	220.40	220.40
1	FRONT GRILLE CHROME MOULDING	CRACKED	120.80	120.80
1	FRONT GRILLE EMBLEM	NECESSARY	45.10	45.10
2	HEADLAMP-LH & RH	CRACKED	1,153.80	1,153.80
1	BONNET	DISTORTED	1,184.00	1,184.00
1	BONNET LOCK	DAMAGED	96.00	96.00
1	BONNET INSULATOR	CRUMPLED	192.00	192.00
1	SET BONNET INSULATOR CLIPS	NECESSARY	30.00	30.00
1	FRONT SUPPORT PANEL	DISTORTED	855.60	855.60
1	FRONT SUPPORT PANEL TOP COVER	DEFORMED	127.10	127.10
1	SET FRONT SUPPORT PANEL TOP COVER CLIPS	NECESSARY	25.00	25.00
1	AIR CON CONDENSER	BENT	906.80	906.80
1	AIR CON DISCHARGE PIPE	NOT NECESSARY	226.30	-
1	AIR CON SUCTION PIPE	NOT NECESSARY	214.90	-
1	RADIATOR	BENT	689.00	689.00
1	RADIATOR FAN ASSY	CRACKED	684.00	684.00
1	RADIATOR TOP HOSE	TORN	52.00	52.00
1	ENGINE TOP COVER	CRACKED	195.40	195.40
2	FRONT FENDER-LH & RH	O/S BUCKLED	980.20	490.10
2	REAR NUMBER PLATE LAMP-LH & RH	N/S DAMAGED	124.20	62.10
1	REAR BUMPER	DISTORTED	447.00	447.00
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER-LH & RH	NECESSARY	76.00	76.00
1	REAR BUMPER SPONGE	DISTORTED	179.30	179.30
1	REAR BUMPER TOW COVER	DEFORMED	15.20	15.20
1	REAR BUMPER REINFORCEMENT	BENT	271.40	271.40

Report Ref No. CS/EGI18010194/Avbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
5	REAR BUMPER REINFORCEMENT BRACKET	BENT	90.00	90.00
1	REAR END PANEL	DISTORTED	364.70	364.70
1	REAR END PANEL TOP GARNISH	DEFORMED	96.20	96.20
2	TAILLAMP-LH & RH	CUT	895.80	895.80
1	TAILGATE	DENTED	1,152.00	1,152.00
1	TAILGATE LOCK	DAMAGED	166.80	166.80
1	TAILGATE WEATHERSTRIPE	CUT	124.80	124.80
1	TAILGATE GLASS MOULDING	NECESSARY	122.40	122.40
1	HYUNDAI WORDING	NECESSARY	38.90	38.90
1	I30 WORDING	NECESSARY	39.40	39.40
1	S WORDING	NECESSARY	30.40	30.40
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	776.20	-
1	SPARE TYRE PANEL TOP COVER	DEFORMED	251.20	251.20
1	SPARE TYRE LOCK SCREW	NOT NECESSARY	46.60	-
1	REAR EXHAUST PIPE	NOT NECESSARY	712.00	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	27.90	-
	LESS 20% DISCOUNT		-3,024.92	-2,513.70
			12,099.68	10,054.80
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	MISSING	30.00	30.00
1	FRONT NUMBER PLATE HOLDER (SN)	MISSING	30.00	30.00
1	REAR NUMBER PLATE (SN)	DISTORTED	30.00	30.00
1	REAR NUMBER PLATE HOLDER (SN)	DISTORTED	30.00	30.00
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	60.00	60.00
			520.00	440.00
	LABOUR			
	TO KNOCKING & PULL OUT FRONT & REAR PORTION & RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL.		2,500.00	1,800.00
	TO PUTTY & SPRAY UP PAINT WORKS.		2,200.00	1,500.00

Report Ref No. CS/EG18010194/Avbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING.	NOT NECESSARY	100.00	60.00
	TO UNDERSEAL.		150.00	80.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO REMOVE UPHOLSTERY.		150.00	80.00
	TO TRANSFER TAILGATE FITTINGS.		150.00	80.00
	TO REMOVE TAILGATE GLASS.		180.00	120.00
	TO REMOVE EXHAUST PIPE.		150.00	-
	TO REMOVE CONDENSER,RADIATOR & TO RE-GAS.		180.00	120.00
			5,860.00	3,890.00
GRAND TOTAL			18,479.68	14,384.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,000.00

Report Ref No. CS/EGI18010194/Avbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.