

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6
 #01-46/48/50 Autobay
 SINGAPORE 417883

VEHICLE NO: GBC 8559M

Not Allowed
 date
 2/5 @ 4500
 3/5/18
 4 day.

QTY	PARTICULAR (NETT ITEM)	AMOUNT
1 PCS	TAILGATE <i>2201</i>	<i>22/3ent</i> \$2,266.10 N ✓
1 PCS	TAILGATE LOWER MEMBER	<i>n</i> \$822.30 N X
2 PCS	TAILGATE LOCK LATCHS @\$119.00	<i>n</i> \$238.00 N X
2 PCS	TAILGATE LOWER 'L' PANELS @\$105.00	<i>n</i> \$210.00 N X
2 PCS	TAILGATE LOWER 'L' PANEL STOPPERS @\$85.00	<i>d/s cut</i> \$170.00 N <i>12c</i>
2 PCS	TAILLAMPS @\$303.00	<i>one</i> \$606.00 N ✓
1 PCS	REAR LICENCE PLATE BRACKET <i>015</i>	<i>Set</i> \$92.30 N ✓
2 PCS	DROP SIDE GATES @\$2685.00	<i>n</i> \$5,370.00 N X
1 PCS	REAR SPARE TYRE BRACKET & CHAIN	<i>20/3m</i> \$399.20 N ✓
		\$10,173.90 N
	S.NETT	
1 SET	REAR REVERSE SENSOR	<i>one</i> \$280.00 <i>200</i>
1 PCS	REAR LICENCE PLATE	<i>Set</i> \$50.00 <i>14</i>
1 PCS	REAR STEP BAR	<i>Set</i> \$680.00 <i>500</i>
1 PCS	TAILGATE '70KM/H' STICKER	<i>rer</i> \$20.00 <i>10</i>
1 SET	TAILGATE CORPORATE STICKER	<i>rer</i> \$380.00 <i>350</i>
1 PCS	TAILGATE '13 PAX' STICKER	<i>rer</i> \$20.00 <i>10</i>
1 SET	DROPSIDE GATE CORPORATE STICKER	<i>rer</i> \$380.00 X

102

3383.5
3045.15

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	<i>30</i>
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00	<i>50</i>
TO SPRAY RUST PROOFING	\$80.00	<i>50</i>
TO STRAIGHTEN REAR CHASSIS FRAME	\$680.00	X
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,080.00	<i>700</i>
TO PUTTY & SPRAY PAINTING	\$1,280.00	<i>680</i>

TOTAL \$15,263.90 *5639.15*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date: