

22/03/2002

ASS. REC. BY:

REF: CS/MSG18010202/A gbez

Special Instruction:

SUBJECT: menmen

Action

ASSIGNMENT (Office)

From (Person):

monica chung

of

mslh

Date/Time:

05062018 1002am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 5582C

Insured:

SLK 6778A

at Workshop m/s

Twincar Automotive

Tel:

68420051

of

2 Kaki Bukit Ave 2 #01-17

Policy No:

A28882518QMX

Claim No:

660125

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02062018

(Client's Record)

CA / REV / REP. / REV 24 HRS (w/p)

H.O.D. Endorsement:

Date/Time:

05062018 1053am

Person Contacted:

Hui Xin

Vehicle W/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKW 5582C - NA /MSG18010202/13
	SLK 6778A - x
17/6/18 @ 11:29am	revised to Monica Chung via menmen.
	Uy \$5800, 5 days (Fed \$5254.70, 48%)

DA: 02062018

REF:

ASS. REC. BY: Adrian King**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: **Yes** or NoGIA / PR Seen: _____ Consistent?: **Yes** or NoEst. Repairs: 5 days Res.: **Yes** or NoLum Sum: _____ % 3 Val.: **Yes** or No**CA / REV / REP. / 24 HRS**Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SKW5582C Yr Regn: 2015, NovType: **M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /****Truck / Trailer or**Make: Toyota Hiace c.c. 1986Colour: Black A/C: **Insured / Std / NI / NA**Sp. Reading: 49439 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: ZSU600054143Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt** orBrake: **Inorder / Jammed / Leaked / Burnt** orModi: **Nil / S/Rim / STD A/Rim** orTyre Size: F: 225/65R17R: 225/65R17**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 05/06/18Survey held at twincatDes. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** orThe **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time

Action / Instruction

TP mslg

RECEIVED 12 OCT 2018.

[Signature]
12/10/2018

Date/Time, File Pass to?

: **Preli. Report**11/10 twincat: **Final Report**

Date/Time, File Return to?

2)

Report Format :

MER-TP

Lump Sum / L.B. (%)

5800Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

20010210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jun 2018		05 Jun 2018 10:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHAM WING TENG, ID: S1490598G		
Main Claimant:	YICK WENG CHEONG WILSON, ID: S7927919F		
Vehicle Reg. No.:	SKW5582C	Date of Loss:	02/06/2018 08:00 - :59 [30 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 560125	Policy/Cover Note No.:	A28882518QMX (Comprehensive) Coverage: 24/01/2018 - 23/01/2019
Vehicle Reg. No. (Insured):	SLK6778A	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/06/2018]		
Driver/Custodian (Insured):	CHAM WING TENG (), NRIC: S1490598G		
Adj Asg. Remarks:	on WP. TP agree on SJE - please assign to Adrian Ling of LKK Auto. Liability : 100%. Contact person: Melody @ 6842 0051 / 6744 0510.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

05/06/2018 @ 1055am
 Elyan veh-in.
 Hui Xin
 Adrian.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 12 Oct 2018

Preliminary Advice

Insured Vehicle No	: SLK6778A	Accident Date	: 02/06/2018
TP Vehicle No	: SKW5582C	Assignment Date	: 05/06/2018
Make	: TOYOTA HARRIER	Est. Duration of Repair	: 5
Date of Inspection	: TWINCAR AUTOMOTIVE PTE LTD		
Inspection At	: 05/06/2018		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,054.70
Revised Amount	:S\$	7,254.19
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,254.19
Lump Sum Repair	:S\$	5,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 6 June 2018 12:00 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SKW 5582C (YOUR REF: 560125)

This mail is associated with :

***SKW5582C (560125)**

[SLK6778A]

TP

YICK WENG CHEONG WILSON

Jun 2 2018 8:00AM

[CHAM WING TENG]

Twincar Automotive Pte Ltd

Dear Monica,

Please be informed that we have inspected the vehicle SKW 5582C on 05/06/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2018 10:13
Date Of Accident	02/06/2018 08:40
Exact Location Of Accident	TAMPINES AVE 2 B4 JUNC OF TAMPINES ST 23
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW5582C
Insured/Policyholder	
Name Of Registered Owner	YICK WENG CHEONG WILSON
NRIC No	S7927919F
Email Address	WILSON.YICK@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97333999
Alternative Phone No	OTHERS-97333999

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28841201 QMY
Cover Note Number	

Driver

Name of Driver	YICK WENG CHEONG WILSON
NRIC No	S7927919F
Date Of Birth	20/09/1979
Occupation	INDOOR
Date Of Driving Pass	19/09/2007
Driving Experience	10 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97333999
Fax Number	
Contact Number	OTHERS-97333999
EMail Address	WILSON.YICK@GMAIL.COM

Address	BLK 15 TAMPINES AVE 8 #12-21
Postcode	529601
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG TAMPINES AVE 2 TWDS TAMPINES AVE 1 ON THE CENTER LANE OF A 3-LANES RD. UPON REACHING AT THE JUNC OF TAMPNES ST 23, I SLOWED DOWN AND STOPPED DUE TO TRAFFIC RED LIGHT SIGNALS. OUT OF THE SUDDEN VEH B CAME FROM THE REAR AND COLLIDED DIRECTLY ONTO THE REAR PORTION OF MY VEH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK6778A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

vinCar AUTOMOTIVE PTE LTD

Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

WILSON YICK WENG CHEONG
BLK 15 TAMPINES AVE 8 #12-21
SINGAPORE 529601

TPMS16.
XiaoChun.

Contact : 97333999

ESTIMATE

Repair Code : CLM14105

Date in : 02/06/2018

Vehicle Num. : SKW5582C

Model : TOYOTA HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD

Chassis/Eng# : ZSU600054143/3ZRB620060

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Del'd</i>	1	1812.25	1,812.25 <i>1381</i>
* REAR BUMPER INNER SPONGE <i>Del'd</i>	1	189.90	189.90 ✓
* REAR BUMPER LH END SEAL COVER <i>Del'd</i>	1	125.30	125.30 ✓
* REAR BUMPER LH REFLECTOR <i>Del'd</i>	1	181.60	181.60 ✓
REAR BUMPER LOWER GARNISH <i>Del'd</i>	1	236.00	236.00 ✓
REAR BUMPER RUBBER STOPPER COVER L/R <i>new</i>	2	32.10	64.20 +
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	131.35	262.70 ✓
* REAR END PANEL TOP COVER <i>Del'd</i>	1	445.00	445.00 ✓
* REAR LH FENDER INNER UPHOLSTERY TRIM COVER <i>Del'd</i>	1	825.00	825.00 ✓
* REAR LH TAILLAMP <i>Del'd</i>	1	460.60	460.60 ✓
REAR LH TAILLAMP BACK RUBBER GASKET <i>new</i>	1	20.60	20.60 +
REAR TAILGATE <i>Del'd</i>	1	1812.40	1,812.40 ✓
REAR TAILGATE 'HARRIER' EMBLEM <i>new</i>	1	61.75	61.75 ✓
REAR TAILGATE INNER RUBBER CAP COVER <i>new</i>	1	13.20	13.20 +
* REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH <i>Del'd</i>	1	453.70	453.70 ✓
REAR TAILGATE LH REFLECTOR <i>new</i>	1	589.90	589.90 +
REAR TAILGATE LH REFLECTOR BACK RUBBER GASKET <i>new</i>	1	51.10	51.10 +
* REAR TAILGATE MECHANISM LOCK <i>RTN</i>	1	954.70	954.70 ✓

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

WILSON YICK WENG CHEONG
BLK 15 TAMPINES AVE 8 #12-21
SINGAPORE 529601

Contact : 97333999

ESTIMATE

Repair Code : CLM14105

Date in : 02/06/2018

Vehicle Num. : SKW5582C

Model : TOYOTA HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD

Chassis/Eng# : ZSU600054143/3ZRB620060

REAR TAILGATE OUTER GARNISH	<i>me</i>	1	695.00	695.00	<i>+</i>
REAR TAILGATE RUBBER GUIDE STOPPER L/R	<i>me</i>	2	43.70	87.40	<i>+</i>
REAR TAILGATE WEATHER STRIP	<i>me</i>	1	387.30	387.30	<i>←</i>
REAR TAILGATE WINDSCREEN MOULDING	<i>me</i>	1	210.00	210.00	<i>←</i>
			Subtotal before discount	9,939.60	
	Percentage discount 25%			2,484.90	
			Sub-total 1	7,454.70	
REAR BUMPER CLIPS - SET	<i>me</i>	1	50.00	50.00	<i>3</i>
REAR BUMPER END SEAL COVER CLIPS L/R - SET	<i>me</i>	2	30.00	60.00	<i>3</i>
REAR BUMPER REVERSE SENSOR	<i>me</i>	1	350.00	350.00	<i>2</i>
REAR END PANEL TOP COVER CLIPS - SET	<i>me</i>	1	30.00	30.00	<i>3</i>
REAR LH FENDER INNER UPHOLSTERY TRIM COVER CLIPS - SET	<i>me</i>	1	50.00	50.00	<i>3</i>
REAR LH TAILLAMP CLIPS - SET	<i>me</i>	1	30.00	30.00	<i>3</i>
REAR NUMBER PLATE	<i>me</i>	1	80.00	80.00	<i>+</i>
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	<i>me</i>	1	100.00	100.00	<i>3</i>
REAR TAILGATE OUTER GARNISH CLIPS - SET	<i>me</i>	1	30.00	30.00	<i>+</i>
REAR TAILGATE SPOILER CLIPS - SET	<i>me</i>	1	50.00	50.00	<i>+</i>
REAR TAILGATE WINDSCREEN SEALANT	<i>me</i>	1	100.00	100.00	<i>6</i>

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

WILSON YICK WENG CHEONG
BLK 15 TAMPINES AVE 8 #12-21
SINGAPORE 529601

Contact : 97333999

ESTIMATE

Repair Code : CLM14105
Date in : 02/06/2018
Vehicle Num. : SKW5582C
Model : TOYOTA HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD
Chassis/Eng# : ZSU600054143/3ZRB620060

Subtotal before discount	930.00
Percentage discount 0%	0.00
Sub-total 2	930.00
Parts-total	8,384.70

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	100.00 50
To remove, reinstall tailgate windscreen	250.00 / 2
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00 80
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	? 1200.00 700
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	900.00 600
To apply anti-rust chemical on repaired and replaced panel.	80.00 40
Labour Total	2,670.00
Parts & Labour Total	11,054.70

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before any spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lij
L/S 05/06/18

04 - 06 Days

Total: 7254.12
L/S: S.R.K.
05 Days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jun 2018		05 Jun 2018 10:02 Edit Adj Rpt	S\$5,800.00 Edit Estimates	S\$5,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	CHAM WING TENG , ID: S1490598G								
Main Claimant:	YICK WENG CHEONG WILSON , ID: S7927919F								
Vehicle Reg. No.:	SKW5582C	Date of Loss:	02/06/2018 08:00 - :59 [30 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 560125	Policy/Cover Note No.:	A28882518QMX (Comprehensive) Coverage: 24/01/2018 - 23/01/2019						
Vehicle Reg. No. (Insured):	SLK6778A	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/07/2018]								
Driver/Custodian (Insured):	CHAM WING TENG (), NRIC: S1490598G								
Adj Asg. Remarks:	on WP. TP agree on SJE - please assign to Adrian Ling of LKK Auto. Liability : 100%. Contact person: Melody @ 6842 0051 / 6744 0510.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW5582C (560125)
[SLK6778A]

TP

YICK WENG CHEONG WILSON

Jun 2 2018 8:00AM

[CHAM WING TENG]

Twincar Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View	
						View in Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print	
1	04/06/18 16:14	Accident Statement From:OD - Reg. No: SLK6778A, Claimant: CHAM WING TENG			Load HTM	<input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	12/10/18 11:29	Adjuster Immediate Advice			Load HTM	<input type="checkbox"/>	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
2	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
3	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
4	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
5	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
6	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
7	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
8	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
9	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
10	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
11	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
12	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
13	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
14	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
15	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
16	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
17	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
18	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
19	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
20	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
21	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
22	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
23	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
24	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
25	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
26	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
27	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
28	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
29	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
30	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
31	11/10/18 17:49	General View			Load JPG	<input checked="" type="checkbox"/>	
32	11/10/18 17:49	General View			Load JPG	<input type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	11/10/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/06/18 14:44	SKW5582C E FILE REPORT.	 Load PDF	
2	04/06/18 16:03	TP agree on SJE - Workshop details	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010202/AQBE2
Date: 16/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28882518QMX
Claimant Vehicle No : SKW5582C	Insured Vehicle No :	SLK6778A
Date of Loss: 02/06/2018	Nature of Claim:	TP Claim No: 560125

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW5582C	Engine No:	3ZRB620060
Make & Model:	TOYOTA HARRIER, 2.0 Elegance (A)	Chassis No:	ZSU600054143
Reg. Date:	04/11/2015 (Man. Year: 2015)	Odometer:	49439 km
Colour:	Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,384.70	5,704.19	2,680.51	31.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,550.00	1,120.00	41.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,054.70	7,254.19	3,800.51	34.38
Approved Total (Overridden) (S\$)		5,800.00		
	(S\$)	11,054.70	5,800.00	5,254.70
	+ GST 7.00/7.00% (S\$)	773.83	406.00	367.83
	Nett Amount (S\$)	11,828.53	6,206.00	5,622.53

INSPECTION

Date of Assignment:	05/06/2018	
Date Inspected:	05/06/2018 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2018)	
Parts: M1-SUV	TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKW5582C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,812.25 FL	*1,381.00 FL
2	1		*REAR BUMPER INNER SPONGE	Cracked	189.90 FL	*189.90 FL
3	1		*REAR BUMPER LH LED END SEAL COVER	Deformed	125.30 FL	*125.30 FL
4	1		*REAR BUMPER LH REFLECTOR	Cracked	181.60 FL	*181.60 FL
5	1		*REAR BUMPER LOWER GARNISH	Deformed	236.00 FL	*236.00 FL
6	2		*REAR BUMPER RUBBER STOPPER COVER L/R	Not Necessary	64.20 FL	*- FL
7	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	262.70 FL	*262.70 FL
8	1		*REAR END PANEL TOP COVER	Deformed	445.00 FL	*445.00 FL
9	1		*REAR LH FENDER INNER UPHOLSTERY TRIM COVER	Deformed	825.00 FL	*825.00 FL
10	1		*REAR LH TAILLAMP	Cracked	460.60 FL	*460.60 FL
11	1		*REAR TAILGATE	Dented	1,812.40 FL	*1,812.40 FL
12	1		*REAR TAILGATE HARRIER EMBLEM	Necessary	61.75 FL	*61.75 FL
13	1		*REAR TAILGATE INNER RUBBER CAP COVER	Not Necessary	13.20 FL	*- FL
14	1		*REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	Deformed	453.70 FL	*453.70 FL
15	1		*REAR TAILGATE LH REFLECTOR	Not Necessary	589.90 FL	*- FL
16	1		*REAR TAILGATE LH REFLECTOR BACK RUBBER GASKET	Not Necessary	51.10 FL	*- FL
17	1		*REAR TAILGATE MECHANISM LOCK	Not Necessary	954.70 FL	*- FL
18	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	695.00 FL	*- FL
19	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Not Necessary	87.40 FL	*- FL
20	1		*REAR TAILGATE WEATHER STRIP	Necessary	387.30 FL	*387.30 FL
21	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	210.00 FL	*210.00 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	2		*SET REAR BUMPER END SEAL COVER CLIPS L/R	Necessary	60.00 FS	*60.00 FS
24	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
25	1		*SET REAR END PANEL TOP COVER CLIPS	Necessary	30.00 FS	*10.00 FS
26	1		*SET REAR LH TAILLAMP CLIPS	Necessary	30.00 FS	*10.00 FS
27	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
28	1		*SET REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS	Necessary	100.00 FS	*30.00 FS
29	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
30	1		*SET REAR TAILGATE SPOILER CLIPS		50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
31	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
32	1		*SET REAR LH FENDER INNER UPHOLSTERY TRIM COVER CLIPS	Necessary	50.00 FS	*30.00 FS
33	1		*REAR LH TAILLAMP BACK RUBBER GASKET	Not Necessary	20.60 FL	*- FL
				Sub Total (\$\$)	10,869.60	7,462.25
				- List Item Discount on L Items 25.00/25.00% (\$\$)	2,484.90	1,758.06
				Total Parts (\$\$)	8,384.70	5,704.19

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	100.00	50.00
2	TO REMOVE, REINSTALL TAILGATE WINDSCREEN	New	250.00	120.00
3	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	140.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	700.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	900.00	600.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	0.00
Gross Labour Cost (\$\$)			2,670.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >