

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/653/2018/PH
Date : 5-Jun-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle is : SLQ 4959 B

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Beng Wee
Address : 77 Punggol Central
#10-80
Singapore 828758
Telephone : HP +65 96184343
Type of Claim : Third Party Claim
Policy No. : 1700032029
Vehicle No : **SCW 7171 L**
Model Code : Audi A4 1.4 TFSI S
Model / Year : Jul-15
Engine No : CVN039002
Chassis No : WAUZZZF40HA165075
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Jun-18
Place of Accident : Hougang St 61

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCW 7171 L .

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor assy.	S/N \$ 360.00	✓
2	To remove rear fittings,dismantle and renew rear bumper.Re-organise rear crash management components.Reinstall all parts removed	\$ 900.00	550
3	To respray rear bumper.	\$ 800.00	550
4	To carry out diagnostic check	\$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCW 7171 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>old</i>	\$ 1,907.00	✓
2	1 SET ATTACHMENT PARTS FOR REAR BUMPER <i>new</i>	\$ 63.00	X
3	REAR BUMPER SPOILER <i>new</i>	\$ 216.00	X
4	SECURING STRIP <i>new</i>	\$ 191.00	X
5	SENSOR <i>new</i>	2 \$ 421.00	X
6	GUIDE SECTION - LH / RH <i>2</i>	2 \$ 38.00	X
7	BUMPER CARRIER <i>new</i>	\$ 786.00	X
8	REAR LIGHT REFLECTOR	2 \$ 70.00	X
9	SUNDRIES <i>?</i>	\$ 200.00	?
TOTAL SPARE PARTS		:	\$ 3,892.00
TOTAL LABOUR CHARGES		:	\$ 2,252.00
GRAND TOTAL		:	\$ 6,144.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 12/06/18
Authorised Date :
Excess Cost :
Liability :
Remarks : xhl Authorised, 03 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant