

ASS. REC. BY:

REF: CS/FCL18010210/Kltbnz Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): W/S Hung Yin Min of FCL Date/Time: 05062018 1252pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 6781D Insured: SHA 9596M

at Workshop m/s Premier Tel: 6544 6671

of 23 Change South Ave 2 #03-02

Policy No: \_\_\_\_\_ Claim No: D18001446MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 01062018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wpe H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 05062018 113pm Person Contacted: Gary Vehicle IN / O/P:

Date/Time	Action/Instruction (✓) Estimate	
	SHC 6781D - CS/MS416005707 / H11h3c2	DAF: 241316
	SHA 9596M - CS/INC D18001494 / Dpn	DAF: 210269
02/6/18 @ 3:37pm	Revised to Hung Yin Min by email.	

108/11/13

Q Insurer: Kalvin

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

ITP /  RES /  OD RES /  EVA /  INV /  MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop no/s: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / .REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHL 6781D Yr Regn: 1 Jan, 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c.: 1685

Colour: Silver A/C: Insured / Std / Nil / NA

Sp. Reading: 643295 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: KNAHM 414MD5-369629

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/m or

Tyre Size; F: 205/65R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 1/6/8 D.O.I. 6/6/8

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/6/8	Inspected 11P \$690/24h. (Red. 650; 48%)

FLZ  
4s

RECEIVED 14 JUN 2010

Date/Time, File Pass to?  : Prell. Report  
1) 1416 Typist  : Final Report

Date/Time, File Return to? \_\_\_\_\_

Report Format: TP  
Lump Sum / I.B.I.: (\$ 690/-)

Days Of Repair: 2  
Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	100
Transportation:	50
S + RS: \$	50
Photos	18
Others	
TOTAL	218



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004446MFSH

Date: 07 June 2018

Our Ref: CS/FCI18010210/K1tb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6781D**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/06/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,340.00</u>
Revised Estimate Amount	: S\$ <u>720.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the o/s rear portion.



Yours faithfully

Kalvin Ang  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	04-06-2018	<b>Our Ref No.</b> D18004446MFSH
<b>Accident Date</b>	01-06-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA9596M	<b>Third Party Vehicle.</b> SHC6781D
<b>Survey Location</b>	23 CHANGI SOUTH AVENUE 2 #03-02	
<b>Contact Person.</b>	GARY SHI	
<b>Contact No.</b>	62148880/ 65446671	<b>Fax No.</b> 62141511
<b>Survey Type</b>	WITHOUT PREJUDICE:	<i>05062018 @ 1:13pm By vehicle</i>
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	AUNGYM	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 7 June 2018 3:37 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18004446MFSH/1  
**Attachments:** CSFCI18010210K1tb.pdf

Dear Yin Min,

Enclosed herewith preliminary advice of SHC 6781D.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)

**Sent:** Tuesday, 5 June 2018 1:19 PM

**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

**Cc:** AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

**Subject:** RE: SURVEY ASSESSMENT - D18004446MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

**Sent:** Tuesday, 5 June, 2018 12:52 PM

**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [AUNGYINMIN@MSFIRSTCAPITAL.COM.SG](mailto:AUNGYINMIN@MSFIRSTCAPITAL.COM.SG)

**Subject:** PRI: SURVEY ASSESSMENT - D18004446MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	11 Jan 2013 / 10:40:45	Receipt No.:	AACCK001-AX239-130111-000006
Asset Type:	Vehicle	Transaction Amount:	\$70,810.00
Asset ID:	SHC6781D	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20130111104045044261		

Vehicle No.:	SHC6781D
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	11 Jan 2013
Original Registration Date:	11 Jan 2013
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MD5369629
Engine No.:	D4FDCH306679
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2012
Open Market Value:	\$17,515.00
Minimum PARF Benefit:	\$6,009.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	11 Jan 2013 10:40:45
COE No.:	2013011101000767N
COE Expiry Date:	10 Jan 2021
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$60,655.00
Lifespan Expiry Date:	10 Jan 2021
Owner ID Type:	Company
Owner ID:	200304975H

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

1-Jun-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6781 D

S/NETT

1 pc	Rear bumper top protector <i>— nlc</i>	\$	<del>80.00</del> 50
1 pc	Rear o/s fender sticker <i>— nlc</i>	\$	60.00
	Sundry <i>nlc</i>	\$	<del>50.00</del> 20
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender, rear bumper, etc.	\$	<del>550.00</del> 200
	To putty and spray painting on rear bumper, rear o/s fender.	\$	<del>500.00</del> 360
	To apply rustproofing on the repaired and replaced panels.	\$	<del>100.00</del> X nlc
		\$	<u>1,340.00</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*Kahrillkk,*  
*6/6/18 0930h,*  
*2 days*  
*L/S*  
*Attn - Repair photo.*

*13/6/18*  
*with PIP\$ 690/2hrs*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010210/K1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9596M	Veh. Inspected	SHC 6781D
Policy No.		Coverage (\$)	0.00
Claim No.	D18004446MFSH	Excess (\$)	0.00
Assign From	AUNGYM	Assign Date	05/06/2018
2. Vehicle Particulars & Condition			
Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KNAGM414MD5369629	Colour	SILVER
Odometer	643295	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R16	ACHILLES	7 mm
L/H Front Tyre	205/65 R16	ACHILLES	7 mm
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/06/2018	Inspection Date	06/06/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6781D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			190.00	130.00
<b>LABOUR</b>				
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE REAR O/S FENDER, REAR BUMPER, ETC.		550.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR O/S FENDER.		500.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	100.00	-
			1,150.00	560.00
<b>GRAND TOTAL</b>			<b>1,340.00</b>	<b>690.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>690.00</b>

Report Ref No. CS/FC118010210/K1tbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.