

7/20/2002

A.S.S. REC. BY:

REF:

CS/FCL18010211/Uqbert

Special Instruction:

SUNVJOY

ASSIGNMENT (Office) ✓

From (Person): CWS Luene Jaw of FCL Date/Time: 05062018 12:21pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 906K Insured: SHC 7169R

at Workshop m/s Hock Wah Tel: 6441 5855

of Bk 3011 Badok Ind Park E # 01-2008

Policy No: Claim No: D1800 4467 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 04062018  
(Client's Record)

CA / REV / REP. / REV 24 HRS DS

H.O.D. Endorsement:

Date/Time: 05062018 1:19pm Person Contacted: Jia Yi Vehicle IN / OUT

| Date/Time        | Action/Instruction ( ✓ ) Estimate               |
|------------------|-------------------------------------------------|
|                  | SKD 906K - x                                    |
|                  | SHC 7169R - CS/FCL17014612 / R1-bn2 DCA: 260717 |
| 12/6/18 @ 3:44pm | revised to Luene by email.                      |
|                  |                                                 |
|                  |                                                 |
|                  |                                                 |
|                  |                                                 |

(08/11/13) waf  
ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKD 906K

at Workshop m/s Woon Woon

of \_\_\_\_\_

Insured: S L C 6451 J

Policy No. SH C 7169 R

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 75k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKD 906K Yr Regn: 8/10 / 11

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Lexus RX 450H C.C. 3456

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 51285 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTJBC11A502427754

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 235/60 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm

L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm


D.O.A. 4/6/18 D.O.I. 11/6/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R.

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

LTA 51517 3yrs. 4ml. Dep 17k. net 23483

20/7/18 confirmed L/S of \$8200 with Anysie  
(Red B 75450.88, 75%)

RECEIVED 23 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

23 x 15 = 345

170 + 345

50

50 + 50

113

778

Report Format: TP

Lump Sum / I.B.I. (\$) 8200

**MOTOR SURVEY ASSIGNMENT**

|                           |                                                                  |                                     |
|---------------------------|------------------------------------------------------------------|-------------------------------------|
| <b>Date</b>               | 04-06-2018                                                       | <b>Our Ref No.</b> D18004467MFSH    |
| <b>Accident Date</b>      | 04-06-2018                                                       | <b>Claim Type.</b> Third Party      |
| <b>Insured Vehicle</b>    | SHC7169R                                                         | <b>Third Party Vehicle.</b> SKD906K |
| <b>Survey Location</b>    | BLK 3011 BEDOK INDUSTRIAL PARK E BEDOK NORTH AVE 4#01-2008/10/12 |                                     |
| <b>Contact Person.</b>    | ANYSIA FOO                                                       |                                     |
| <b>Contact No.</b>        | 64415655/ 0                                                      | <b>Fax No.</b> 62438121             |
| <b>Survey Type</b>        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:      |                                     |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                                     |                                     |
| <b>Contact Person</b>     | NA                                                               | <b>Fax No.</b> 68416315             |
| <b>Contact Number.</b>    | NA                                                               |                                     |

05062018 @ 1149pm  
Jia Yi veh not in

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                                    |                                |
|--------------------------|------------------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | HOCK WAH MOTOR<br>WORKSHOP PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                                 | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | LURENE                             |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Tuesday, 12 June 2018 3:11 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18004467MFSH/1  
**Attachments:** CSFCI18010211Uqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SKD 906K.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 5 June 2018 1:21 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18004467MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 5 June, 2018 12:21 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [LURENEJAW@MSFIRSTCAPITAL.COM.SG](mailto:LURENEJAW@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004467MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004467MFSH

Date: 12 June 2018

Our Ref: CS/FCI18010211/Uqb

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SKD 906K .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/06/2018 at the premises of M/s HOCK WAH. and have the following to report:-

|                          |                          |
|--------------------------|--------------------------|
| Workshop Estimate Amount | : <u>S\$ 33,452.88</u> . |
| Revised Estimate Amount  | : <u>S\$ 7,415.55</u> .  |
| "Check" Items Amount     | : <u>S\$ 17,846.89</u> . |
| Market Value             | : <u>S\$ -</u> .         |
| LTA Reimbursement Value  | : <u>S\$ -</u> .         |
| Nett Value               | : <u>S\$ -</u> .         |

Description of Damage:  
The vehicle sustained damages  
at the rear & front portion.



Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars      |                               |
|--------------------------------|-------------------------------|
| Owner ID Type:                 | Foreign Identification Number |
| Owner ID:                      | 6943T                         |
| Vehicle Details                |                               |
| Vehicle No.:                   | SKD906K                       |
| Vehicle to be Exported:        | No                            |
| Intended De-registration Date: | 11 Jun 2018                   |
| Vehicle Make:                  | TOYOTA                        |
| Vehicle Model:                 | LEXUS RX450H                  |
| Primary Colour:                | Black                         |
| Manufacturing Year:            | 2011                          |
| Engine No.:                    | 2GRJ490485                    |
| Chassis No.:                   | JTJBC11A502427754             |
| Maximum Power Output:          | 220.0 kW (295 bhp)            |
| Open Market Value:             | \$75,921.00                   |
| Original Registration Date:    | 28 Oct 2011                   |
| First Registration Date:       | 28 Oct 2011                   |
| Transfer Count:                | 1                             |
| Actual ARF Paid:               | \$45,553.00 22776             |
| Intended PARF Rebate Details   |                               |
| PARF Eligibility:              | Yes                           |
| PARF Eligibility Expiry Date:  | 27 Oct 2021                   |
| PARF Rebate Amount:            | \$29,609.00                   |
| Intended COE Rebate Details    |                               |
| COE Expiry Date:               | 27 Oct 2021                   |
| COE Category:                  | B - Car (1601cc & above)      |
| COE Period(Years):             | 10                            |
| QP Paid:                       | \$64,889.00                   |
| COE Rebate Amount:             | \$21,908.00                   |
| <b>Total Rebate Amount:</b>    | <b>\$51,517.00</b>            |

The information contained herein is correct as at 11 Jun 2018

OK

**Post an Advertisement**


Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

New 5 Years COE Renewal Toyota Altis 1.6A.



\$2800 Down Payment Monthly  
 From \$688 Onwards. Lowest  
 3.68%P.A@GV Cars Financing.  
 GV Credit Pte Ltd StarAd



Browse by Category ▾

Sort by

**1 vehicles**

Lexus RX450h

Advanced

|                         | Make                | Model | Price | Depreciation | Reg Date    | Eng Cap | Mileage |
|-------------------------|---------------------|-------|-------|--------------|-------------|---------|---------|
| <b>Search Selection</b> | <b>Lexus RX450h</b> |       | Any   | Any          | <b>2011</b> | Any     |         |

**Lexus RX450h Hybrid****\$81,800****\$17,260 /yr****19-Dec-2011****3,456 cc****Fuel Type:** Petrol-Electric

Hurry! Beautiful SUV With Ultra Spacious, Powerful And Very Comfortable Seating. Benchmark Of Luxury In SUV Sector. Number. Flexible Loan. Flexible Loan And High Trade In A...

Classic Credit Pte Ltd

Posted: 04-May-2018 Tags: 2011 Lexus RX450h, Lexus RX450h, Lexus, RX450h, Used Lexus

Save this search criteria, to get email alerts whenever a match is found.

| Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage |
|------|-------|-------|--------------|----------|---------|---------|
|------|-------|-------|--------------|----------|---------|---------|

For old advertisements, view **Expired ads**
[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [For](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, buy used Lexus RX450h, Lexus RX450h Singapore, used Lexus RX450h Singapore, used Lexus RX450h, used vehicles Singapore or even buy used cars from dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, comments.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or wa

**Follow sgCarMart.com**
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection](#)

©2004-2018 sgCarMart. All rights reserved.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                    |
|----------------------------|------------------------------------|
| Date Of Report             | 04/06/2018 15:28                   |
| Date Of Accident           | 04/06/2018 14:15                   |
| Exact Location Of Accident | PIE TUAS BEFORE CLEMENTI ROAD EXIT |
| Country/State Of Loss      | SINGAPORE                          |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKD906K              |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | SUN MIN              |
| NRIC No                     | G5866943T            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-98351062 |
| Alternative Phone No        | OTHERS-98351062      |

### Vehicle Particulars

|                                                                    |         |
|--------------------------------------------------------------------|---------|
| Manufacturer                                                       | LEXUS   |
| Model                                                              | RX450 H |
| Exact Purpose for which vehicle was being used at time of accident | LEISURE |

Are you claiming under your own insurance policy for repair to your vehicle? NO

|                                        |             |
|----------------------------------------|-------------|
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category                       | PRIVATE CAR |

### Insurance Company


|                           |                                        |
|---------------------------|----------------------------------------|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5091372203-01                          |
| Cover Note Number         | DRIVO CLASSIC                          |

### Driver

|                      |                      |
|----------------------|----------------------|
| Name of Driver       | SUN MIN              |
| NRIC No              | G5866943T            |
| Date Of Birth        | 10/04/1979           |
| Occupation           | INDOOR               |
| Date Of Driving Pass | 31/08/2017           |
| Driving Experience   | 0 YEAR AND 9 MONTH   |
| Gender               | MALE                 |
| Mobile Number        | (LOCAL) +65-98351062 |
| Fax Number           |                      |
| Contact Number       | OTHERS-98351062      |
| Email Address        | NOEMAIL              |

|                                     |                   |
|-------------------------------------|-------------------|
| Vehicle Registration Number         | SHC7169R          |
| Vehicle Make/Model/Colour           |                   |
| Details Of Properties               |                   |
| Vehicle Category                    | TAXI              |
| Name of Driver                      | JAMEL BIN MOHAMED |
| NRIC/Passport Number                | S0072048H         |
| Contact Number                      | 81086226          |
| Address                             |                   |
| Postcode                            |                   |
| Insurance Company Name              |                   |
| Nature Of Damage                    |                   |
| No. Of Passenger (Including Driver) |                   |

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling behind vehicle B. Suddenly, vehicle B jammed brakes. Upon seeing this, I jammed my brakes and avoided hitting into the rear of vehicle B. Moments after, vehicle C hit into the rear of my vehicle A. The impact pushed my vehicle A forward and hit into the rear of vehicle B. Thus, in total, there were 3 vehicles involved in this chain collision.

Declaration

I/We declare the foregoing particulars are true in every respect.

  
04-06-18 / 15:23  
Policyholder's Signature / Date & Time

04-06-18 / 15:23  
Driver's Signature (if driver is not the policyholder) / Date & Time

Alan Tang (S098825)  
Customer Care Executive  
Motor Service Centre  
  
Witnessed by Reporting Centre Personnel

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01,2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : G5866943T

SUN MIN  
NO 238A THOMSON ROAD  
18-08 NOVENA SQAURE  
SINGAPORE 307684  
TEL : FAX :  
PH : 98351062  
ATTN :

## ESTIMATE BILL

Number : EB00004849  
Date : 05/06/2018  
Case No : AD00009767  
Vehicle No : SKD906K  
Chassis : JTB11A502427754  
Year of Mfr : 2011  
Policy No : 5091372203-01  
Model : TOYOTA LEXUS  
RX450H

Term:

| Sn | DESCRIPTION                             | QTY | U PRICE  | DISC | AMOUNT   |
|----|-----------------------------------------|-----|----------|------|----------|
| 1  | TAILGATE R                              | 1.0 | 2,170.25 | 10   | 1,953.23 |
| 2  | TAILGATE EMBLEM                         | 1.0 | 69.37    | 10   | 62.43    |
| 3  | TAILGATE LOGO - RX450H                  | 1.0 | 92.70    | 10   | 83.43    |
| 4  | TAILGATE CHROME                         | 1.0 | 217.75   | 10   | 195.98   |
| 5  | TAILGATE WINDSCREEN GLASS WITH MOULDING | 1.0 | 2,759.16 | 10   | 2,483.24 |
| 6  | REAR BUMPER                             | 1.0 | 987.46   | 10   | 888.71   |
| 7  | REAR BUMPER REINFORCEMENT               | 1.0 | 748.95   | 10   | 674.06   |
| 8  | REAR BUMPER RETAINER RH                 | 1.0 | 96.70    | 10   | 87.03    |
| 9  | REAR BUMPER RETAINER LH                 | 1.0 | 96.70    | 10   | 87.03    |
| 10 | REAR BUMPER SPONGE                      | 1.0 | 125.80   | 10   | 113.22   |
| 11 | REVERSE SENSOR                          | 4.0 | 398.70   | 10   | 1,435.32 |
| 12 | REAR EXHAUST PIPE                       | 1.0 | 725.40   | 10   | 652.86   |
| 13 | END PANEL                               | 1.0 | 957.96   | 10   | 862.16   |
| 14 | BONNET                                  | 1.0 | 1,238.75 | 10   | 1,114.88 |
| 15 | BONNET LOCK                             | 1.0 | 159.60   | 10   | 143.64   |
| 16 | BONNET BOTTOM LOCK                      | 1.0 | 97.96    | 10   | 88.16    |
| 17 | HEADLAMP LH                             | 1.0 | 2,786.92 | 10   | 2,508.23 |
| 18 | HEADLAMP RH                             | 1.0 | 2,786.92 | 10   | 2,508.23 |
| 19 | HEADLAMP LOWER BRACKET RH               | 1.0 | 49.76    | 10   | 44.78    |
| 20 | HEADLAMP LOWER BRACKET LH               | 1.0 | 49.76    | 10   | 44.78    |
| 21 | SUPPORT PANEL                           | 1.0 | 1,565.91 | 10   | 1,409.32 |
| 22 | BRACE PANEL                             | 1.0 | 99.57    | 10   | 89.61    |
| 23 | AIR CON CONDENSER                       | 1.0 | 1,859.75 | 10   | 1,673.78 |
| 24 | RADIATOR                                | 1.0 | 2,779.86 | 10   | 2,501.87 |
| 25 | RADIATOR COWLING                        | 1.0 | 351.72   | 10   | 316.55   |
| 26 | RADIATOR FAN                            | 1.0 | 276.36   | 10   | 248.72   |
| 27 | RADIATOR MOTOR                          | 1.0 | 595.74   | 10   | 536.17   |
| 28 | FRONT GRILLE                            | 1.0 | 698.72   | 10   | 628.85   |
| 29 | HEADLAMP NOZZLE RH                      | 1.0 | 605.81   | 10   | 545.23   |
| 30 | HEADLAMP NOZZLE LH                      | 1.0 | 605.81   | 10   | 545.23   |
| 31 | FRONT TOWING COVER RH                   | 1.0 | 48.70    | 10   | 43.83    |
| 32 | FRONT TOWING COVER LH                   | 1.0 | 48.70    | 10   | 43.83    |
| 33 | FRONT BUMPER                            | 1.0 | 782.51   | 10   | 704.26   |
| 34 | FRONT BUMPER RETAINER RH                | 1.0 | 95.91    | 10   | 86.32    |

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : G5866943T

SUN MIN  
NO 238A THOMSON ROAD  
18-08 NOVENA SQAURE  
SINGAPORE 307684  
TEL : FAX :  
PH : 98351062  
ATTN :

## ESTIMATE BILL

Number : EB00004849  
Date : 05/06/2018  
Case No : AD00009767  
Vehicle No : SKD906K  
Chassis : JTJBC11A502427754  
Year of Mfr : 2011  
Policy No : 5091372203-01  
Model : TOYOTA LEXUS  
RX450H

Term:

| Sn                                   | DESCRIPTION                                      | QTY | U PRICE  | DISC | AMOUNT    |
|--------------------------------------|--------------------------------------------------|-----|----------|------|-----------|
| 35                                   | FRONT BUMPER RETAINER LH <i>sup</i>              | 1.0 | 95.91    | 10   | 86.32     |
| 36                                   | FRONT BUMPER REINFORCEMENT <i>11</i>             | 1.0 | 487.60   | 10   | 438.84    |
| 37                                   | FRONT BUMPER BRACKET LH <i>11</i>                | 1.0 | 92.70    | 10   | 83.43     |
| 38                                   | FRONT BUMPER BRACKET RH <i>11</i>                | 1.0 | 92.70    | 10   | 83.43     |
| 39                                   | FRONT BUMPER SPONGE <i>70.7</i>                  | 1.0 | 210.57   | 10   | 189.51    |
| 40                                   | FRONT BUMPER LOWER GRILLE <i>tw</i>              | 1.0 | 172.72   | 10   | 155.45    |
| 41                                   | FRONT BUMPER INNER CENTER BRACKET <i>sup</i>     | 1.0 | 107.96   | 10   | 97.16     |
| 42                                   | FRONT BUMPER NUMBER GARNISH <i>70.7</i>          | 1.0 | 159.80   | 10   | 143.82    |
| 43                                   | FRONT BUMPER LOWER SIDE GARNISH RH <i>11</i>     | 1.0 | 186.77   | 10   | 168.09    |
| 44                                   | FRONT BUMPER LOWER SIDE GRNISH LH <i>11</i>      | 1.0 | 186.77   | 10   | 168.09    |
| 45                                   | FRONT NUMBER PLATE HOLDER <i>25</i>              | 1.0 | 30.00    | 10   | 27.00     |
| 46                                   | ENGINE LOWER DUST COVER <i>11</i>                | 1.0 | 176.41   | 10   | 158.77    |
| List Price - Parts Sub Total         |                                                  |     |          |      | 27,204.88 |
| 47                                   | FRONT NUMBER PLATE HOLDER <i>sup</i>             | 1.0 | 30.00    | 0    | 30.00     |
| 48                                   | FRONT NUMBER PLATE <i>sup</i>                    | 1.0 | 30.00    | 0    | 30.00     |
| 49                                   | WINDSCREEN SEALANT <i>11</i>                     | 2.0 | 24.00    | 0    | 48.00     |
| 50                                   | REAR NUMBER PLATE <i>11</i>                      | 1.0 | 30.00    | 0    | 30.00     |
| 51                                   | REAR NUMBER PLATE HOLDER <i>11</i>               | 1.0 | 30.00    | 0    | 30.00     |
| 52                                   | FRONT FENDER RH - REPAIR <i>11</i>               | 1.0 |          |      |           |
| 53                                   | FRONT FENDER LH - REPAIR <i>11</i>               | 1.0 |          |      |           |
| Special Nett Price - Parts Sub Total |                                                  |     |          |      | 168.00    |
| Parts Total                          |                                                  |     |          |      | 27,372.88 |
| 54                                   | LABOUR TO REMOVE & REFIT NECESSARY PARTS (REAR)  | 1.0 | 1,200.00 | 0    | 1,200.00  |
| 55                                   | SPRAY PAINT ON THE AFFECTED AREAS (REAR)         | 1.0 | 1,000.00 | 0    | 1,000.00  |
| 56                                   | ANTI-RUST COATING (REAR)                         | 1.0 | 180.00   | 0    | 180.00    |
| 57                                   | TO REMOVE & REFIT WINDSCREEN (REAR)              | 1.0 | 180.00   | 0    | 180.00    |
| 58                                   | FOUR WHEEL ALIGNMENT                             | 1.0 | 180.00   | 0    | 180.00    |
| Labour 1 Sub Total                   |                                                  |     |          |      | 2,740.00  |
| 59                                   | LABOUR TO REMOVE & REFIT NECESSARY PARTS (FRONT) | 1.0 | 1,500.00 | 0    | 1,500.00  |
| 60                                   | SPRAY PAINT ON THE AFFECTED AREAS (FRONT)        | 1.0 | 1,300.00 | 0    | 1,300.00  |
| 61                                   | ANTI-RUST COATING (FRONT)                        | 1.0 | 280.00   | 0    | 280.00    |
| 62                                   | WIRING (FRONT)                                   | 1.0 | 80.00    | 0    | 80.00     |

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

8543.7 2610  
7689.33  
10299.33

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : G5866943T

SUN MIN  
NO 238A THOMSON ROAD  
18-08 NOVENA SQAURE  
SINGAPORE 307684  
TEL : FAX :  
PH : 98351062  
ATTN :

## ESTIMATE BILL

Number : EB00004849  
Date : 05/06/2018  
Case No : AD00009767  
Vehicle No : SKD906K  
Chassis : JTJBC11A502427754  
Year of Mfr : 2011  
Policy No : 5091372203-01  
Model : TOYOTA LEXUS  
RX450H

Term:

| Sn                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | DESCRIPTION                     | QTY | U_PRICE     | DISC | AMOUNT    |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|-----|-------------|------|-----------|
| 63                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | TO SERVICE & TOP-UP AIR-CON GAS | 1.0 | 180.00      | 0    | 180.00    |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | Labour 2 Sub Total              |     |             |      | 3,340.00  |
| <div>LKK Auto Consultants hence notify the Repaire of the following:<ul style="list-style-type: none"><li>• To resurvey before after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul>Acknowledged by Repairer:<br/>Signature:<br/>Date:</div> |                                 |     |             |      |           |
| SINGAPORE DOLLARS : THIRTY-FIVE THOUSAND SEVEN HUNDRED NINETY-FOUR AND CENTS FIFTY-EIGHT ONLY                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                 |     | Less Excess |      | 0.00      |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                                 |     | SUBTOTAL    |      | 33,452.88 |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                                 |     | GST 7.00%   |      | 2,341.70  |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                                 |     | TOTAL       |      | 35,794.58 |

Date of accident : 04/06/2018 02:15 PM. Place : PIE TUAS BEFORE CLEMENTI ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                  |                                                                                                 |                 |                            |                                                                                     |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|-----------------|----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                        |                                                                                                 |                 | Ref : CS/FCI18010211/Uqbe2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                              |                                                                                                 |                 | Date : 27-07-2018          |  |
|                                                                                                                                                                                    |                                                                                                 |                 | Code : FCI2                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                  |                                                                                                 |                 |                            |                                                                                     |
| Insured Veh.                                                                                                                                                                       | SHC 7169R                                                                                       | Veh. Inspected  | SKD 906K                   |                                                                                     |
| Policy No.                                                                                                                                                                         |                                                                                                 | Coverage (\$)   | 0.00                       |                                                                                     |
| Claim No.                                                                                                                                                                          | D18004467MFSH                                                                                   | Excess (\$)     | 0.00                       |                                                                                     |
| Assign From                                                                                                                                                                        | LURENE JAW                                                                                      | Assign Date     | 05/06/2018                 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                      |                                                                                                 |                 |                            |                                                                                     |
| Make & Model                                                                                                                                                                       | TOYOTA LEXUS RX450H (A)                                                                         | c.c             | 3456                       |                                                                                     |
| Engine No.                                                                                                                                                                         | HIDDEN                                                                                          | Year of Reg.    | 2011                       |                                                                                     |
| Chassis No.                                                                                                                                                                        | JTJBC11A502427754                                                                               | Colour          | BLACK                      |                                                                                     |
| Odometer                                                                                                                                                                           | 51295                                                                                           | Steering        | IN ORDER                   |                                                                                     |
| Brakes                                                                                                                                                                             | IN ORDER                                                                                        | Modification    | SPORTS RIM                 |                                                                                     |
| General                                                                                                                                                                            | GOOD                                                                                            |                 |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                      |                                                                                                 |                 |                            |                                                                                     |
|                                                                                                                                                                                    | Size                                                                                            | Make            | Balance                    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                     | 235/60 R18                                                                                      | BRIDGESTONE     | 6 mm                       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                     | 235/60 R18                                                                                      | BRIDGESTONE     | 6 mm                       |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                      | 235/60 R18                                                                                      | BRIDGESTONE     | 6 mm                       |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                      | 235/60 R18                                                                                      | BRIDGESTONE     | 6 mm                       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                   |                                                                                                 |                 |                            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                                                               |                                                                                                 |                 |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                      |                                                                                                 |                 |                            |                                                                                     |
| Accident Date                                                                                                                                                                      | 04/06/2018                                                                                      | Inspection Date | 11/06/2018                 |                                                                                     |
| Survey held at                                                                                                                                                                     | HOCK WAH MOTOR WORKSHOP PTE LTD<br>3011 BEDOK INDUSTRIAL PARK E<br>#01-2008<br>SINGAPORE 489977 |                 |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                 |                                                                                                 |                 |                            |                                                                                     |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                 |                 |                            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                 |                                                                                                 |                 |                            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                |                                                                                                 |                 | <b>7 Working Days</b>      |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 906K

| Qty | Description of Parts                    | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>      |                      |                           |                   |
| 1   | TAILGATE                                | TO REPAIR SEE LABOUR | 2,170.25                  | -                 |
| 1   | TAILGATE EMBLEM                         | NECESSARY            | 69.37                     | 69.37             |
| 1   | TAILGATE LOGO - RX450H                  | NECESSARY            | 92.70                     | 92.70             |
| 1   | TAILGATE CHROME                         | NOT NECESSARY        | 217.75                    | -                 |
| 1   | TAILGATE WINDSCREEN GLASS WITH MOULDING | NOT NECESSARY        | 2,759.16                  | -                 |
| 1   | REAR BUMPER                             | DISTORTED            | 987.46                    | 987.46            |
| 1   | REAR BUMPER REINFORCEMENT               | NOT NECESSARY        | 748.95                    | -                 |
| 1   | REAR BUMPER RETAINER RH                 | BENT                 | 96.70                     | 96.70             |
| 1   | REAR BUMPER RETAINER LH                 | BENT                 | 96.70                     | 96.70             |
| 1   | REAR BUMPER SPONGE                      | TORN                 | 125.80                    | 125.80            |
| 4   | REVERSE SENSOR @\$398.70                | SHORTED-2PCS ONLY    | 1,594.80                  | 797.40            |
| 1   | REAR EXHAUST PIPE                       | BENT / TWISTED       | 725.40                    | 725.40            |
| 1   | END PANEL                               | TO REPAIR SEE LABOUR | 957.96                    | -                 |
| 1   | BONNET                                  | DENTED / BUCKLED     | 1,238.75                  | 1,238.75          |
| 1   | BONNET LOCK                             | NOT NECESSARY        | 159.60                    | -                 |
| 1   | BONNET BOTTOM LOCK                      | NOT NECESSARY        | 97.96                     | -                 |
| 1   | HEADLAMP LH                             | NOT NECESSARY        | 2,786.92                  | -                 |
| 1   | HEADLAMP RH                             | NOT NECESSARY        | 2,786.92                  | -                 |
| 1   | HEADLAMP LOWER BRACKET RH               | NOT NECESSARY        | 49.76                     | -                 |
| 1   | HEADLAMP LOWER BRACKET LH               | NOT NECESSARY        | 49.76                     | -                 |
| 1   | SUPPORT PANEL                           | TO REPAIR SEE LABOUR | 1,565.91                  | -                 |
| 1   | BRACE PANEL                             | TWISTED              | 99.57                     | 99.57             |
| 1   | AIR CON CONDENSER                       | BENT / PUNCTURE      | 1,859.75                  | 1,859.75          |
| 1   | RADIATOR                                | NOT NECESSARY        | 2,779.86                  | -                 |
| 1   | RADIATOR COWLING                        | NOT NECESSARY        | 351.72                    | -                 |
| 1   | RADIATOR FAN                            | NOT NECESSARY        | 276.36                    | -                 |
| 1   | RADIATOR MOTOR                          | NOT NECESSARY        | 595.74                    | -                 |

Report Ref No. CS/FCI18010211/Uqbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|----------------------|---------------------------|-------------------|
| 1   | FRONT GRILLE                       | CRACKED              | 698.72                    | 698.72            |
| 1   | HEADLAMP NOZZLE RH                 | NOT NECESSARY        | 605.81                    | -                 |
| 1   | HEADLAMP NOZZLE LH                 | NOT NECESSARY        | 605.81                    | -                 |
| 1   | FRONT TOWING COVER RH              | NOT NECESSARY        | 48.70                     | -                 |
| 1   | FRONT TOWING COVER LH              | NOT NECESSARY        | 48.70                     | -                 |
| 1   | FRONT BUMPER                       | DENTED / DEFORMED    | 782.51                    | 782.51            |
| 1   | FRONT BUMPER RETAINER RH           | BENT                 | 95.91                     | 95.91             |
| 1   | FRONT BUMPER RETAINER LH           | BENT                 | 95.91                     | 95.91             |
| 1   | FRONT BUMPER REINFORCEMENT         | NOT NECESSARY        | 487.60                    | -                 |
| 1   | FRONT BUMPER BRACKET LH            | NOT NECESSARY        | 92.70                     | -                 |
| 1   | FRONT BUMPER BRACKET RH            | NOT NECESSARY        | 92.70                     | -                 |
| 1   | FRONT BUMPER SPONGE                | TORN                 | 210.57                    | 210.57            |
| 1   | FRONT BUMPER LOWER GRILLE          | TWISTED              | 172.72                    | 172.72            |
| 1   | FRONT BUMPER INNER CENTER BRACKET  | BENT                 | 107.96                    | 107.96            |
| 1   | FRONT BUMPER NUMBER GARNISH        | TORN                 | 159.80                    | 159.80            |
| 1   | FRONT BUMPER LOWER SIDE GARNISH RH | NOT NECESSARY        | 186.77                    | -                 |
| 1   | FRONT BUMPER LOWER SIDE GARNISH LH | NOT NECESSARY        | 186.77                    | -                 |
| 1   | FRONT NUMBER PLATE HOLDER          | DISTORTED            | 30.00                     | 30.00             |
| 1   | ENGINE LOWER DUST COVER            | NOT NECESSARY        | 176.41                    | -                 |
|     | LESS 10% DISCOUNT                  |                      | -3,022.77                 | -854.37           |
|     |                                    |                      | 27,204.88                 | 7,689.33          |
|     | <b>SPECIAL NETT ITEMS</b>          |                      |                           |                   |
| 1   | FRONT NUMBER PLATE HOLDER (SN)     | BENT                 | 30.00                     | 20.00             |
| 1   | FRONT NUMBER PLATE (SN)            | BENT                 | 30.00                     | 20.00             |
| 2   | WINDSCREEN SEALANT @\$24.00 (SN)   | NOT NECESSARY        | 48.00                     | -                 |
| 1   | REAR NUMBER PLATE (SN)             | NOT NECESSARY        | 30.00                     | -                 |
| 1   | REAR NUMBER PLATE HOLDER (SN)      | NOT NECESSARY        | 30.00                     | -                 |
| 1   | FRONT FENDER RH (NPA) (SN)         | TO REPAIR SEE LABOUR | -                         | -                 |
| 1   | FRONT FENDER LH (NPA) (SN)         | TO REPAIR SEE LABOUR | -                         | -                 |
|     |                                    |                      | 168.00                    | 40.00             |

Report Ref No. CS/FCI18010211/Uqbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts                                                                                                                                 | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | <b>LABOUR</b>                                                                                                                                        |               |                           |                   |
|     | LABOUR TO REMOVE & REFIT NECESSARY PARTS (REAR).                                                                                                     |               | 1,200.00                  | 600.00            |
|     | SPRAY PAINT ON THE AFFECTED AREAS (REAR).                                                                                                            |               | 1,000.00                  | 600.00            |
|     | ANTI-RUST COATING (REAR).                                                                                                                            | NOT NECESSARY | 180.00                    | -                 |
|     | TO REMOVE & REFIT WINDSCREEN (REAR).                                                                                                                 | NOT NECESSARY | 180.00                    | -                 |
|     | FOUR WHEEL ALIGNMENT.                                                                                                                                | NOT NECESSARY | 180.00                    | -                 |
|     | LABOUR TO REMOVE & REFIT NECESSARY PARTS (FRONT).INCLUSIVE OF THE REPAIR OF TAILGATE, END PANEL, SUPPORT PANEL, FRONT FENDER RH AND FRONT FENDER LH. |               | 1,500.00                  | 600.00            |
|     | SPRAY PAINT ON THE AFFECTED AREAS (FRONT).                                                                                                           |               | 1,300.00                  | 600.00            |
|     | ANTI-RUST COATING (FRONT).                                                                                                                           |               | 280.00                    | 50.00             |
|     | WIRING (FRONT).                                                                                                                                      |               | 80.00                     | 20.00             |
|     | TO SERVICE & TOP-UP AIR-CON GAS.                                                                                                                     |               | 180.00                    | 100.00            |
|     |                                                                                                                                                      |               | 6,080.00                  | 2,570.00          |
|     | <b>GRAND TOTAL</b>                                                                                                                                   |               | <b>33,452.88</b>          | <b>10,299.33</b>  |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>                                                                          |               |                           | <b>8,200.00</b>   |

Report Ref No. CS/FCI18010211/Uqbe2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.