

12/03/2002

ASS. REC. BY:

REF: CS/FCI18010212/Kibonz

Special Instruction:

SUNW/JOY

Kenneth

ASSIGNMENT (Office)

From (Person): (WS) May Chua

of FCI

Date/Time: 05062018 12.13pm

Estimated Cost:

Bill to:

OD (TI) / WS / TP RES / OD RES / EYA / INV / MY / CS

To Inspect Vehicle No: SLR 297Z

Insured: SHD 6610J

at Workshop m/s Hui Yang

Tel: 9047 3466

of Blk 176 Sin Ming Drive #04-02

Policy No:

Claim No: D18004391MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 31052018

CA / REV / REP. / REV 24 HRS' Wp.

06062018 @ after 11am

H.O.D. Endorsement:

Date/Time: 05062018 1.21pm

Person Contacted: Bel

Vehicle: IN / ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate
	SLR 297Z - X
	SHD 6610J - X

REF: FCI

ASSIGNMENT

From:

Date: 06/06/18

Veh No:

SLR 297Z

Yr Regr:

17

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SLR 297Z

Make:

Honda

SA

CC:

1496

at Workshop no:

Hui Yang

Colour:

M. Brown

A/C:

Insured / Std / NI / NA

of: Blk 176, Sin Ming Drive # 04-02

Sp. Reading:

45022

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

RU 3

1254280

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)


after 11 am

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD / A/Rim or

(Policy Condition)



Tyre Size:

F:

R:

215/60R16

Remark: The veh had commenced its repair at the time of inspection.

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

885/c

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

7

mm

R/Bal.

5

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

7

mm

L/Bal.

5

mm

Est. Repairs:

02 days

Res: Yes or No

D.O.A.

3115118

D.O.I.

01/01/18

Lum Sum:

1.31%

3 Val: Yes or No

Survey held at



CA / REV / REP. / 24 HRS

(sup)

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/16 File parts to Catherine @ 886-co email, 2 days. Red: 1333.36, 60%.

RECEIVED 12 JUN 2018

Date/Time: File Pass to?

Preli. Report

Days Of Repair: 2

by: tpist

Final Report

Resurvey No. of Trip: 1

Date/Time: File Return to?

Survey Fee:

Transportation

3:

Add Fee:

Site Insp (\$)

(\$ + RS) \$

Interview (\$)

Photos

Tech. Invs (\$)

Others

Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$ 886)

TOTAL

225

110
50
50
15
225



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D18004391MFSH

Our Ref: CS/FCI18010212/Krb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLR 297Z .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06.06.2018 at the premises of M/s HUI YANG MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,219.36</u> .
Revised Estimate Amount	: S\$ <u>886.00</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at n/s rear portion.



Yours faithfully
KENNETH
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	01-06-2018	Our Ref No. D18004391MFSH
Accident Date	31-05-2018	Claim Type. Third Party
Insured Vehicle	SHD6610J	Third Party Vehicle. SLR297Z
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	BEL	
Contact No.	6451 5752/ 90473466	Fax No. 6451 4658
Survey Type	WITHOUT PREJUDICE:	<i>05062018 @ 121pm Bel veh not in 05062018 @ after 11am</i>
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

*First Capital
(KW for date)
LKK Surveyor
(after Nam)*

31/05/2018

Owner: SKYWAY MOTOR PTE LTD

*Not authorized
Running After claim
\$ 886.00
2 days*

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLR297Z

1pc	rear LH side bumper	<i>SW</i>	\$ 195.20	X
1pc	rear LH side bumper retainer	<i>SW</i>	\$ 121.50	X
1pc	rear LH fender protector	<i>SW</i>	\$ 195.00	✓
			\$ 511.70	
	less 20%		\$ 102.34	
			\$ 409.36	
1pc	rear LH sport rim	<i>l.n SW</i>	s.nett \$ 580.00	<i>60sw</i>
	alignment		\$ 80.00	<i>601</i>
	spray painting		\$ 650.00	<i>3601</i>
	labour charges		\$ 500.00	<i>2501</i>
	Total		\$ 2,219.36	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010212/Krbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6610J	Veh. Inspected	SLR 297Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18004391MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	05/06/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31254280	Colour	METALLIC BRONZE
Odometer	45022	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	7 mm
L/H Front Tyre	215/60 R16	DUNLOP	7 mm
R/H Rear Tyre	215/60 R16	DUNLOP	5 mm
L/H Rear Tyre	215/60 R16	DUNLOP	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/05/2018	Inspection Date	06/06/2018
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 297Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR LH SIDE BUMPER	SERVICEABLE	195.20	-
1	REAR LH SIDE BUMPER RETAINER	SERVICEABLE	121.50	-
1	REAR LH FENDER PROTECTOR	DENTED / CUT	195.00	195.00
	LESS 20% DISCOUNT		-102.34	-39.00
			409.36	156.00
SPECIAL NETT ITEMS				
1	REAR LH SPORT RIM (LOCAL REPAIR)(SN)	SCRATCHED	580.00	60.00
			580.00	60.00
LABOUR				
	ALIGNMENT.		80.00	60.00
	SPRAY PAINTING.		650.00	360.00
	LABOUR CHARGES.		500.00	250.00
			1,230.00	670.00
GRAND TOTAL			2,219.36	886.00
RECOMMENDED COST OF REPAIRS				886.00

Report Ref No. CS/FCI18010212/Krbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.