untain	Rasul		A	SSIG	NME	NT (Office)		.)-0
Mulmm. From (Person):		Yma	of	of f		Alh	Date/Time:	04062018 228pm
Estimated Cost:		J				Bill to:		
on (m) ws / To Inspect Vehi	icle No:		SIT	518	1R		Insured: Tel: 1853	SLV 6875U
at Workshop m. of		3	ubi	Rd	4			1101
Policy No:						Claim No:		
Sum Insured:						Excess:		28
Make of Veh: (Client's Record) CA / REV / Date/Time;	REP. / REV		RS 'WP'	n Cont		06062018 Chris		01062018
Date/Time	-) [s	timat	ę	wiew demand	
	SL7 518B							
	SLV 934	5U-	χ					
8/6/18	Diment	ال م ا			-			

SHYMADO REF:		3622n
antique of the second	ASSIGNMENT	
From: Date: C	Veh No. SLT 5/	Van / Lorry / Taxi / Prime Mover /
To Inspect Vehicle No: SLT 518B	Make: SEAT TOLE	A/C: Insured / Std / NI / NA
at Workshop m/s VERTEX ENRO	Sp.Reading 43801	T/Radio: Insured / Std / NI / NA
Insured: A14	Eng/No:	2NHZH1017537
Policy No. Claims No.	Gen. Cond: Good / Al / Poo	
Sum Insured: Excess:	Steering (norder / Jammed / Brake, (norder / Jammed /	
(Client's Record) Make of Veh:	Modi: Nil / strim / STD	
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection.	Tyre Size: F: R: BS / DUN / EXNOVA / GY / F TOYO / YOKO or	S/LIZA/MIC/OHTSU/PIR/SUMI/
Bal. or Market Value:	Front	Rear
IDAC Accident Rport: Consistent? : Yes or No		m R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No Est. Repairs: 5 days Res.: Yes or N	1 1111	D.O.I. 06/06/18
Lum Sum: % 3 Val.: Yes or N	Survey held at V	GRIEX EWO
CA / REV / REP. / 24 HRS	Des. of Damages For / Reactive IN / OUT	ar r ora r mra r oro r Koontop or
Date: Person Contacted:		ne / Body Structure affected due to collision.
Date / Time Action / Instruction		
21/6/18 Submit DAR Report.		
Date/Time, File Pass to? : Prefi. Report	Days Of Repair:	
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip:	Survey Fee: Transportation
2)	Add Fee: : Site Insp (\$: Interview (\$)S +RS,SI) Photos
Report Format :	Tech, Invs (\$) Others
Lump Sum / I.B.I: (\$: Weekend (\$)
-amp vann, n-m/s		

.

- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED V... Page 1 of 1

- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLV6875U AND SLT518B ON 01/06/2018

From: Chin, Lee-Ying

To: assigni

assignments@lkkauto.com, Admin A

Cc: Sent:

Monday, 4 June, 2018 2:28:41 PM

Attachments:

FaxFED2,TIF

Hi LKK,

Kindly assist to survey.

Fong, Andy-SY

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Singapore 079120 Tel +(65) 6419 1947 | Fax +(65) 6835 7416 Lee-Ying.Chin@aig.com | www.aig.com.sg

02005018 CHINA 02005018

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

12



Daniel Poon Choon Kow LL. B. (Hons), LLM 133 New Bridge Road #11-02 Chinatown Point Singapore 059413 Tel: +65 6227-2469 Fax: +65 6225-2579 Email: law@dpco.com.sg (UEN: 53130838C)

Our Ref:

DP.sl.isk.10506.18.VT

Your Ref:

Please quote our reference number when replying

Date: 04 JUNE 2018

M/S AIG ASIA PACIFIC INSURANCE PTE. LTD. AIG BUILDING 78 SHENTON WAY #08-16 SINGAPORE 079120 ATIN: MOTOR CLAIMS DEPARTMENT FAX (6835-7416) ONLY

DEAR SIRS.

PRE-REPAIR INSPECTION

YOUR INSURED VEHICLE REGISTRATION NO: SLV 6875U ACCIDENT ON 01 JUNE 2018 INVOLVING SLT 518B AND SLV 6875U AT THE JUNCTION OF TANJONG KATONG ROAD & PARKSTONE ROAD

We are instructed by Crescendo Gifts & Trading Supplies to notify you of a road traffic accident on 01st June 2018 at about 08:10 at the junction of Tanjong Katong Road & Parkstone Road involving our client's vehicle registration number SLT 518B and vehicle registration number SLV 6875U driven by your insured at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair inspection of the vehicle, by the attached list of ten (10) surveyor which our client deemed suitable to be appointed.

If the aforesaid is not agreeable, kindly therefore instruct your appointed surveyor for a prerepair inspection of our client's vehicle at by making a prior appointment with the repairer stated below:-

M/S VERTEX EURO PTE LTD 3 UBI ROAD 4 SINGAPORE 408608 ATIN: CHRIS (6742-9368 / 9853-1969)

Date: 04th June 2018

Page 2 Messrs Daniel Poon & Co. Our Ref: DP.sl.isk.10506.18.VT

If we do not receive any agreement from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully A C.

c.c M/S VERTEX EURO PTE LTD

PAX (6742-8127) ONLY

NAME OF MOTOR SURVEYOR

- 1) CHANG FUH KEONG, DAVE (SINCERE APPRAISAL SERVICES)
- 2) HOO JOO LOONG, DANNY (HJL AUTO APPRAISAL SERVICES)
- 3) HOW ANDREW (PROMINENT APPRAISER SERVICES)
- 4) ANG GUEA KIANG (CA APPRAISAL PTE LTD)
- 5) LEE KOK WENG (LEE AUTOMOBILE APPRAISERS SERVICES)
- 6) NG SOON AIK FRANCIS (PRESTIGE APPRAISER SERVICES)
- 7) ONG AH KENG, KENT (KTO AUTOMOBILE ASSESSORS)
- 8) ONG POH MENG (AEON AUTO CONSULTANTS LLP)
- 9) PHILIP FOO (PRECISION APPRAISAL SERVICES)
- 10) NG SOON CHUAN LOUIS (PRESTIGE APPRAISER SERVICES)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCIE	CENT	CT	A T E	MAC	мт
ACCIE		311	-11	1000	

Date Of Report

01/06/2018 10:38

Date Of Accident

01/06/2018 08:10

Exact Location Of Accident

TG KATONG RD / PARKSTONE RD JUNCTION

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLT518B

Insured/Policyholder

Name Of Registered Owner

CRESCENDO GIFTS & TRADING SUPPLIES

Co Reg No

53313622M

Email Address

FRANCIS6880@GMAIL.COM

Mobile Phone No

(LOCAL) +65-83331818

Alternative Phone No

OFFICE-83331818

Vehicle Particulars

Manufacturer

SEAT

Model

TOLEDO

Exact Purpose for which vehicle was being used at WORK PURPOSE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

Policy Number

5094947140 (DRIVO PREMIUM)

Cover Note Number

Driver

CHAN KHENG YONG Name of Driver

S1524183G NRIC No. 18/06/1962 Date Of Birth OUTDOOR Occupation 29/07/1985 Date Of Driving Pass

32 YEARS AND 10 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-83331818 Mobile Number

Fax Number

OTHERS-83331818 Contact Number

FRANCIS6880@GMAIL.COM EMail Address

Address

BLK 129 #02-1555 ANG MO KIO AVENUE 3

Postcode

560129

Was driver an employee of the Insured's Company NO OTHER - SELF-EMPLOYED

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - MAJOR/MINOR RD

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

NO 2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLV6875U

Vehicle Make/Model/Colour

VOLVO

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

Contact Number

YANG MIN YI S9473222J

NRIC/Passport Number

96735063

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME:

: UNKNOWN

GENDER:

: FEMALE

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my daims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

n 1 JUN 2018

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

NRIC/FIN No.:

Reporting Centre Personnel's Signature

Sketch Plan #2 Pg. 1

SKETCH PLAN		and the same of th
	1 196K 2194E	1-1-1-1-1-1-1-1
TAJONG-KATONG REO	8	
- F. 67	12 18 1111	
LTS183.		TITE 2 1
12/80 V		
N 0842N		
	-{-}-{-}-}-	
DESCRIBE CIRCUMSTANCES OF	THE ACCIDENT	
DESCRIBE CIRCUIVISTANCES OF		11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
T was transfer along	Tariona Katono Ruad. Vehida B'	suddenly made a right turn
- was travelled mand	Tanjong Katong Road. Vehicle 'B' without stopping at the watop in	a I couldn't broke in time
from Parketine Road	without stopping at the supply	C
and collided onto the	front day.	
ave colligent and are	2 (40) 400.	
		NOTE SETS AND
		(S)
CRECO		1 to 1 and the second
DECLARATION		1 to 1 and the second
DECLARATION	lars are true in every respect.	
DECLARATION	7 01 000	
DECLARATION	7 01 000	
DECLARATION I/We declary to the particular p	Writer 81 JUN 201	S CONTRACTOR OF THE PARTY OF TH
DECLARATION	7 01 000	

Condition.ICON:
(91)Bers (2)Dented (3)Dissorted (4)Cracked (5)Cur (6)Berstched (07)Deformed (05)Shifted (97)Duckled (16)Broken (11)Necessary (12)Missing (13)Tore (14)Unconfirmed (15)Net Working

MOTOR CAR (Frt)

ACTION 1.8.C) Aug 3005 (1)Replace (*/*) (2)Replace (*/*) (3)Check (*/*) (4)Nec Consultate (***C)

Vehicle No: SLT 518 B

AC	INC	reciti	CON		Qty
001	991886	Frt Number Plate	DT	~	
002	991887	Frt Number Plate Base	BR	~	-
		Frt Number Plate Garnish	Alie i	-	-
		Frt Bumper	Om4	V	-
005	992341	Frt Bumper Clips	MEL	V	
1006	991325	Frt Bumper Bracket	DT	4	-
1007	991462	Frt Bumper Side Retainer	NEC	×	-
008	991433	Frt Bumper Reinforcement	DT	~	-
1009	991318	Frt Bumper Beam		_	⊢
1010	991468	Frt Bumper Sponge	CKK	1	_
1011		Frt Bumper Protector			L
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	CRK	V	1
1014	991301	Frt Bumper Moulding		_	1
1015	991407	Frt Bumper Lower Spoiler	-	-	+
1016	991438	Fri Bumper Sensor	DM6	1	+
1017	995100	Fri LH Bumper Fog Lamp Cover	200	+	+
1018	991355	Frt RH Bumper Fog Lamp Cover	CRK	1	+
1019	995079	Frt LH Bumper Fog Lamp	Ø n	+	+
		Frt RH Bumper Fog Lamp	BR	V	+
		Fn Gnile	-	+	-
1022	991328	Fri Grille Emblem	-	1	+
1023	991799	Frt Grille Chrome Moulding	CUT	1	+
1024	991222	Frt Apron Panel	-	+	+
1025	992013	Frt Support Panel	DT	_	+
1026	992025	Fri Support Panel Top Garnish Cover	CRK	V	4
1027	992416	Hom	-	+	+
1028	99127	7 Frt Brace Panel	BR	+	+
1029	99515	Fn LH Headlamp Assy	BA		+
1030	99182	Fri RH Headlamp Assy	5 8	¥	+
1031	99508	8 Frt LH Side Lamp	-	+	+
		9 Frt RH Side Lamp	OT	+	+
1033	99024	8 Bonnet	01	-	+
1034	99132	8 Bonnet Emblem	10-	+	+
		7 Bonnet Lock	DT	-	4
1036	99028	5 Bonnet Insulator	BT	-14	4
1037	99027	3 Bonnet Hinge RH / LH	DT	V	4
1038	99026	1 Bonnet Damper	+	+	+
1039	99030	5 Bonnet Rubber	+	+	+
		2 Bonnet Cable	-	+	+
104	99031	1 Bonnet Stand	01	+	1
	2 99011	9 Air Con Condenser	Chi		+
104	3 99012	2 Air Con Fan Assy	Cur	+	+
104	4 99013	4 Air Con Suction Pipe (Low Pressure)	+	+	+
104	5 99011	8 Air Con Suction Hose	+	+	+
104	6 99013	3 Air Con Discharge Pipe (High Pressure	4	+	+
104	7 99011	4 Air Con Discharge Hose	+	+	+
104	8 99014	19 Air Con Liquid Pipe	+-	+	+
104	9 99500	66 Air Con Receiver Drier	-	+	+
		1 Air Con Compressor Assy	+	+	+
105	1 99529	94 Air Con Belt	+	+	+
105	2 9950	74 Radiator			1
105	3 992?	38 Radiator Cowling	+-	+	-
105	4 99274	42 Radiator Fan Assy	-	-	+
105	5 9927	45 Radiator Fan Clutch	+	+	+
105	5 9927	58 Radiator Hose Top	+	+	+
_		57 Radiator Hose Bottom	-	+	-
105		41 Radiator Expansion Tank	- 0	-	1
		51 Air Duct	Del	sim	0
100	9900	70 Air Cleaner Assy	-	-	-
100	9900	56 Air Cleaner Hose	-	1	1
100	9900	89 Air Cleaner Resonator	-		
100	53 9917	12 Frt Exhaust Manifold	_		
100	54 9917	13 Frt Exhaust Manifold Cover	1	- 1	1.
100	65 9910	54 Frt Exhaust Manifold Sensor (Oxygen			
	66 0017	14 Front Exhaust Pipe			
10	00 1 3311				
10	67 9902	19 Battery			
10	67 9902	19 Battery 24 Battery Cover	J	7	-

		Vehicle No:			_
AC	INC	Item	CON	ACC)ty
071		Fuse Box			
072		Relay Box			
073	995053	Wiper Washer Tank			
074	995052	Wiper Washer Tank Motor			
075	990159				
076		Alternator Belt		\neg	
077	992688	Power Steering Pump		7	
		Power Steering Belt			
078		Power Steering Belt		-	_
079	994431	Power Steering Cooler Pipe		-	_
080		Power Steering Hose		-	_
081	990010	ABS Pump Control Unit			_
082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			_
1085	991011	Engine Under Cover			_
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt	-		_
1088		Engine Mounting LH			_
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091		Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	-	Frt RH Chassis Member			
1094	_	Frt Vertical Cross Member			
1094	_	Fri Lower Cross Member	1		
1095		Frt LH Fender			
1090		Fri LH Fender Inner Panel	1		-
1097		Frt LH Fender Lamp			1
1099	00514	Frt LH Fender Protector	1		
1100	00174	Fri LH Fender Inner Shield	+		
_	-	Frt LH Mudflap			-
1101	99517	Frt LH Wheel Rim	+		Н
1102	99317	5 Frt LH Rim Cover	+	-	-
1103			1	+	Н
_	_	5 Frt LH Tyre	DT	17	۰
1105		Frt RH Fender	_	V	H
1106	99173	9 Frt RH Fender Inner Panel	DT	R	⊢
1107	99174	4 Frt RH Fender Lamp	+	-	H
1108	99175		CUT	1	1
1109	99174	0 Frt RH Fender Inner Shield	_	-	₽
1110	99188	4 Frt RH Mudflap		-	1
111		7 Frt RH Wheel Rim	-	-	1
1112	2 99402	5 Frt RH Rim Cover	_	-	-
111	3 99506	5 Frt RH Tyre	1000	1	1
1114	4 99209	3 Frt Windscreen Glass	CRK	1	₽
111	5 99211	7 Frt Windscreen Rubber			L
111	6 99210	8 Frt Windscreen Moulding			
111	7 99209	8 Frt Windscreen Sealant	NEC	1	1
111	8 99101	9 ERP Bracket			T
111	9 9010	0 ERP Unit			T
112	0 99214	0 Frt Wiper Arm			T
112	1 99214	2 Frt Wiper Blade			T
112	2 9950	5 Wiper Panel Garnish			T
112	3 9911	26 Firewall Panel			T
112	4 9907	53 Dashboard Assy			T
112	5 9922	32 Glove Box Cover		T	T
112	6 0022	81 Glove Box Compartment			Ť
112	7 0044	83 Steering Wheel Airbag	Pur	U	1
114	0 0044	85 Steering Wheel Airbag Sensor		1	1
112	8 9944	15 Seering which Airbag Senson	Pur	J	1
112	9 9967	49 Dashboard Airbag			1
113	9907	50 Dashboard Airbag Sensor	50	-1-	+
113	31 9900	29 Airbag Control Unit	-		+
11:	32 9908	64 Frt Driver Seat	-	4	_
113	33 9919	22 Frt RH Seat Belt Assy	JA	MV	1
11	34 9918	99 Frt Passenger Seat			
11	35 9951	82 Frt LH Seat Belt Assy	CH	TV	
11	36 9902	47 Sticker			J
		Fot RH door	to	AT F	3
_			11/4		1
				_	_

No of Items:_

Acsessor:

original capy

...CLAIM SUBFOLDER...(Pending for Survey Report)

Clise	Notified	Est Submitted	Adi Assigned	Adj Rpt	Ad	Subn	nitted	Ins Auth'ed	Status		
Main	07 Jun 2018 Edit Reg	Lat Sub-titles	04 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimate	200	0.00 iew Rp	t		Pending for Surve Report Cancel Case		ey
	Main	Re	ference	CI	aim Deta	ails	\Box	Documen	nts	Sh	low All
CLAIM SU	BFOLDER DE	TAILS			9001020140140		[Create	ed by adjuster]			
Insured:	TUNG JUG	MEI, ID: 5698	5749C								
Main Claimant:		DO GIFTS & TRA		S, Co. Reg.	No.: 533	13622					
Vehicle Reg	SLT518	В			Date of	Loss:	01/06/2 [7 Mont	018 08:00 - :59 hs and 16 Days Fr	rom LTA Re	m LTA Reg Date (Man Yr)]	
Claim Type	TP / 964	10802954SG			Policy/C Note No	CONTRACT OF	1800005	1800005210 (Comprehensive)			
Vehicle Reg No. (Insured):	SLV6875	U			Policy N (Claima						
(anisarea)					Excess:						
Repairer:	Vertex E	uro Pte Ltd (HQ)	3 UBI ROAD 4,	408608 Ubi - 1	Tel: 98531	1969				0.171010	innle
Handling Insurer:	WZ Tan@:	Pacific Insurance									
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel	: 6256-3561	. [Handle	d by N	MOHD RA	ASUL] [Final	Kpt due	18/06/20	10]
Claimant's Solicitor:	Daniel Po	oon & Co									
ASSOCIA	TED MAIL RE	ECEIVED							View All	Compose	Case M
AIG_SG	(07/06/2018)	Request To Up	load TP GIA Re	eport							
ALL ASS	OCIATED TA	sks ^[]					View A	All Search Tasks	Create N	New Task	Comple
Due Da		Type Task	Group Sub	oject Hand	ler A	Assign	ed By	Completed O	n Cre	eated On	Don

Claim Documents

*SLT518B (9640802954SG) [SLV6875U] TP **CRESCENDO GIFTS & TRADING SUPPLIES** Jun 1 2018 8:00AM [TUNG JUO MEI] Vertex Euro Pte Ltd

Pho	tos/Images		3 per	page ▼	1
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/06/18 11:51	General View	0	Load JPG	•
2	07/06/18 11:51	General View	0	Load JPG	1
3	07/06/18 11:51	General View	0	Load JPG	•
4	07/06/18 11:51	General View	0	Load JPG	•
5	07/06/18 11:51	General View	0	Load JPG	•
6	07/06/18 11:51	General View	0	Load JPG	•
7	07/06/18 11:51	General View	0	Load JPG	•
8	07/06/18 11:51	General View	0	Load JPG	•
9	07/06/18 11:51	General View	0	Load JPG	•
10	07/06/18 11:51	General View	0	Load JPG	•
11	07/06/18 11:51	General View	0	Load JPG	•
12	07/06/18 11:51	General View	0	Load JPG	•
13	07/06/18 11:51	General View	0	Load JPG	•
14	07/06/18 11:51	General View	0	Load JPG	•
15	07/06/18 11:51	General View	0	Load JPG	~
16	07/06/18 11:51	General View	0	Load JPG	•
17	07/06/18 11:51	General View	0	Load JPG	•
18	07/06/18 11:51	General View	0	Load JPG	•
19	07/06/18 11:51	General View	0	Load JPG	
20	07/06/18 11:51	General View	0	Load JPG	~
21	07/06/18 11:51	General View	0	Load JPG	~
22	07/06/18 11:51	General View	0	Load JPG	~
23	07/06/18 11:51	General View	0	Load JPG	1
24	07/06/18 11:51	General View	0	Load JPG	1
25	07/06/18 11:51	General View	0	Load JPG	~
26	07/06/18 11:51	General View	0	Load JPG	2
27	07/06/18 11:51	General View	0		•
28	07/06/18 11:51	General View	0	Load JPG	
29	07/06/18 11:51	General View	0	Load JPG	
30		General View	0		
31	07/06/18 11:51	General View	0	Load JPG	•
32	07/06/18 11:51	General View	0	Load JPG	•
33		General View	0	Load JPG	
34		General View	0	Load JPG	6
35		General View	0	Load JPG	

Pho	tos/Images			7	✓
Vo.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
6	07/06/18 11:51	General View	0	Load JPG	•
7	07/06/18 11:51	General View	0	Load JPG	•
8	07/06/18 11:51	General View	0	Load JPG	•
9	07/06/18 11:51	General View	0	Load JPG	•
0	07/06/18 11:51	General View	0	Load JPG	•
1	07/06/18 11:51	General View	0	Load JPG	•
12	07/06/18 11:51	General View	0	Load JPG	~
3	07/06/18 11:51	General View	0	Load JPG	•
14	07/06/18 11:51	General View	0	Load JPG	•
5	07/06/18 11:51	General View	0	Load JPG	€
6	07/06/18 11:51	General View	0	Load JPG	•
17	07/06/18 11:51	General View	0	Load JPG	•
18	07/06/18 11:51	General View	0	Load JPG	•
19	07/06/18 11:51	General View	0	Load JPG	€
50	07/06/18 11:51	General View	0	Load JPG	•
51	07/06/18 11:51	General View	0	Load JPG	•
52	07/06/18 11:51	General View	0	Load JPG	•
53	07/06/18 11:51	General View	0	Load JPG	Y
54	07/06/18 11:51	General View	0	Load JPG	•
55	07/06/18 11:51	General View	0	Load JPG	•
56	07/06/18 11:51	General View	0	Load JPG	4
57	07/06/18 11:51	General View	0	Load JPG	1
58	07/06/18 11:51	General View	0	Load JPG	
59	07/06/18 11:51	General View	0	Load JPG	•
60	07/06/18 11:51	General View	0	Load JPG	-
51	07/06/18 11:51	General View	0	Load JPG	1000
62	07/06/18 11:51	General View	0	Load JPG	
63	07/06/18 11:51	General View	0	Load JPG	
64	07/06/18 11:51	General View	0	Load JPG	-
65	07/06/18 11:51	General View	0		~
66	07/06/18 11:52	General View	0		-
67	07/06/18 11:52	General View	0		
68	07/06/18 11:52	General View	0		
69	07/06/18 11:52	General View	0		- 12
70	21/06/18 16:20	Dismantled Parts	0		- 63
71	21/06/18 16:20	Dismantled Parts	0		
72	21/06/18 16:20	Dismantled Parts	0	The second second	1 100
73	21/06/18 16:20	Dismantled Parts	0		
74	21/06/18 16:20	Dismantled Parts	0		
75	21/06/18 16:20	Dismantled Parts	0		
76	21/06/18 16:20	Dismantled Parts	0		
77	21/06/18 16:20	Dismantled Parts	0		
78	21/06/18 16:20	Dismantled Parts	0		
79	21/06/18 16:20	Dismantled Parts	0		
80	21/06/18 16:20	Dismantled Parts	0		
81	21/06/18 16:20	Dismantled Parts	0	S	-
82	21/06/18 16:20	Dismantled Parts	0		
83	21/06/18 16:20	Dismantled Parts	•	Load JPG	5

Photos/Images					
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
34	21/06/18 16:20	Dismantled Parts	0	Load JPG	1
5	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
6	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
7	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
8	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
9	21/06/18 16:20	Dismantled Parts	0	Load JPG	1
0	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
1	21/06/18 16:20	Dismantled Parts	0	Load JPG	1
92	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
93	21/06/18 16:20	Dismantled Parts	0	Load JPG	1
)4	21/06/18 16:20	Dismantled Parts	0	Load JPG	
95	21/06/18 16:20	Dismantled Parts	0	Load JPG	2
96	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
97	21/06/18 16:20	Dismantled Parts	0	Load JPG	4
98	21/06/18 16:20	Dismantled Parts	0	Load JPG	
99	21/06/18 16:20	Dismantled Parts	0	Load JPG	
100		Dismantled Parts	0	Load JPG	•
.05.65	21/06/18 16:20	Dismantled Parts	0	Load JPG	
101	Control of Control	Dismantled Parts	0	Load JPG	
102		Dismantled Parts	0	Load JPG	
103		Dismantled Parts	0	Load JPG	
104		Dismantled Parts	0	Load JPG	
105		Dismantled Parts	0	Load JPG	
106		Dismantled Parts	0	Load JPG	
Saleste	21/06/18 16:20	Dismantled Parts	0	Load JPG	
70.00	21/06/18 16:20	Dismantled Parts	0	Load JPG	
	21/06/18 16:20	Dismantled Parts	0		
	21/06/18 16:20		0		
1000	21/06/18 16:20	Dismantled Parts	0		
	21/06/18 16:20	Dismantled Parts	0	_	
-	21/06/18 16:20	Dismantled Parts	0		-
	21/06/18 16:20	Dismantled Parts	0		
115		Dismantled Parts	0	-	6
10.13	21/06/18 16:20	Dismantled Parts	0		
11		Dismantled Parts	0		-
1400	3 21/06/18 16:20	Dismantled Parts Dismantled Parts	0		- 20
	21/06/18 16:20		0	-	-
(1000	21/06/18 16:20	Dismantled Parts	0	The second second second	
12		Dismantled Parts	0		. 6
12		Dismantled Parts	0	100000000000000000000000000000000000000	
12		Dismantled Parts	0	_	. 8
	4 21/06/18 16:20	Dismantled Parts	0		
12		Dismantled Parts	0		
12		Dismantled Parts	0		
12		Dismantled Parts	0		
1000	8 21/06/18 16:20	Dismantled Parts	6		
100	9 21/06/18 16:20	Dismantled Parts	0		
13	0 21/06/18 16:20 1 21/06/18 16:20	Dismantled Parts Dismantled Parts	0		

Phot	os/Images			•	•
	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
10000	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
134	21/06/18 16:20	Dismantled Parts	0	Load JPG	₹
20000	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
137	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
138	21/06/18 16:20	Dismantled Parts	0	Load JPG	€
139	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
140	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
141	21/06/18 16:20	Dismantled Parts	0	Load JPG	1
142	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
143	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
144	21/06/18 16:20	Dismantled Parts	0	Load JPG	€
145	21/06/18 16:20	Dismantled Parts	0	Load JPG	€
146	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
147	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
148	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
149	21/06/18 16:20	Dismantled Parts	0	Load JPG	2
150	21/06/18 16:20	Dismantled Parts	0	Load JPG	•
Doc	umentation		1 per	page ▼	•
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnai	Prin
1	07/06/18 11:50	OI GIA REPORT	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG18010217/R1Z4BS2

Date:

02/07/2018

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800005210

Claimant Vehicle No:

SLT518B

Insured Vehicle No:

SLV6875U

Engine No:

Odometer:

Chassis No:

Date of Loss:

01/06/2018

Nature of Claim:

TP

9640802954SG Claim No:

VSSZZZNHZH1017537

CUS344934

43801 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Reg. Date:

SLT518B

Make & Model:

SEAT TOLEDO, 2.0 FSI (A) 16/10/2017 (Man. Year: 2017)

Colour: Engine Capacity: Grey 1422 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Fair Steering (Serviceable): Yes

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Yes

Engine Modification:

No

215/45R16

Front Tyre Size: Front Left Side:

Dunlop 6 mm Dunlop 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 215/45R16 Dunlop 6 mm Dunlop 6 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

04/06/2018

Vertex Euro Pte Ltd (HQ)

Date Inspected:

06/06/2018

Inspected At:

3 UBI ROAD 4

Singapore 408608

Estimated Period of Repair:

5.0 days

Adjuster: MOHD RASUL Manager:

Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

R	01	20	mr	ne	nd	ed	Pa	rts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT NUMBER PLATE	Dented	0.00 F	*-F
2	1	*FRT NUMBER PLATE BASE	Broken	0.00 F	*-F
3	1	*FRT BUMPER	Damaged	0.00 F	*-F
4	1	*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
5	1	*FRT BUMPER BRACKET	Dented	0.00 F	*- F
6	1	*FRT NUMBER SIDE RETAINER	Necessary	0.00 F	*- F
7	1	*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*-F
8	1	*FRT BUMPER SPONGE	Cracked	0.00 F	*-F
9	1	*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
10	1	*FRT BUMPER SPONGE	Damaged	0.00 F	*-F
11	1	*FRT RH BUMPER FOG LAMP COVER	Cracked	0.00 F	*- F
12	1	*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*- F
13	1	*FRT GRILLE CHROME MOULDING	Cut	0.00 F	*- F
14	1	*FRT SUPPORT PANEL	Dented	0.00 F	*- F
15	1	*FRT SUPPORT PANEL TOP GARNISH COVER	Cracked	0.00 F	*- F
16	1	*FRT LH HEADLAMP ASSY	Broken	0.00 F	*-F
17	1	*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
18	1	*BONNET	Dented	0.00 F	*- F
19	1	*BONNET LOCK	Dented	0.00 F	*- F
20	1	*BONNET INSULATOR	Bent	0.00 F	*- F
21	1	*BONNET HINGE RH/LH	Dented	0.00 F	*-F
22	1	*AIR CON CONDENSER	Dented	0.00 F	*-F
23	1	*AIR CON FAN ASSY	Cut	0.00 F	*- F
24	1	*AIR DUCT	Deformed	0.00 F	*- F
25	1	*BATTERY COVER	Torn	0.00 F	*- F
26	1	*FRT RH FENDER	Dented	0.00 F	*- F
27	1	*FRT RH FENDER INNER PANEL	Repair	0.00 F	*- F
28	1	*FRT RH FENDER PROTECTOR	Cut	0.00 F	*-F
29	1	*FRT WINDSCREEN GLASS	Cracked	0.00 F	*- F
30	1	*FRT WINDSCREEN SEALANT	Necessary	0.00 F	*- F
31	1	*STEERING WHEEL AIRBAG	Punctured	0.00 F	*- F
32	1	*STEERING WHEEL AIRBAG SENSOR	Short Circuit	0.00 F	*- F
33	1	*DASHBOARD AIRBAG	Punctured	0.00 F	*- F
34	1	*DASHBOARD AIRBAG SENSOR	Short Circuit	0.00 F	*- F
35	1	*FRT RH SEAT BELT ASSY	Jammed	0.00 F	*- F
36	1	*FRT LH SEAT BELT ASSY	Cut	0.00 F	*- F
37	1	*FRT RH DOOR	Repair	0.00 F	*- F
F≡Fr	anchise part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >