

ASS. REC. BY: Adrian Ling

REF:

CC3 / MSB18010225 / Agbonz

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: TBF 7670P

Policy No. MSO/VM7/18-3M100-CA

Claims No. MSC/V/18-00772

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SF59996T

Yr Regn:

2011 Sept.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 523i

C.C 2497.

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

211012

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAFP32040C867126

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R18

R:

245/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

dy

mm

R/Bal.

dy

mm

L/Bal.

dy

mm

L/Bal.

dy

mm

D.O.A.

D.O.I.

04/06/18

Survey held at

Fastede

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TPMS16

06/6/18 @ 9.34am Email GIA report to Elaine Ngu & Hasvanah.

13/7/18 @ 10.33am visited to Elaine Ngu via Wechat.

Have checked with Asnean, he had checked on the parts prices.
US \$5600, 4 days (Red \$4196.73, 75%).

RECEIVED 17 JUL 2018

Date/Time, File Pass to?



Preli. Report

1) 12/7/18 by [signature]



Final Report

Date/Time, File Return to?

2)

Report Format:

MER-1

Lump Sum / L.B.I. (%)

54%

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

200

Transportation:

10

S + RS. SI

Photos

Others

TOTAL

210

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 13 Jul 2018

Preliminary Advice

Insured Vehicle No	: FBF7670P	Accident Date	: 01/06/2018
TP Vehicle No	: SFJ9996T	Assignment Date	: 06/06/2018
Make	: BMW 523I	Est. Duration of Repair	: 4.00
Date of Inspection	: 04/06/2018		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	21,596.73
Revised Amount	:SS	6,750.93
Check Items (Estimated)	:SS	0.00
Total	:SS	6,750.93
Lump Sum Repair	:SS	5,400.00

Total Loss Consideration

New for Old Value	:SS
Pre-Accident Value	:SS
COE / PARF Rebate	:SS
Salvage Value	:SS
Margin for Repair	:SS

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 6 June 2018 9:34 AM
To: Elaine Ngu; Hasrianah Binte Hassan
Cc: KKLau; SUR; Accounts (LKKAUTO)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 01/06/2018, SFJ 9996T (TP VEHICLE), FBF 7670P (OI VEHICLE)
Attachments: SFJ9996T GIA.pdf

Dear Elaine and Hasrianah,

Please be informed that we had inspected the vehicle SFJ 9996T at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 04/06/2018.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2018 09:08
Date Of Accident	01/06/2018 14:15
Exact Location Of Accident	TAMPINES AVE 5 TOWARDS TAMPINES HUB
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFJ9996T
Insured/Policyholder	
Name Of Registered Owner	YEE KENG YIP
NRIC No	S0147819B
Email Address	KYYEE1953@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90921996
Alternative Phone No	OTHERS-90921996

Vehicle Particulars

Manufacturer	BMW
Model	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	B 27189314 SMP
Cover Note Number	

Driver

Name of Driver	YEE KENG YIP
NRIC No	S0147819B
Date Of Birth	31/08/1953
Occupation	INDOOR
Date Of Driving Pass	14/07/1971
Driving Experience	46 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90921996
Fax Number	
Contact Number	OTHERS-90921996
E-Mail Address	KYYEE1953@GMAIL.COM

Address 96 SEA BREEZE AVENUE

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : NG SIEW CHENG

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: WITH DRIVER

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBF7670P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category MOTORCYCLE

Name of Driver MUHAMMAD FAIRUL RIZAL BIN HANAFI

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 418033
Tel: 67492305
Fax: 67492305
Email: vackbi@singnet.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Vehicle A: SFJ 9996T

Vehicle B: FBF 7670P



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I was driving on the stated venue. When I'm approaching the traffic light junction, the traffic light was in Red hence the vehicles in front of me stopped and I stopped. Suddenly vehicle B (FBF 7670P) hit onto my rear portion of my car & the great impact causes damages to my car. No one was injured.

Vehicle A: SFJ 9996T (1 passenger)

Vehicle B: FBF 7670P (0 passenger)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IBAC KAKI BUKIT (VAGI)
23 KAKI BUKIT AVE 4
Singapore 415933
Reporting Centre Personnel's Signature
Name: Paul
NRIC/FIN No.: 67492305
Email: vackb@sinagel.com.sg

GENERAL INSURANCE ASSOCIATION OF SINGAPORE (GIA)
GIA RECORDS MANAGEMENT CENTRE
10 Anson Road #06-16 International Plaza Singapore 079903 Tel: 6224 0010 Fax: 6224 0030
Operating hours: Monday – Friday 9.00 am to 5.00 pm


1.4 Receiving Party acknowledges and agrees that, due to the unique nature of personal data, a remedy at law for breach by Receiving Party of this Clause 1 may not be adequate and that such breach would cause irreparable harm to GIA; therefore GIA shall be entitled to seek equitable relief such as an injunction or specific performance, in addition to whatever remedies it might have at law or under this Agreement.

D. **PARTICULARS OF APPLICANT**

Name/Company: Kim chwee Auto P/L NRIC No: _____
Address: _____ Your Ref: _____
_____ Co Reg No: 199802379R
Tel / Hp No: _____ Fax No: _____

E. **DETAILS OF TRAFFIC ACCIDENT**

Date/Time of Accident: 1/6/18 @ 2.15pm Vehicle Number for requested Accident Report: FBF7670P
Place of Accident: Tampines Ave 5 towards Tampines Hub

Applicant's signature & Date  Company's Stamp

F. **UNDERTAKING BY INDIVIDUAL INVOLVED/PROXY OR ATTACH WARRANT TO ACT**

I Yee Keng Yip NRIC No/Co Reg No. 50147819B
(Driver/Owner Name)
my vehicle registration No. SFS 9996T was involved in this accident.
☐ I wish to apply for the Non – Injury Accident Report and undertake to pay for the necessary fees.
☒ I hereby authorize Kim chwee Auto P/L of NRIC No/Co Reg No. 199802379R
to apply for the Non – Injury Accident Report on my behalf. I undertake to pay the necessary fees.

X chakanyip
Driver/Owner's Signature & Date

G. **UNDERTAKING BY LAW FIRMS/INSURANCE COMPANIES AND LOSS ADJUSTERS ONLY**

We act on behalf of _____ NRIC No/Co Reg No. _____
whose vehicle Reg No. _____ was involved in this accident. We undertake to pay for all the necessary fees.

FOR GIARMC OFFICIAL USE:

Receipt No: _____ ☐ Cash ☐ Giro ☐ Cheque _____

FASTECH AUTO PTE LTD

PAGE 1 OF 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

WBAFP320400867126

Estimate : 20330

TPMS19

Xiao Chen

Date : 04.06.2018

Vehicle Num : SFG9996T

Make/Model : BMW 523i

Chassis/Engine no :

Accident Date : 01.06.2018

Claim No : 0518-20330

Qty	Particular	Amount S\$	
1 pc	Rear boot <i>Dented</i>	\$ 2,650.00	✓
1 pc	Rear boot lock <i>new</i>	\$ 465.00	+
2 pc	Rear boot hinge @ 166.00 <i>new</i>	\$ 332.00	+
1 pc	Rear boot rubber <i>new</i>	\$ 295.00	✓
1 pc	Rear boot inner cover <i>new</i>	\$ 285.00	+
1 pc	Rear boot logo <i>new</i>	\$ 85.00	✓
2 pc	Rear boot reflector @ 295.00 <i>LH out</i>	\$ 590.00	285
1 pc	Rear boot outer handle <i>new</i>	\$ 215.00	+
1 pc	Rear boot centre garnish <i>new</i>	\$ 135.00	+
2 pc	Rear boot inner stopper @ 25.00 <i>new</i>	\$ 50.00	+
1 pc	Rear boot emblem (523) <i>new</i>	\$ 65.00	✓
1 pc	Rear end panel <i>new</i>	\$ 850.00	+
1 pc	Rear end panel top garnish <i>new</i>	\$ 188.00	+
2 pc	Rear tail lamp @ 659.00 <i>LH out</i>	\$ 524 1,318.00	659
2 pc	Rear tail lamp panel @ 185.00 <i>new</i>	\$ 370.00	+
1 pc	Rear spare tyre panel	\$ 895.00	+
1 pc	Rear spare tyre top cover board <i>new</i>	\$ 495.00	+
1 pc	Rear spare tyre tool tray	\$ 215.00	+
1 pc	Rear lock antenna	\$ 328.00	+
2 pc	Rear bumper side retainer @ 95.00 <i>LH new</i>	\$ 190.00	85
2 pc	Rear bumper towing cover @ 35.00 <i>new</i>	\$ 70.00	+
1 pc	Rear bumper reinforcement <i>Bent</i>	\$ 697 845.00	845
4 pc	Rear bumper sensor @ 235.00 <i>1 piece damaged</i>	\$ 940.00	235
1 pc	Rear bumper centre retainer <i>new</i>	\$ 250.00	98
2 pc	Rear bumper reflector @ 85.00 <i>LH missing</i>	\$ 5867.70 170.00	85
2 pc	Rear bumper inner dust cover @ 85.00 <i>new</i>	\$ 5280.93 170.00	+
2 pc	Rear fender inner garnish @ 385.00 <i>new</i>	\$ 770.00	+
2 pc	Rear fender dust cover @ 169.00 <i>new</i>	\$ 338.00	+
1 pc	Rear bumper inner bootlid kicking upener mould <i>new</i>	\$ 342.00	T
1 pc	Rear bumper inner centre retainer <i>new</i>	\$ 98.70	✓
1 Set	Rear exhaust silencer box pipe <i>new</i>	\$ 2,350.00	1532
1 pc	Rear bumper <i>new</i>	\$ 1,850.00	+
2 pc	Rear exhaust chrome tail pipe @ 185 <i>Bent</i>	\$ 370.00	24
Nett Item Total :		\$ 18,579.70	
Discount 10 %		\$ 1,857.97	
		\$ 16,721.73	

FASTECH AUTO PTE LTD

PAGE 2 OF 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 20330

Date : 04.06.2018

Vehicle Num : SFG9996T

Make/Model : BMW 523i

Chassis/Engine no :

Accident Date : 01.06.2018

Claim No : 0518-20330

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

Special Nett Item :

1 pc	Rear end panel sealant	40	\$	80.00	+
1 pc	Rear reverse camera		\$	650.00	+
8 pc	Rear bumper lower clips @ 5.00		\$	40.00	+
1 pc	Rear number plate		\$	45.00	+
Special Nett Total :				\$	815.00

Labour Charge :

To check wiring and reset		\$	450.00	50
Tuff kote	1430	\$	250.00	+
Remove and replace sensor		\$	200.00	80
Remove and replace exhaust pipe		\$	160.00	+
To remove and replace spare part and panel beating		\$	1,500.00	850
To spray painting and etc		\$	1,500.00	800
Labour Charge Total :		\$	4,060.00	

h/s Adrian Lim
04/06/18
04 Days

Total Amount : \$ 21,596.73

FASTECH AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6750.93
L/S: 54K.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18010225/AQBN2
Date: 18/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-381100-CA	Claim No:	MSC/V/18-00772
Claimant Vehicle No :	SFJ9996T	Insured Vehicle No :	FBF7670P		
Date of Loss:	01/06/2018	Nature of Claim:	TP		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFJ9996T	Engine No:	08387812N52B25AF
Make & Model:	BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Chassis No:	WBAFP32040C867126
Reg. Date:	30/09/2011 (Man. Year: 2011)	Odometer:	211012 km
Colour:	Blue		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	17,536.73	5,320.93	12,215.80	69.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	1,430.00	2,630.00	64.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,596.73	6,750.93	14,845.80	68.74
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	21,596.73	5,400.00	16,196.73	75.00
+ GST 7.00/7.00% (S\$)	1,511.77	378.00	1,133.77	75.00
Nett Amount (S\$)	23,108.50	5,778.00	17,330.50	75.00

INSPECTION

Date of Assignment:	06/06/2018	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Date Inspected:	04/06/2018 Inspected At:	

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2018)
Parts:	143	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFJ9996T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	2,650.00 FN	*1,563.00 FN
2	1		*REAR BOOT LOCK	Not Necessary	465.00 FN	*- FN
3	2		*REAR BOOT HINGE	Not Necessary	332.00 FN	*- FN
4	1		*REAR BOOT RUBBER	Necessary	295.00 FN	*295.00 FN
5	1		*REAR BOOT INNER COVER	Not Necessary	285.00 FN	*- FN
6	1		*REAR BOOT LOGO	Necessary	85.00 FN	*85.00 FN
7	1		*REAR BOOT REFLECTOR	N/s Cut	590.00 FN	*295.00 FN
8	1		*REAR BOOT OUTER HANDLE	Not Necessary	215.00 FN	*- FN
9	1		*REAR BOOT CENTRE GARNISH	Not Necessary	135.00 FN	*- FN
10	2		*REAR BOOT INNER STOPPER	Not Necessary	50.00 FN	*- FN
11	1		*REAR BOOT EMBLEM (523)	Necessary	65.00 FN	*65.00 FN
12	1		*REAR END PANEL	Repair	850.00 FN	*- FN
13	1		*REAR END PANEL TOP GARNISH	Not Necessary	188.00 FN	*- FN
14	1		*REAR TAIL LAMP	N/s Cut	1,318.00 FN	*524.00 FN
15	2		*REAR TAIL LAMP PANEL	Repair	370.00 FN	*- FN
16	1		*REAR SPARE TYRE PANEL	Not Necessary	895.00 FN	*- FN
17	1		*REAR SPARE TYRE TOP COVER BOARD	Not Necessary	495.00 FN	*- FN
18	1		*REAR SPARE TYRE TOOL TRAY	Not Necessary	215.00 FN	*- FN
19	1		*REAR LOCK ANTENNA	Not Necessary	328.00 FN	*- FN
20	1		*REAR BUMPER SIDE RETAINER	N/s Necessary	190.00 FN	*95.00 FN
21	2		*REAR BUMPER TOWING COVER	Not Necessary	70.00 FN	*- FN
22	1		*REAR BUMPER REINFORCEMENT	Bent	845.00 FN	*697.00 FN
23	1		*REAR BUMPER SENSOR (4 Pcs)	Damaged (1pc only)	940.00 FN	*235.00 FN
24	1		*REAR BUMPER CENTRE RETAINER	Cracked	250.00 FN	*98.00 FN
25	1		*REAR BUMPER REFLECTOR	N/s Missing	170.00 FN	*85.00 FN
26	2		*REAR BUMPER INNER DUST COVER	Not Necessary	170.00 FN	*- FN
27	2		*REAR FENDER INNER GARNISH	Not Necessary	770.00 FN	*- FN
28	2		*REAR FENDER DUST COVER	Not Necessary	338.00 FN	*- FN
29	1		*REAR BUMPER INNER BOOTLID KICKING UPENER MODULE	Not Necessary	342.00 FN	*- FN
30	1		*REAR BUMPER INNER CENTRE RETAINER	Cracked	98.70 FN	*98.70 FN
31	1		*SET REAR EXHAUST SILENCER BOX PIPE	Not Necessary	2,350.00 FN	*- FN
32	1		*REAR BUMPER	Deformed	1,850.00 FN	*1,532.00 FN
33	2		*REAR EXHAUST CHROME TAIL PILE	Bent	370.00 FN	*200.00 FN
34	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*REAR REVERSE CAMERA	Not Necessary	650.00 FS	*- FS
36	8		*REAR BUMPER LOWER CLIPS	Necessary	40.00 FS	*40.00 FS
37	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$) 19,394.70 5,907.70
 - Nett Item Discount on N Items 10.00/10.00% (\$\$) 1,857.97 586.77

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	17,536.73	5,320.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET	New	450.00	50.00
2	TUFF KOTE	New	250.00	-
3	REMOVE AND REPLACE SENSOR	New	200.00	80.00
4	REMOVE AND REPLACE EXHAUST PIPE	New	160.00	-
5	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	1,500.00	500.00
6	TO SPRAY PAINTING AND ETC	New	1,500.00	800.00
Gross Labour Cost (S\$)			4,060.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >