

ASS. REC. BY:

REF: CS/CTI18010255/T14d3 Special Instruction:

Surveyor: Tauheh  
From (Person): Meimen Chong Boon Sen of CTI

Date/Time: 5/6/18 @ 15.50

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBH 3651K

Insured:

at Workshop m/s

Borneo MOTOR

Tel: 9336 6875

of 2 Pandan Crescent - level 4  
Policy No: CN60012962

Claim No: SNM1800252201

Sum Insured:

Excess: \$350.00

Make of Veh:  
(Client's Record)

D.O.A. 18/05/2018

7/6/18 @ 3pm owner weibney

H.O.D. Endorsement:

CA /  REV / REP. / REV 24 HRS

Date/Time: 9:08am @ 6/6/18

Person Contacted: Sashi

Vehicle IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBH 3651K - X</u>
<u>08/6/18 @ 1.53pm</u>	<u>revert to Chong Boon Sen via Meimen.</u>
<u>12/6/18 @ 10:49am</u>	<u>authorise repair by Alfred Toh</u>
<u>12/6/18 @ 3:03pm</u>	<u>email to Sashi authorise repair excess \$350-</u>
	<u>Part by Part \$13,247- (Red: 2919.50, 18%)</u>

Tanpin

REF: CTI

ASSIGNMENT

From Date: 07/06/18

Veh No: GBH 3651K. Yr Regn: 2018 May.

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / City / Taxi / Primo Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: GBH 3651K

Make: Toyota Dyna c.c. 2982.

at Workshop m/s Borneo Motor

Colour: Si/wh A/C: Insured / Std / NI / NA

of 2penden Crescent - level 4

Sp. Reading: 841 T/Radio: Insured / Std / NI / NA

Insured.

Eng/No:

Policy No.

C/No: JTFA+35YXOK-210435

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

3pm @ owner waiting

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Sushi @ 9336 6875

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

<u>✓</u>	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 195/75R15

R: 185/R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

\$774K.

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal. 7 mm

R/Bal. 7/7 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal. 7 mm

L/Bal. 7/7 mm

Est. Repairs:

days Res.: Yes or No

D.O.A.

D.O.I. 7/6/18 @ 3pm

Lum Sum:

% 3 Val: Yes or No

Survey held at

Borneo Motor

CA /  REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt N/S

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 29 JAN 2019

*[Signature]*  
28/1/2019

Date/Time File Pass to?

: Preli. Report

Days Of Repair: 8

20/1/2019

: Final Report

Resurvey No. of Trip: 1

Date/Time File Return to?

Survey Fee:

220

Transportation

\_\_\_\_ \$ + RS \_\_\_\_ \$

Photos

Other

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

B.2471-

Add Fee:  : Site Insp (\$

: Interview (\$

: Tech. Serv (\$

: Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18010255/T1td3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 06-06-2018



Code : CTI

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBH 3651K
Policy No.	CN60012962	Coverage (\$)	0.00
Claim No.	SNM18D02522C01	Excess (\$)	350.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	06/06/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	18/05/2018	Inspection Date	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Case
Main	05 Jun 2018		05 Jun 2018 15:50 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>HMECH AUTOMATION PTE LTD</b> , Co. Reg. No.: 201409830Z		
Vehicle Reg. No.:	<b>GBH3651K</b>	Date of Loss:	18/05/2018 22:00 - :59
Claim Type:	<b>OD / SNM18D02522C01</b>	Policy/Cover Note No.:	CN60012962 (Comprehensive)
		Excess:	S\$350.00
Repairer:	<b>Borneo Motors (singapore) Pte Ltd - (pandan) (HQ)</b> Toyota Bodycare Centre, No. 2 Pandan Crescent, 128462 West Coast - Tel: 66311188		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Final Rpt due 14/06/2018</b> ]		
Driver/Custodian:	MANIKANDAN RAMALINGAM (40 / Male), NRIC: S7884813H, Tel: +6585713019		
Adj Asg. Remarks:	SURVEY REVERT		

[View All](#) [Compose Case Mail](#)

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Chong Boon Sen

---

**From:** Shashi PTCBC <Shashitharan@borneomotors.com.sg>  
**Sent:** Tuesday, 5 June, 2018 8:58 AM  
**To:** Claims Dept of CTI  
**Subject:** RE:GBH3651K OD CLAIM  
**Attachments:** SAS2409121.PDF; 05062018085451-0001.pdf  
**Importance:** High

Hi

Kindly arrange to survey the above mentioned vehicle.

Thanks  
Shashi  
Motor Claim Assessor  
D:6631 1864 | M: 9336 6875 | F:6773 3094

---

**From:** Shashi PTCBC  
**Sent:** Tuesday, June 5, 2018 8:56 AM  
**To:** Shashi PTCBC  
**Subject:** SAS2409121.PDF

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

### View Received Message

This mail is associated with :  
**\*GBH3651K (SNM18D02522C01)**  
OD  
May 18 2018 10:00PM  
[HYMECH AUTOMATION PTE LTD]  
Borneo Motors (singapore) Pte Ltd - (pandan)

- Reply
- Reply All
- Mark as Unread
- Print Message
- Delete Message
- Forward

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 12/06/2018 10:49 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$12338.60) - GBH3651K - Claim Handler: Chong Boon Sen

Approved:12338.60.

**DOCUMENTS SUMMARY**

There are no documents.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Tuesday, 12 June 2018 3:03 PM  
**To:** Shashi PTCBC  
**Cc:** Wally Tan TCBC; SUR  
**Subject:** GBH 3651K / OD / CHINA TAI PING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBH 3651K (Excess \$350/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 08 Jun 2018

**Preliminary Advice**

Vehicle No	: GBH3651K	Accident Date	: 18/05/2018
Make	: TOYOTA DYNA 150	Policy No.	: CN60012962
Assignment Date	: 05/06/2018	Excess	: S\$350.00
Date of Inspection	: 07/06/2018	Est. Duration of Repair	: 8.00
Inspection At	: BORNEO MOTORS (SINGAPORE) PTE LTD - (PANDAN) (HQ) TOYOTA BODYCARE CENTRE, NO. 2 PANDAN CRESENT SINGAPORE 128462		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,082.60
Revised Amount	:S\$	12,105.40
Check Items (Estimated)	:S\$	233.20
Total	:S\$	12,338.60
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	29,341.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,659.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

TYPE OF CLAIM:  DOD  OD/UL  DSMCA: Shunh.

## MOTOR ACCIDENT REPORT

Date Of Report: 19.05.2018 Time: 09.30 AM Date Of Accident: 18.05.2018 Time: 22.15Exact Location Of Accident: JURONG WEST STREET 93. (Near Caltex Petrol Station)Country/State of Loss: Singapore  / Wilayah Persekutuan  / Selangor Darul Ehsan  / Negeri Sembilan  / Melaka  / Pahang  /

## OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: GBH 3651K Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: 201409830ZName Of Registered Owner: HMECH AUTOMATION PTE LTDMobile Number: 85713019 Alternative No: 81612466 Email Address: SALES@HMECHAUTOMATION.COM.SG

## Vehicle Particulars

Manufacturer: Toyota  Lexus  Suzuki  Hino  Model: DYNA 150 5MTExact Purpose for which vehicle was being used at time of accident: Normal Usage  Other  (please specify):Are you claiming under your own insurance policy for repair to your vehicle? Yes  Reporting Only  Third Party Vehicle Category: Private Car  Commercial Vehicle  Others 

## Insurance Company

Name of Insurance Company: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTDType Of Coverage: Comprehensive  Third Party  Third Party Fire and/or Theft Fleet Policy: Yes  No  Policy / Cover Note No: 60012962

## DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: MANIKANDAN RAMALINGAM NRIC/ Passport / FIN No: S7884813HDate Of Birth: 31-03-1978 Occupation: Indoor  Outdoor Date Of Driving Pass: 30-03-2016 Gender: Male  Female Mobile Number: 85713019 Fax No: Alternative No:Address: BLK 90B, JURONG WEST STREET 91, #02-153, SINGAPORE Postal Code: 640905

Email Address:

Was driver an employee of the Insured's Company? Yes  No  State relationship of the driver with the insured:

Vehicle Registration Number of Driver's Own Vehicle (if applicable):

Insurance Company of Driver's Own Vehicle (if applicable):

## GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: frontal collisionNumber of Passengers in the above vehicle (Including Driver): 2 / If more than 2 Pax Please fill ANNEX B

## PASSENGER 1

Name: DEEPAN Gender: Male  Female Weather Conditions: Clear  Raining  Others  (if others, please state condition):Road Surface: Wet  Dry  Others  (if others, please state condition):Was any body injured in the Accident? No  Yes Was any injured conveyed to hospital by ambulance? No  Yes Was any foreign vehicle involved in this accident? No  Yes  Vehicle No: Vehicle type:Number of vehicles involved in the accident: 1Was there any witness? No  Yes  If yes, please furnish witness details column below

Witness Name: Contact No.: Email:

Was there any other vehicle or property damaged? No  Yes Was there any video captured by Car Camera? No  Yes  Are accident scene photos available for attachment? No  Yes Was the accident reported to the police? No  Yes  (if yes, please state which Police Station):Was notice of intended Prosecution given? No  Yes  (if yes, please state against whom):I have been approached by unknown person(s) soliciting/offering accident claims assistance. No  Yes 

## DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SLQ 2325T Vehicle Make/Model/Colour: MITSUBISHI/LANCER/RED

Details Of Properties Damage in Accident:

Vehicle Category:

Name of Driver: PARMINDER SINGHNRIC/Passport/FIN Number: S2172052F Contact Number:Address: BLK 726, JURONG WEST AVENUE 5, #06-256, SINGAPORE Postal Code: 640726Insurance Company Name: AIANature Of Damage: No. Of Passenger (Including Driver): 1

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature  
Date & Time


  
19.05.18 20:45

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel



### Sketch Plan



**Describe Circumstances of the Accident**

Driving along Junoy West St 93 the car in front  
stopped to turn into the petrol station.

I was unable to stop in time and hit the car  
at the back


**Declaration**

We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time



  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel



### MOTOR COVER NOTE

 Cover Note No : 60012962  
 Agent Code : AN0633A

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers Bureau of Singapore dated 22 February 1975, or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurer's Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule is hereby HELD COVERED under the terms of the Company usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which cases the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

### SCHEDULE

INSURED	M/S HYMECH AUTOMATION PTE LTD
MAKE/MODEL OF VEHICLE	TOYOTA DYNA150
*YEAR OF MANUFACTURE	2018
YEAR OF REGISTRATION	2018
ENGINE NO.	1KD2798654
CHASSIS NO.	JTFAT35YX0K210435
ENGINE CAPACITY/TONNAGE	1.75
TYPE OF COVER	COMPREHENSIVE
SUM INSURED	MARKET VALUE
PERIOD OF INSURANCE	FROM: 04 MAY 2018 TO: 03 MAY 2019 <i>luby</i>
EXCESS	SS 350.00
AUTOSAFE	NO
HIRE PURCHASE CO.	UNITED OVERSEAS BANK LIMITED

**I/We hereby Certify** that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Not valid unless counter signed by Authorised Agent

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.



Agent Name &amp; Date



Authorised Signatory

### PREMIUM PAYMENT WARRANTY

For Individual Customer:

Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.

For Non-Individual Customer

Please note that where the period of cover is for more than 60days, the premium in full should be paid within 60days on inception/renewal/endorsement. For all other cases, the premium in full should be paid before inception.

**\*IMPORTANT NOTICE : THIS COVER NOTE IS VALID FOR 30DAYS FROM 03-05-2018.**

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9830Z
Vehicle Details	
Vehicle No.:	GBH3651K
Vehicle to be Exported:	No
Intended De-registration Date:	08 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2798654
Chassis No.:	JTFAT35YX0K210435
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	04 May 2018
First Registration Date:	04 May 2018
Transfer Count:	1
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 May 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$29,630.00
COE Rebate Amount:	\$29,341.00
Total Rebate Amount:	<b>\$29,341.00</b>

The information contained herein is correct as at 08 Jun 2018

OK





Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

Online Service Booking ;  
 www.toyotasingapore.com.sg  
 Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462  
 Tel no. : 6631 1188

**ESTIMATE**

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	
		Document No	
		Document Date	
		0	M/S Skylink Auto Pte Ltd 21 Toh Guan Road East #01-12 Toh Guan Centre Singapore 608609  Work: 82689687
		05/06/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	TLMKY	S5	04/05/2018	GBH3651K	0	31702	:60D/GBH3651K/05061:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTFAT35YXOK210435	1KD2798654	60		Shashitharan	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:CN60012962 ACC DATE:18/05/18 DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50.100.00
2	S	BP-SUBLET CHECK WIRING AND REFOCUS HEADLAMP				✓ 169.50
3	S	BP-SUBLET R/I FRT WINDSCREEN				✓ 436.00
4	S	BP-SUBLET R/I FRT DASHBOARD TO FAC REPAIR - photo				✓ 1356.00
5	S	BP-SUBLET REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA				✓ 27123390.00
6	S	BP-SUBLET RESRPAY ACC AFF AREA				2224
7	L	BP-LPO SUPPLY REGN PLATE (PO#)				2780.00
8	L	BP-LPO SUPPLY DOOR STICKER (PO#)				80.00
9	Z	BP-SLANT SUPPLY SEALANT (NETT)				50.00
10	1	T52101-37985 BUMPER SUB-ASSY, FR	1.00	727.10		100.00
11	2	T52011-37070 ARM SUB-ASSY, FR LH	1.00	253.30		735.30
12	3	T52012-37070 ARM SUB-ASSY, FR RH	1.00	253.30		256.20
13	4	T81482-37040 COVER, FOG LAMP, LH	1.00	60.90		X 253.30
14	5	T81481-37040 COVER, FOG LAMP, RH	1.00	60.90		X 60.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3670678

TO SECURITY GUARD

3670678

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 05/06/2018  
 TIME 08:51

VEHICLE NO GBH3651K

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors**



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

**ESTIMATE**

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 120462  
Tel no.: 6631 1188

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	M/S Skylink Auto Pte Ltd 21 Toh Guan Road East #01-12 Toh Guan Centre Singapore 608609  Work: 02689687	
		Document No		
		0		
		Document Date		
		05/06/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	TLMKY	S5	KDY231R	04/05/2018	GBH3651K	0	31702 :60D/GBH3651K/05061:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTFAT35YXOK210435	1KD2798654	60		Shashitharan	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	6	T53111-37A01 B1 GRILLE, RADIATOR	1.00	577.70	584.30	577.70
16	7	T53115-37080 BRACKET, RADIATOR	1.00	24.00		24.00
17	8	T56121-25040 FRONT W/SCREEN MLDG,	1.00	309.50	313.30	309.50
18	9	T55078-37110 COVER SUB-ASSY, FR	1.00	302.20	305.90	302.20
19	0	T55700-37350 COWL ASSY	1.00	1156.70	1171.20	1156.70
20	1	T53814-37100 B1 PANEL, FR SIDE, LH	1.00	325.70	329.80	325.70
21	2	T53822-37060 BRACKET, FR FENDER,	1.00	60.30		60.30
22	3	T55738-37080 PROTECTOR, FR PANEL	1.00	88.00		88.00
23	4	T75315-37080 ORNAMENT, RADIATOR	1.00	68.50	69.30	68.50
24	5	T75311-25100 PLATE, FR NAME, NO.1	1.00	61.40	62.20	61.40
25	6	T81110-37660 HEADLAMP ASSY, RH	1.00	1145.80		1145.80
26	7	T81150-37660 HEADLAMP ASSY, LH	1.00	1145.80	1153.10	1145.80

Tanjin 97495749  
Not Authorise  
7/6/18  
Ex: to be advise -  
8 days  
Resurvey before print  
sur @ lkkauto.com.

13/6/18

15140.30  
16224.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total	15,082.60
Please acknowledge receipt of vehicle		Parts	GST 7.00%	1,055.78
		Labour	Less	0.00
		Materials		
		Lubrication/Fluid		
		Others		
			Amount Due	16,138.38

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TO SECURITY GUARD  
Acknowledged by Repairer  
DATE 05/06/2018  
TIME 08:51

PLEASE ALLOW THE UNMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO **GBH3651K**

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors**

16.166.50

3670679

3670679



Borneo Motors (Singapore) Pte Lt

Online Service Booking :  
www.toyotasingapore.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no. : 6631 1188

Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Skylink Auto Pte Ltd 21 Toh Guan Road East #01-12 Toh Guan Centre Singapore 608609 Work: 82689687	
		Document No		
		0		
		Document Date		
		11/07/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	TLMKY	S5	KDY231R 04/05/2018	GBH3651K	1	31702	60D/GBH3651K/05061
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTFAT35YXOK210435	1KD2798654	60	Shashitharan		--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:CN60012962 ACC DATE:18/05/18 DRIVE IN:04/07/18 EXCESS:\$350 DATE-IN:04/07/18 DATE SURVEY:07/06/18 NO OF REPAIR DAYS:8 BY:taufikh AUTHORIZED ON:04/07/18				50.00
2	S	BP-SUBLET CHECK WIRING AND REFOCUS HEADLAMP	A45			169.50
3	S	BP-SUBLET R/I FRT WINDSCREEN	A45			436.00
4	S	BP-SUBLET R/I FRT DASHBOARD TO FAC REPAIR	A45			1356.00
5	S	BP-SUBLET REPL ACC AFF PARTS AND PANEL	A45			2712.00
6	S	BP-SUBLET STRAIGHTEN AND REALIGN ACC AFF AREA				2224.00
7	L	BP-LPO RESRPAY ACC AFF AREA	A45			80.00
8	L	BP-LPO SUPPLY REGN PLATE (PO# )	E33			50.00
9	Z	BP-SLANT SUPPLY DOOR STICKER (PO# )	E33			100.00
10	1	T52101-37985 SUPPLY SEALANT (NETT)	1.00	735.30		735.30
11	2	T52012-37070 BUMPER SUB-ASSY, FR	1.00	256.20		256.20
12	3	T53111-37A01 B1 ARM SUB-ASSY, FR	1.00	584.30		584.30
13	4	T56121-25040 GRILLE, RADIATOR	1.00	313.30		313.30
14	5	T55078-37110 WEATHERSTRIP	1.00	305.90		305.90
		T55078-37110 COVER SUB-ASSY, FR				

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

3723131

PLEASE TEAR ALONG PERFORATED LINE

3723131

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 11/07/2018  
TIME 15:48

VEHICLE NO GBH3651K

SIGNATURE





Borneo Motors (Singapore) Pte Lt

Online Service Booking :  
www.toyotasingapore.com.sg  
Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no. 6631 1188

Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Skylink Auto Pte Ltd 21 Toh Guan Road East #01-12 Toh Guan Centre Singapore 608609 Work: 82689687
		Document No	
		0	
		Document Date	
		11/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	TLMKY S5	KDY231R	04/05/2018	GBH3651K	1	31702	:60D/GBH3651K/05061!

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTFAT35YXOK210435	1KD2798654	60	Shashitharan	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	6	T55700-37350 COWL ASSY	1.00	1171.20		1171.20
16	7	T53814-37100 B1 PANEL, FR SIDE, LH	1.00	329.80		329.80
17	8	T75315-37080 ORNAMENT, RADIATOR	1.00	69.30		69.30
18	9	T75311-25100 PLATE, FR NAME, NO.1	1.00	62.20		62.20
19	0	T81150-37660 HEADLAMP ASSY, LH	1.00	1158.10		1158.10
20	1	T88460-25211 CONDENSER ASSY	1.00	803.10		bt - 803.10
21	2	T55736-37020 REINFORCEMENT, COWL	1.00	39.00		bt - 39.00
22	3	T53898-37010 PLATE, FR PILLAR TO	1.00	11.40		dl - 11.40
23	4	T90467-08208 CLIP	2.00	2.40		nl - 4.80
24	5	T75395-37010 CLIP, OUTSIDE	2.00	6.60		nl - 13.20
25	6	T87965-37030 GROMMET, OUTER	1.00	33.70		dl - 33.70
26	7	T51211-25100 CROSSMEMBER, FRAME	1.00	178.70		bt - 178.70

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	13,247.00
	Please acknowledge receipt of vehicle	Parts 6,069.50 Labour 150.00 Materials 7,027.50 Lubrication/Fluid 0.00 Others 0.00	GST 7.00%	927.29
			Less	0.00
			Amount Due	14,174.29

3723132

PLEASE TEAR ALONG PERFORATED LINE

3723132

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 11/07/2018  
TIME 15:48

VEHICLE NO GBH3651K

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

CUSTOMER

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jun 2018		05 Jun 2018 15:50 <a href="#">Edit Adj Rpt</a>	<b>S\$13,247.00</b> <a href="#">Edit Estimates</a>	<b>S\$13,247.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	HYMECH AUTOMATION PTE LTD, Co. Reg. No.: 201409830Z		
Vehicle Reg. No.:	GBH3651K	Date of Loss:	18/05/2018 22:00 - :59 [14 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D02522C01	Policy/Cover Note No.:	CN60012962 (Comprehensive)
		Excess:	S\$350.00
Repairer:	Borneo Motors (singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent, 128462 West Coast - Tel: 66311188		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/06/2018]		
Driver/Custodian:	MANIKANDAN RAMALINGAM (40 / Male), NRIC: S7884813H, Tel: +6585713019		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>• CHINA_TAIPING (24/01/2019): Alert - Adj Mandate Approved (S\$13247.00) - GBH3651K - Claim Handler: Chong Boon...</li> <li>• CHINA_TAIPING (12/06/2018): Alert - Adj Mandate Approved (S\$12338.60) - GBH3651K - Claim Handler: Chong Boon...</li> </ul>		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													



## Claim Documents

\*GBH3651K (SNM18D02522C01)  
 OD  
 May 18 2018 10:00PM  
 [HYMECH AUTOMATION PTE LTD]  
 Borneo Motors (singapore) Pte Ltd - (pandan)

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View <input type="button" value="View in Browser"/>
<b>Assessment Reports</b>			1 per page <input type="button" value=""/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail Print
1	19/05/18 12:23	<b>Accident Statement</b>	<input type="button" value="1"/> Load HTM <input type="button" value=""/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	08/06/18 13:52	<b>Adjuster Immediate Advice</b>	<input type="button" value="1"/> Load HTM <input type="button" value=""/>
2	23/01/19 15:01	<b>Adjuster Immediate Advice</b>	<input type="button" value="1"/> Load HTM <input type="button" value=""/>
<b>Photos/Images</b>			3 per page <input type="button" value=""/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail Print
1	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
2	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
3	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
4	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
5	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
6	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
7	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
8	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
9	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
10	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
11	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
12	19/05/18 12:19	<b>Accident Scene Photo</b> [Linked Accident Report Documents]	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	08/06/18 13:41	<b>Odometer Reading</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
2	08/06/18 13:41	<b>Chassis Number</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
3	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
4	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
5	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
6	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
7	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
8	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
9	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
10	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
11	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
12	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
13	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>
14	08/06/18 13:41	<b>General View</b>	<input type="button" value="1"/> Load JPG <input type="button" value=""/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
15	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
18	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
19	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
27	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
29	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
30	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
31	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
32	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
33	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
34	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/06/18 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	23/01/19 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
63	23/01/19 14:34	<b>Reinspection Photo</b>		<input checked="" type="checkbox"/>
64	23/01/19 14:34	<b>Reinspection Photo</b>		<input checked="" type="checkbox"/>
65	23/01/19 14:34	<b>Reinspection Photo</b>		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/06/18 15:51	<b>CONTACT DETAIL</b>		
2	05/06/18 15:51	<b>REPAIR ESTIMATE</b>		
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	19/05/18 12:20	<b>Accident Sketch Plan</b> [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
2	19/05/18 12:20	<b>Common Statement</b> [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
3	19/05/18 12:20	<b>CI</b> [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
4	19/05/18 12:20	<b>Nric And Driving Licence</b> [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/06/18 13:43	<b>ESTIMATE</b>		
2	23/01/19 14:35	<b>SUPPLEMENTARY</b>		<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	1 per page	<input checked="" type="checkbox"/>
1	19/05/18 12:23	<b>Accident Statement</b>		
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
2	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
3	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
4	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
5	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
6	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
7	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
8	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
9	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
10	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
11	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
12	19/05/18 12:19	<b>Accident Scene Photo</b>		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	19/05/18 12:20	<b>Accident Sketch Plan</b>		<input checked="" type="checkbox"/>
2	19/05/18 12:20	<b>Common Statement</b>		<input checked="" type="checkbox"/>
3	19/05/18 12:20	<b>CI</b>		<input checked="" type="checkbox"/>
4	19/05/18 12:20	<b>Nric And Driving Licence</b>		<input checked="" type="checkbox"/>

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI18010255/T1TD3S2  
**Date:** 29/01/2019

### REFERENCE

Insured/Claimant: HYMECH AUTOMATION PTE LTD Policy No: CN60012962  
Date of Loss: 18/05/2018 Nature of Claim: OD Claim No: SNM18D02522C01

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH3651K** Engine No: 1KD2798654  
Make & Model: TOYOTA DYNA 150, 2.0 YY211 (M) Chassis No: JTFAT35YX0K210435  
Reg. Date: 04/05/2018 (Man. Year: 2018) Odometer: 841 km  
Colour: Silver  
Engine Capacity: 2982 cc  
Market Value/New Car Price: S\$74,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 195/75 R15 Rear Tyre Size: 155 R12(D)  
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7/7 mm  
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,092.70	6,349.50	1,743.20	21.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,131.50	6,897.50	1,234.00	15.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,224.20</b>	<b>13,247.00</b>	<b>2,977.20</b>	<b>18.35</b>
<b>- Excess (S\$)</b>	<b>350.00</b>	<b>350.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>15,874.20</b>	<b>12,897.00</b>	<b>2,977.20</b>	<b>18.75</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,111.19</b>	<b>902.79</b>	<b>208.40</b>	<b>18.75</b>
<b>Nett Amount (S\$)</b>	<b>16,985.39</b>	<b>13,799.79</b>	<b>3,185.60</b>	<b>18.75</b>

### INSPECTION

Date of Assignment: 05/06/2018  
Date Inspected: 07/06/2018 Inspected At: Borneo Motors (S) Pte Ltd  
No. 2 Pandan Crescent  
Singapore 128462  
Estimated Period of Repair: 8.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 29 Jan 2019)
<b>Parts:</b>	N/A TOYOTA DYNA 150 2.0 YY211 (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH3651K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER SUB-ASSY, FR	Bent	735.30 FS	*735.30 FS
2	1		*ARM SUB-ASSY, FR LH	Bent	256.20 FS	*256.20 FS
3	1		*ARM SUB-ASSY, FR RH	Not Necessary	253.30 FS	*- FS
4	1		*COVER, FOG LAMP, LH	Not Necessary	60.90 FS	*- FS
5	1		*COVER, FOG LAMP, RH	Not Necessary	60.90 FS	*- FS
6	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
7	1		*REGN PLATE (PO#	Bent	80.00 FS	*80.00 FS
8	1		*DOOR STICKER (PO#	Necessary	50.00 FS	*50.00 FS
9	1		*SEALANT	Necessary	100.00 FS	*100.00 FS
10	1		*GRILLE, RADIATOR	Cracked	584.30 FS	*584.30 FS
11	1		*BRACKET, RADIATOR	Not Necessary	24.00 FS	*- FS
12	1		*FRONT W/SCREEN MLDG,	Necessary	313.30 FS	*313.30 FS
13	1		*COVER SUB-ASSY, FR	Deformed	305.90 FS	*305.90 FS
14	1		*COWL ASSY	Bent	1,171.20 FS	*1,171.20 FS
15	1		*PANEL, FR SIDE, LH	Deformed	329.80 FS	*329.80 FS
16	1		*BRACKET, FR FENDER,	Not Necessary	60.30 FS	*- FS
17	1		*PROTECTOR, FR PANEL	Not Necessary	88.00 FS	*- FS
18	1		*ORNAMENT, RADIATOR	Necessary	69.30 FS	*69.30 FS
19	1		*PLATE, FR NAME, NO.1	Necessary	62.20 FS	*62.20 FS
20	1		*HEADLAMP ASSY, RH	Not Necessary	1,145.80 FS	*- FS
21	1		*HEADLAMP ASSY, LH	Cracked	1,158.10 FS	*1,158.10 FS
22	1		*CONDENSER ASSY	Bent	803.10 FS	*803.10 FS
23	1		*REINFORCEMENT, COWL	Bent	39.00 FS	*39.00 FS
24	1		*PLATE, FR PILLAR TO	Deformed	11.40 FS	*11.40 FS
25	2		*CLIP	Necessary	4.80 FS	*4.80 FS
26	2		*CLIP, OUTSIDE	Necessary	13.20 FS	*13.20 FS
27	1		*GROMMET, OUTER	Deformed	33.70 FS	*33.70 FS
28	1		*CROSSMEMBER, FRAME	Bent	178.70 FS	*178.70 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>8,092.70</b>	<b>6,349.50</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING AND REFOCUS HEADLAMP.	New	169.50	169.50
2	R/I FRT WINDSCREEN.	New	436.00	436.00
3	R/I FRT DASHBOARD TO FAC REPAIR.	New	1,356.00	1,356.00
4	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA.	New	3,390.00	2,712.00
5	RESPRAY ACC AFF AREA.	New	2,780.00	2,224.00
<b>Gross Labour Cost (S\$)</b>			<b>8,131.50</b>	<b>6,897.50</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >