



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9398T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	490.50	490.50
1	REAR BUMPER REINFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER RETAINER LH	NECESSARY	92.30	92.30
1	REAR BUMPER MUD-FLAPS LH	NOT NECESSARY	95.03	-
1	REAR BUMPER DIFFUSER	DEFORMED	558.30	558.30
1	REAR BUMPER DIFFUSER EXTENSION LH	DEFORMED	119.90	119.90
1	REAR BUMPER TOWING CAP	NOT NECESSARY	21.70	-
1	REAR BUMPER ANTENNA KEY	NOT NECESSARY	116.40	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	629.80	-
1	BOOTLID	TO REPAIR SEE LABOUR	1,113.40	-
1	BOOTLID REGISTERED GARNISH	TO REPAIR SEE LABOUR	891.20	-
1	BOOTLID EMBLEM - LOGO	NECESSARY	56.70	56.70
1	BOOTLID EMBLEM - HYBRID	NECESSARY	49.97	49.97
1	BOOTLID EMBLEM - PRIUS	NECESSARY	56.70	56.70
1	TAIL LAMP UPPER LH	NOT NECESSARY	438.10	-
1	TAIL LAMP BOTTOM LH	CRACKED	486.80	486.80
	LESS 25% DISCOUNT		-	-557.50
			5,535.60	1,672.47
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	25.00	25.00
1	REAR BUMPER REVERSE SENSOR (SN)	CUT	230.00	200.00
1	SET REAR BUMPER SCREW & GROMMET (SN)	NECESSARY	25.00	25.00
1	REAR END PANEL SCREW & GROMMET (SN)	NOT NECESSARY	25.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	BOOTLID STICKER - COMFORTDELGRO BOOKING 65521111 (SN)	NECESSARY	80.00	80.00
1	BOOTLID STICKER - APPS BOOK NOW (SN)	NECESSARY	60.00	60.00

Report Ref No. CS/AGI18010256/T1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER RUBBER PROTECTOR PAD (SN)	NECESSARY	180.00	180.00
			725.00	600.00
	LABOUR			
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF REAR END PANEL, BOOTLID AND BOOTLID REGISTERED GARNISH.		700.00	400.00
	R&R BOOTLID COMPONENTS.	NOT NECESSARY	120.00	-
	R&R SPARE TYRE BOARD / CARPET/ TRIM.		120.00	40.00
	R&R REAR WINDSCREEN UPPER & LOWER GLASS.	NOT NECESSARY	180.00	-
	CHECK WIRING AND LIGHTING SYSTEM.		80.00	30.00
	RUST PROOFING.	NOT NECESSARY	80.00	-
	RESPRAY REAR BUMPER.		250.00	200.00
	RESPRAY REAR END PANEL.	NOT NECESSARY	250.00	-
	RESPRAY BOOTLID.	NOT NECESSARY	250.00	-
	RESPRAY BOOTLID REGISTERED GARNISH.		250.00	200.00
	RESPRAY REAR DIFFUSER EXTENSION LH.		150.00	80.00
			2,430.00	950.00
GRAND TOTAL			8,690.60	3,222.47
RECOMMENDED COST OF REPAIRS				3,222.47

Report Ref No. CS/AGI18010256/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.