

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 07 Jun 2018

**Preliminary Advice**

Vehicle No	: SLK6778A	Accident Date	: 02/06/2018
Make	: HONDA VEZEL	Policy No.	: A28882518QMX
Assignment Date	: 05/06/2018	Excess	: S\$500.00
Date of Inspection	: 06/06/2018	Est. Duration of Repair	: 4.00
Inspection At	: JACK CARS ENTERPRISE PTE LTD (HQ) 61 UBI AVENUE 2, #01-20 AUTOMOBILE MEGAMART SINGAPORE 408898		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,172.81
Revised Amount	:S\$	3,568.93
Check Items (Estimated)	:S\$	555.50
Total	:S\$	4,124.43
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	49,725.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,275.00

**Remarks** ( X ) The vehicle is economical for repair. ( ) The above survey was conducted on a 'without prejudice' basis.