

ASS. REC. BY:

REF

08/CT11E010266/Kqd3

Special Instruction:

SURVEYOR
Maximen

Kenneth
Irene Tay

ASSIGNMENT (Office)

of ETI

Date/Time: 5/6/18 @ 3:38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 2522S

Insured:

PA 9006E

at Workshop n/s:

S & H Motor

Tel:

6453 4730

of

160 Ring Ming Drive # 07-02

Policy No:

DMB ISN 1740961700

Claim No:

8NM18D 02701C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

29/05/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

9:56am 06/6/18

Person Contacted:

Dumis

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (→ Estimate

XD 2522S - CC4/LPC1800 9746 / T1e a3

DOA: 29/5/2018

PA 9006E - CC4/LPC1800 9746 / T1e a3

DOA: 29/5/2018

18/10 6/12 8/11, 60d email Contact by email (Red 8 5496, 32/1)

ASS. REC. BY:

REF: CTZ/

ASSIGNMENT

Kennerh

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

16 File sent to Corbin

RECEIVED 13 OCT 2018

Date/Time, File Pass to?

11/13/10

Date/Time, File Return to?

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

8

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

: Fuel

: Others

TOTAL

Veh No:

X025225

Yr Regn:

04, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

N/S GKB4

c.c

13014

Colour:

N/A: Colour

A/C:

Insured / Std / NI / NA

Sp. Reading

439955

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

GKB4CLB. 00241

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N/A / S/Rim / STD A/Rim or

Tyre Size:

Marshal

B.S R:

295/80R22.5CD1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

99

mm

L/Bal.

7

mm

L/Bal.

mm

D.O.A.

295/80R22.5CD1

D.O.I.

6/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S 141

The U/C / Chassis frame / Body Structure affected due to collision.

Report Format:

Lump Sum / L.B.T. (\$

over TP

11600

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CT118010266/Kqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 06-06-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 9006E	Veh. Inspected	XD 2522S
Policy No.	DMB1SN1740961700	Coverage (\$)	0.00
Claim No.	SNM18D02701C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	06/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/05/2018	Inspection Date	06/06/2018
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	XD2522S
Vehicle Type:	B36 - Goods (Open) Prime Mover
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	NISSAN
Vehicle Model:	GKB45CL8HNB
Chassis No.:	GKB4CLB00241
Propellant:	Diesel
Engine No.:	GE13334816B
Engine Capacity:	13074 cc
Maximum Power Output:	-
Maximum Laden Weight:	50000 kg
Unladen Weight:	6660 kg
Year Of Manufacture:	2008
Original Registration Date:	25 Apr 2008
Lifespan Expiry Date:	24 Apr 2028
COE Category:	C - Goods Vehicle & Bus
PQP Paid:	\$18,773.00
COE Expiry Date:	24 Apr 2023
Road Tax Expiry Date:	24 Oct 2018
Inspection Due Date:	24 Oct 2018
Intended Transfer Date:	01 Jun 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

Message

This vehicle has a road tax Over Payment of \$426.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2018 17:26
Date Of Accident	29/05/2018 16:40
Exact Location Of Accident	JURONG WEST ST 76 CARPARK TOWARDS TUAS RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD2522S
Insured/Policyholder	
Name Of Registered Owner	AW TRANSPORT & WAREHOUSING PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98929531
Alternative Phone No	OFFICE-98929531

Vehicle Particulars

Manufacturer	NISSAN
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/18VC10/101630
Cover Note Number	

Driver

Name of Driver	YANG JINBIN
Work Permit No	G5379697X
Date Of Birth	29/12/1969
Occupation	OUTDOOR
Date Of Driving Pass	02/12/2014
Driving Experience	3 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98929531
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRUC/FIN No.:



TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
PECK KANG CHUA

Singapore

Claimant Insurer: Lonpac Insurance Bhd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/05/2018
Vehicle Reg. No.:	XD2522S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	YANG JINBIN		
Make/Model:	NISSAN GKB45CLBHNB, 13.1 D (A)	Vehicle Reg. Date:	25/04/2008
Vehicle Colour:	BEIGE		
Engine No:	GE13334816B	Chassis No:	GKB4CLB00241
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10 days		
Description of Accident/Loss	REFER ATTACHED REPORT.		
Present Location:	S & H MOTOR PTE LTD (SIN MING)		

Not Authorise
LI Sing 87
Resing After Point

COST OF CLAIMS	Amount
Parts	14,000.00
Miscellaneous Items	26.00
Labour	2,690.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	16,716.00
+ GST 7.00% (S\$)	1,170.12
Nett Amount (S\$)	17,886.12

This claim is handled by: MYINT MYINT THAN

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 01 Jun 2018)

Parts: N/A NISSAN GKB45CLBHNB 13.1 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: S & H Motor Pte Ltd/XD2522S/01/06/2018 16:00

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*RH OUTER MIRROR	CM	0.00	0.00 *950.00 F	
2	1		*RH OUTER MIRROR HOLDER BRECKET	R	0.00	0.00 *650.00 F	
3	1		*RH FRONT END CONNER GARNISH	CM	0.00	0.00 *450.00 F	
4	1		*RH FRONT END CONNER GARNISH RUBBER	T	0.00	0.00 *210.00 F	
5	1		*RH DOOR CUP DOOR	Bu	0.00	0.00 *1,800.00 F	
6	1		*BONNET	n	0.00	0.00 *1,350.00 F	x
7	1		*RH DOOR CUP SIGNAL LIGHT	Bu	0.00	0.00 *285.00 F	
8	1		*RH DOOR TOP HINGE	R	0.00	0.00 *380.00 F	
9	1		*RH DOOR BOMTTOM HINGE	R	0.00	0.00 *380.00 F	
10	1		*RH DOOR UD LOGO	M	0.00	0.00 *180.00 F	
11	1		*RH STEP PANEL	Di	0.00	0.00 *380.00 F	
12	1		*RH STEP PANEL METAL BRECKET	R	0.00	0.00 *220.00 F	
13	1		*RH FRONT BUMPER	R	0.00	0.00 *800.00 F	
14	1		*FRONT CENTER BUMPER	R	0.00	0.00 *980.00 F	
15	1		*RH FRONT BUMPER END GARNISH	CM	0.00	0.00 *290.00 F	
16	1		*RH FRONT BUMPER LAMP	Bu	0.00	0.00 *380.00 F	
17	1		*LH FRONT BUMPER LAMP	L	0.00	0.00 *380.00 F	x
18	1		*RH FRONT BUMPER SIGNAL LAMP	Bu	0.00	0.00 *240.00 F	
19	1		*RH HEAD LAMP	CM	0.00	0.00 *1,300.00 F	
20	1		*FRONT BUMPER CENTER TOP GARNISH	CM	0.00	0.00 *290.00 F	
21	1		*RH HEAD LAMP METAL REINFORCEMENT BRECKET (HEAD LAMP HOLDER)	R	0.00	0.00 *190.00 F	
22	1		*FRONT WINDSCREEN GLASS	CM	0.00	0.00 *1,380.00 F	
23	1		*FRONT WINDSCREEN GLASS WEATHER STRIP	Null	0.00	0.00 *350.00 F	
24	1		*RH BUMPER AND HEAD LAMP BOMTTOM GARNISH	Mr	0.00	0.00 *185.00 F	
25	1		*AIR PRESSURE PIPE	in	0.00	0.00 -	x

F=Franchise part.

Total Parts (\$\$) 14,000.00

S & H Motor Pte Ltd/XD2522S/01/06/2018 16:00. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	ERP BRECKET	26.00
Sub Total (S\$)			26.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	New	60.00
2	TO RESPRAY PAINTING THE FRONT ACCIDENT AND REPAIR AREAS.	New	850.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS	New	250.00
4	LABOUR TO CHECK AIR PRESSURE PIPE FOR AIR LECK TEST	New	180.00
5	TOWING CHARGES	New	250.00
6	LABOUR TO REMOVE DAMAGED PARTS AND JACK OUT RH DOOR CUP DOOR HINGE PILLAR, WILDING REPAIR, PANEL BEATING, REINSTALL DAMAGED PARTS AND ADJUST DOOR BUMPER AND DOOR CUP ALIGNMENT.	New	1,100.00
Gross Labour Cost (S\$)			2,690.00

S & H Motor Pte Ltd/XD2522S/01/06/2018 16:00. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
PECK KANG CHUA

Singapore

Claimant Insurer: Lonpac Insurance Bhd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/05/2018
Vehicle Reg. No.:	XD2522S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	YANG JINBIN		
Make/Model:	NISSAN GKB45CLBHNB, 13.1 D (A)	Vehicle Reg. Date:	25/04/2008
Vehicle Colour:	BEIGE	Chassis No:	GKB4CLB00241
Engine No:	GE13334816B		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10 days		
Description of Accident/Loss	REFER ATTACHED REPORT.		
Present Location:	S & H MOTOR PTE LTD (SIN MING)		

Not Notified
61 Lms & 11,600
Repair After Paint

COST OF CLAIMS

	Amount
Parts	14,000.00
Miscellaneous Items	26.00
Labour	2,690.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	16,716.00
+ GST 7.00% (S\$)	1,170.12
Nett Amount (S\$)	17,886.12

This claim is handled by: MYINT MYINT THAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 01 Jun 2018)
 Parts: N/A NISSAN GKB45CLBHNB 13.1 D (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: S & H Motor Pte Ltd/XD2522S/01/06/2018 16:00
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*RH OUTER MIRROR	CM	0.00	0.00	*950.00 F	—
2	1		*RH OUTER MIRROR HOLDER BRACKET	R	0.00	0.00	*650.00 F	—
3	1		*RH FRONT END CONNER GARNISH	CM	0.00	0.00	*450.00 F	—
4	1		*RH FRONT END CONNER GARNISH RUBBER	T	0.00	0.00	*210.00 F	—
5	1		*RH DOOR CUP DOOR	B	0.00	0.00	*1,800.00 F	—
6	1		*BONNET	n	0.00	0.00	*1,350.00 F	X
7	1		*RH DOOR CUP SIGNAL LIGHT	R	0.00	0.00	*285.00 F	—
8	1		*RH DOOR TOP HINGE	R	0.00	0.00	*380.00 F	—
9	1		*RH DOOR BOMTTOM HINGE	R	0.00	0.00	*380.00 F	—
10	1		*RH DOOR UD LOGO	M	0.00	0.00	*180.00 F	—
11	1		*RH STEP PANEL	D	0.00	0.00	*380.00 F	—
12	1		*RH STEP PANEL METAL BRACKET	R	0.00	0.00	*220.00 F	—
13	1		*RH FRONT BUMPER	R	0.00	0.00	*800.00 F	—
14	1		*FRONT CENTER BUMPER	R	0.00	0.00	*980.00 F	—
15	1		*RH FRONT BUMPER END GARNISH	CM	0.00	0.00	*290.00 F	—
16	1		*RH FRONT BUMPER LAMP	B	0.00	0.00	*380.00 F	—
17	1		*LH FRONT BUMPER LAMP	L	0.00	0.00	*380.00 F	X
18	1		*RH FRONT BUMPER SIGNAL LAMP	B	0.00	0.00	*240.00 F	—
19	1		*RH HEAD LAMP	CM	0.00	0.00	*1,300.00 F	—
20	1		*FRONT BUMPER CENTER TOP GARNISH	CM	0.00	0.00	*290.00 F	—
21	1		*RH HEAD LAMP METAL REINFORCEMENT BRACKET (HEAD LAMP HOLDER)	R	0.00	0.00	*190.00 F	—
22	1		*FRONT WINDSCREEN GLASS	CM	0.00	0.00	*1,380.00 F	—
23	1		*FRONT WINDSCREEN GLASS WEATHER STRIP	D	0.00	0.00	*350.00 F	—
24	1		*RH BUMPER AND HEAD LAMP BOMTTOM GARNISH	M	0.00	0.00	*185.00 F	—
25	1		*AIR PRESSURE PIPE	J	0.00	0.00	—	X
Total Parts (\$\$)							14,000.00	

F=Franchise part.

S & H Motor Pte Ltd/XD2522S/01/06/2018 16:00. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 ERP BRACKET

Amount

26.00

Sub Total (S\$)

26.00

Estimates on Labour

No Particulars

Labour Items

- 1 To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.
- 2 TO RESPRAY PAINTING THE FRONT ACCIDENT AND REPAIR AREAS.
- 3 TO REMOVE AND RENEW FRONT WINDSCREEN GLASS
- 4 LABOUR TO CHECK AIR PRESSURE PIPE FOR AIR LECK TEST
- 5 TOWING CHARGES
- 6 LABOUR TO REMOVE DAMAGED PARTS AND JACK OUT RH DOOR CUP DOOR HINGE PILLAR, WILDING REPAIR, PANEL BEATING, REINSTALL DAMAGED PARTS AND ADJUST DOOR BUMPER AND DOOR CUP ALIGNMENT.

Lab.Type

Amount

New

60.00 301

New

850.00 801

New

250.00 1501

New

180.00 X

New

(B711) 250.00 1201

New

1,100.00 9001

Gross Labour Cost (S\$)

2,690.00

S & H Motor Pte Ltd/XD2522S/01/06/2018 16:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

Workshop: 160 Sin Ming Drive #07-02, Sin Ming AutoCity, Sin Ming 575722. Tel: 6453 4730 Fax: 6457 1931 E-mail: shmotor@singnet.com.sg
Co. Reg. No. 196701322K GST Reg. No. N2-0076289-0

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	To advertiment front right sticker	380.00
Sub Total (S\$)			380.00

2501

Estimates on Labour

There are no labour items selected.

S & H Motor Pte Ltd/XD2522S/09/10/2018 18:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Workshop: 160 Sin Ming Drive #07-02, Sin Ming AutoCity, Sin Ming 575722. Tel: 6453 4730 Fax: 6457 1931 E-mail: shmotor@singnet.com.sg
Co. Reg. No. 138701322K GST Reg. No. M2-0075258-0

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Jun 2018 Sendback Est	01 Jun 2018 16:00 S\$16,716.00	05 Jun 2018 15:38 Edit Adj Rpt	S\$11,600.00 Edit Estimates	S\$11,600.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	09 Oct 2018 18:51	09 Oct 2018 18:53 S\$380.00	09 Oct 2018 18:53			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	PECK KANG CHUA, ID: S6800347D		
Main Claimant:	AW TRANSPORT & WAREHOUSING PTE LTD, Co. Reg. No.: -		
Vehicle Reg. No.:	XD2522S	Date of Loss:	29/05/2018 16:00 - :59 [121 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D02701C02	Policy/Cover Note No.:	DMB1SN1740961700
Vehicle Reg. No. (Insured):	PA9006E	Policy No. (Claimant):	Z/18VC10/101630
		Excess:	S\$0.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/06/2018]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

XD2522S (SNM18D02701C02)
[PA9006E]

TP
AW TRANSPORT & WAREHOUSING PTE LTD
May 29 2018 4:00PM
[PECK KANG CHUA]
S & H Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	30/05/18 17:39	Accident Statement	1	Load HTM	
2	01/06/18 16:00	Repairer Estimates	1	Load HTM	
3	09/10/18 18:53	Repairer Estimates Suppl. #1	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	30/05/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
2	30/05/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
3	30/05/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
4	30/05/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
5	30/05/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
6	30/05/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
7	30/05/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/10/18 14:45	General View	1	Load JPG	☒
2	19/10/18 14:45	General View	1	Load JPG	☒
3	19/10/18 14:45	General View	1	Load JPG	☒
4	19/10/18 14:45	General View	1	Load JPG	☒
5	19/10/18 14:45	General View	1	Load JPG	☒
6	19/10/18 14:45	General View	1	Load JPG	☒
7	19/10/18 14:45	General View	1	Load JPG	☒
8	19/10/18 14:45	General View	1	Load JPG	☒
9	19/10/18 14:45	General View	1	Load JPG	☒
10	19/10/18 14:45	General View	1	Load JPG	☒
11	19/10/18 14:45	General View	1	Load JPG	☒
12	19/10/18 14:45	General View	1	Load JPG	☒
13	19/10/18 14:45	General View	1	Load JPG	☒
14	19/10/18 14:45	General View	1	Load JPG	☒
15	19/10/18 14:45	General View	1	Load JPG	☒
16	19/10/18 14:45	General View	1	Load JPG	☒
17	19/10/18 14:45	General View	1	Load JPG	☒
18	19/10/18 14:45	Odometer Reading	1	Load JPG	☒
19	19/10/18 14:45	Chassis Number	1	Load JPG	☒
20	19/10/18 14:46	Reinspection Photo	1	Load JPG	☒
21	19/10/18 14:46	Reinspection Photo	1	Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
S & H Motor Pte Ltd (Sin Ming)					
Documentation				1 per page	☒
No	Finalized On			Thumbnail	Print
1	30/05/18 17:31	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	30/05/18 17:31	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
3	30/05/18 17:31	Sketch Plan #3 [Linked Accident Report Documents]		Load TIF	
China Taiping Insurance (Singapore) Pte. Ltd. (HQ)					
1	05/06/18 15:41	INSURED GIA REPORT		Load PDF	
LKK Auto Consultants Pte Ltd (HQ)					
1	23/10/18 10:27	SUPPLEMENTARY PART		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
S & H Motor Pte Ltd (Sin Ming)					
1	30/05/18 17:39	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On			Thumbnail	Print
S & H Motor Pte Ltd (Sin Ming)					
1	30/05/18 17:30	Accident Photo		Load JPG	☒
2	30/05/18 17:30	Accident Photo		Load JPG	☒
3	30/05/18 17:30	Accident Photo		Load JPG	☒
4	30/05/18 17:30	Accident Photo		Load JPG	☒
5	30/05/18 17:30	Accident Photo		Load JPG	☒
6	30/05/18 17:30	Accident Photo		Load JPG	☒
7	30/05/18 17:30	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On			Thumbnail	Print
S & H Motor Pte Ltd (Sin Ming)					
1	30/05/18 17:31	Sketch Plan		Load TIF	
2	30/05/18 17:31	Sketch Plan #2		Load TIF	
3	30/05/18 17:31	Sketch Plan #3		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18010266/KQD3Q2

Date: 23/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN1740961700

Claimant Vehicle No: XD2522S Insured Vehicle No: PA9006E

Date of Loss: 29/05/2018 Nature of Claim: TP Claim No: SNM18D02701C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD2522S

Make & Model: NISSAN GKB45CLBHNH, 13.1 D (A) Engine No: GE13334816B

Reg. Date: 25/04/2008 (Man. Year: 2008) Chassis No: GKB4CLB00241

Colour: Multi-colour Odometer: 459955 km

Engine Capacity: 13074 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Marshal 7 mm Rear Left Side: Bridgestone 9/9 mm

Front Right Side: Marshal 7 mm Rear Right Side: Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,000.00	12,270.00	1,730.00	12.36
Miscellaneous Items	406.00	276.00	130.00	32.02
Labour	2,690.00	2,000.00	690.00	25.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,096.00	14,546.00	2,550.00	14.92
Approved Total (Overridden) (S\$)		11,600.00		
(S\$)	17,096.00	11,600.00	5,496.00	32.15
+ GST 7.00/7.00% (S\$)	1,196.72	812.00	384.72	32.15
Nett Amount (S\$)	18,292.72	12,412.00	5,880.72	32.15

INSPECTION

Date of Assignment: 05/06/2018 Present Location: S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 06/06/2018 Inspected At: S & H Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #07-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Oct 2018)	
Parts:	N/A	NISSAN GKB45CLBHN 13.1 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD2522S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH OUTER MIRROR	Cracked	950.00 F	*950.00 F
2	1		*RH OUTER MIRROR HOLDER BRECKET	Bent	650.00 F	*650.00 F
3	1		*RH FRONT END CONNER GARNISH	Cracked	450.00 F	*450.00 F
4	1		*RH FRONT END CONNER GARNISH RUBBER	Torn	210.00 F	*210.00 F
5	1		*RH DOOR CUP DOOR	Buckled	1,800.00 F	*1,800.00 F
6	1		*BONNET	Repair	1,350.00 F	*- F
7	1		*RH DOOR CUP SIGNAL LIGHT	Broken	285.00 F	*285.00 F
8	1		*RH DOOR TOP HINGE	Bent	380.00 F	*380.00 F
9	1		*RH DOOR BOMTTOM HINGE	Bent	380.00 F	*380.00 F
10	1		*RH DOOR UD LOGO	Necessary	180.00 F	*180.00 F
11	1		*RH STEP PANEL	Distorted	380.00 F	*380.00 F
12	1		*RH STEP PANEL METAL BRECKET	Bent	220.00 F	*220.00 F
13	1		*RH FRONT BUMPER	Bent	800.00 F	*800.00 F
14	1		*FRONT CENTER BUMPER	Bent	980.00 F	*980.00 F
15	1		*RH FRONT BUMPER END GARNISH	Cracked	290.00 F	*290.00 F
16	1		*RH FRONT BUMPER LAMP	Broken	380.00 F	*380.00 F
17	1		*LH FRONT BUMPER LAMP	Serviceable	380.00 F	*- F
18	1		*RH FRONT BUMPER SIGNAL LAMP	Broken	240.00 F	*240.00 F
19	1		*RH HEAD LAMP	Cracked	1,300.00 F	*1,300.00 F
20	1		*FRONT BUMPER CENTER TOP GARNISH	Cracked	290.00 F	*290.00 F
21	1		*RH HEAD LAMP METAL REINFORCEMENT BRECKET (HEAD LAMP HOLDER)	Bent	190.00 F	*190.00 F
22	1		*FRONT WINDSCREEN GLASS	Cracked	1,380.00 F	*1,380.00 F
23	1		*FRONT WINDSCREEN GLASS WEATHER STRIP	Dented / Cut	350.00 F	*350.00 F
24	1		*RH BUMPER AND HEAD LAMP BOMTTOM GARNISH	Missing	185.00 F	*185.00 F
25	1		*AIR PRESSURE PIPE (NPA)	Serviceable	-	*- F

F=Franchise part.

Total Parts (S\$) 14,000.00 12,270.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	ERP BRECKET (NECESSARY)	26.00	26.00
Supplementary #1				
2	1	To advertiment front right sticker	380.00	250.00
Sub Total (S\$)			406.00	276.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	New	60.00	30.00
2	TO RESPRAY PAINTING THE FRONT ACCIDENT AND REPAIR AREAS.	New	850.00	800.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS	New	250.00	150.00
4	LABOUR TO CHECK AIR PRESSURE PIPE FOR AIR LECK TEST	New	180.00	0.00
5	TOWING CHARGES	New	250.00	120.00
6	LABOUR TO REMOVE DAMAGED PARTS AND JACK OUT RH DOOR CUP DOOR HINGE PILLAR, WILDING REPAIR, PANEL BEATING, REINSTALL DAMAGED PARTS AND ADJUST DOOR BUMPER AND DOOR CUP ALIGNMENT.	New	1,100.00	900.00
Gross Labour Cost (S\$)			2,690.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >