

ASS. REC. BY:

REF: CS/MSG180 10267/Atd3/4

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSG

Date/Time:

05/06/18 @ 5.54pm

Estimated Cost:

Bill to:

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SGW 8500S

Insured:

SJP 121G

at Workshop m/s

Success United

Tel:

9223 6288

of

2 Kaki Bkt Ave 2 # 01-33

Policy No.:

A28738402QMX

Claim No.:

560239

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.:

01/06/2018

CA / REV / REP. / REV 24 HRS

Cup)

H.O.D. Endorsement:

Date/Time:

10.06am @ 6/6/18

Person Contacted:

Irina

Vehicle  IN  OUT

Date/Time

Action/Instruction

(✓) Estimate

SGW 8500S-x

SJP 121G-x

08/6/18 @ Hair informed Lionel Tan, we are pending estimate from repairer.

Lump Sum \$11,600 - (Red: 17947.94 (60%))

REF: MS1G

ASSIGNMENT

From: Date: 6/6/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGW 8500S

at Workshop n/s: Success United

at 2 Kaki Bkt Ave 2 #01-33

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS <sup>lup</sup>

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGW8500S Yr Regn: 2010 May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 523i cc 2497

Colour: Black A/C Insured / Std / NI / NA

Sp Reading: 132412 T/Radio: Insured / Std / NI / NA

Eng No:

C/No: WBAFP32050CS44008

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17

R: 225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. D.O.I: 06/06/18

Survey held at: Success United

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction TP MS1G

MV: 50K PV: 29.1K Netf: 20.9K

RECEIVED 12 JUL 2018

117 - Adrian say part price checked.

Date/Time File Pass to?  Prel. Report

127 Typist  Final Report

Date/Time File Return to?

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee

Transportation

Add Fee:  Site Insp (\$)

Interview (\$)

Tech. trvs (\$)

Workshop (\$)

1.3 + PC \$

1. Phone

1. Other

Report Format: TP

Lump Sum / I.B.F: 11,600

TOTAL





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18010267/Atd3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 06-06-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 121G	Veh. Inspected	SGW 8500S
Policy No.	A28738402QMX	Coverage (\$)	0.00
Claim No.	560239	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	06/06/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	01/06/2018	Inspection Date	06/06/2018
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/06/2018 12:13
Date Of Accident	01/06/2018 10:05
Exact Location Of Accident	BRADDELL ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGW8500S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG ENG HUAT
NRIC No	S8026179I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88389196
Alternative Phone No	OFFICE-88389196

### Vehicle Particulars

Manufacturer	BMW
Model	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091869407 CLASSIC

Cover Note Number


### Driver

Name of Driver	NG ENG HUAT
NRIC No	S8026179I
Date Of Birth	25/08/1980
Occupation	INDOOR
Date Of Driving Pass	01/08/2000
Driving Experience	17 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88389196
Fax Number	
Contact Number	OFFICE-88389196
Email Address	NOEMAIL

Vehicle Make/Model/Colour	LEXUS GS300
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

- A) SGW 85005
- B) SJP 121G
- C) SFS 1089S



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AT 1005AM ON 1ST JUNE 2018, MY CAR SGW85005 WAS TRAVELING ON BRADDELL RD RIGHT LANE.

WHEN I STOP MY CAR DUE TO THE CAR STOP, THE CAR BEHIND HIT ME, CAUSING MY CAR TO HIT THE FRONT CAR.

THE CAR BEHIND IS A WHITE HONDA CIVIC SJP121G.

PROVIDING VIDEO AS EVIDENCE.

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature  
Date & Time: 1 JUN 2018

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

IDAC KAKI BUKIT (VAL),  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature  
Name:  
NIC/PIK No.:

ASK • DISCUSS  
LEARN • SHARE

- 2017 2nd Generation Mazda CX-5
- Exercising and losing weight
- Taxis - High mileage, but still running well

**FOR SALE BY OWNER**

**Post an Advertisement**  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

**New 5 Years Coe Renewal Honda Stream 1.8A R5Z**

\$2800 Downpayment Monthly From \$738 Onwards. Lowest 3.68%PA @GV Cars Financing

[View Details](#)

**CERTIFIED PRE-OWNED MERCEDES-BENZ**

[View our cars](#)

Browse by Category Save Search Print
Sort by Date Posted | 20 results/page

31 vehicles | **Search**  Advanced Search | Search | View All

| 
  | 
  | 
  | 
  | 
  | 
  | 
  |

Search Selection	5 Series 523i	Any	Any	2010	Any	Any	Any	Available
------------------	---------------	-----	-----	------	-----	-----	-----	-----------

**BMW 5 Series 523i** | **\$49,777** | **\$15,370 /yr** | **18-May-2010** | **2,497 cc** | **-** | **Luxury** | **Available**

Luxurious & Sporty 523i Executive Sedan, For Your True Driving Pleasure! At Affordable Price. Nice Bidded Plate. New Road Tax. Regularly Serviced. Pristine Condition. For That Responsive, Smooth And Q...

Posted: 03-Jun-2018 | Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i** | **\$48,800** | **\$14,520 /yr** | **18-May-2010** | **2,497 cc** | **-** | **Luxury** | **Available**

Guaranteed Lowest Price And Best Condition In Market! Well Maintained, Highest Trade In With Lowest In House Interest Easy Loan, 1 Year Warranty Comes With 3 Free Servicing! \$3k Deposit, Low Down Paym...

Posted: 19-May-2018 | Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i** | **\$51,300** | **\$15,760 /yr** | **20-May-2010** | **2,497 cc** | **118,000 km** | **Luxury** | **Available**

Well Maintained By Fussy Owner, Excellent Condition, Accident Free, In House Loan Available With Fast Approval. Attractive Interest Rate, Up To 80% To 90% Loan Approval. Lowest Price In The Market. No...

Think One Automobile & Trading

Posted: 25-May-2018 | Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i** | **\$51,888** | **\$16,400 /yr** | **20-May-2010** | **2,497 cc** | **64,800 km** | **Luxury** | **Available**

Low Mileage Done! Agent Unit! Beautiful Interior, Very Well Maintained, Flexible In House Loan And Trade In Available! Call Now To View!

Posted: 08-May-2018 | Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

[Car Buying](#) | 
 [Car Selling](#) | 
 [Car Ownership](#) | 
 [Car Aftermarket](#) | 
 [On The Move](#) | 
 [Lifestyle](#)

**TYREPAC**

Buy Tyres Online!  
Latest Special Offers from Tyrepac

**BMW 5 Series 523i** | **\$48,822** | **\$14,630 /yr** | **21-May-2010** | **2,497 cc** | **123,500 km** | **Luxury** | **Available**

Latest Addition! 1 Single Owner Only. Low Mileage Done 15k KM Per Annum. Accident Free Unit. Agent PML Unit. Best Selling BMW Luxury Executive Sedan In Singapore. Very Responsive Engine, Very Smooth D...

Posted: 24-Apr-2018 | Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i** | **\$48,900** | **\$13,450 /yr** | **24-May-2010** | **2,497 cc** | **125,050 km** | **Luxury** | **Available**

New Facelift, PML Service, New 18" Tyres.

Posted: 02-Jun-2018 | Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i** | **\$52,000** | **\$15,990 /yr** | **26-May-2010** | **2,497 cc** | **124,384 km** | **Luxury** | **Available**

Purchased And Serviced By My PML. Silver With Black Interior. View By Appointment. Road Tax Renewed And New Tyres.

Posted: 02-Jul-2018 | Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i** | **\$47,800** | **\$14,260 /yr** | **27-May-2010** | **2,497 cc** | **110,000 km** | **Luxury** | **Available**

PML Unit. Best Price In Market. 1 Owner. High Loan Available, Trade In Welcome. Comes With Warranty And Servicing Package. Free Car Recording Camera Worth \$1K From BMW. Call Now For Viewing



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	61791
Vehicle Details	
Vehicle No.:	SGW85005
Vehicle to be Exported:	Yes
Intended De-registration Date:	07 Jun 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	10047394N52B25AF
Chassis No.:	WBAFP32050C544008
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$38,510.00
Original Registration Date:	31 May 2010
First Registration Date:	31 May 2010
Transfer Count:	2
Actual ARF Paid:	\$38,510.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2020
PARF Rebate Amount:	\$21,180.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$43,003.00
COE Rebate Amount:	\$7,914.00
<b>Total Rebate Amount:</b>	<b>\$29,094.00</b>

The information contained herein is correct as at 07 Jun 2018

OK

**Shiau Chan (LKKAuto)**

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Friday, 8 June 2018 11:00 AM  
**To:** do-not-reply@merimen.com  
**Cc:** SUR  
**Subject:** VEHICLE SGW 8500S (YOUR REF: 560239)

This mail is associated with :

**\*SGW8500S (560239)**

**[SJP121G]**

TP

NG ENG HUAT

Jun 1 2018 10:00AM

[LAU YEW HOONG]

Success United Pte Ltd

Dear Lionel,

Please be informed that we have inspected the vehicle SGW 8500S on 06/06/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms) on behalf of Denise

LKK Auto Consultants Pte Ltd

Tel :6256 1161

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

Estimate : **TP/18-068**

M/s **MSIG Insurance (Singapore) Pte Ltd**  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Date : 5th June 2018

Vehicle No : **SGW 8500S**  
Make/ Model : BMW 523i  
Chassis No : WBAFP32050C544008  
Acc. Date : 01.06.18  
Policy No :

Attn : Motor Claim

*Denise*

Tel: 68277888

Fax: 62257402

Email: [claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)

Your Ref : SJP 121G

S/n.	Qty	Particulars	Unit Price	Amount
<u>Materials</u>				
1	1 pc	Rear Boot Lid <i>Buckled</i>		\$ 1,856.30 ✓ 1563
2	1 pc	Rear Boot Weatherstrip <i>cut</i>		\$ 251.52 ✓
3	1 pc	Rear Boot Mechanism Lock <i>change</i>		\$ 542.35 ✓ 358.
4	1 pc	Rear Boot Lid 523i Emblem <i>free</i>		\$ 82.66 ✓
5	1 pc	Rear Boot Lid BMW Logo		\$ 79.50 ✓
6	2 pc	Rear Boot Lamp L/R <i>cutted</i>	\$ 638.00	\$ 1,276.00 ✓ 609.20
7	2 pc	Rear Boot Lid Hinge L/R <i>new</i>	\$ 113.65	\$ 227.30 ✓
8	1 pc	Rear Boot Lid Motor <i>new</i>		\$ 685.65 ✓
9	2 pc	Rear Lamp L/R <i>cutted</i>	\$ 672.52	\$ 1,345.04 ✓ 1058
10	1 pc	Rear Bumper <i>disturbed</i>		\$ 1,576.80 ✓ 1532
11	12 pc	Rear Bumper Clips <i>new</i>	\$ 5.00	\$ 60.00 ✓ 30
12	2 pc	Rear Bumper Side Holder L/R <i>new</i>	\$ 214.55	\$ 429.10 ✓ 196.60
13	1 pc	Rear Bumper Lower Diffuser <i>disturbed</i>		\$ 550.72 ✓
14	1 pc	Rear Bumper Tow Hook Cover <i>missing</i>		\$ 64.54 ✓
15	1 pc	Rear Bumper Inner Sponge <i>new</i>		\$ 80.35 ✓
16	1 pc	Rear Bumper Reinforcement <i>best</i>		\$ 947.52 ✓ 696.
17	2 pc	Rear Bumper Reflector Lamp L/R <i>new</i>	\$ 53.20	\$ 106.40 ✓
18	4 pc	PDC Reverse Sensor <i>2 pieces damaged</i>	\$ 268.53	\$ 1,074.12 ✓ 500.
19	1 pc	Rear Bumper Bracket <i>new</i>		\$ 76.53 ✓
20	1 pc	Rear End Panel <i>disturbed</i>		\$ 978.80 ✓
21	1 pc	Rear End Panel Inner Top Garnish <i>del</i>		\$ 211.30 ✓
22	1 pc	Rear Spare Tire Panel <i>repair</i>		\$ 2,839.30 ✓
23	1 pc	Rear Spare Tire Trim Board <i>del</i>		\$ 1,010.40 ✓ 608.
24	1 pc	Rear Spare Tire Inner Tray <i>new</i>		\$ 159.31 ✓
25	1 pc	Rear Spare Tire Undershield <i>new</i>		\$ 767.56 ✓ 75
26	10 pc	Rear Undershield Clip <i>new</i>	\$ 6.00	\$ 60.00 ✓ 30
27	1 pc	Rear Exhaust Silencer Box <i>best</i>		\$ 1,526.10 ✓ 1379
28	1 pc	Rear Exhaust Box Bush <i>new</i>		\$ 59.12 ✓
29	1 pc	Rear Exhaust Aluminium Shield <i>new</i>		\$ 183.51 ✓
30	1 pc	Rear Exhaust End Chrome Pipe <i>missing</i>		\$ 250.55 ✓
31	1 pc	Rear Fender Inner Upholstry LH <i>new</i>		\$ 218.20 ✓
32	1 pc	Driver Seat Headrest <i>new</i>		\$ 721.20 ✓
33	1 pc	Passenger Seat Headrest <i>new</i>		\$ 721.20 ✓
34	1 pc	SRS Sensor <i>new</i>		\$ 418.31 ✓
35	1 pc	SRS Module ECU <i>new</i>		\$ 788.54 ✓
				\$ 22,225.80
Less 5% :				\$ 1,111.29
S/Nett :				\$ 55.00 ✓
Total Parts :				\$ 21,169.51



聯成汽車維修

**SUCCESS UNITED PTE LTD**

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg Co. / GST Reg: 200402570G

Labour

- 1 To remove, rearrange electrical wirings, check lightings
- 2 To remove, instal upholstery, inner trim garnishes.
- 3 To remove, replace exhaust silencer, re-align pipe line.
- 4 To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.
- 5 To putty and respray painting on affected area.
- 6 Reset SRS re-program ECU
- 7 Respray tuff kote
- 8 Recoating of NANO sealant.

2960

\$ 180.00 30  
 \$ 320.00 100  
 \$ 280.00 100  
 \$ ~~3,500.00~~ 1200  
 \$ 1,800.00 1000  
 \$ 300.00 150  
 \$ 280.00 80  
 \$ 380.00 300

Total Labour : \$ 7,040.00

**Total Parts & Labour : \$ 28,209.51**



Success United Pte Ltd

No of Days \_\_\_\_\_

Re-Survey Before/After Paint  
 Part By Part/Lump Sum

Surveyed By \_\_\_\_\_ Contact No. \_\_\_\_\_

Date of Survey \_\_\_\_\_ Fax No. \_\_\_\_\_

NOTE: LUMP SUM WILL BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

Adrian hiny  
 w/s 06/06/18

OT Days:

Supplementary: 106903.

total 14578.77

w/s : 11.61c

29,547.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_



聯成汽車維修

**SUCCESS UNITED PTE LTD**

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg Co. / GST Reg: 200402570G

Supplementary : TP/18-068

M/s **MSIG Insurance (Singapore) Pte Ltd**  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Date : 13th June 2018

Attn : Motor Claim

Vehicle No : **SGW 8500S**  
Make/ Model : BMW 523I  
Chassis No : WBAFP32050C544008  
Acc. Date : 01.06.18  
Policy No :

Tel: 68277888

Fax: 62257402

Email: [claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)

Your Ref : SJP 121G

S/n.	Qty	Particulars	Unit Price	Amount
<u>Materials</u>				
1	1 pc	Rear Brake Module <i>cracked.</i>		\$ 1,138.57
2	1 pc	Rear Bumper Reinforcement Cover <i>crack'd</i>		\$ 75.00
3	1 pc	Rear Bumper Inner Frame <i>cracked.</i>		\$ 195.30
				\$ 1,408.87
Less 5%				\$ 70.44
<b>Total</b>				<b>\$ 1,338.43</b>

855  
1125.30  
1069.03

Success United Pte Ltd

Supplementary : ~~188843~~ 1069.03

## ...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jun 2018		05 Jun 2018 17:54 <a href="#">Edit Adj Rpt</a>	<b>S\$11,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$11,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	LAU YEW HOONG, ID: S12832071, Tel: +6597505749								
Main Claimant:	NG ENG HUAT, ID: S80261791								
Vehicle Reg. No.:	SGW8500S	Date of Loss:	01/06/2018 10:00 - :59 [96 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 560239	Policy/Cover Note No.:	A28738402QMX (Comprehensive) Coverage: 28/05/2018 - 27/05/2019						
Vehicle Reg. No. (Insured):	SJP121G	Policy No. (Claimant):							
		Excess:	S\$700.00						
Repairer:	Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub, 417921 Kaki Bukit - Tel: 6746 1515								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pel - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Imm.Advice due 06/06/2018]								
Driver/Custodian (Insured):	IAU WEN HONG, RUSSELL DAVE (33 / Male), NRIC: S8426832A, Tel: +6597597221								
Adj Asg. Remarks:	on WP. SJE - AGREED ( CAR IN ) Please appoint LKK AUTO CONSULTANTS to conduct the survey and Kindly contact SIRINA SOON @ 9223 6288 . Liability : Clear								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• MSIG_LTTP (12/07/2018): Final Report - SGW 8500S (YOUR REF: 560239)									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGW8500S (560239)  
[SJP121G]  
TP  
NG ENG HUAT  
Jun 1 2018 10:00AM  
[LAU YEW HOONG]  
Success United Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="button" value="Print"/>
1	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
2	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
3	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
4	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
5	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
6	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
7	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
8	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
9	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
10	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
11	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
12	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
13	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
14	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
15	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
16	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
17	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
18	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
19	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
20	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
21	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
22	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
23	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
24	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
25	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
26	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
27	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
28	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
29	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
30	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
31	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
32	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
33	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
34	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
35	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
36	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
37	11/07/18 13:55	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/07/18 13:55	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/07/18 13:55	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/07/18 13:55	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/07/18 13:55	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/07/18 13:55	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/07/18 13:55	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/07/18 13:55	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/07/18 13:55	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	12/07/18 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
89	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
90	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
91	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
92	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
93	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
94	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
95	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
96	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
97	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
98	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
99	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
100	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
101	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
102	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
103	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
104	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
105	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
106	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
107	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
108	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
109	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
110	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
111	12/07/18 16:18	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/06/18 09:16	OI SJP121G GIA REPORT		Load PDF <input type="checkbox"/>
2	05/06/18 09:16	TPD SGW8500S GIA REPORT		Load PDF <input type="checkbox"/>
3	05/06/18 11:12	Reply email from TP & appoint LKK AUTO		Load PDF <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/07/18 17:19	SUPPLEMENTARY PART		Load PDF <input type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010267/ATD3Q2

Date: 12/07/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28738402QMX
Claimant Vehicle No :	SGW8500S	Insured Vehicle No :	SJP121G
Date of Loss:	01/06/2018	Nature of Claim:	TP
		Claim No:	560239

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGW8500S		
Make & Model:	BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Engine No:	10047394N52B25AF
Reg. Date:	31/05/2010 (Man. Year: 2010)	Chassis No:	WBAFP32050C544008
Colour:	Black	Odometer:	132412 km
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	22,507.94	11,618.78	10,889.16	48.38	
Miscellaneous Items	0.00	0.00	0.00		
Labour	7,040.00	2,960.00	4,080.00	57.95	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>29,547.94</b>	<b>14,578.78</b>	<b>14,969.16</b>	<b>50.66</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>11,600.00</b>			
	(S\$)	29,547.94	11,600.00	17,947.94	60.74
	+ GST 7.00/7.00% (S\$)	2,068.36	812.00	1,256.36	60.74
	<b>Nett Amount (S\$)</b>	<b>31,616.30</b>	<b>12,412.00</b>	<b>19,204.30</b>	<b>60.74</b>

## INSPECTION

Date of Assignment:	05/06/2018	
Date Inspected:	06/06/2018 Inspected At:	Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	7.0 days	

---

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2018)
<b>Parts:</b> 143	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGW8500S)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	1,856.30 FL	*1,563.00 FL
2	1		*REAR BOOT WEATHERSTRIP	Cut	251.52 FL	*251.52 FL
3	1		*REAR BOOT MECHANISM LOCK	Damaged	542.35 FL	*358.00 FL
4	1		*REAR BOOT LID 523I EMBLEM	Necessary	82.66 FL	*82.66 FL
5	1		*REAR BOOT LID BMW LOGO	Necessary	79.50 FL	*79.50 FL
6	2		*REAR BOOT LAMP L/R	Cracked	1,276.00 FL	*609.80 FL
7	2		*REAR BOOT LID HINGE L/R	Not Necessary	227.30 FL	*- FL
8	1		*REAR BOOT LID MOTOR	Not Necessary	685.65 FL	*- FL
9	2		*REAR LAMP L/R	Cracked	1,345.04 FL	*1,058.00 FL
10	1		*REAR BUMPER	Distorted	1,576.80 FL	*1,532.00 FL
11	12		*REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
12	2		*REAR BUMPER SIDE HOLDER L/R	Necessary	429.10 FL	*196.60 FL
13	1		*REAR BUMPER LOWER DIFFUSER	Distorted	550.72 FL	*550.72 FL
14	1		*REAR BUMPER TOW HOOK COVER	Missing	64.54 FL	*64.54 FL
15	1		*REAR BUMPER INNER SPONGE	Not Necessary	80.35 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	947.52 FL	*696.00 FL
17	2		*REAR BUMPER REFLECTOR LAMP L/R	Not Necessary	106.40 FL	*- FL
18	4		*PDC REVERSE SENSOR	Damaged (2 PCS ONLY)	1,074.12 FL	*500.00 FL
19	1		*REAR BUMPER BRACKET	Not Necessary	76.53 FL	*- FL
20	1		*REAR END PANEL	Distorted	978.80 FL	*978.80 FL
21	1		*REAR END PANEL INNER TOP GARNISH	Deformed	211.30 FL	*211.30 FL
22	1		*REAR SPARE TIRE PANEL	Repair	2,839.30 FL	*- FL
23	1		*REAR SPARE TIRE TRIM BOARD	Deformed	1,010.40 FL	*608.00 FL
24	1		*REAR SPARE TIRE INNER TRAY	Not Necessary	159.31 FL	*- FL
25	1		*REAR SPARE TIRE UNDERSHIELD	Torn	767.56 FL	*75.00 FL
26	10		*REAR UNDERSHIELD CLIP	Necessary	60.00 FL	*30.00 FL
27	1		*REAR EXHAUST SILENCER BOX	Bent	1,526.10 FL	*1,379.00 FL
28	1		*REAR EXHAUST BOX BUSH	Not Necessary	59.12 FL	*- FL
29	1		*REAR EXHAUST ALUMINIUM SHIELD	Not Necessary	183.51 FL	*- FL
30	1		*REAR EXHAUST END CHROME PIPE	Missing	250.55 FL	*250.55 FL
31	1		*REAR FENDER INNER UPHOLSTRY LH	Not Necessary	218.20 FL	*- FL
32	1		*DRIVER SEAT HEADREST	Not Necessary	721.20 FL	*- FL
33	1		*PASSENGER SEAT HEADREST	Not Necessary	721.20 FL	*- FL
34	1		*SRS SENSOR	Not Necessary	418.31 FL	*- FL
35	1		*SRS MODULE ECU	Not Necessary	788.54 FL	*- FL
36	1		*REAR NO PLATE W/FRAME	Not Necessary	55.00 FS	*- FS
37	1		*REAR BRAKE MODULE	Cracked	1,138.57 FL	*855.00 FL
38	1		*REAR BUMPER REINFORCEMENT COVER	Cracked	75.00 FL	*75.00 FL
39	1		*REAR BUMPER INNER FRAME	Cracked	195.30 FL	*195.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
<small>F=Franchise part. S=SpcNett. L=ListItemDisc</small>							
					<b>Sub Total (\$)</b>	<b>23,689.67</b>	<b>12,230.29</b>
					<b>- List Item Discount on L Items 5.00/5.00% (\$)</b>	<b>1,181.73</b>	<b>611.51</b>
					<b>Total Parts (\$)</b>	<b>22,507.94</b>	<b>11,618.78</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTINGS	New	180.00	30.00
2	TO REMOVE ,REINSTAL UPHOLSTERY ,INNER TRIM GARNISHES	New	320.00	100.00
3	TO REMOVE, REPLACE EXHAUST SILENCER ,RE-ALIGN PIPE LINE	New	280.00	100.00
4	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	3,500.00	1,200.00
5	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,800.00	1,000.00
6	RESET SRS RE-PROGRAM ECU	New	300.00	150.00
7	RESPRAY TUFF KOTE	New	280.00	80.00
8	RECOATING OF NANO SEALANT	New	380.00	300.00
<b>Gross Labour Cost (S\$)</b>			<b>7,040.00</b>	<b>2,960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >