

Signature: *[Signature]*

REF:

CC3/MS618010272/R1thn2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SLX 4375Z

Policy No. 29077442QMY

Claims No. 559945

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 601K

Yr Regn: 2015 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIUS

C.C. 1798

Colour:

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

344684

T/Radio: Insured / Std / NI / NA

Eng/No:

350KN 364805 758743

C/No:

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

28/05/18

D.O.I.

01/06/18

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/A

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHB 601K - NS / INC 1600076 / K1th302

09/07/2016

05/18/2135

SLX 4375Z - X

06/6/18 @ 3:36pm Reused to Email: GIA, estimate to Catherine Thia to Margaret MS14

Lump Sum.

\$3,000/- (Red: 4785.60 59.9%) SLX 4375Z

RECEIVED 04 JUL 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 317 Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos:

) Others:

TOTAL

150

10

160

Report Format :

Lump Sum / I.B.I. (\$

TP

3000/-

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 6 June 2018 3:26 PM  
**To:** Catherine Thia; Margaret Loh  
**Cc:** KKLau; SUR; Accounts (LKKAUTO)  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD (TP VEHICLE: SHB 601K, INSURED VEHICLE: SLX 4375Z, DOA: 28-05-2018)  
**Attachments:** CC3MSG18010272R1tb.pdf; SHB601 EST.pdf; SHB601 GIA.pdf

Dear Catherine and Margaret,

Please be informed that we had inspected the vehicle **SHB 601K** at M/s: **SMRT AUTOMOTIVE SERVICES PTE LTD**, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705

Enclosed herewith a copy of TP's GIA report and estimate.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: Please advise

Date: 06<sup>th</sup> June 2018

Our Ref: CC3/MSG18010272/R1tb

The Motor Claims Department  
MSIG Insurance Singapore Pte Ltd

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SHB 601K**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/06/2018 at the premises of M/s SMRT and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,485.60</u>
Revised Estimate Amount	: S\$ <u>3,431.95</u>
"Check" Items Amount	: S\$ <u>235.45</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Comments/ Present Status:

Damages consistent.

We have not authorized repair.

Yours faithfully

Rasul  
Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/05/2018 15:48
Date Of Accident	28/05/2018 19:05
Exact Location Of Accident	MARINA BLVD TOWARDS ECP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB601K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

### Driver

Name of Driver	CHIA KOK KEONG
NRIC No	S1346518E
Date Of Birth	07/11/1959
Occupation	OUTDOOR
Date Of Driving Pass	01/01/2000
Driving Experience	18 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	08-3029
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 28/5. @1905HRS, I WAS DRIVING SHB601K STOPPED AT MARINA BLVD TOWARDS ECP. WHEN THE LIGHTS TURNED GREEN, I JUST MOVED AND PREPARED TO TURN LEFT INTO ECP, SUDDENLY A VEHICLE SLX4375Z SWERVED TO MY PATH AND GRAZED ONTO MY FRONT RIGHT SIDE. THE VEHICLE SLX4375Z SWERVED AT A VERY FAST SPEED AND COLLIDED ONTO MY RFONT SIDE

#### Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX4375Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

### SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time: 

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 30/5/18 1555 hrs

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Accident Sketch Plan Pg. 1



On 28/5 @ 1905hrs I driving SHB601K stopped at Marina Blvd X ECP.

when the lights turned green, I just moved and prepared to turn left into ECP, Suddenly a vehicle SLX4375Z ~~swerved~~ <sup>swerved</sup> onto my path and grazed onto my front right side. The Vehicle SLX4375Z swerved <sup>at a</sup> very fast speed and Collided my front right side.

Date



## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB601K  
Ref. No : TAX/05/18/2135  
Reg. Date : 02/03/2015  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS  
Name of Driver : CHIA KOK KEONG  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 28/05/2018 07:05:00 PM  
Accident Reported Date / Time : 30/05/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by :  
Vehicle is Towed Back? : Yes  
Towed Back Date/Time : 31/05/2018  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024096374  
Special Instruction to ARC, if any :  
TOWED \$110 / SLX4375Z / *mish / Resumy after repair*  
Prepared Date : 01/06/2018 09:25:52 AM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U805758743

Mileage

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	0.00
Total Spray Painting Charges	: 1,116.00	0.00
Total Material Charges	: 3,228.68	3,294.58
Other Charges	: 494.00	0.00
<b>TOTAL</b>	<b>: 5,514.68</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 5,500.00</b>	<b>0.00</b>
No. of Repair Days	: 5.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 01/06/2018 11:46:01 AM	01/01/1900 12:00:00 AM



4 days - 4/3

01/06/18 @1430

Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/06/2018 11:46:02 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	676.00	0.00 400
<b>Total Labour</b>	<b>676.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 100
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 100
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,116.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	154.00	0.00 110 receipt ?
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 240
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>494.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>DE</i>	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>ne</i>	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace <i>SCA</i>	No
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace <i>SCA</i>	No
81519-47060			BRACKET, FR TURN UPPER RH	1	24.40	25.00	18.30	Replace	Replace <i>SCA</i>	No
81519-47060			BRACKET, FR TURN	1	58.20	25.00	43.65	Replace	Replace <i>SCA</i>	No
81519-47050			BRACKET, FR TURN LOWER RH	1	26.00	25.00	19.50	Replace	Replace <i>SCA</i>	No
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace <i>SCA</i>	No
85315-47140			WIPER WASHER JAR	1	180.10	25.00	135.07	Replace	Replace <i>DE</i>	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace <i>CRA</i>	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace <i>Repair</i>	No
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace <i>SCA</i>	No
53851-47040			FENDER LINER PAD, FR WHEEL RH	1	49.30	25.00	36.97	Replace	Replace <i>SCA</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>ne</i>	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace <i>Repair</i>	No
<b>TOTAL MATERIALS</b>								<b>4,118.25</b>	<b>4,118.22</b>	
<b>TOTAL MATERIALS(Discounted)</b>							<b>3,228.68</b>	<b>3,294.58</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

7485.60



60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672


6-6-18 / 10:53  
6-6-18 / 14:53

## SMRT Accident Vehicle Repair Estimates

1-6-18 / 14:53

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB601K  
Ref. No : TAX/05/18/2135  
Reg. Date : 02/03/2015  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS  
Name of Driver : CHIA KOK KEONG  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 28/05/2018 07:05:00 PM  
Accident Reported Date / Time : 30/05/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : Rasul  
Vehicle is Towed Back? : Yes  
Towed Back Date/Time : 31/05/2018  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024096374  
Special Instruction to ARC, if any :



TOWED \$110 / SLX4375Z mslk p/p  
Before paint photo, After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL  
/ HP : 9001 0068. email: rasul@lkkauto.com  
lumpsum repair

Prepared Date : 01/06/2018 09:25:52 AM

12:00 6-6-18 pass

Recording Camera ☐ ☒  
Radio Antenna ☐ ☒  
1<sup>st</sup> witness 2  
2<sup>nd</sup> witness 6  
Date 1-6-18  
Date 6-6-18

344685  
↓  
1 1 1 1  
4 2 4 1

344753

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

6-6-18

Vehicle Return Time:

11:25

Signature:

*[Signature]*

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U805758743


Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	400.00
Total Spray Painting Charges	: 1,116.00	600.00
Total Material Charges	: 1,894.36	1,833.54
Other Charges	: 494.00	180.00
<b>TOTAL</b>	<b>: 4,180.36</b> <i>6326.60</i>	<b>3,013.54</b>
<b>Lump Sum Total</b>	<b>: 4,200.00</b>	<b>3,000.00</b>
No. of Repair Days	: 5.00	4.00
Prepared / Adjusted By	:	RASUL (LKK)
Arc / Surveyor Sign Off Date	: 01/06/2018 11:46:01 AM	01/06/2018 02:53:07 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/06/2018 11:46:02 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**Quotation No : *QN-1806-0506*

Invoice No :

Quotation Date : *23/6*

Invoice Date :

Invoice Amount :

Prepared Date :

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	676.00	400.00
<b>Total Labour</b>	<b>676.00</b>	<b>400.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	100.00
TO RESPRAY FRONT FENDER RH	378.00	200.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	100.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,116.00</b>	<b>600.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	154.00	110.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>494.00</b>	<b>180.00</b>

# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
52119-47930		6505517	BUMPER FRT	1	482.00	30.00	337.40	Replace	Replace	No ✓	de
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	30.00	53.48	Replace	Replace	No ✓	rec
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	30.00	217.77	Replace	Replace	No ✓	scr
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace	No ✓	scr
81519-47060			BRACKET, FR TURN UPPER RH	1	24.40	30.00	17.08	Replace	Check	No X	SVC
81519-47060			BRACKET, FR TURN	1	58.20	30.00	40.74	Replace	Check	No X	SVC
81519-47050			BRACKET, FR TURN LOWER RH	1	26.00	30.00	18.20	Replace	Check	No X	SVC
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace	No ✓	BRO
85315-47140			WIPER WASHER JAR	1	180.10	30.00	126.07	Replace	Replace	No ✓	DE
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	30.00	89.39	Replace	Replace	No ✓	CRA
53801-47050		6505557	FENDER FRT/RH	1	723.40	100.00	0.00	Replace	Repair	No R	R
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	30.00	120.19	Replace	Replace	No ✓	cut
53851-47040			FENDER LINER PAD, FR WHEEL. RH	0	49.30	30.00	0.00	Replace	Not given	No X	SVC
75374-47051			NAME PLATE (HYBRID)	1	51.90	30.00	36.33	Replace	Replace	No ✓	rec
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	100.00	0.00	Replace	Repair	No R	
TOTAL MATERIALS							2,367.95	2,291.93			
TOTAL MATERIALS(Discounted)							1,894.36	1,833.54			

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

2291.93  
- 208  
1833.54  
+ 400.00  
+ 780.00  


---

3013.54  
45 \$3000/-

3471.93

7485.60





24  
HOURS

HOTLINE: 9182 8211

# ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719  
Telephone: 6747 7400 Email: islandrecovery@gmail.com  
Facsimile: 6844 7233 Web: www.islandrecovery.com.sg  
GST Reg.No: M90370499P Co. Reg. 53120055L

Cash Sales/ Work Order

NO. 1184926

Date: 31/5/18

M/S:

SMART

Vehicle No: SHB 601 K Model: Toyota Prius Hybrid

From: 118 Aljunied Ave 2 4A Time Start: 17:42 / 18:18

To: SMART Time End: 20:40

Remarks: Acc & No Key

- ☐ Change Tyres / Jump Start
- ☒ Basement / Multi Carpark
- ☒ Using King Dolly

- ☒ Accident
- ☐ Crane Up / Winch Out
- ☐ Dismantle Shaft / Brake

- ☐ Use Car Carrier
- ☐ Open Door
- ☐ Loaded

AMOUNT S\$ 110

GST S\$ 7.70

TOTAL S\$ 117.70

Received By

bizSAFE<sub>3</sub>

Important Note:

HK 5837

Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18010272/R1TBN2  
Date: 06/07/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29077442QMY
Claimant Vehicle No :	SHB601K	Insured Vehicle No :	SLX4375Z
Date of Loss:	28/05/2018	Nature of Claim:	TP
		Claim No:	559945

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHB601K	Engine No:	2ZR6312285
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKN36U805758743
Reg. Date:	02/03/2015 (Man. Year: 2015)	Odometer:	344684 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,199.60	2,291.93	2,907.67	55.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,286.00	1,180.00	1,106.00	48.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,485.60</b>	<b>3,471.93</b>	<b>4,013.67</b>	<b>53.62</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,485.60</b>	<b>3,000.00</b>	<b>4,485.60</b>	<b>59.92</b>

## INSPECTION

Date of Assignment:	03/07/2018	
Date Inspected:	01/06/2018 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2018)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB601K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRT (DISC 30%)	Deformed	482.00 F	*337.40 F
2	1		*BUMPER SUPPORT F/RH (DISC 30%)	Necessary	76.40 F	*53.48 F
3	1		*BUMPER GRILLE SUB-ASSY, LOWER (DISC 30%)	Scratched	311.10 F	*217.77 F
4	1		*WIPER WASHER JAR (DISC 30%)	Deformed	180.10 F	*126.07 F
5	1		*BUMPER FRT ABSORBER LOWER (DISC 30%)	Cracked	127.70 F	*89.39 F
6	1		*FENDER LINER FRT/RH (DISC 30%)	Cut	171.70 F	*120.19 F
7	1		*NAME PLATE (HYBRID) (DISC 30%)	Necessary	51.90 F	*36.33 F
8	1		*LENS & BODY, FR TURN RH (DISC 10%)	Scratched	511.80 F	*460.62 F
9	1		*HEAD LAMP RH (DISC 10%)	Broken	945.20 F	*850.68 F
10	1		*BRACKET, FR TURN UPPER RH	Serviceable	24.40 F	*- F
11	1		*BRACKET, FR TURN	Serviceable	58.20 F	*- F
12	1		*BRACKET, FR TURN LOWER RH	Serviceable	26.00 F	*- F
13	1		*FENDER LINER PAD, FR WHEEL RH	Serviceable	49.30 F	*- F
14	1		*FENDER FRT/RH	Repair	723.40 F	*- F
15	1		*SUPPORT SUB-ASSY	Repair	1,460.40 F	*- F
F=Franchise part.						
Total Parts (\$\$)					5,199.60	2,291.93

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	676.00	400.00
2	SPRAY PAINT	New	1,116.00	600.00
3	TOWING CHARGE	New	154.00	110.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	40.00
6	TO REPLACE SUNDRY PARTS	New	100.00	-
7	TO WASH AND VCUUM	New	60.00	-
Gross Labour Cost (S\$)			2,286.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >