



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
 Spray-Painting, Mechanical Repair And Customizing of Cars
 BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
 Bus. Reg. No. 251513/00M

AXA/AIG
 LKIC

AXA/AIG (SJF4939R)
 DOA: 27/05/2018@1730

AIG ASIA PACIFIC INSURANCE PTE LTD

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SLU 6558 R - HYUNDAI TL TUCSON 1.6 GLS T-GDI DCT 2WD

CHASSIS NO: KMHJ3812VJU628440 (2017)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

2/6/2018

Acknowledged by Repairer
 Signature:
 Date:

1 pc	Rear boot garnish emblem 'TUCSON'	\$ 29.10	see ✓
1 pc	Rear boot garnish emblem 'TURBO'	\$ 59.00	see ✓
1 pc	Rear boot garnish emblem 'S'	\$ 20.20	see ✓
1 pc	Rear bumper (upper)	\$ 446.50	dec ✓
1 pc	Rear bumper (lower)	\$ 334.70	cut ✓
1 pc	Rear bumper reflector RH	\$ 103.00	cut ✓
1 pc	Rear bumper mudflag RH	\$ 20.00	cut ✓
1 pc	Rear bumper sensor	\$ 140.20	?
1 pc	Rear bumper retainer RH	\$ 24.50	?
		\$ 1,177.20	
	LESS 20%	\$ 235.44	
		\$ 941.76	
	Check wiring function	\$ 40.00	20 ✓
	Remove/replace/reinstall necessary parts: jacking, panel beating, repair and straighten rear boot garnish and rear bumper.	\$ 400.00	300 ✓
	Putty and respray rear inner panel, rear boot garnish and rear bumper.	\$ 450.00	350 ✓
		\$ 1,831.76	
	ADD 7% GST	\$ 128.22	
		\$ 1,959.98	

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

Tanjihh 97495749
 - WP'
 5/6/18 @ 2pm
 Resurvey before paint
 3 days
 suw@lkkauto.com