

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8769C

DATE 6/5/2018 11:47

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (LH) X Repair <i>rear fender (LH) repair</i>			\$ 1,351.10
	SUB TOTAL			\$ 1,351.10
	LESS 20%			\$ 270.22
	DISCOUNTED TOTAL			\$ 1,080.88
	Rear Door Comfortdelgro & Apps Sticker (LH) ✓			\$ 80.00
				\$ 80.00
	Labour Charge			
	Panel Beating			\$ 380.00 ²⁰⁰
	Spray Painting Charge (Fender / Door)			\$ 500.00 ⁴⁰⁰
	Tuff Kote			\$ 50.00 ^X
	Transfer of Door			\$ 120.00 ^X
	TOTAL LABOUR			\$ 1,050.00
	ESTIMATE TOTAL			\$ 2,210.88

1 Calvin Ullrich
 5/6/18 1300h.
 2671.
 PIP
 After Repair p/c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Date: