

CHUNNI MOTOR WORK PTE LTD

To Survey by LKK1

REPAIR ESTIMATE

INDIA

VEHICLE NO : SHC 1222J

DATE : 28.05.2018

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR FENDER, RH <i>Dented</i>			\$ 817.50	✓
REAR FENDER INNER PANEL, RH <i>NN</i>			\$ 728.00	X
REAR FENDER OUTER PANEL, RH <i>NN</i>			\$ 486.00	X
REAR FENDER SHEILD (RH) <i>SVC</i>			\$ 134.20	X
PANEL SUB-ASSY. FRONT DOOR, RH <i>Dented</i>			\$ 1,227.00	✓
REAR DOOR RUBBER SEAL OUTER <i>N/C</i>			\$ 257.90	✓
PANEL SUB-ASSY, REAR DOOR, RH <i>Dented</i>			\$ 1,227.00	✓
REAR DOOR HINGE UPPER, RH <i>NN</i>			\$ 82.30	X
REAR DOOR HINGE LOWER, RH <i>NN</i>			\$ 82.30	X
REAR DOOR CHECK, RH <i>NN</i>			\$ 153.00	X
REAR DOOR TRIMBOARD, RH <i>NN</i>			\$ 725.00	X
DOOR CENTRE PILLAR <i>Dented repair</i>			\$ 1,590.60	was X
MOTOR ASSY, POWER WINDOW REGULATOR REAR, RH <i>NN</i> Down <i>NN</i>			\$ 941.80	X
REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH <i>NN</i> Down			\$ 228.40	X ✓
REINFORCE SUB-ASSY, ROCKER, OUTER RH <i>Cnt</i> <i>Dented</i>			\$ 519.80	✓
CENTRE ROCKER PANEL (GARNISH) <i>Cnt</i>			\$ 576.00	✓
REAR TYRE RIM (RH) <i>Cnt</i>			\$ 1,555.00	✓
REAR WHEEL HUB CAP (RH) <i>Cnt</i>			\$ 175.80	✓
REAR WHEEL BEARING ING & HUB <i>2 Down</i>			\$ 493.00	2 ✓
REAR CROSS MEMBER <i>2 distorted</i>			\$ 2,179.40	2 ✓
REAR SHOCK ABSORBER, RH <i>2 distorted</i>			\$ 116.00	2 ✓
REAR SHOCK ABSORBER MOUNTING, RH <i>NN</i>			\$ 125.30	X
REAR LOWER ARM,, RH <i>2 distorted</i>			\$ 345.70	2 ✓
REAR UPPER ARM, RH <i>2 distorted</i>			\$ 348.80	2 ✓
REAR KNUCKLE ARM, RH <i>2 distorted</i>			\$ 800.73	2 ✓
REAR STABILIZER BAR <i>2 distorted</i>			\$ 311.50	2 ✓
REAR STABILIZER LINK, RRH <i>2 distorted</i>			\$ 147.90	2 ✓
REAR TRAILING ARM, RH <i>2 distorted</i>			\$ 262.90	2 ✓
REAR ASSIST ARM, RH <i>2 distorted</i>			\$ 342.20	2 ✓
SUB TOTAL			\$ 16,981.03	
LESS 20%			\$ 3,396.21	
DISCOUNTED TOTAL			\$ 13,584.82	
FRONT DOOR COMFORT LOGO <i>N/C</i>			\$ 75.00	NETT ✓
REAR DOOR COMFORT & APPS STICKER <i>N/C</i>			\$ 80.00	NETT ✓
REAR TYRE (RH) <i>SVC</i>			\$ 216.00	NETT X
			\$ 371.00	

SHC 1222J

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
LABOUR CHARGE			
Panel Beating			\$ 2,000.00 1000/-
Spray Painting Charge			\$ 1,500.00 800/-
Wiring Charge			\$ 50.00 NN
Tuff Kote			\$ 100.00 40/-
Towing Charge			\$ 50.00 NN
Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
Remove/Refix Reverse Sensor			\$ 120.00 40/-
Remove/Refix Undercarriage (RR)			\$ 400.00 180/-
Transfer of Door		\$ 120.00	\$ 240.00 120/-
Rear Wheel Alignment			\$ 120.00 60/-
TOTAL LABOUR			\$ 4,730.00
ESTIMATE TOTAL			\$ 18,685.82
01/06/2018 @ 1330 hrs NA Antenna P/Part. 9 days  2kk Ant  Photo 1st paint with damaged parts.			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.