

INS. CASE OWNER:

CC

/ Apr

180

10285

K#A39

LKK:

IDAC:

50113

Surveyor:

Kenneth

DOI:

6/6/18

Date / Time:

6/6/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLQ 2204J

Name of Insured:

Lee Yeeu Fung

Insured Tel No.:

HP:

96860101

Excess Sec II :SS

D.O.A.:

4/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S8m00J08

hx

Policy No.:

Make / Model:

BMW 520

Place of Accident:

CUP RD off Longkeng East Ave

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

RD 6220H



INSRS:

WSP:

Tel:

Liability:

RMKS:

Good Hade mfg



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC	
1/16	RD 6220H - X; SLQ 2204J - X	Non-Reporting ltr (1st):		
CPC		Non-Reporting ltr (2nd):		
		Non-Reporting ltr (Final):		
		Notification ltr (if non-pickup):		
19/6/2018	Spoke to OJ, watched accident statement, informed TP (Plains and H&M) issue. Agree to settle and endorse of H&M	Call OI:	5/14/18/18 2/16/18	
2pm	Have send letter to OJ	After call ltr to OI:		
3/7/2018	H&M DS instructions.	Documentation Check List:	Handler Typist	
		Notification ltr (if non-pickup)	☒	☐
		After call ltr to OI:	☒	☐
		Authorisation To Act:	☒	☐
		Release Voucher:	☒	☐
		Final Repair Bill:	☒	☐
		Car Rental Invoice:	☒	☐
		Towing Invoice	☒	☐
		LTA / GIA :	☒	☐
		Medical Bill	☒	☐
		PIR:	☒	☐
		Mandate/Reject Instruction:	☒	☐
		LOD	☒	☐
		Payment Breakdown Form:	☒	☐
		Post-Repair Photos:	☒	☐
		Others:	☒	☐

PRELIMINARY ADVICE		Date/Time:	2/6	Sent By:	Hm
FINALIZATION		Date/Time:		Confirm with:	Kenneth
Repair Cost:	SS \$200.00	(2 days) Reduction:	\$195.54 % 53	Confirm by:	Kenneth
FINAL SETTLEMENT		Date/Time:	9/6/2018	Confirm with:	William
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27	Email ☐	Call ☐
Repair Cost:	SS \$200.00	If NO or B 28, Ass. Lia:			
Loss of Rental (LOR):	SS -	(days)			
Loss of Use (LOU):	SS \$360.00	(\$90 x 4 days)			
Loss of Income (LOI):	SS -	(\$ x days)			
LOR only ☐	LOU only ☒	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	SS \$2.00				
Medical:	SS -				
Disbursement:	SS -	(e.g. Tow/ Independent)			
Legal Cost	SS -				
Total:	SS \$2062.00	Global Sum SS:	2000.00		
FINAL PAYMENT		Date/Time:		Confirm with:	
Payee 1:	SS \$2000.00	Name 1:	Lee Yeeu Fung	Email ☒	Call ☐
Payee 2: (Strike if N.A.)	SS -	Name 2:			
Payee 3: (Strike if N.A.)	SS -	Name 3:			

COPY SENT
16/6/2020

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

7/16 File pass to Catherine

11 Pm 8/1 food email

(Red - 81951.54/637)

4 repair days + 4 PRS = 4 days

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

: Fuel

: Others

TOTAL

Veh No:

RD 622014

Yr Regn:

1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

BYD e6

C.G

Colour:

White / Cream

AC:

Insured / Std / NI / NA

Sp. Reading

103214

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LC0CE40BPM.1012676

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

225/65R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

4 mm

R/Bal.

8 mm

L/Bal.

6 mm

L/Bal.

8 mm

D.O.A.

4/6/18

D.O.I.

6/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18010285/Kfa3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 06-06-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 2204J	Veh. Inspected	RD 6220H	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00J08	Excess (\$)	0.00	
Assign From		Assign Date	06/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/06/2018	Inspection Date	06/06/2018	
Survey held at	SOON HOCK MOTOR PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PK 2A #01-05/06 AMK AUTOPOINT . SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

05/06/18

QUOTATION FOR VEHICLE RD 6220 H

PARTS

1	1	REAR BUMPER	\$ <i>Sm</i>	996.72	✓
2	1	REAR BUMPER SIDE REFLECTOR (RED)(RH)	\$ <i>Sm</i>	38.40	X
3	1	REAR BUMPER SIDE REFLECTOR (YELLOW)(RH)	\$ <i>Sm</i>	29.60	X
4	1	REAR BUMPER REINFORCEMENT	\$ <i>B1</i>	605.22	✓
5	1	REAR BUMPER CENTRE GRILLE	\$ <i>m</i>	199.63	✓
6	1	REAR LAMP (RH)	\$ <i>Sm</i>	533.48	X
7	1	REAR FENDER SHIELD (RH)	\$ <i>h</i>	197.28	X
		SUB TOTAL	\$	2,600.33	
		LESS 10%	\$	260.03	
		DISCOUNTED SUB TOTAL	\$	2,340.30	

S/NETT

1	1	REAR PARKING SENSOR (1 SET OF 4)	\$	421.24	X
		SUB TOTAL	\$	421.24	

LABOUR

1	PANEL BEATING	\$	380.00	2001
2	SPRAYPAINTING CHARGES	\$	380.00	2201
3	WIRING CHARGES	\$	30.00	151
4	REMOVE/REFIX REAR PARKING SENSOR	\$	100.00	601
	SUB TOTAL	\$	890.00	

GRAND TOTAL	\$	3,651.54
-------------	----	----------

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF REPAIRS. WE WOULD INFORM YOU ACCORDINGLY FOR THE NECESSARY ACTIONS. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

NOT Withheld
~~1 day~~, 61 Long 8?
 2 days
 61 Long 8 1700h



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before clear spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Requester

Signatures:

Date: _____



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 7/6/2018

Survey Details:

Date of loss	4-Jun-18
Date of appointment	6-Jun-18
Date of survey	6-Jun-18
Location of survey	Soon Hock Motor Pte Ltd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	RD 6220H
Make and Model	BYD E3Y- (A)
Date of registration	-
Excess	
Market Value	\$ -
Part Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate	\$ 3,651.54
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,076.72
Check items (estimate)	\$ 544.70
Labour	\$ 495.00
Total	\$ 2,116.42
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>2 days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 22/07/2019

Survey Details:

Date of loss	4-Jun-18
Date of appointment	6-Jun-18
Date of survey	6-Jun-18
Location of survey	SOON HOCK MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	RD 6220H
Make and Model	BYD E3Y-(A) Electric Taxi
Date of registration	
Excess	
Market Value	\$0
Part Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 3,651.54
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,621.41	list price -10%
Check items (estimate)	\$ -	
Labour	\$ 495.00	
Total	\$ 2,116.41	
Lump Sum(if applicable)	\$ 1,700.00	after -20%

Number of days for repair	2
---------------------------	---



Remarks:

Liability: Insured collided into the rear of third party vehicle, Liability is down against our insured. We We did clarify with OI (Mr Lee) the nature of the accident, He is agree to settle, aware that NCD (if any) is affected.

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	1,700.00
Loss of use	\$	400.00 (\$100.00 x 4 days)
Loss of rental	\$	-
Loss of income	\$	-
GIA search fees	\$	2.00
Others	\$	-
Proposed Total	\$	2,102.00

English (default) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

 SERVICE REQUESTS

MESSAGES

CLAIMS

<<

TP MANDATE IA < S8M00JO8>

Type

 Question

Message

Dear KC, Liability: Insured collided into the rear of third party vehicle, Liability is down against our insured. We We did clarify with OI (Mr Lee) the nature of the accident, He is agree to settle, aware that NCD (if any) is affected. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. We hereby seek your approval to offer Third Party repairer M/s "Soon Hock Motor Pte Ltd" is as follows: - 1) COR: \$1,700.00 + 2) Loss of Revenue (4 days x \$100.00): \$400.00 + 3) GIA: \$2.00 = Total: \$2,102.00. **2 days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please. PohKin- LKK- 22/07/2019





SOON HOCK MOTOR PTE LTD

HDT SINGAPORE TAXI PTE LTD NO. 47 JALAN PEMIMPIN HALCYON 2 #03-05 SINGAPORE 577200	VEHICLE NO
	RD 6220 H
	DATE
	12/04/2019
	INVOICE NO
	005006
	ACC DATE/TIME
	04.06.2018 @ 09:00 HRS

Cost of Repair \$ 1,700.00

TOTAL \$ 1,700.00

(SGD DOLLARS: ONE THOUSAND AND SEVEN HUNDRED ONLY)

Kindly arrange for payment as soon as possible. All cheques must be crossed and made payable to **SOON HOCK MOTOR PTE LTD**.





Re:TP MANDATE IA < S8M00JO8>

Type

🔔 Question

Message

PLS PROCEED QUANTUM AS PROPOSED, FOR LOSS OF REVENUE PLS START AT \$70 PER DAY UP TO MAX \$100.00

Reply



SOON HOCK MOTOR PTE LTD

Poh Kin

Our Ref: MTP/5019/18

Your Ref: SLQ 2204 J

Date: 08 Jun 2019

WITHOUT PREJUDICE

The Motor Claims Department
LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Ind Park
Singapore 408933

Dear Sir/Madam

RE: ACCIDENT INVOLVING RD 6220 H & SLQ 2204 J ALONG SENGKANG EAST
AVE ON 04 JUN 2018.

We are authorised by the owner of motor vehicle/taxi, RD 6220 H, which was involved in the above-mentioned accident to claim damages against you.

The motor vehicle/taxi was surveyed by your appointed appraiser at the premises of M/s Soon Hock Motor Pte Ltd. The accident was caused by your insured's negligent driving and/or management of his vehicle. Therefore, we are claiming property damages and losses sustained by our client against you in connection with the accident based on the appraiser's recommendation

Our claim is as follows:

1) Cost of Repair	S\$ 1,700.00
2) Loss of Revenue	S\$ 1,250.00
3) LTA Search	S\$ 2.00
	<u>S\$ 2,952.00</u>

We enclose herewith the following relevant supporting documents:

- a) Authorisation Letter
- b) Final Repair Bill
- c) GIA Report
- d) LTA Search
- e) Certificate of Insurance

Any settlement is limited to the aforesaid claim only and does not prejudice our hirer's rights to any personal injury claims and/or losses in future should such a claim arises.

Yours faithfully,



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18010285/Kga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN		Date : 19-03-2020 Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 2204J	Veh. Inspected	RD 6220H ✓	
Policy No.	CN837132 ✓	Coverage (\$)	0.00	
Claim No.	S8M00JO8	Excess (\$)	0.00	
Assign From		Assign Date	06/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	BYD E6Y (A)	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	LC0CE4DB9H1012676	Colour	WHITE/GREEN	
Odometer	103214 ✓	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	PIRELLI	4 mm	
L/H Front Tyre	225/65 R17	PIRELLI	4 mm	
R/H Rear Tyre	225/65 R17	PIRELLI ✓	8 mm	
L/H Rear Tyre	225/65 R17 ✓	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/06/2018	Inspection Date	06/06/2018 ✓	
Survey held at	SOON HOCK MOTOR PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PK 2A #01-05/06 AMK AUTOPOINT. SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. RD 6220H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	BUCKLED	996.72	996.72
1	REAR BUMPER SIDE REFLECTOR (RED) (RH) (CONSISTENT)	SERVICEABLE	38.40	-
1	REAR BUMPER SIDE REFLECTOR (YELLOW) (RH) (CONSISTENT)	SERVICEABLE	29.60	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	605.22	605.22
1	REAR BUMPER CENTRE GRILLE (CONSISTENT)	DENTED	199.63	199.63
1	REAR LAMP (RH) (CONSISTENT)	SERVICEABLE	533.48	-
1	REAR FENDER SHIELD (RH) (CONSISTENT)	SERVICEABLE	197.28	-
	LESS 10% DISCOUNT		-260.03	-180.16
			2,340.30	1,621.41
SPECIAL NETT ITEMS				
1	REAR PARKING SENSOR (1 SET OF 4) (SN) (CONSISTENT)	SERVICEABLE	421.24	-
			421.24	-
LABOUR				
	PANEL BEATING.		380.00	200.00
	SPRAYPAINTING CHARGES.		380.00	220.00
	WIRING CHARGES.		30.00	15.00
	REMOVE/ REFIX REAR PARKING SENSOR .		100.00	60.00
			890.00	495.00
GRAND TOTAL			3,651.54	2,116.41
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CC4/ASM18010285/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SRM00J08
Reference	CC4/ASM18010285/KgaDu2
Loss Date	4 June 2018
Report Date	5 Jun 2018 3:34:29 PM
Request Date	21 August 2018
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	RD6J20H
Make	TPWD BYD
Model	E6Y-W
Service Address	
...	
Primary Contact/Insured	
LEE YEOW FONG	
574 HOUGANG STREET S1, S30574, Singapore	
62209266	
MOTOROPERATIONS@GHM.COM	
Claim Handler	
CHAN Kian Chuan	
68905444	
kianchuan.chan@axa.com.sg	

Additional Instructions

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (5).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK Inspection (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKKAdjustment1a (8).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 TP letter of demand.pdf	Forms / Claim Documents	Claim Form	LKK AUTO CONSULTANTS PTE LTD (TP)	22 July 2019
 Immediate Advice (with mandate) dated 22.07.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 July 2019
 GIA search fee.pdf	Forms / Claim Documents	Claim Form	LKK AUTO CONSULTANTS PTE LTD (TP)	22 July 2019
 Letter to OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	22 July 2019
 LKK RESURVEY PHOTO-AFTER PAINT.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 July 2019
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 July 2019
 OI traffic police report.pdf	Reports & Statement	Accident statement	LKK AUTO CONSULTANTS PTE LTD (TP)	3 July 2018
 TP ESTIMATE-MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	9 June 2018
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	8 June 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	8 June 2018
 TP PR RECEIVED FROM WORKSHOP WITH GIA AND ESTIMATE.mig	Letters and Correspondence	Workshop	DHAKAL Raghav	5 June 2018
 SLQ2204J INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	5 June 2018
 RD6220H TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	5 June 2018