

QUOTATION FOR VEHICLE RD 6220 H

PARTS			
1	1	REAR BUMPER	\$ <i>Bu</i> 996.72 ✓
2	1	REAR BUMPER SIDE REFLECTOR (RED)(RH)	\$ <i>Sn</i> 38.40 X
3	1	REAR BUMPER SIDE REFLECTOR (YELLOW)(RH)	\$ <i>Sn</i> 29.60 X
4	1	REAR BUMPER REINFORCEMENT	\$ 605.22 7
5	1	REAR BUMPER CENTRE GRILLE	\$ <i>Sn</i> 199.63 ✓
6	1	REAR LAMP (RH)	\$ <i>Sn</i> 533.48 X
7	1	REAR FENDER SHIELD (RH)	\$ <i>R</i> 197.28 X
		SUB TOTAL	\$ 2,600.33
		LESS 10%	\$ 260.03
		DISCOUNTED SUB TOTAL	\$ 2,340.30
S/NETT			
1	1	REAR PARKING SENSOR (1 SET OF 4)	\$ <i>Sn</i> 421.24 X
		SUB TOTAL	\$ 421.24
LABOUR			
1		PANEL BEATING	\$ 380.00 <i>2001</i>
2		SPRAYPAINTING CHARGES	\$ 380.00 <i>2201</i>
3		WIRING CHARGES	\$ 30.00 <i>151</i>
4		REMOVE/REFIX REAR PARKING SENSOR	\$ 100.00 <i>601</i>
		SUB TOTAL	\$ 890.00
		GRAND TOTAL	\$ 3,651.54

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF REPAIRS. WE WOULD INFORM YOU ACCORDINGLY FOR THE NECESSARY ACTIONS. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

SOON HOCK MOTOR PTE LTD
 Blk 10 Ang Mo Kio Industrial Park 2A
 #01-05/06 AMK Autopoint
 Singapore 568047
 - 6483 6016 (3 Lines) Fax: 6483 6011
 Co. Reg. No. 199804869H1

Not Authorized
1-B, 1, 11 Sep 8?
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: