

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Migrate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(2.5 days) x \$119.78

Loss of Use (LOU):

S\$

(3 - x - days)

Loss of Income (LOI):

S\$

(350 x 7.5 days)

LOR only ☐ LOU only ☐

S\$

LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$: 14w-w

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Comfortelgru Engineering Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$4w-w

COPY SENT
11/11/1901w
13/11/19
01w

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6550Z

MAKE :

MODEL : HYUNDAI i40

DATE 4/6/2018 16:09

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper — <i>Defunct</i>			\$ 603.60
	Rear Bumper Clips — <i>me</i>			\$ 22.00
	<i>Rear Fender (RH) x 2</i>			
	SUB TOTAL			\$ 625.60
	LESS 20%			\$ 125.12
	DISCOUNTED TOTAL			\$ 500.48
	Rear Bumper Reverse Sensor <i>x 2</i>			\$ 135.70
	Rear Bumper Rubber Mat — <i>me</i>			\$ 50.00
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 120.00
	R/Refix Reverse Sensor			\$ 720.00
	TOTAL LABOUR			\$ 1,406.18
	ESTIMATE TOTAL			\$ 1,656.18
	<i>Kaharub (11/14)</i>			
	<i>5/6/18 1230L</i>			
	<i>2 Rys.</i>			
	<i>4/5</i>			
	<i>A the Repair photo</i>			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

ARC Repair TP(CLS0)1

JOB CARD Sales Order: 3829283

JC NO305169396

COMFORT TRANSPORTATION PTE LTD
7010045
183 SIN MING DRIVE
Singapore SINGAPORE 575717
5508755 (O)

REGN NO: SHD6550Z	MILEAGE
MAKE: HYUNDAI	FUEL E 1/2 F
MODEL: I-40	DATE/TIME IN 04.06.2018 11:20
YR OF MANU: 04.11.2014	TARGET DATE
CHASSIS CODE KMHLE41UMEU061393	COMPLETION DATE/TIME:

ARD NO.

ent Date: 03.06.2018
t: 3P 03.06.18/B

JOB DESCRIPTION

EQ

LABOR CODE

DESCRIPTION

PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

int Slip

Exit Pass

SHD6550Z

FZ EQ

Vehicle No.: SHD6550Z

r Advisor

Signature/Date

Name of Service Advisor

Date

o Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6550Z

MAKE :

MODEL : HYUNDAI i40

DATE 4/6/2018 16:09

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Clips			\$ 22.00
	<i>Rear Fender (RH) x 1</i>			
	SUB TOTAL			\$ 625.60
	LESS 20%			\$ 125.12
	DISCOUNTED TOTAL			\$ 500.48
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Rubber Mat			\$ 50.00
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 120.00
	R/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 720.00
	ESTIMATE TOTAL			\$ 1,406.18
	<i>Katana 6 (11/14)</i>			
	<i>11/5/18 1230L</i>			
	<i>2 Pgs</i>			
	<i>4/5</i>			
	<i>After Repair photo</i>			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modifications allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305169396
Date : 06.06.2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SHD6550Z

Fax :
Date of Accident : 03.06.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ — SKC5956M
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$0.00
 - (b) Labour Charges \$0.00
 - Total for Part-By-Part Repair Cost \$0.00**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$950.00
Final Lumpsum Repair cost \$950.00

3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :
Name : FAUZY BIN MOKHTAR
Tel : 62148319
Fax : 65468156

Signature :
Name :
Date : 7/6/8

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Hsiao Tong (LKKAUTO)

From: Jim Wong See Pah <jimwong@cdge.com.sg>
Sent: Monday, 11 November 2019 9:41 AM
To: Hsiao Tong (LKKAUTO)
Subject: Re: Your Ref: T 0618/ SHD6550Z/ JW(st) *LKK Ref: CC3/EQI18010287/K1pa3 [ACCIDENT INVOLVING SKC 5956M(EQ) AND SHD 6550Z ON 03/06/2018]


Dear Ms Chew

Please process settlement in sum \$ 1400.00 to resolve our property damage claim amicably.

Additionally, it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Thank you.

Best Regards
Jim Wong
Claims Dept / ComfortDelgro Engineering Pte Ltd



From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Saturday, 9 November 2019 9:51 AM
To: Jim Wong See Pah <jimwong@cdge.com.sg>
Subject: Your Ref: T 0618/ SHD6550Z/ JW(st) *LKK Ref: CC3/EQI18010287/K1pa3 [ACCIDENT INVOLVING SKC 5956M(EQ) AND SHD 6550Z ON 03/06/2018]

Your Ref: **T 0618/ SHD6550Z/ JW(st)** **Without Prejudice**
LKK Ref: CC3/EQI18010287/K1pa3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SKC 5956M(EQ) AND SHD 6550Z ON 03/06/2018

We refer to the above matter.

We propose settlement at a global sum of **\$1,400.00(all-in)**.

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199508048W]



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 19/11/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SKC 5956M	(Insd Veh)	Your Ref. No. : DM18HO01447/JT
	SHD 6550Z	(TP Veh)	Our Ref. No. : CC3/EQ18010287/K1pa3q2
Date of Accident	3/6/2018		

Liability	100%	
Final Repair Cost	: \$ 1,016.50	
Loss of Income	: \$ 125.00	2.5 days
Rental (If any)	: \$ 298.20	2.5 days
Others:	: \$ 7.49	
	: \$	
	1,447.19	
Final Settlement Sum	: \$ 1,400.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	COMFORTDELGRO ENGINEERING PTE LTD	: \$ 1,400.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ18010287/K1pa3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 19-11-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKC 5956M	Veh. Inspected	SHD 6550Z
Policy No.	DMPPHQ17-003390	Coverage (\$)	0.00
Claim No.	DM18HO01447/JT	Excess (\$)	0.00
Assign From		Assign Date	05/06/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHLB41UMEU061393	Colour	BLUE
Odometer	401921	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	CAMPEON	7 mm
L/H Front Tyre	205/60 R16	CAMPEON	7 mm
R/H Rear Tyre	205/60 R16	CAMPEON	7 mm
L/H Rear Tyre	205/60 R16	CAMPEON	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/06/2018	Inspection Date	05/06/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6550Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR FENDER (RH) (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-125.12	-125.12
			500.48	500.48
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			185.70	50.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER (RH).		350.00	200.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	R/REFIX REVERSE SENSOR .		120.00	30.00
			970.00	630.00
	GRAND TOTAL		1,656.18	1,180.48
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			950.00

Report Ref No. CC3/EQ118010287/K1pa3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.