

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6550Z

DATE 4/6/2018 16:09

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper — <i>Defunct</i>			\$ 603.60
	Rear Bumper Clips — <i>me</i>			\$ 22.00
	<i>Rear Fender (RH) x 2</i>			
	SUB TOTAL			\$ 625.60
	LESS 20%			\$ 125.12
	DISCOUNTED TOTAL			\$ 500.48
	Rear Bumper Reverse Sensor <i>X sec</i>			\$ 135.70
	Rear Bumper Rubber Mat — <i>me</i>			\$ 50.00
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 350.00 <i>200</i>
	Spray Painting Charge			\$ 100 <i>400</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>70</i>
	TOTAL LABOUR			\$ 720.00
	ESTIMATE TOTAL			\$ 1,406.18
	<i>Kaharut (LKK)</i>			
	<i>5/6/18 1230 hrs</i>			
	<i>2 hrs.</i>			
	<i>4/5</i>			
	<i>After Repair photo.</i>			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.