

ASS. REC. BY:

REF: CS/FCI18010288/Krd3<sup>n2</sup>

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

WS

From (Person):

Eileen Lee

of

FCI

Date/Time:

06/06/18 @ 12:45pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 5307Y

Insured:

SHB 6398H

at Workshop m/s

Trans-Cab

Tel:

of

No. 2 AMK 8trf 63

Policy No:

Claim No:

D18004484MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:46pm @ 6/6/18

Person Contacted:

Ghien Yee Long

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SHC 5307Y - X

SHB 6398H - CS / FCI17019115/R/gbn2

DOA: 30/04/2017

13/6/18

Revert thru email

ASS. REC. BY:

REF: PC71

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

2 1/2 days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 53074Yr Regn: 03, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Peugeot1000cc1995Colour: White / Red

A/C: Insured / Std / NI / NA

Sp. Reading: 331570

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VIF1ABL 15AUC 27 6796Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / LS/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

215/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Giti

Front

Rear

R/Bal. \_\_\_\_\_

R/Bal. \_\_\_\_\_

mm

mm

L/Bal. \_\_\_\_\_

L/Bal. \_\_\_\_\_

mm

mm

D.O.A. 216/18D.O.I. 6/6/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
cls body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/6

File pass to Catherine

1 Rmp @ 4350. (Red - @ 22918.04, 8471.)

RECEIVED 14 JUN 2010

Date/Time, File Pass to?



: Prell. Report

1) by post

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 2.5

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐

: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Fuel

) Others

TOTAL

17X15: 255

170+255

50

15

490

Report Format: TP

Lump Sum / LBI: (\$

4350



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                              |                           |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|--|
| FIRST CAPITAL INSURANCE LTD                                                                                                            |                                                                              | Ref : CS/FCI18010288/Krd3 |                                                                                     |  |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                  |                                                                              | Date : 06-06-2018         |  |  |
|                                                                                                                                        |                                                                              | Code : FCI2               |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                              |                           |                                                                                     |  |
| Insured Veh.                                                                                                                           |                                                                              | Veh. Inspected            | SHC 5307Y                                                                           |  |
| Policy No.                                                                                                                             |                                                                              | Coverage (\$)             | 0.00                                                                                |  |
| Claim No.                                                                                                                              | D18004484MFSH                                                                | Excess (\$)               | 0.00                                                                                |  |
| Assign From                                                                                                                            | CWS (EILEEN LEE)                                                             | Assign Date               | 06/06/2018                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                              |                           |                                                                                     |  |
| Make & Model                                                                                                                           |                                                                              | c.c                       | 0                                                                                   |  |
| Engine No.                                                                                                                             | HIDDEN                                                                       | Year of Reg.              |                                                                                     |  |
| Chassis No.                                                                                                                            |                                                                              | Colour                    |                                                                                     |  |
| Odometer                                                                                                                               | -                                                                            | Steering                  |                                                                                     |  |
| Brakes                                                                                                                                 |                                                                              | Modification              |                                                                                     |  |
| General                                                                                                                                |                                                                              |                           |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                              |                           |                                                                                     |  |
|                                                                                                                                        | Size                                                                         | Make                      | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                         |                                                                              |                           | mm                                                                                  |  |
| L/H Front Tyre                                                                                                                         |                                                                              |                           | mm                                                                                  |  |
| R/H Rear Tyre                                                                                                                          |                                                                              |                           | mm                                                                                  |  |
| L/H Rear Tyre                                                                                                                          |                                                                              |                           | mm                                                                                  |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                              |                           |                                                                                     |  |
|                                                                                                                                        |                                                                              |                           |                                                                                     |  |
| <b>5. General Information</b>                                                                                                          |                                                                              |                           |                                                                                     |  |
| Accident Date                                                                                                                          | 02/06/2018                                                                   | Inspection Date           | 06/06/2018                                                                          |  |
| Survey held at                                                                                                                         | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                           |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                              |                           |                                                                                     |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                           |                                                                                     |  |

**MOTOR SURVEY ASSIGNMENT**

|                    |                                                             |                               |
|--------------------|-------------------------------------------------------------|-------------------------------|
| Date               | 05-06-2018                                                  | Our Ref No. D18004484MFSH     |
| Accident Date      | 02-06-2018                                                  | Claim Type. Third Party       |
| Insured Vehicle    | SHB6398H                                                    | Third Party Vehicle. SHC5307Y |
| Survey Location    | NO. 2 ANG MO KIO STREET 63                                  |                               |
| Contact Person.    | GHIEEN YEE LOONG                                            |                               |
| Contact No.        | 62876666/ 0                                                 | Fax No. 62571330              |
| Survey Type        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                                |                               |
| Contact Person     | NA                                                          | Fax No. 68416315              |
| Contact Number.    | NA                                                          |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                                 |                         |
|-------------------|---------------------------------|-------------------------|
| Cc : Workshop     | TRANS-CAB AUTO SERVICES PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                              | TP Solicitor Fax No. NA |
| Officer Incharge  | EILEEN LEE                      |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241120)



PRI Documents



Close



## PRI Header Details

|                   |                                                                       |                                   |                                                                                                                      |                      |               |
|-------------------|-----------------------------------------------------------------------|-----------------------------------|----------------------------------------------------------------------------------------------------------------------|----------------------|---------------|
| Claim No          | D18004484MFSH                                                         | Policy No                         | D-18088936MFSH                                                                                                       | Claimant S.No & Name | 1 & TRANS-CAB |
| Workshop Name     | TRANS-CAB AUTO SERVICES PTE LTD<br>(Contact Person : GHIEN YEE LOONG) | Survey Location & Contact Details | NO. 2 ANG MO KIO STREET 63<br>Mobile: 0 , Phone: 62876666 , Fax: 62571330<br>EmailId: GHIENYEE.LOONG@TRANSCAB.COM.SG |                      |               |
| Our Surveyor      | LKK AUTO CONSULTANTS PTE LTD                                          | Instructions To Surveyor          | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM                                                                        |                      |               |
| Insured Name      | COMFORT TRANSPORTATION PTE LTD                                        | Insured Vehicle No                | SHB6398H                                                                                                             | TP Vehicle No        | SHC5307Y      |
| PRI Recieved Date | 05-06-2018 06:30:42 PM                                                | Surveyor Appointed Date           | 06-06-2018 12:44:42 PM                                                                                               | Surveyor Accept Date | 06-06-2018 0  |

## Survey Report Upload

|                             |  |                      |            |                         |                                            |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|
| Surveyor Inspection Date *: |  | Surveyor Report Date | 06-06-2018 | Upload Survey Report *: | <input type="button" value="Choose File"/> |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|

## Vehicle Particulars

|           |                                                 |                |                                                  |         |                                          |
|-----------|-------------------------------------------------|----------------|--------------------------------------------------|---------|------------------------------------------|
| Make      | <input type="text" value="Please Select Make"/> | Model          | <input type="text" value="Please Select Model"/> | Year    | <input type="text" value="Select Year"/> |
| Chasis No | <input type="text"/>                            | Engine No      | <input type="text"/>                             | Mileage | <input type="text"/>                     |
| Color     | <input type="text"/>                            | Cubic Capacity | <input type="text"/>                             |         |                                          |

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004484MFSH

Our Ref: CS/FCI18010288/Krd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5307Y .**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06.06.2018 at the premises of M/s TRANS-CAB AUTO PTE LTD and have the following to report:-

|                          |                                     |
|--------------------------|-------------------------------------|
| Workshop Estimate Amount | : S\$ <u>27,268.04</u> .            |
| Revised Estimate Amount  | : S\$ <u>5,442.38</u> .             |
| "Check" Items Amount     | : S\$ <u>                    </u> . |
| Market Value             | : S\$ <u>-</u> .                    |
| LTA Reimbursement Value  | : S\$ <u>-</u> .                    |
| Nett Value               | : S\$ <u>-</u> .                    |

Description of Damage:

The vehicle sustained damages  
at o/s body.



Yours faithfully  
KENNETH  
Automotive Assessor

[> Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                      |
|-------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                      |
| Owner ID Type:                      | Company                              |
| Owner ID:                           | 3878K                                |
| <b>Vehicle Details</b>              |                                      |
| Vehicle No.:                        | SHC5307Y                             |
| Vehicle to be Exported:             | Yes                                  |
| Intended De-registration Date:      | 04 Jun 2018                          |
| Vehicle Make:                       | RENAULT                              |
| Vehicle Model:                      | LATITUDE 2.0L DCI AUTO D/AB 4DR      |
| Primary Colour:                     | Red                                  |
| Manufacturing Year:                 | 2013                                 |
| Engine No.:                         | M9R8839C000961                       |
| Chassis No.:                        | VF1ABL15AUC276796                    |
| Maximum Power Output:               | 127.0 kW (170 bhp)                   |
| Open Market Value:                  | \$19,998.00                          |
| Original Registration Date:         | 21 Mar 2014                          |
| First Registration Date:            | 21 Mar 2014                          |
| Transfer Count:                     | 0                                    |
| Actual ARF Paid:                    | \$12,498.00                          |
| <b>Intended PARF Rebate Details</b> |                                      |
| PARF Eligibility:                   | Yes                                  |
| PARF Eligibility Expiry Date:       | 20 Mar 2022                          |
| PARF Rebate Amount:                 | \$9,373.00                           |
| <b>Intended COE Rebate Details</b>  |                                      |
| COE Expiry Date:                    | 20 Mar 2022                          |
| COE Category:                       | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):                  | 8                                    |
| PQP Paid:                           | \$58,745.00                          |
| COE Rebate Amount:                  | \$27,852.00                          |
| <b>Total Rebate Amount:</b>         | <b>\$37,225.00</b>                   |
| <b>Message</b>                      |                                      |

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Jun 2018

OK

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5307Y****AAD1806-016***Not Authorized  
C/Smp \$ 4350k*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC 5307Y**

VF1ABL15AUC276796

RENAULT

LATITUDE

2.6.2018

**FCIL****PART****LIST**

|   |                               |    |                     |   |
|---|-------------------------------|----|---------------------|---|
| 1 | FENDER PANEL FRT LH           | \$ | <i>N</i> 783.83     | X |
| 1 | WHEELARCH FRT LH              | \$ | <i>Sn</i> 278.84    | X |
| 1 | FENDER BRACKET LOWER LH       | \$ | <i>Sn</i> 15.79     | X |
| 1 | FENDER INSULATOR LH           | \$ | <i>Sn</i> 130.84    | X |
| 1 | DOOR PANEL FRT LH             | \$ | <i>By</i> 2,844.66  | ✓ |
| 1 | DOOR HINGE UPPER LH L70Y      | \$ | <i>N</i> 261.28     | X |
| 1 | DOOR HINGE LOWER LH           | \$ | <i>N</i> 300.55     | X |
| 1 | DOOR CHECK FRT LH             | \$ | <i>Sn</i> 194.77    | X |
| 1 | DOOR CHECK BOLT               | \$ | <i>Sn</i> 22.69     | X |
| 1 | DOOR LOCK FRT LH              | \$ | <i>N</i> 908.75     | X |
| 1 | DOOR CATCH FRT LH             | \$ | <i>Sn</i> 131.23    | X |
| 1 | DOOR HANDLE OUTER FRT LH      | \$ | <i>mir</i> 477.76   | ✓ |
| 1 | DOOR HANDLE COVER FRT LH      | \$ | <i>mir</i> 13.22    | ✓ |
| 1 | DOOR HANDLE MODULE FRT LH     | \$ | <i>mir</i> 133.60   | ✓ |
| 1 | DOOR REGULATOR FRT LH         | \$ | <i>N</i> 505.19     | X |
| 1 | DOOR REGUALTOR MOTOR FRT LH   | \$ | <i>Sn</i> 796.46    | X |
| 1 | DOOR REGULATOR GUIDE FRT LH   | \$ | <i>Sn</i> 120.97    | X |
| 1 | DOOR PANEL REAR LH L70Y       | \$ | <i>N</i> 2,844.66   | X |
| 1 | DOOR MIRROR ASSY LH           | \$ | <i>CMS</i> 1,483.40 | ✓ |
| 1 | ROCKER PANEL INNER GARNISH LH | \$ | <i>Sn</i> 466.51    | X |
| 1 | ROCKER PANEL INNER LH         | \$ | <i>N</i> 1,024.79   | X |
| 1 | ROCKER PANEL CENTER LH        | \$ | <i>N</i> 990.25     | X |
| 1 | DOOR HARNESS WIRE             | \$ | <i>Sn</i> 2,670.00  | X |

|    |                  |
|----|------------------|
| \$ | <b>17,400.05</b> |
|----|------------------|

|        |                 |
|--------|-----------------|
| 10% \$ | <b>1,740.00</b> |
|--------|-----------------|

|    |                  |
|----|------------------|
| \$ | <b>15,660.04</b> |
|----|------------------|



**Trans-cab Auto Services Pte Ltd**

AAD1806-016

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5307Y

**Special Nett**

|      |                                |    |    |        |      |
|------|--------------------------------|----|----|--------|------|
| 1SET | BUMPER CLIP FRT                | \$ | na | 66.00  |      |
| 1    | BUMPER BRACKET CLIP FRT LH     | \$ | na | 12.00  |      |
| 1    | BUMPER SUPPORT CLIP FRT LH     | \$ | na | 10.50  |      |
| 1SET | BUMPER GRILLE LOWER CLIP       | \$ | na | 69.00  |      |
| 1SET | FRAME FULL SUPPORT PANEL CLIP  | \$ | na | 70.00  |      |
| 2    | FRAME FULL SUPPORT PANEL NUT   | \$ | na | 20.00  |      |
| 2    | FRAME FULL SUPPORT PANEL STUD  | \$ | na | 30.00  |      |
| 1SET | WHEELARCH CLIP FRT LH          | \$ | na | 30.50  |      |
| 1    | FRONT DOOR STICKER 'Trans-cab' | \$ | na | 80.00  | 60sa |
| 1    | FRONT DOOR STICKER 'Chassis'   | \$ | na | 50.00  | 15sa |
| 1    | REAR DOOR STICKER '6555 3333'  | \$ | na | 80.00  | 60sa |
| 1    | FRONT LEFT TYRE RIM            | \$ | na | 380.00 | X    |

|              |           |               |
|--------------|-----------|---------------|
| <b>TOTAL</b> | <b>\$</b> | <b>898.00</b> |
|--------------|-----------|---------------|

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>16,558.04</b> |
|--------------------|-----------|------------------|

**LABOUR**

|                                                                                                                           |    |          |          |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|----------|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 4,500.00 | 30d      |
| Putty and spray painting of the affected portion.                                                                         | \$ | 4,000.00 | 50d      |
| To rust-proofing of the affected areas.                                                                                   | \$ | 170.00   | 3d       |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | na       | 380.00 X |
| To check steering geometry and computer wheel alignment                                                                   | \$ | na       | 220.00 X |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | na       | 170.00 X |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00   | 2d       |

**Trans-cab Auto Services Pte Ltd****AAD1806-016**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5307Y**

To transfer of front fender fittings, attachment and  
perform water seepage test. \$ *na* 380.00 X

To vacuum, replace, refix and recharge air condenser \$ 4 380.00 X

To replace, refix and top up coolant for radiator \$ 4 170.00 X

To vacuum, replace, refix and recharge Air Intercooler \$ 4 170.00 X

**TOTAL \$ 10,710.00**

**Over All Total \$ 27,268.04**

**LUMP SUM (REPAIR DAY)****15 DAYS***2 1/2 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                              |                             |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|--|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                              | Ref : CS/FCI18010288/Krd3n2 |                                                                                     |  |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                              | Date : 20-06-2018           |  |  |
|                                                                                                                                                                                        |                                                                              | Code : FCI2                 |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                              |                             |                                                                                     |  |
| Insured Veh.                                                                                                                                                                           | SHB 6398H                                                                    | Veh. Inspected              | SHC 5307Y                                                                           |  |
| Policy No.                                                                                                                                                                             | D-18088936MFSH                                                               | Coverage (\$)               | 0.00                                                                                |  |
| Claim No.                                                                                                                                                                              | D18004484MFSH                                                                | Excess (\$)                 | 0.00                                                                                |  |
| Assign From                                                                                                                                                                            | EILEEN                                                                       | Assign Date                 | 06/06/2018                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                              |                             |                                                                                     |  |
| Make & Model                                                                                                                                                                           | RENAULT LATITUDE (A)                                                         | c.c                         | 1995                                                                                |  |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                       | Year of Reg.                | 2014                                                                                |  |
| Chassis No.                                                                                                                                                                            | VF1ABL15AUC276796                                                            | Colour                      | WHITE / RED                                                                         |  |
| Odometer                                                                                                                                                                               | 331570                                                                       | Steering                    | IN ORDER                                                                            |  |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                     | Modification                | NIL                                                                                 |  |
| General                                                                                                                                                                                | GOOD                                                                         |                             |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                              |                             |                                                                                     |  |
|                                                                                                                                                                                        | Size                                                                         | Make                        | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                   | GITI                        | 9 mm                                                                                |  |
| L/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                   | GITI                        | 9 mm                                                                                |  |
| R/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                   | GITI                        | 9 mm                                                                                |  |
| L/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                   | GITI                        | 9 mm                                                                                |  |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                              |                             |                                                                                     |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.                                                                                                                                         |                                                                              |                             |                                                                                     |  |
| DAMAGES SEE DETAILS.                                                                                                                                                                   |                                                                              |                             |                                                                                     |  |
| <b>5. General Information</b>                                                                                                                                                          |                                                                              |                             |                                                                                     |  |
| Accident Date                                                                                                                                                                          | 02/06/2018                                                                   | Inspection Date             | 06/06/2018                                                                          |  |
| Survey held at                                                                                                                                                                         | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                             |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                              |                             |                                                                                     |  |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                             |                                                                                     |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                              |                             |                                                                                     |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                              | 2.500 Working Days          |                                                                                     |  |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5307Y

| Qty | Description of Parts          | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>   |                      |                           |                   |
| 1   | FENDER PANEL FRT LH           | TO REPAIR SEE LABOUR | 783.83                    | -                 |
| 1   | WHEELARCH FRT LH              | SERVICEABLE          | 278.84                    | -                 |
| 1   | FENDER BRACKET LOWER LH       | SERVICEABLE          | 15.79                     | -                 |
| 1   | FENDER INSULATOR LH           | SERVICEABLE          | 130.84                    | -                 |
| 1   | DOOR PANEL FRT LH             | BENT                 | 2,844.66                  | 2,844.66          |
| 1   | DOOR HINGE UPPER LH L70Y      | TO REPAIR SEE LABOUR | 261.28                    | -                 |
| 1   | DOOR HINGE LOWER LH           | TO REPAIR SEE LABOUR | 300.55                    | -                 |
| 1   | DOOR CHECK FRT LH             | SERVICEABLE          | 194.77                    | -                 |
| 1   | DOOR CHECK BOLT               | SERVICEABLE          | 22.69                     | -                 |
| 1   | DOOR LOCK FRT LH              | TO REPAIR SEE LABOUR | 908.75                    | -                 |
| 1   | DOOR CATCH FRT LH             | SERVICEABLE          | 131.23                    | -                 |
| 1   | DOOR HANDLE OUTER FRT LH      | MISSING              | 477.76                    | 477.76            |
| 1   | DOOR HANDLE COVER FRT LH      | MISSING              | 13.22                     | 13.22             |
| 1   | DOOR HANDLE MODULE FRT LH     | MISSING              | 133.60                    | 133.60            |
| 1   | DOOR REGULATOR FRT LH         | TO REPAIR SEE LABOUR | 505.19                    | -                 |
| 1   | DOOR REGULATOR MOTOR FRT LH   | SERVICEABLE          | 796.46                    | -                 |
| 1   | DOOR REGULATOR GUIDE FRT LH   | SERVICEABLE          | 120.97                    | -                 |
| 1   | DOOR PANEL REAR LH L70Y       | TO REPAIR SEE LABOUR | 2,844.66                  | -                 |
| 1   | DOOR MIRROR ASSY LH           | CRACKED              | 1,483.40                  | 1,483.40          |
| 1   | ROCKER PANEL INNER GARNISH LH | SERVICEABLE          | 466.51                    | -                 |
| 1   | ROCKER PANEL INNER LH         | TO REPAIR SEE LABOUR | 1,024.79                  | -                 |
| 1   | ROCKER PANEL CENTER LH        | TO REPAIR SEE LABOUR | 990.25                    | -                 |
| 1   | DOOR HARNESS WIRE             | SERVICEABLE          | 2,670.00                  | -                 |
|     | LESS 10% DISCOUNT             |                      | -1,740.00                 | -495.26           |
|     |                               |                      | 15,660.04                 | 4,457.38          |

Report Ref No. CS/FCI18010288/Krd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                                                                                                                                                                                                                                                                                                | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | <b>SPECIAL NETT ITEMS</b>                                                                                                                                                                                                                                                                                                           |               |                           |                   |
| 1   | SET BUMPER CLIP FRT (SN)                                                                                                                                                                                                                                                                                                            | NOT NECESSARY | 66.00                     | -                 |
| 1   | BUMPER BRACKET CLIP FRT LH (SN)                                                                                                                                                                                                                                                                                                     | NOT NECESSARY | 12.00                     | -                 |
| 1   | BUMPER SUPPORT CLIP FRT LH (SN)                                                                                                                                                                                                                                                                                                     | NOT NECESSARY | 10.50                     | -                 |
| 1   | SET BUMPER GRILLE LOWER CLIP (SN)                                                                                                                                                                                                                                                                                                   | NOT NECESSARY | 69.00                     | -                 |
| 1   | SET FRAME FULL SUPPORT PANEL CLIP (SN)                                                                                                                                                                                                                                                                                              | NOT NECESSARY | 70.00                     | -                 |
| 2   | FRAME FULL SUPPORT PANEL NUT (SN)                                                                                                                                                                                                                                                                                                   | NOT NECESSARY | 20.00                     | -                 |
| 2   | FRAME FULL SUPPORT PANEL STUD (SN)                                                                                                                                                                                                                                                                                                  | NOT NECESSARY | 30.00                     | -                 |
| 1   | SET WHEELARCH CLIP FRT LH (SN)                                                                                                                                                                                                                                                                                                      | NOT NECESSARY | 30.50                     | -                 |
| 1   | FRONT DOOR STICKER "TRANS-CAB" (SN)                                                                                                                                                                                                                                                                                                 | NECESSARY     | 80.00                     | 60.00             |
| 1   | FRONT DOOR STICKER "CHASSIS" (SN)                                                                                                                                                                                                                                                                                                   | NECESSARY     | 50.00                     | 15.00             |
| 1   | REAR DOOR STICKER "6555-3333" (SN)                                                                                                                                                                                                                                                                                                  | NECESSARY     | 80.00                     | 60.00             |
| 1   | FRONT LEFT TYRE RIM (SN)                                                                                                                                                                                                                                                                                                            | SERVICEABLE   | 380.00                    | -                 |
|     |                                                                                                                                                                                                                                                                                                                                     |               | 898.00                    | 135.00            |
|     | <b>LABOUR</b>                                                                                                                                                                                                                                                                                                                       |               |                           |                   |
|     | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FENDER PANEL FRT LH,DOOR HINGE UPPER LH L70Y,DOOR HINGE LOWER LH,DOOR LOCK FRT LH,DOOR REGULATOR FRT LH,DOOR PANEL REAR LH L70Y,ROCKER PANEL INNER LH AND ROCKER PANEL CENTER LH. |               | 4,500.00                  | 300.00            |
|     | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                                                                                                                                                                                                                                   |               | 4,000.00                  | 500.00            |
|     | TO RUST-PROOFING OF THE AFFECTED AREAS                                                                                                                                                                                                                                                                                              |               | 170.00                    | 30.00             |
|     | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.                                                                                                                                                                                                                                        | NOT NECESSARY | 380.00                    | -                 |
|     | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                                                                                                                                                                                                                                                                            | NOT NECESSARY | 220.00                    | -                 |
|     | TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.                                                                                                                                                                                                                                                                                     | NOT NECESSARY | 170.00                    | -                 |
|     | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                                                                                                                                                                                                                             |               | 170.00                    | 20.00             |
|     | TO TRANSFER OF FRONT FENDER FITITNGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                                                     | NOT NECESSARY | 380.00                    | -                 |

Report Ref No. CS/FCI18010288/Krd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                  | Description of Parts                                  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------|-------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                      | TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.   | NOT NECESSARY | 380.00                    | -                 |
|                                                                      | TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.     | NOT NECESSARY | 170.00                    | -                 |
|                                                                      | TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER. | NOT NECESSARY | 170.00                    | -                 |
|                                                                      |                                                       |               | 10,710.00                 | 850.00            |
| GRAND TOTAL                                                          |                                                       |               | 27,268.04                 | 5,442.38          |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |                                                       |               |                           | 4,350.00          |

Report Ref No. CS/FC118010288/Krd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.