

INS. CASE OWNER:

CC

4/ Asm 180

10289 /

Cwa3

LKK:

IDAC:

50077

ASSIGNMENT

Surveyor:

Kenneth

DOI:

5/6/18

Date / Time:

5/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX7073A

Name of Insured:

Zhang Rui

Insured Tel No.:

HP:

80080866

Excess Sec II :SS

D.O.A.:

4/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

58m007JA

Policy No.:

G 7356083

Make / Model:

H-Jazz

Place of Accident:

Ple

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJB3458P



INSRS:

WSP:

Tel:

Liability:

RMKS:

AH Lim
6077777

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

12/6/18

SJB3458P-NBA/PAI/6013769/Y; DOA: 23/07/18
SLX7073A-X

12/6/18

confirm accident details. inform TP claim.
letter email out

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

6/6

Sent By:

bmr

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

S\$5,150.00

(10 days)

Reduction:

39 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: Mui Hong

Email

Call

ASS. REC. BY:

REF: AA /Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 834k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 109 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

6/6 File notes to Customer45: +5150 (RED: +3633.56 39%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Fixtures

Others

TOTAL

Veh No: STB 3458PYr Regn: 01, 08Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Civicc.c. 1799Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 205911

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMF-D 16308-S 270705Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hankook

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 4/8/18D.O.I. 5/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18010289/Kwa3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 06-06-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLX 7073A	Veh. Inspected	SJB 3458P	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00JJA	Excess (\$)	0.00	
Assign From		Assign Date	06/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/06/2018	Inspection Date	05/06/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JAMES ONG KAY SIANG
BLK 10P BRADDELL HILL
#03-67
SINGAPORE 579733

Estimate No: MC0913149
Date: 05 Jun 2018
Policy No: MT/00045111/06
Veh Reg No: SJB3458P
Make/Model: HONDA CIVIC 1.8L A

ATTN:

Your Ref No: SJB3458P
Claim Type: Third Party
Accident Date: 04/06/2018
TP Veh Reg No: SLX7073A

Estimate Repair Cost to Vehicle No :SJB3458P

Description	Quantity	List Price SS	Amount SS
SPARE PARTS			
1 REAR BOOT	1 PC	By 610.70	✓
2 REAR BOOT-HINGE-LH & RH	2 PC	By 97.20	X
3 REAR BOOT EMBLEM	1 PC	By 25.70	✓
4 REAR BOOT CIVIC LOGO	1 PC	By 29.10	✓
5 REAR BOOT I-VTEC LOGO	1 PC	By 34.10	✓
6 REAR BOOT LAMP LH & RH	2 PC	291.80	✓
7 REAR BOOT NO PLATE LAMP LH & RH	2 PC	36.00	X
8 REAR BOOT NO PLATE GARNISH	1 PC	By 121.60	X
9 REAR BOOT OUTER LOCK CYLINDER	1 PC	By 97.20	X
10 REAR BOOT RUBBER	1 PC	By 97.60	30% ✓
11 REAR BOOT INSULATOR	1 PC	133.70	✓
12 REAR BOOT INSULATOR CLIPS	10 PC	By 35.00	✓
13 REAR BOOT INNER LOCK	1 PC	By 194.50	✓
14 REAR BOOT INNER LOCK STRIKER	1 PC	By 27.50	X
15 TAILAMP LH & RH	2 PC	CM 452.40	✓
16 TAILAMP PANEL LH & RH	2 PC	By 131.40	X
17 REAR BUMPER	1 PC	By 638.00	✓
18 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	By 29.20	✓
19 REAR BUMPER CLIPS	15 PC	By 58.50	✓
20 REAR BUMPER BRACKET LH & RH	2 PC	By 27.80	✓
21 REAR BUMPER MUDFLAP LH & RH	2 PC	CM 149.80	✓
22 REAR END PANEL	1 PC	By 300.50	✓
23 REAR END PANEL TOP GARNISH	1 PC	By 56.10	✓
24 SPARE TYRE PANEL	1 PC	By 992.00	✓
25 SPARE TYRE PANEL TOP TRIMBOARD	1 PC	By 316.00	✓
26 TOOLBOX	1 PC	By 46.80	X
27 SPARE TYRE BRACKET BOLT	1 PC	By 10.00	✓
28 SPARE TYRE HOLDER ADAPTER	1 PC	By 9.00	✓
29 REAR FENDER INNER TRIM LH & RH	2 PC	By 291.80	X
30 REAR FENDER INNER TRIM CLIPS	20 PC	By 90.00	X
31 REAR EXHAUST PIPE	1 PC	By 535.00	✓
32 REAR EXHAUST PIPE CHROME LH & RH	2 PC	By 197.40	✓
33 REAR EXHAUST PIPE MOUNTING	4 PC	By 66.00	✓
34 REAR EXHAUST PIPE TOP HEAT SHIELD	1 PC	By 43.80	✓
		6,273.20	
Less 20%		1,254.64	5,018.56

Special Nett



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JAMES ONG KAY SIANG
BLK 10P BRADDELL HILL
#03-67
SINGAPORE 579733

Estimate No: MC0913149
Date: 05 Jun 2018
Policy No: MT/00045111/06
Veh Reg No: SJB3458P
Make/Model: HONDA CIVIC 1.8L A

ATTN:
Your Ref No: SJB3458P
Claim Type: Third Party
Accident Date: 04/06/2018
TP Veh Reg No: SLX7073A

Estimate Repair Cost to Vehicle No :SJB3458P

Description	Quantity	List Price	Amount
		SS	SS
35 NUMBER-PLATE	1 PC	35.00	X
36 REVERSE SENSOR	1 SET	200.00	✓
37 SPARE TYRE CHECK PRICE	1 PC	0.00	7
38 SPARE TYRE RIM CHECK PRICE	1 PC	0.00	7
		235.00	235.00

LABOUR

39 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	200
40 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	600
41 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	1000
42 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	350.00	2200
43 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	500
44 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	120.00	900
45 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00	600
46 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL, TAILAMP PANEL LH & RH. TO KNOCK & REPAIR REAR FENDER LH & RH, REAR CHASSIS LH & RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,600.00	12000
47 TO SPRAY REAR BOOT, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, TAILAMP PANEL LH & RH, REAR CHASSIS LH & RH.	1 PC	1,600.00	18000
		4,130.00	4,130.00

Total S\$ 9,383.56

Add GST @ 7% 656.85

Total Amount Payable S\$ 10,040.41

TOTAL: SINGAPORE DOLLAR TEN THOUSAND FORTY AND CENTS FORTY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

9880.32

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : JAMES ONG KAY SIANG
BLK 10P BRADDELL HILL
#03-67
SINGAPORE 579733

Estimate No: MC0913149
Date: 13 Jun 2018
Policy No: MT/00045111/06
Veh Reg No: SJB3458P
Make/Model: HONDA CIVIC 1.8L A

ATTN:
Your Ref No: SJB3458P
Claim Type: Third Party
Accident Date: 04/06/2018
TP Veh Reg No: SLX7073A

Estimate Repair Cost to Vehicle No :SJB3458P

Description	Quantity	List Price S\$	Amount S\$
Supplementary Parts to Repair			
SPARE PARTS			
1 REAR EXHAUST CENTRE PIPE	1 PC	620.95	
		620.95	
	Less 20%	124.19	496.76
	Total		S\$ 496.76
	GST Amount		S\$ 34.77
	Total Amount Payable		S\$ 531.53

The above vehicle was surveyed by KENNETH KONG -LKK on 05/06/2018

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Endorsed by Repairer:



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : JAMES ONG KAY SIANG
BLK 10P BRADDELL HILL
#03-67
SINGAPORE 579733

Claim No: MC0913149
No: MF0911177
Date: 28 Jul 2018
Policy No: MT/00045111/06
Veh Reg No: SJB3458P
Make/Model: HONDA CIVIC 1.8L A

ATTN:

Your Ref No: SJB3458P
Claim Type: Third Party
Accident Date: 04/06/2018
TP Veh Reg No: SLX7073A

Repair Cost to Vehicle No (For Finalization):SJB3458P

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT	1 PC	610.70	
2 REAR BOOT EMBLEM	1 PC	25.70	
3 REAR BOOT CIVIC LOGO	1 PC	29.10	
4 REAR BOOT I-VTEC LOGO	1 PC	34.10	
5 REAR BOOT LAMP RH	1 PC	145.90	
6 REAR BOOT INSULATOR	1 PC	133.70	
7 REAR BOOT INSULATOR CLIPS	10 PC	35.00	
8 REAR BOOT INNER LOCK	1 PC	194.50	
9 TAILAMP LH & RH	2 PC	452.40	
10 REAR BUMPER	1 PC	638.00	
11 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	29.20	
12 REAR BUMPER CLIPS	15 PC	58.50	
13 REAR BUMPER BRACKET LH & RH	2 PC	27.80	
14 REAR BUMPER MUDFLAP LH & RH	2 PC	149.80	
15 REAR END PANEL	1 PC	300.50	
16 REAR END PANEL TOP GARNISH	1 PC	56.10	
17 SPARE TYRE PANEL	1 PC	992.00	
18 SPARE TYRE PANEL TOP TRIMBOARD	1 PC	316.00	
19 SPARE TYRE BRACKET BOLT	1 PC	10.00	
20 REAR EXHAUST PIPE CHROME LH & RH	2 PC	197.40	
21 REAR EXHAUST PIPE TOP HEAT SHIELD	1 PC	43.80	
22 REAR EXHAUST CENTRE PIPE	1 PC	620.95	
		5,101.15	
	Less 20%	1,020.23	4,080.92
Special Nett			
23 REAR BOOT RUBBER (50% OF 97.60)	1 PC	48.80	
24 REVERSE SENSOR	1 SET	200.00	
		248.80	248.80
LABOUR			
25 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
26 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	60.00	
27 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	100.00	
28 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	220.00	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : JAMES ONG KAY SIANG
BLK 10P BRADDELL HILL
#03-67
SINGAPORE 579733

Claim No: MC0913149
No: MF0911177
Date: 28 Jul 2018
Policy No: MT/00045111/06
Veh Reg No: SJB3458P
Make/Model: HONDA CIVIC 1.8L A

ATTN:

Your Ref No: SJB3458P
Claim Type: Third Party
Accident Date: 04/06/2018
TP Veh Reg No: SLX7073A

Repair Cost to Vehicle No (For Finalization):SJB3458P

Description	Quantity	List Price S\$	Amount S\$
29 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
30 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	90.00	
31 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	60.00	
32 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,SPARE TYRE PANEL,TAILAMP PANEL LH & RH.TO KNOCK & REPAIR REAR FENDER LH & RH,REAR CHASSIS LH & RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,200.00	
33 TO SPRAY REAR BOOT,REAR BUMPER,END PANEL, SPARE TYRE PANEL,REAR FENDER LH & RH,TAILAMP PANEL LH & RH,REAR CHASSIS LH & RH.	1 PC	1,100.00	
		2,900.00	2,900.00
	Total		S\$ 7,229.72
	Lump Sum Less 20%		-1,445.94
	Sub Total		S\$ 5,783.78
	Less Rounding		-33.78
	Lum Sum Repair		S\$ 5,750.00
	Less Excess		S\$ 0.00
	Amount Before GST		S\$ 5,750.00
	Add GST @ 7%		402.50
	Total Amount Payable		S\$ 6,152.50

TOTAL: SINGAPORE DOLLAR SIX THOUSAND ONE HUNDRED FIFTY TWO AND CENTS FIFTY ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 05/06/2018

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JAMES ONG KAY SIANG
BLK 10P BRADDELL HILL
#03-67
SINGAPORE 579733

Estimate No: MC0913149
Date: 05 Jun 2018
Policy No: MT/00045111/06
Veh Reg No: SJB3458P
Make/Model: HONDA CIVIC 1.8L A

ATTN:

Your Ref No: SJB3458P
Claim Type: Third Party → AXA
Accident Date: 04/06/2018
TP Veh Reg No: SLX7073A

Not Authorised
11 Lyr @ 7
Recovery After Paving 10 days

Estimate Repair Cost to Vehicle No :SJB3458P

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BOOT	1 PC	610.70	✓
2 REAR BOOT HINGE LH & RH	2 PC	97.20	X
3 REAR BOOT EMBLEM	1 PC	25.70	✓
4 REAR BOOT CIVIC LOGO	1 PC	29.10	✓
5 REAR BOOT I-VTEC LOGO	1 PC	34.10	✓
6 REAR BOOT LAMP LH & RH	2 PC	291.80	X
7 REAR BOOT NO PLATE LAMP LH & RH	2 PC	36.00	X
8 REAR BOOT NO PLATE GARNISH	1 PC	121.60	7
9 REAR BOOT OUTER LOCK CYLINDER	1 PC	97.20	X
10 REAR BOOT RUBBER	1 PC	97.60	50% off
11 REAR BOOT INSULATOR	1 PC	133.70	✓
12 REAR BOOT INSULATOR CLIPS	10 PC	35.00	✓
13 REAR BOOT INNER LOCK	1 PC	194.50	✓
14 REAR BOOT INNER LOCK STRIKER	1 PC	27.50	X
15 TAILAMP LH & RH	2 PC	452.40	✓
16 TAILAMP PANEL LH & RH	2 PC	131.40	X
17 REAR BUMPER	1 PC	638.00	✓
18 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	29.20	✓
19 REAR BUMPER CLIPS	15 PC	58.50	✓
20 REAR BUMPER BRACKET LH & RH	2 PC	27.80	✓
21 REAR BUMPER MUDFLAP LH & RH	2 PC	149.80	✓
22 REAR END PANEL	1 PC	300.50	✓
23 REAR END PANEL TOP GARNISH	1 PC	56.10	✓
24 SPARE TYRE PANEL	1 PC	992.00	✓
25 SPARE TYRE PANEL TOP TRIMBOARD	1 PC	316.00	✓
26 TOOLBOX	1 PC	46.80	X
27 SPARE TYRE BRACKET BOLT	1 PC	10.00	✓
28 SPARE TYRE HOLDER ADAPTER	1 PC	9.00	7
29 REAR FENDER INNER TRIM LH & RH	2 PC	291.80	X
30 REAR FENDER INNER TRIM CLIPS	20 PC	90.00	X
31 REAR EXHAUST PIPE	1 PC	535.00	7
32 REAR EXHAUST PIPE CHROME LH & RH	2 PC	197.40	✓
33 REAR EXHAUST PIPE MOUNTING	4 PC	66.00	7
34 REAR EXHAUST PIPE TOP HEAT SHIELD	1 PC	43.80	7
		6,273.20	
Less 20%		1,254.64	5,018.56

Special Nett



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JAMES ONG KAY SIANG
BLK 10P BRADDELL HILL
#03-67
SINGAPORE 579733

Estimate No: MC0913149
Date: 05 Jun 2018
Policy No: MT/00045111/06
Veh Reg No: SJB3458P
Make/Model: HONDA CIVIC 1.8L A

ATTN:
Your Ref No: SJB3458P
Claim Type: Third Party
Accident Date: 04/06/2018
TP Veh Reg No: SLX7073A

Estimate Repair Cost to Vehicle No :SJB3458P

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
35 NUMBER PLATE	1 PC	35.00	X
36 REVERSE SENSOR	1 SET	200.00	✓
37 SPARE TYRE - CHECK PRICE	1 PC	0.00	7
38 SPARE TYRE RIM - CHECK PRICE	1 PC	0.00	7
		235.00	235.00
LABOUR			
39 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20d
40 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	60d
41 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	100d
42 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	350.00	220d
43 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	50d
44 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	120.00	90d
45 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00	60d
46 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,SPARE TYRE PANEL,TAILAMP PANEL LH & RH.TO KNOCK & REPAIR REAR FENDER LH & RH,REAR CHASSIS LH & RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,600.00	1200d
47 TO SPRAY REAR BOOT,REAR BUMPER,END PANEL, SPARE TYRE PANEL,REAR FENDER LH & RH,TAILAMP PANEL LH & RH,REAR CHASSIS LH & RH.	1 PC	1,600.00	1100d
		4,130.00	4,130.00

Total SS 9,383.56

Add GST @ 7% 656.85

Total Amount Payable SS 10,040.41

TOTAL: SINGAPORE DOLLAR TEN THOUSAND FORTY AND CENTS FORTY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You



For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 6/6/2018

Survey Details:

Date of loss	4-Jun-18
Date of appointment	5-Jun-18
Date of survey	5-Jun-18
Location of survey	AH LIM MOTOR COMPANY

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SJB 3458P
Make and Model	HYUNDAI CIVIC 1.8L A - 1799cc
Date of registration	9-Jan-08
Excess	
Market Value	\$ 34,000.00
Part Rebate	\$ 24,014.00
Nett Loss	\$ 9,986.00

Repair details:

Initial Estimate	\$ 9,383.56
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 3,797.92
Check items (estimate)	\$ 620.32
Labour	\$ 2,900.00
Total	\$ 7,318.24
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>10 days</u>
---------------------------	----------------



Service Request Details

Claim

S8M00JJA

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Reference

None

Loss Date

June 4, 2018

Request Date

June 5, 2018

Due Date

June 12, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

05062018 @ 2.09pm
Wei Jie veh in.
Kenneth.

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

SJB3458P

Make

TPVD HONDA

Service Address

...

Primary Contact/Insured

ZHANG RUI

604C, EAST COAST ROAD, 459002, Singapore

81020866

Claim Handler

TAY Ernest

6568804835

ernest.tay@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



MANDATE IA (S8M00JJA)

Type

 Question

Message

Liability: Insured swerved into third party lane and hit third party vehicle (refer to tp video). Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$6,152.50 (w/GST) Loss of Rental: \$1,560.00 (13days x \$120) LTA : \$2.00 Total: \$7,714.50 Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (06/03/2019)

Reply



Re:MANDATE IA (S8M00JJA)

Type

🔗 Question

Message

PLS PROCEED FOR SETTLEMENT AS FOLLOWS: COR \$5,842.20 W/GST LOR \$1,200.00 LTA \$2.00 TOTAL
\$7,044.00 ~ \$7,050.00 LOR SUBJECTED TO TP RENTED VEH

Reply



Re:RE: Re:MANDATE IA (S8M00JJA)

Type

🔗 Question

Message

PLS PROCEED AS PROPOSED LOR SUBJECTED TO TP RENTED VEH

Reply



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

Our Ref : MC0913149

Your Ref : SLX7073A

Date : 04/08/2018

AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

Dear Sir/Madam,

Request for Direct Settlement for Accident involving our client's vehicle SJB3458P and your Insured SLX7073A ON 04/06/2018 13:45 ALONG PIE TWDS CITY NEAR KALLANG BENDEMEER EXIR

We refer to the above matter.

Please assess through your Insured's (SLX7073A) report and our Client (SJB3458P) – JAMES ONG KAY SIANG's report as attached and advise whether there are possibilities of direct settlement.

Please find attached the following :

- 1) Final Bill
- 2) GIA Motor Accident Report form
- 3) Certificate of Insurance, IC and Driving Licence, Vehicle Acknowledgement form
- 4) LTA Search & Rental Invoice

The above vehicle was surveyed by Kenneth from LKK as appointed by AXA on 05/06/2018.

We would quantify our claim as below:-

Cost of Repair : \$6,152.50

Rental : \$1,560.00(13 Day X \$120) Surveyor recommend 10 days . Add 2 Sundays and 1

Public Holiday

LTA Search : \$2.00

=====

Total : \$7,714.50

Kindly acknowledge and revert on the possibility of direct settlement within 14 days.

Thank You.

Yours faithfully,

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 Fax: 6483 6170

Kee Mui Hong

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLX 7073A (Insd veh)	Model:	HONDA CIVIC (A)
	SJB 3458P (TP veh)		
Date of Accident:	04/06/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	10,571.94
Final Repair Cost	:	\$	6,152.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,560.00 13 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	7,714.50

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	AH LIM MOTOR COMPANY	:	\$ 7,714.50

NUR SHAQILAH BTE ABDOL
WAHAB

02/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18010289/Kea3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN			Date : 02-05-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLX 7073A	Veh. Inspected	SJB 3458P	
Policy No.	GA354083	Coverage (\$)	0.00	
Claim No.	S8M00JJA	Excess (\$)	0.00	
Assign From	KIAN CHUAN	Assign Date	05/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMF16308S210705	Colour	WHITE	
Odometer	205911	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55R16	HANKOOK	5 mm	
L/H Front Tyre	205/55R16	HANKOOK	5 mm	
R/H Rear Tyre	205/55R16	HANKOOK	5 mm	
L/H Rear Tyre	205/55R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/06/2018	Inspection Date	05/06/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 3458P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT (CONSISTENT)	BENT	610.70	610.70
2	REAR BOOT HINGE LH & RH (CONSISTENT)	TO REPAIR SEE LABOUR	97.20	-
1	REAR BOOT EMBLEM (CONSISTENT)	NECESSARY	25.70	25.70
1	REAR BOOT CIVIC LOGO (CONSISTENT)	NECESSARY	29.10	29.10
1	REAR BOOT I-VTEC LOGO (CONSISTENT)	NECESSARY	34.10	34.10
2	REAR BOOT LAMP LH & RH (CONSISTENT)	O/S CRACKED	291.80	145.90
2	BOOT LID NO PLATE LAMP LH & RH (CONSISTENT)	SERVICEABLE	36.00	-
1	REAR BOOT NO PLATE GARNISH (CONSISTENT)	NOT NECESSARY	121.60	-
1	REAR BOOT OUTER LOCK CYLINDER (CONSISTENT)	SERVICEABLE	97.20	-
1	REAR BOOT INSULATOR (CONSISTENT)	DEFORMED	133.70	133.70
10	REAR BOOT INSULATOR CLIPS (CONSISTENT)	NECESSARY	35.00	35.00
1	REAR BOOT INNER LOCK (CONSISTENT)	DENTED	194.50	194.50
1	REAR BOOT INNER LOCK STRIKER (CONSISTENT)	TO REPAIR SEE LABOUR	27.50	-
2	TAILAMP LH & RH (CONSISTENT)	CRACKED	452.40	452.40
2	TAILAMP PANEL LH & RH (CONSISTENT)	TO REPAIR SEE LABOUR	131.40	-
1	REAR BUMPER (CONSISTENT)	BENT	638.00	638.00
2	REAR BUMPER SIDE RETAINERS LH & RH (CONSISTENT)	DISTORTED	29.20	29.20
15	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	58.50	58.50
2	REAR BUMPER BRACKET LH & RH (CONSISTENT)	DISTORTED	27.80	27.80
2	REAR BUMPER MUDFLAP LH & RH (CONSISTENT)	CRACKED	149.80	149.80
1	REAR END PANEL (CONSISTENT)	BENT	300.50	300.50
1	REAR END PANEL TOP GARNISH (CONSISTENT)	MTG DISTORTED	56.10	56.10
1	SPARE TYRE PANEL (CONSISTENT)	BENT / BUCKLED	992.00	992.00
1	SPARE TYRE PANEL TOP TRIMBOARD (CONSISTENT)	DEFORMED	316.00	316.00
1	TOOLBOX (CONSISTENT)	SERVICEABLE	46.80	-
1	SPARE TYRE BRACKET BOLT (CONSISTENT)	BENT	10.00	10.00
1	SPARE TYRE HOLDER ADAPTER (CONSISTENT)	SERVICEABLE	9.00	-
2	REAR FENDER INNER TRIM LH & RH (CONSISTENT)	SERVICEABLE	291.80	-

Report Ref No. CC4/ASM18010289/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
20	REAR FENDER INNER TRIM CLIPS (CONSISTENT)	NOT NECESSARY	90.00	-
1	REAR EXHAUST PIPE (CONSISTENT)	TO REPAIR SEE LABOUR	535.00	-
2	REAR EXHAUST PIPE CHROME LH & RH (CONSISTENT)	DENTED	197.40	197.40
4	REAR EXHAUST PIPE MOUNTING (CONSISTENT)	SERVICEABLE	66.00	-
1	REAR EXHAUST PIPE TOP HEAT SHIELD (CONSISTENT)	DENTED	43.80	43.80
1	REAR EXHAUST CENTRE PIPE (CONSISTENT) (ADDITIONAL)	BENT	620.95	620.95
	LESS 20% DISCOUNT		-1,359.31	-1,020.23
			5,437.24	4,080.92
1	REAR BOOT RUBBER (50%) (SN) (CONSISTENT)	DENTED / DISTORTED	97.60	48.80
	LESS 20% DISCOUNT		-19.52	-
			78.08	48.80
	SPECIAL NETT ITEMS			
1	NUMBER PLATE (SN) (CONSISTENT)	SERVICEABLE	35.00	-
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	200.00	200.00
1	SPARE TYRE (NPA) (SN) (CONSISTENT)	SERVICEABLE	-	-
1	SPARE TYRE RIM (NPA) (SN) (CONSISTENT)	SERVICEABLE	-	-
			235.00	200.00
	LABOUR			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		80.00	60.00
	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		180.00	100.00
	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.		350.00	220.00
	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR BUMPER SENSORS.		80.00	50.00
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.		120.00	90.00

Report Ref No. CC4/ASM18010289/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REALIGN, DISMANTLE AND REINSTALL / REPLACE EXHAUST PIPE.		80.00	60.00
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL, TAILAMP PANEL LH & RH. TO KNOCK & REPAIR REAR FENDER LH & RH, REAR CHASSIS LH & RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF REAR BOOT HINGE LH & RH, REAR BOOT INNER LOCK STRIKER, TAILAMP PANEL LH & RH AND REAR EXHAUST PIPE.		1,600.00	1,200.00
	TO SPRAY REAR BOOT, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, TAILAMP PANEL LH & RH, REAR CHASSIS LH & RH.		1,600.00	1,100.00
			4,130.00	2,900.00
GRAND TOTAL			9,880.32	7,229.72

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,750.00
--	--	--	----------

Report Ref No. CC4/ASM18010289/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.