



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JAMES ONG KAY SIANG
BLK 10P BRADDELL HILL
#03-67
SINGAPORE 579733

Estimate No: MC0913149
Date: 05 Jun 2018
Policy No: MT/00045111/06
Veh Reg No: SJB3458P
Make/Model: HONDA CIVIC 1.8L A

ATTN:

Your Ref No: SJB3458P
Claim Type: Third Party → AXA
Accident Date: 04/06/2018
TP Veh Reg No: SLX7073A

Not Notarize
11 Lyr @ 7
Repair After Pains 10 days

Estimate Repair Cost to Vehicle No :SJB3458P

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BOOT	1 PC	610.70	✓
2 REAR BOOT HINGE LH & RH	2 PC	97.20	X
3 REAR BOOT EMBLEM	1 PC	25.70	✓
4 REAR BOOT CIVIC LOGO	1 PC	29.10	✓
5 REAR BOOT I-VTEC LOGO	1 PC	34.10	✓
6 REAR BOOT LAMP LH & RH	2 PC	291.80	✓
7 REAR BOOT NO PLATE LAMP LH & RH	2 PC	36.00	X
8 REAR BOOT NO PLATE GARNISH	1 PC	121.60	?
9 REAR BOOT OUTER LOCK CYLINDER	1 PC	97.20	X
10 REAR BOOT RUBBER	1 PC	97.60	✓
11 REAR BOOT INSULATOR	1 PC	133.70	✓
12 REAR BOOT INSULATOR CLIPS	10 PC	35.00	✓
13 REAR BOOT INNER LOCK	1 PC	194.50	✓
14 REAR BOOT INNER LOCK STRIKER	1 PC	27.50	X
15 TAILAMP LH & RH	2 PC	452.40	✓
16 TAILAMP PANEL LH & RH	2 PC	131.40	X
17 REAR BUMPER	1 PC	638.00	✓
18 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	29.20	✓
19 REAR BUMPER CLIPS	15 PC	58.50	✓
20 REAR BUMPER BRACKET LH & RH	2 PC	27.80	✓
21 REAR BUMPER MUDFLAP LH & RH	2 PC	149.80	✓
22 REAR END PANEL	1 PC	300.50	✓
23 REAR END PANEL TOP GARNISH	1 PC	56.10	✓
24 SPARE TYRE PANEL	1 PC	992.00	✓
25 SPARE TYRE PANEL TOP TRIMBOARD	1 PC	316.00	✓
26 TOOLBOX	1 PC	46.80	X
27 SPARE TYRE BRACKET BOLT	1 PC	10.00	✓
28 SPARE TYRE HOLDER ADAPTER	1 PC	9.00	?
29 REAR FENDER INNER TRIM LH & RH	2 PC	291.80	X
30 REAR FENDER INNER TRIM CLIPS	20 PC	90.00	X
31 REAR EXHAUST PIPE	1 PC	535.00	?
32 REAR EXHAUST PIPE CHROME LH & RH	2 PC	197.40	✓
33 REAR EXHAUST PIPE MOUNTING	4 PC	66.00	?
34 REAR EXHAUST PIPE TOP HEAT SHIELD	1 PC	43.80	?
		6,273.20	
Less 20%		1,254.64	5,018.56

Special Nett



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JAMES ONG KAY SIANG
BLK 10P BRADDELL HILL
#03-67
SINGAPORE 579733

Estimate No: MC0913149
Date: 05 Jun 2018
Policy No: MT/00045111/06
Veh Reg No: SJB3458P
Make/Model: HONDA CIVIC 1.8L A

ATTN:
Your Ref No: SJB3458P
Claim Type: Third Party
Accident Date: 04/06/2018
TP Veh Reg No: SLX7073A

Estimate Repair Cost to Vehicle No :SJB3458P

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
35 NUMBER PLATE	1 PC	35.00	X
36 REVERSE SENSOR	1 SET	200.00	✓
37 SPARE TYRE - CHECK PRICE	1 PC	0.00	7
38 SPARE TYRE RIM - CHECK PRICE	1 PC	0.00	7
		235.00	235.00
LABOUR			
39 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	200
40 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	600
41 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	1000
42 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	350.00	2200
43 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	500
44 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	120.00	900
45 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00	600
46 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD END PANEL, SPARE TYRE PANEL, TAILAMP PANEL LH & RH, TO KNOCK & REPAIR REAR FENDER LH & RH, REAR CHASSIS LH & RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,600.00	12000
47 TO SPRAY REAR BOOT, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, TAILAMP PANEL LH & RH, REAR CHASSIS LH & RH.	1 PC	1,600.00	14000
		4,130.00	4,130.00

Total S\$ 9,383.56

Add GST @ 7% 656.85

Total Amount Payable S\$ 10,040.41

TOTAL: SINGAPORE DOLLAR TEN THOUSAND FORTY AND ONE CENTS FORTY ONE ONLY

Please arrange this vehicle to be surveyed as soon as possible.
Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for viewing and price
- Parts prices are subject to confirmation
- Third party survey is on a "no prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE