

ASS. REC. BY:

REF: es/FCS18010291/N rd3 ⁿ² Special Instruction:

Surveyor: Schuyler ASSIGNMENT (Office)

From (Person): Eileen Lee of FCS Date/Time: 6/6/18 @ 1:01pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SIP 76342 Insured: SHC 2488C

at Workshop m/s: World Auto Tel: 64513933

of: No.1 Kranji loop

Policy No: _____ Claim No: D18004166MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23/05/2018

(Client's Record) CA / REV / REP. / REV 24 HRS ^(up) 19.06.2018 H.O.D. Endorsement: _____

Date/Time: 1:50pm @ 6/6/18 Person Contacted: Ainee Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SIP 76342-X</u>
	<u>SHC 2488C-CC3/A1909000610/Caw</u> <u>DOA: 06/01/2009</u>

REF: FCI

ASSIGNMENT

From: _____ Date: 19/6/18

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLP 7634Z

at Workshop m/s: World Auto

of: No. 1 Krunji loop

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SLP 7634Z Yr Regn: Jun / 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prius CC: 1798

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 111399 T/Radio: Insured / Std / NI / NA

Eng/No: 2ZRS052892

C/No: JTDKB3FU603560117

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: 195/65 R15
R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal. 6 mm		R/Bal. 6 mm	
L/Bal. 6 mm		L/Bal. 6 mm	
D.O.A. 23/5/2018		D.O.I. 19/6/2018	

Survey held at: World Auto

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Des. of Damages: Fr / Rear / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Final big \$1723.78 (Red. 443.72, 71%)

RECEIVED 15 OCT 2018

Date/Time File Pass to? : Preli. Report

: Final Report

Date/Time File Return to? _____

Report Format: TP

Lump Sum / (B): \$ 1723.78

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: Site Insp \$
 Interview \$
 Tech. Invs \$
 Weekend \$

Survey Fee: _____
Transportation: _____
S+RD: \$ _____
Photos: _____
Others: _____

145
50
50750
30
325

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010291/Vrd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2488C	Veh. Inspected	SLP 7634Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18004166MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	06/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/05/2018	Inspection Date	
Survey held at	NO.1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	24-05-2018	Our Ref No. D18004166MFSH
Accident Date	23-05-2018	Claim Type. Third Party
Insured Vehicle	SHC2488C	Third Party Vehicle. SLP7634Z
Survey Location	NO.1 KRANJI LOOP	
Contact Person.	YVONNE WONG	
Contact No.	64513933/ 0	Fax No. 64557576
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WORLD AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240730)



PRI Documents



Close



PRI Header Details

Claim No	D18004166MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & WORLD A
Workshop Name	WORLD AUTO PTE LTD (Contact Person : YVONNE WONG)	Survey Location & Contact Details	NO.1 KRANJI LOOP Mobile: 0 , Phone: 64513933 , Fax: 64557576 EmailId: YVONNE.WONG@WORLDAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC2488C	TP Vehicle No	SLP7634Z
PRI Recieved Date	04-06-2018 06:43:41 PM	Surveyor Appointed Date	06-06-2018 12:59:56 PM	Surveyor Accept Date	06-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	06-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLP7634Z
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR5052892
Chassis No.:	JTDKB3FU603560117
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	16 Jun 2017
First Registration Date:	16 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jun 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,106.00
COE Rebate Amount:	\$46,054.00
Total Rebate Amount:	\$49,804.00

The information contained herein is correct as at 13 Oct 2018

OK

Sketch Plan #3



WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

1031.70
 - 25%
 773.775
 + 30
 + 920
 1723.78

FIRST CAPITAL INSSURANCE LIMITED
 80 ROBINSON RD #09-02/03
 068898

Estimate : ES000174

COR: \$1723.78
 @
 3 days

Attention : Motor Claim Department
 Contact : 6222 2311 Fax No. : 6222 3547

Date : 18/06/2018
 Vehicle Num. : SLP 7634Z (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 23/05/2018
 Claim No. :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BUMPER ✓ DMG	550.00	450
2.	1	FRONT BUMPER RETAINER RH ✗ ✓ DLS	130.00	107.20
3.	1	FRONT FENDER - RH R	960.00	
4.	1	FRONT FENDER UNDER DUST COVER - RH ✗ NN	250.00	
5.	1	FRONT HEADLAMP - RH ✗ NN	2,560.00	
6.	1	FRONT FOG LAMP - RH ✓ SCR	980.00	474.50

List Total S\$: 5,410.00
 25.00% Discount S\$: 1,352.50
4,057.50

SPECIAL NETT ITEMS :				
1.	1	FRONT BUMPER CLIP NCC	50.00	30
2.	1	FRONT FENDER UNDER DUST COVER CLIPS NN	50.00	X

Special Nett Total S\$: 100.00

LABOUR :
 LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS. 900.00 400

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER) 800.00 400

REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME. 280.00 120

Labour Total S\$: 1,980.00

E. & O.E. Total S\$: 6,137.50
 =====

3 days

for WORLD AUTO PTE LTD

Sathya Sai
 19/6/2018

Sathya Sai @ lkkauto.com

- Part by part repair
- Question mark item photo
- Photo before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010291/Nrd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-10-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2488C	Veh. Inspected	SLP 7634Z
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18004166MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	06/06/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU603560117	Colour	SILVER
Odometer	111399	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	PIRELLI	6 mm
L/H Front Tyre	195/65 R15	PIRELLI	6 mm
R/H Rear Tyre	195/65 R15	PIRELLI	6 mm
L/H Rear Tyre	195/65 R15	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/05/2018	Inspection Date	19/06/2018
Survey held at	NO.1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 7634Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DAMAGED	550.00	450.00
1	FRONT BUMPER RETAINER RH	DISTORTED	130.00	107.20
1	FRONT FENDER-RH	TO REPAIR SEE LABOUR	950.00	-
1	FRONT FENDER UNDER DUST COVER-RH	NOT NECESSARY	250.00	-
1	FRONT HEADLAMP-RH	NOT NECESSARY	2,550.00	-
1	FRONT FOG LAMP-RH	SCRATCHED	980.00	474.50
	LESS 25% DISCOUNT		-1,352.50	-257.92
			4,057.50	773.78
SPECIAL NETT ITEMS				
1	FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	FRONT FENDER UNDER DUST COVER CLIPS (SN)	NOT NECESSARY	50.00	-
			100.00	30.00
LABOUR				
	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT,CUT/WELD,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER-RH.		900.00	400.00
	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER).		800.00	400.00
	REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME.		280.00	120.00
			1,980.00	920.00
GRAND TOTAL			6,137.50	1,723.78
RECOMMENDED COST OF REPAIRS				1,723.78

Report Ref No. CS/FC118010291/Nrd3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.