

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB574E  
Ref. No : TAX/05/18/2142  
Reg. Date : 12/09/2014  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS  
Name of Driver : LOW SIEW KIONG  
Type of Accident : CHAIN COLLISION  
Date / Time of Accident : 31/05/2018 01:45:00 PM  
Accident Reported Date / Time : 31/05/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by :  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024096363  
Special Instruction to ARC, if any :  
SLH4499J - AIG - LKK / *Repair after repair*  
Prepared Date : 31/05/2018 03:56:56 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36UX05748358

Mileage

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 558.00	0.00
Total Material Charges	: 1,005.82	1,005.82
Other Charges	: 280.00	0.00
<b>TOTAL</b>	<b>: 2,181.82</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 2,200.00</b>	<b>0.00</b>
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 31/05/2018 04:22:52 PM	01/01/1900 12:00:00 AM

01/06/18 @ 1435

Prepared / Adjusted Date :

Remarks :

Prepared Date : 31/05/2018 04:22:52 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	338.00	0.00 <del>338</del> 200
<b>Total Labour</b>	<b>338.00</b>	<b>0.00</b>

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 X
<b>Total Spray Painting &amp; Panel Beating</b>	<b>558.00</b>	<b>0.00</b>

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>280.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>Turn</i>	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace <i>AM</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>Ma</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>?</i>	No
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace <i>?</i>	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace <i>?</i>	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace <i>?</i>	No
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace <i>?</i>	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace <i>?</i>	No
<b>TOTAL MATERIALS</b>								<b>1,257.30</b>	<b>1,257.28</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>1,005.82</b>	<b>1,005.82</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									