

15/5/2019

INS CASE OWNER:

Francis

CC4 ASM
AXA 1801 0302, web352LKK:
IDAC:

Surveyor:

mrm

DOI:

ASSIGNMENT

Date / Time:

6/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDE 7504

Name of Insured:

EOM HONG LAM KENNY

Insured Tel No.:

HP:

3/6/18

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

880002 / 50009

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLO 8507p



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans
Eurosars

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

7/6/18
Asher

SLO 8507p - X

SDE 7504 - X

Smartclaim

- OMR, sent out 1st letter

19-6-18 12pm CAUSED OLD CONFIRMED ACCIDENT. OLD REPAIR ENDED TP, INFORM TP CLAIM AGREE TO SETTLE AND PAYMENT FROM NOD ISSUE.

Email WSP LIABILITY CLAIM.

STAGE

DATE / PIC

Non-Reporting ltr (1st): 6-6-18

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

EMAIL 5.7.18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 3.7.18

Sent By: 159

FINALIZATION

Date/Time: 23.8.18

Confirm with: CAR

Confirm by: DKS

Repair Cost:

PIP

SS 5,434.50

(6 days) Reduction:

53 %

Email

Call

FINAL SETTLEMENT

Date/Time: 21.12.18

Confirm with: 364

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

31

If NO or B 28, Ass. Lia:

Repair Cost:

a/651:

SS 5,814.92

OLD REPAIR ENDED TP

Loss of Rental (LOR):

a/651:

SS 749.00

(7 days) x 100

Loss of Use (LOU):

SS -

(S

x days)

Loss of Income (LOI):

SS -

(S

x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 350

Total:

SS 6,565.92

Global Sum SS:

FINAL PAYMENT

Date/Time: 21.12.18

Confirm with: 364

Email

Call

Payee 1:

SS 6,565.92

Name 1:

TRANS EUROKARS PTE LTD.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASSIGNMENT

From: Date: 02/07/2018

Estimated Cost:

On TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 8507P

at Workshop m/s TransEurokars

of No. 5 ubi close

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record) after 11 am

Make of Veh: Vion

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 6816

IDAC Accident Rpt: Consistent? : Yes or No

GA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction 17452724 Pys.

PP: 5,434.50 (RED: 6,021.19 525/-)

Veh No: SLD 8507P Yr Regn: 6, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: mazda 2 sp c.c. 1496

Colour: Gray A/C: Insured / Std / NI / NA

Sp. Reading: 24004 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MM 6DL 25AAGW 192154

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 185/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 4/6/18

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 2/7/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18010302/eb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 06-06-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDE 750U	Veh. Inspected	SLD 8507P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	04/06/2018	Inspection Date	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Wong Mei-Yi Vivian ADDRESS : Blk 9 Simei Street 4 #11-03 Singapore 529865 TEL :		WIP : 19044 EXCESS : DATE: 5-Jun-18	
VEH NO :	SLD8507P	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	MM6DL2SAAGW192154	MILEAGE :		TYPE OF CLAIM :	Third Party Claim
MODEL :	MAZDA2	DATE REG.:	29-Jun-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	1	MDB7A-50-221BBB	10/12	—	\$ 909.00 ✓
2	1	MD350-51-5L0E	11	X	\$ 50.40
3	1	MD350-51-5M0E	11	X	\$ 50.40
4	1	MDB7A-50-2J1	11	X	\$ 21.70
5	1	MDB7A-50-2H1	11	X	\$ 21.70
6	1	MDB7H-50-251	11	X	\$ 23.20
7	1	MKD53-50-251	11	X	\$ 5.10
8	2	MDB7A-50-271	11	X	\$ 24.60
9	7	MB45A-56-146A	11	—	\$ 19.60 ✓
10	4	MBHN1-50-021A	11	—	\$ 10.00 ✓
11	1	M9991-00-501	11	—	\$ 2.80 ✓
12	3	MG51D-50-EM1A	11	—	\$ 24.30 ✓
13	1	MDAY0-52-61X	11	X	\$ 820.70
14	1	MDB7A-56-951	11	X	\$ 107.50
15	1	MDB7A-56-820A	11	X	\$ 181.80
16	1	MDB7G-51-721	11	✓	\$ 55.10 ✓
17	1	MDB7G-51-730	11	✓	\$ 55.40 ✓
18	1	MDB7G-51-771	11	✓	\$ 64.30 ✓
19	1	MDBYA-70-75Z	11	X	\$ 624.70
20	1	MKD47-67-6NXX	11	—	\$ 105.80 ✓
21	1	MKD45-67-6NYA	11	—	\$ 2.50 ✓
22	1	MK1Y9-67-SH3	11	X	\$ 17.30
23	1	MDB7A-51-163	11	✓	\$ 31.90 ✓
24	1	MDB7A-51-153	11	✓	\$ 31.90 ✓
25	1	MDB7A-51-3J8	11	✓	\$ 46.20 ✓
26	1	MDB7A-51-3H8	11	✓	\$ 46.20 ✓
TOTAL PARTS					\$ 3,354.10
LESS 10%					\$ 335.41
TOTAL PARTS COST					\$ 3,018.69

Labour Description				
1		TO REPLACE REAR BUMPER, REAR END PANEL AND BOOT LID. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1650 ✓	\$ 2,640.00
2		TO RESPRAY REAR BUMPER, REAR END PANEL, BOOT LID.	1890 ✓	\$ 2,520.00
3	MZ-BR-REVSSEN	TO TRANSFER REVERSE SENSORS.	330 ✓	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	11 X	\$ 660.00
5	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	11 X	\$ 350.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	11 X	\$ 250.00
7	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	11 X	\$ 660.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120 ✓	\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150 ✓	\$ 350.00
10	MZ-BR-SUNDRI	SUNDRIES.	net 30 ✓	NETT \$ 100.00

not allowed
 due to excess
 2/7/18
 Tel. 62863561
 the ph. Behn party.
 G L.

TOTAL LABOUR	\$ -	\$ 8,440.00
TOTAL PARTS	\$ -	\$ 3,018.69
TOTAL	\$ -	\$ 11,458.69
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
 THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
 REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
 CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
 WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED
 ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
 PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair/painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALIZATION COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Wong Mei-Yi Vivian ADDRESS : Blk 9 Simei Street 4 #11-03 Singapore 529865 TEL :		WIP : 19044 EXCESS : DATE: 5-Jun-18	
VEH NO :	SLD8507P	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	MM6DL2SAAGW192154	MILEAGE :		TYPE OF CLAIM :	Third Party Claim
MODEL :	MAZDA2	DATE REG.:	29-Jun-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MD87A-50-221B8B	\$ 909.00	\$ 909.00
2	REFLECTOR LHS	1	MD350-51-5L0E	\$ -	\$ 50.40
3	REFLECTOR RHS	1	MD350-51-5M0E	\$ -	\$ 50.40
4	RETAINER LHS	1	MD87A-50-2J1	\$ -	\$ 21.70
5	RETAINER RHS	1	MD87A-50-2H1	\$ -	\$ 21.70
6	BRACKET LHS, REAR BUMPER	1	MD87H-50-251	\$ -	\$ 23.20
7	BRACKET CENTER, REAR BUMPER	1	MKD53-50-251	\$ -	\$ 5.10
8	STAY BRACKET, REAR BUMPER	2	MD87A-50-271	\$ -	\$ 24.60
9	FASTENER, REAR BUMPER	7	MB45A-56-146A	\$ 19.60	\$ 19.60
10	GROMMET, REAR BUMPER	4	MBHN1-50-021A	\$ 10.00	\$ 10.00
11	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80	\$ 2.80
12	TAPE, PROTECTOR, REVERSE SENSOR	3	MGS1D-50-EM1A	\$ 24.30	\$ 24.30
13	BOOTLID	1	MDAY0-52-61X	\$ -	\$ 820.70
14	WEATHERSTRIP, BOOTLID	1	MD87A-56-951	\$ -	\$ 107.50
15	LOCK, BOOTLID	1	MD87A-56-820A	\$ -	\$ 181.80
16	ORNAMENT, MAZDA2	1	MD87G-51-721	\$ 55.10	\$ 55.10
17	MASCOT, REAR	1	MD87G-51-730	\$ 55.40	\$ 55.40
18	ORNAMENT, SKYACTIVE	1	MD87G-51-771	\$ 64.30	\$ 64.30
19	REAR END PANEL	1	MDBYA-70-75Z	\$ -	\$ 624.70
20	ANTENNA, SMART KEYLESS	1	MKD47-67-6NXA	\$ 105.80	\$ 105.80
21	CLIP, ANTENNA	1	MKD45-67-6NYA	\$ 2.50	\$ 2.50
22	CORD, SHORT ANTENNA	1	MK1Y9-67-SH3	\$ -	\$ 17.30
23	GASKET(LHS), TAILLAMP	1	MD87A-51-163	\$ 31.90	\$ 31.90
24	GASKET(RHS), TAILLAMP	1	MD87A-51-153	\$ 31.90	\$ 31.90
25	GASKET(LHS), BOOTLID	1	MD87A-51-3J8	\$ 46.20	\$ 46.20
26	GASKET(RHS), BOOTLID	1	MD87A-51-3H8	\$ 46.20	\$ 46.20
TOTAL PARTS				\$ 1,405.00	\$ 3,354.10
LESS 10%				\$ 140.50	\$ 335.41
TOTAL PARTS COST				\$ 1,264.50	\$ 3,018.69

Labour Description				
1		TO REPLACE REAR BUMPER, REAR END PANEL AND BOOT LID.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,650.00	\$ 2,640.00
2		TO RESPRAY REAR BUMPER, REAR END PANEL, BOOT LID.	\$ 1,890.00	\$ 2,520.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ -	\$ 660.00
5	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	\$ -	\$ 350.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ -	\$ 250.00
7	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ -	\$ 660.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
10	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
TOTAL LABOUR			\$ 4,170.00	\$ 8,440.00
TOTAL PARTS			\$ 1,264.50	\$ 3,018.69
TOTAL			\$ 5,434.50	\$ 11,458.69
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 5,434.50	
GST 7%			\$ 380.42	\$ -
GRAND TOTAL			\$ 5,814.92	\$ -

NUMBER OF DAYS: 6 WORKING DAYS(EXCLUDE WAITING FOR PARTS,SURVEY,AUTHORIZATION,SATURDAY,SUNDAY& PH)




Service Request Details

Claim

S8M00JLZ

Reference

None 

Loss Date

June 4, 2018

Request Date

June 5, 2018

Due Date

June 12, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLD8507P

Make

TPVD MAZDA

Service Address

...

Primary Contact/Insured

KOH HONG LIANG KENNY

9, CHENG SOON CRESENT, 599881, Singapore

KOHKENNY22@GMAIL.COM

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

INSD GIA NOT REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

06 JUNE 2018

**KOH HONG LIANG KENNY
9, CHENG SOON CRESENT
Singapore 599881**

Dear Sir,

**OUR REF : CC4/ASM18010302/eb3
YOUR REF : SDE 750U**

**ACCIDENT INVOLVING SDE 750U & SLD 8507P ALONG PIE TOWARDS TUAS
BEFORE ADAM ROAD ON 04/06/2018**

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)

- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to AsherSng@lkkauto.com or deliver it by hand to 51 Ubi Avenue 1, #01-25 Paya Ubi Ind. Park S(408933).

You should also IMMEDIATELY forward us by hand any letters or Courts Summons received from the other party involved in the accident. You should not negotiate, admit liability or offer payment to them.

We would like to bring to your attention that under Policy Condition, your insurer shall have full discretion in the process and settlement of the said third party claim subject to the merits of the case and according to the rights afforded under the policy.

Your NCD (No Claim Discount) will be reduced by 30% (20% for motorcycle/commercial vehicles) if a claim is made under your policy.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter. In accordance with the policy conditions, your insurer reserve the right to repudiate the said claim to you should you not give proper notice to us of any occurrence which may give rise to it.

Kindly contact us at 6841 6051 if you have any further enquiries.

Yours sincerely,
Claim department

This is a computer generated letter and no signature is required.

CC: AXA INSURANCE PTE LTD



MANDATE REQUEST FOR S8M00JLZ

✓.✓

Type

🔗 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$5,814.92 (w/GST) Loss of Rental: \$749.00 (7days x \$100) (w/GST) LTA : \$2.00 Total: \$6,565.92 Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (24/11/2018)

[Reply](#)



Re:MANDATE REQUEST FOR S8M00JLZ

Type

🔗 Question

Message

PLS PROCEED QUANTUM AS PROPOSED

Reply

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SDE 750U (Insd veh)	Model:	MAZDA 2 SP (A)
	SLD 8507P (TP veh)		
Date of Accident:	03/06/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	12,260.80
Final Repair Cost	:	\$	5,814.92
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	749.00 7 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	6,565.92

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____ _____			

Payment Instruction: Payee's Breakdown			
1)	TRANS EUOKARS PTE LTD	:	\$ 6,565.92

NUR SHAQILAH BTE ABDOL
WAHAB

11/02/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18010302/Ueb3s2	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: KIAN CHUAN			Date : 11-02-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDE 750U	Veh. Inspected	SLD 8507P	
Policy No.	GA025652	Coverage (\$)	0.00	
Claim No.	S8M00JLZ	Excess (\$)	0.00	
Assign From	KIAN CHUAN	Assign Date	06/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 2 SP (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MM6DL2SAAGW192154	Colour	GREY	
Odometer	24004	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60R16	DUNLOP	6 mm	
L/H Front Tyre	185/60R16	DUNLOP	6 mm	
R/H Rear Tyre	185/60R16	DUNLOP	6 mm	
L/H Rear Tyre	185/60R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/06/2018	Inspection Date	02/07/2018	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 8507P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	DENTED / DEFORMED	909.00	909.00
1	REFLECTOR LHS (CONSISTENT)	NOT NECESSARY	50.40	-
1	REFLECTOR RHS (CONSISTENT)	NOT NECESSARY	50.40	-
1	RETAINER LHS (CONSISTENT)	NOT NECESSARY	21.70	-
1	RETAINER RHS (CONSISTENT)	NOT NECESSARY	21.70	-
1	BRACKET LHS, REAR BUMPER (CONSISTENT)	NOT NECESSARY	23.20	-
1	BRACKET CENTER, REAR BUMPER (CONSISTENT)	NOT NECESSARY	5.10	-
2	STAY BRACKET, REAR BUMPER (CONSISTENT)	NOT NECESSARY	24.60	-
7	FASTENER, REAR BUMPER (CONSISTENT)	NECESSARY	19.60	19.60
4	GROMMET, REAR BUMPER (CONSISTENT)	NECESSARY	10.00	10.00
1	GROMMET, REAR BUMPER (CONSISTENT)	NECESSARY	2.80	2.80
3	TAPE, PROTECTOR, REVERSE SENSOR (CONSISTENT)	NECESSARY	24.30	24.30
1	BOOTLID (CONSISTENT)	NOT NECESSARY	820.70	-
1	WEATHERSTRIP, BOOTLID (CONSISTENT)	NOT NECESSARY	107.50	-
1	LOCK, BOOTLID (CONSISTENT)	NOT NECESSARY	181.80	-
1	ORNAMENT, MAZDA2 (CONSISTENT)	NECESSARY	55.10	55.10
1	MASCOT, REAR (CONSISTENT)	NECESSARY	55.40	55.40
1	ORNAMENT, SKYACTIVE (CONSISTENT)	NECESSARY	64.30	64.30
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	624.70	-
1	ANTENNA, SMART KEYLESS (CONSISTENT)	BROKEN	105.80	105.80
1	CLIP, ANTENNA (CONSISTENT)	CRACKED	2.50	2.50
1	CORD, SHORT ANTENNA (CONSISTENT)	NOT NECESSARY	17.30	-
1	GASKET(LHS), TAILLAMP (CONSISTENT)	NECESSARY	31.90	31.90
1	GASKET(LHS), TAILLAMP (CONSISTENT)	NECESSARY	31.90	31.90
1	GASKET(LHS), BOOTLID (CONSISTENT)	NECESSARY	46.20	46.20
1	GASKET(RHS), BOOTLID (CONSISTENT)	NECESSARY	46.20	46.20
	LESS 10% DISCOUNT		-335.41	-140.50
			3,018.69	1,264.50

Report Ref No. CC4/ASM18010302/Ueb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	30.00
			100.00	30.00
	LABOUR			
	TO REPLACE REAR BUMPER, REAR END PANEL AND BOOT LID. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		2,640.00	1,650.00
	TO RESPRAY REAR BUMPER, REAR END PANEL, BOOT LID.		2,520.00	1,890.00
	TO TRANSFER REVERSE SENSORS.		660.00	330.00
	TO TRANSFER REVERSE CAMERA.	NOT NECESSARY	660.00	-
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	NOT NECESSARY	350.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	NOT NECESSARY	660.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
			8,340.00	4,140.00
	GRAND TOTAL		11,458.69	5,434.50
	RECOMMENDED COST OF REPAIRS			5,434.50

Report Ref No. CC4/ASM18010302/Ueb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.