



ESTIMATE TO REPAIR

VEHICLE NO. : SKB 6555 K
 MAKE : PORSCHE
 MODEL : 981 BOXSTER PDK WO SES
 YEAR : 2014
 CHASSIS NO : WP0ZZZ98ZDK103454

SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

DATE : 5-Jun-18
 DATE OF ACCIDENT : 23-May-18
 THIRD PARTY REF : SLL6616D / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 1,920.00
1 pc	Rear Bumper Lower Spoiler				\$ 355.00
2 pcs	Rear Bumper Sensor		\$ 130.00		\$ 260.00
					\$ 2,535.00
	Less 10%				\$ 253.50
					\$ 2,281.50
	To putty & spray painting.				\$ 350.00
	To check rear wiring and replace sensor.				\$ 150.00
	Labour Charges.				\$ 300.00
TG-RA/-	TOTAL				\$ 3,081.50

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
 Co.Reg No. I99307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd