



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18010304/Kps3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 14-05-2020



ATTN:STACEY NG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SFX 57P	<b>Veh. Inspected</b>	SLR 9687Y
<b>Policy No.</b>	GA318840/1	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S8M00JMF	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	06/06/2018

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA VIOS (A)	<b>c.c</b>	1497
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2008
<b>Chassis No.</b>	MR053HY9305072404	<b>Colour</b>	METALLIC BLACK
<b>Odometer</b>	187419	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/55 R16	BRIDGESTONE	5 mm
<b>L/H Front Tyre</b>	195/55 R16	BRIDGESTONE	5 mm
<b>R/H Rear Tyre</b>	195/55 R16	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	195/55 R16	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	28/05/2018	<b>Inspection Date</b>	11/06/2018
<b>Survey held at</b>	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------