

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5779Z
 Ref. No : TAX/06/18/2016
 Reg. Date : 12/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : ONG CHIN LYE
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 05/06/2018 03:40:00 PM
 Accident Reported Date / Time : 05/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096448
 Special Instruction to ARC, if any :
 SGH1815J - AXA
 Prepared Date : 05/06/2018 04:56:10 PM



Catuya Sai

6/6/2018

sebastianyeang@lkkauto.com

- Part by Part repair
- Question mark item photo
- Photo before paint

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU003575874

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,656.00	0.00
Total Material Charges	: 3,702.13	3,702.13
Other Charges	: 676.88	0.00
TOTAL	: 7,049.01	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00 2 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 06/06/2018 10:46:58 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/06/2018 10:46:50 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 6/6/2018 10:49:33 AM

Section B - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 400
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
TO RESPRAY TAIL GATE	378.00	0.00 x
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 x
TO RESPRAY REAR PANEL	180.00	0.00 ?
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 ?
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 ?
Total Spray Painting & Panel Beating	1,656.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 150
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 50
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 40
TO WASH AND VACUUM	60.00	0.00 x
Total Other Costs	676.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY ✓ _{SCR}	1	423.90	25.00	317.92	Replace	Replace	No
52161160 10			CLIPS PIECE, FRT & RR BUMPER ✓ _{NEC}	10	1.50	25.00	11.25	Replace	Replace	No
52462470 30			PAD, RR BUMPER, RH & LH, 1 ?	2	3.80	25.00	5.70	Replace	Replace	No
52462470 20			PAD, RR BUMPER, RH & LH, 2 ?	2	3.80	25.00	5.70	Replace	Replace	No
52462470 10			PAD, RR BUMPER, RH & LH, 3 ?	2	3.80	25.00	5.70	Replace	Replace	No
52191470 30			SEAL, RR BUMPER ARM, RH & LH ?	2	11.00	25.00	16.50	Replace	Replace	No
52023470 30			REAR BUMPER REINFORCEMENT ?	1	318.80	25.00	239.10	Replace	Replace	No
			SENSOR REVERSE ?	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER ✓ _{NEC}	2	60.00	0.00	120.00	Replace	Replace	No
52576470 40			RETAINER, RR BUMPER, LH ?	1	111.50	25.00	83.62	Replace	Replace	No
52575470 40			RETAINER, RR BUMPER, RH ?	1	112.70	25.00	84.52	Replace	Replace	No
52453470 10			GUARD, RR BUMPER, LOWER ?	1	558.30	25.00	418.72	Replace	Replace	No
52169470 20			COVER, GUARD RR BUMPER LOWER ✓ _{CUT}	1	14.80	25.00	11.10	Replace	Replace	No
52461470 10			PAD, RR BUMPER, CTR ?	3	2.20	25.00	4.95	Replace	Replace	No
52566479 00			FILLER, RR BUMPER, LH ?	1	119.90	25.00	89.92	Replace	Replace	No
52565479 00			FILLER, RR BUMPER, RH ?	1	119.90	25.00	89.92	Replace	Replace	No
67005474 40			TAIL GATE PANEL SUB-ASSY, BACK DOOR X _{NN}	1	929.60	25.00	697.20	Replace	Replace	No
76801471 10A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY X _{NN}	1	891.20	25.00	668.40	Replace	Replace	No
75403480 10			EMBLEM SUB-ASSY REAR X _{NN}	1	46.30	25.00	34.72	Replace	Replace	No
75441470 90			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR X _{NN}	1	52.30	25.00	39.22	Replace	Replace	No
75442471 30			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR X _{NN}	1	52.30	25.00	39.22	Replace	Replace	No
	COMMO N		SMRT LOGO X _{NN}	1	7.80	0.00	7.80	Replace	Replace	No
	COMMO N		STICKER DECAL 6555 8888 X _{NN}	1	21.60	0.00	21.60	Replace	Replace	No
58307470 30			END PANEL SUB-ASSY, BODY LOWER BACK ?	1	629.80	25.00	472.35	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX X _{NN}	1	37.00	0.00	37.00	Replace	Replace	No
TOTAL MATERIALS								3,702.18	3,702.13	
TOTAL MATERIALS(Discounted)							3,702.13	3,702.13		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									